

**Release Notes**  
**for**  
**OmniVista 2500 NMS Enterprise**  
**Version 4.4R1**



**September 2019**  
**Revision C**  
**Part Number 033422-10**  
**READ THIS DOCUMENT**

**OmniVista 2500 NMS**  
**for**  
**VMware ESXi: 5.5, 6.0, 6.5, 6.7**  
**VirtualBox: 5.2.x**  
**MS Hyper-V: 2012 R2 and 2016**  
**MS Hyper-V on Windows 10**  
**Professional**

ALE USA Inc.  
26801 West Agoura Road  
Calabasas, CA 91301  
+1 (818) 880-3500

## Table of Contents

<b>1.0 Introduction</b> .....	<b>1</b>
1.1 Technical Support Contacts .....	1
1.2 Documentation .....	1
1.3 New in 4.4R1.....	1
1.4 Feature Set Support .....	4
<b>2.0 System Requirements</b> .....	<b>7</b>
2.1 Proxy Requirements.....	9
2.2 Firewall Requirements.....	9
2.3 Recommended System Configurations .....	11
2.4 High-Availability Installation Limitations .....	12
<b>3.0 Installation</b> .....	<b>12</b>
3.1 Licensing.....	13
3.2 Upgrading a Starter Pack or Evaluation License to a Production License.....	14
<b>4.0 Launching OmniVista 2500 NMS</b> .....	<b>15</b>
4.1 Logging Into OmniVista 2500 NMS-E 4.4R1 .....	15
<b>5.0 Known Problems</b> .....	<b>15</b>
5.1 Known Analytics Problems .....	15
5.2 Known Application Visibility Problems .....	16
5.3 Known AP Registration Problems.....	16
5.4 Known CLI Scripting Problems.....	17
5.5 Known Discovery Problems.....	17
5.6 Known Locator Problems .....	18
5.7 Known Notifications Problems .....	18
5.8 Known PolicyView Problems .....	19
5.9 Known Report Problems.....	20
5.10 Known Resource Manager Problems .....	20
5.11 Known Topology Problems.....	21
5.12 Known Unified Access Problems.....	21
5.13 Known UPAM Problems .....	22
5.14 Known Users and User Groups Problems .....	24
5.15 Known VM Manager Problems.....	24
5.16 Known WLAN Problems.....	25
5.17 Known Other Problems .....	25

## Table of Contents (continued)

<b>6.0 Release Notes PRs Fixed .....</b>	<b>29</b>
6.1 PRs Fixed Since 4.3R3 .....	29
6.2 PRs Fixed Since 4.3R2 .....	32
6.3 PRs Fixed Since 4.3R1 .....	33
6.4 PRs Fixed Since 4.2.2.R01 (MR 2).....	35
6.5 PRs Fixed Since 4.2.2.R01 (MR 1).....	36
6.6 PRs Fixed Since 4.2.2.R01 GA .....	36
6.7 PRs Fixed Since 4.2.1.R01 (MR 2).....	36
6.8 PRs Fixed Since 4.2.1.R01 (MR 1).....	37
6.9 PRs Fixed Since 4.2.1.R01 GA .....	38
6.10 PRs Fixed Since 4.1.2.R03 .....	38
6.11 PRs Fixed Since 4.1.2.R02 .....	39
6.12 PRs Fixed Since 4.1.2.R01 Maintenance Release .....	39
6.13 PRs Fixed Since 4.1.2.R01 .....	39
6.14 PRs Fixed Since Release 4.1.1 .....	39
6.15 PRs Fixed Since 3.5.7 Maintenance Build .....	39
6.16 PRs Fixed Since Release 3.5.7 GA.....	39
<b>Appendix A – Enabling DCOM on Hyper-V.....</b>	<b>A-1</b>
Enable DCOM on Hyper-V (Standalone Installation) .....	A-1
Enable DCOM on Hyper-V (High-Availability Installation).....	A-2

## Revision History

Release	Revision	Date	Description of Changes
4.4R1	C	09/09/19	Release Notes Update
4.4R1	B	07/24/19	Release Notes Update
4.4R1	A	07/15/19	GA Release
4.3R3	A	03/15/19	GA Release
4.3R2	B	01/21/19	Release Notes Update
4.3R2	A	11/27/18	GA Release
4.3R1	B	07/12/18	Release Notes Update
4.3R1	A	06/06/18	GA Release
4.2.2.R01	C	01/26/18	Maintenance Release 2
4.2.2.R01	B	12/11/17	Maintenance Release 1
4.2.2.R01	A	08/24/17	GA Release
4.2.1.R01	E	06/16/17	MR 2 Release Notes Update
4.2.1.R01	D	05/30/17	Maintenance Release 2
4.2.1.R01	C	02/02/17	Maintenance Release 1
4.2.1.R01	B	09/30/16	Release Notes Update
4.2.1.R01	A	09/22/16	GA Release
4.1.2.R03	A	01/29/16	GA Release
4.1.2.R02	A	05/22/15	GA Release
4.1.2.R01	B	12/19/14	Maintenance Release
4.1.2.R01	A	10/24/14	GA Release
4.1.1	B	12/19/14	Maintenance Release
4.1.1	A	09/10/14	GA Release
3.5.7	B	04/21/14	Maintenance Release
3.5.7	A	01/27/14	GA Release

## 1.0 Introduction

This document details known problems and limitations in OmniVista 2500 NMS Enterprise 4.4R1 (OV 2500 NMS-E 4.4R1), and workarounds are included. Please read the applicable sections in their entirety as they contain important operational information that may impact successful use of the application.

OmniVista 2500 NMS Enterprise 4.4R1 (OV 2500 NMS-E 4.4R1) is installed as a Virtual Appliance, and can be deployed on the following hypervisors: VMware ESXi, VirtualBox, and MS Hyper-V:

- VMware ESXi: 5.5, 6.0, 6.5, and 6.7
- VirtualBox: 5.2.x
- MS Hyper-V: 2012 R2 and 2016
- MS Hyper-V on Windows 10 Professional.

## 1.1 Technical Support Contacts

For technical support, contact your sales representative or go to the ALE Business Portal:

- <https://businessportal2.alcatel-lucent.com>

## 1.2 Documentation

The user documentation is contained in the on-line help installed with this product. Click on the Help link (?) in the upper-right corner of a page to access the online help for the page.

## 1.3 New in 4.4R1

### Hardware/Release Support

#### *Devices*

- **OS6900-V72/C32 Switches** - OS6900-V72 and C32 Switches are now supported in all OmniVista applications.

#### *Software*

- **AOS 6.7.2.R06** - OmniVista 2500 NMS now supports AOS 6.7.2.R06 on all previously supported OS6350 and OS6450 Switches.
- **AOS 8.5R4, AOS 8.6R1** - OmniVista 2500 NMS now supports AOS 8.5R4 and AOS 8.6R1 on OS6900-V72 and C32 Switches as well as all previously supported switches.
- **AWOS 3.0.6.28** - OmniVista 2500 NMS now supports AWOS 3.0.6.28 on all previously supported Stellar AP Devices.

### UI Enhancements Across Applications

- **Chinese Mandarin Localization** - OmniVista is now available in Chinese Mandarin. The language (English or Chinese) can be set during OmniVista installation; or it can be set at any time after installation in the Preferences application (Administration – Preferences – User Settings – Locale). Go to the Locale page and

Once OmniVista is installed, you must import the Chinese language online help files. The help files are contained in a Zip File on the Business Portal Website under "[R4.4 R01 – OmniVista 2500 NMS Enterprise](#)" (click on the Build 58 GA drop-down to locate the "Online Help – Chinese" file). Download the file to your computer, then import the file (zn-ch.zip) into OmniVista.

The help files are imported on the Install Locale Screen in the Preferences application (Administration – Preferences – System Settings – Install Locale). Go to the Install Locale Screen, click on the **Browse** button to locate the file (zn-ch.zip) on your computer, then click on the **Import** button. The import can take several minutes. When the import is complete, the following message will appear at the top of the screen: "Import file zh-cn.zip successful." The Chinese help files will now display in the Chinese UI.

**Note:** While it is allowed, users should **not** enter Chinese characters in OmniVista forms. You must enter English in any fields in OmniVista. The limitation exists because managed devices do not support the Chinese language.

### IPv6 Support

- IPv6 is supported for wireless clients in the UPAM, WLAN, Unified Access, Locator, and Groups (Network Groups, Multicast Groups) applications. IPv6 is also supported when configuring the Captive Portal Virtual IP.

### Application Updates/Enhancements

The following section detail updates and enhancements to existing OmniVista applications.

#### *AP Registration*

- **Stellar AP Neighbor Table** - You can click on the Static Neighbor AP field in the Access Points Detail Panel to view information about any neighbors for the AP.

#### *Application Visibility*

- **OS6900/OS10K Switch Support** - Application Visibility is no longer supported on OS6900/OS10K Switches.
- **Additional Reports Supported on Stellar APs** - "Top Users Per Application" and "Top Applications Per User Reports" are now supported on Stellar APs in addition to OS6860E Devices.

#### *Audit*

- **Collect Support Info** - OmniVista now collects Support Information Logs for APs, in addition to AOS Devices. In addition, logs are now stored on the OmniVista Cirrus Server and can be downloaded to an OmniVista Client at any time. The logs are retained on the Server as configured in the new Preferences - Collect Support Info Screen.

#### *Discovery*

- **Managed Device Geo Site Assignment** - When adding a device, a new option allows you to initially assign the device to a Geo Site.

## Notifications

- **Trap Name Filter** - You can now filter traps from the OmniVista Database by Trap Name. Click on the "Filter" drop-down at the top of the table and enter a trap name(s) in the Trap Name field to display specific traps.

## Topology

- **Map Status Indicator** - A device status indicator is now displayed on the Globe icon in the Map drop-down in the upper left corner of the screen. The Globe icon in the drop-down displays the status of the highest-level notification of any device in the map (e.g., if all devices in a map are "Up", the icon is green, if a device in a map is a "Warning" state, the icon is orange, if a device in a map is "Down", the icon is Red).
- **Map Pin** - You can click on the Pin icon in the Map drop-down keep the Topology Map drop-down open. Click the Pin icon again to close it.
- **AP Mesh Network View** - AP Mesh networks are now displayed on Topology maps for Stellar APs in the Mesh Network are identified by Wi-Fi icons at endpoints between APs and a network symbol next to the Root AP in the network. A Mesh Link filter has also been added to Topology maps.
- **Geo Map Sub-Sites** - You can now create Sub-Sites within a Site (e.g., buildings, floors) by creating child maps from the logical Site map that is automatically created when you create a Site. The new Sub-Site map will appear as a sub-map under the Site in the Map drop-down at the upper-left corner of the screen. When you go to the Geo Map view, the total number of devices at the Site will be displayed in the Site circle (the total number of devices at the Site including all Sub-Sites), along with the device status and notifications status for all devices at the Site.

## Unified Access

- **Option 82 Feature** - A new DHCP Option 82 Feature has been added to the Global Configuration Template group to allow a DHCP Relay Agent to insert specific information into a request that is being forwarded to a DHCP Server by a Stellar AP. Once the feature is configured, it is enabled/disabled as part of an Access Role Profile. This feature is supported on AWOS 3.0.6.28 (GA) and higher.

## UPAM

- **UPAM Support for OAW Controllers and IAPs (including Aruba-branded devices)** - OAW Controllers and IAPs (including Aruba-branded devices) can now use UPAM for client authentication.
  - UPAM Works for IAPs for all use cases
  - UPAM works for OAW Controllers for MAC and 802.1x Authentication use cases
  - UPAM does not work for OAW Controllers for Captive Portal Authentication use cases
- **Machine Authentication for AD Servers** - OmniVista now supports 802.1x authentication of existing users in a Microsoft Active Directory in cases where the NETBIOS is not the same as the Active Directory name.

## WLAN

- **SSID Improvements** - The following improvements have been made to the SSIDs application:
  - **ESSID Renamed to SSID** - The ESSID field has been renamed to SSID.
  - **Multiple SSID Services** - You can now configure multiple SSID Services using the same SSID (previously called ESSIDs). For example, you could define an SSID called "Student" and have two SSID Services at different locations - "School 1" and "School 2".
  - **Implicit Access Policy** - A default Access Policy is automatically created for an SSID using the SSID Name when UPAM is selected for authentication. You can customize the default Access Policy by creating the SSID and then editing it. You can also select an existing Access Policy when configuring the SSID.
  - **Support for Multiple RADIUS Servers** - Multiple External RADIUS Servers are now supported when configuring an SSID.
  - **SSID Order Preference** - The order of the SSIDs listed is persisted for a user if the user changes the order of the SSIDs displayed.
  - **Horizontal Scroll Bar Visibility** - The horizontal scroll bar is now visible at all times.
  - **Expanded SSID Drop-Down List** - The SSID drop-down list at the top of each SSID column can now display up to 10 SSIDs.
- **WPA3 Encryption** - WPA3 Encryption is now supported in the WLAN application when configuring a wireless network.
- **Fixed Channel Width Setting in RF Profile** - You can now specify a fixed Channel width if needed even when the Channel Setting is "Auto". This ensures that all APs configured with the same RF profile are assigned channels that abide by the configured channel width.
- **Heat Map Stellar AP Neighbor Display** - You can now highlight neighbor Stellar APs in a Heat Map. Select an AP and click on the "Display Neighbor AP" in the Survey Toggle Panel to highlight any static neighbor APs or automatic discovery neighbor APs.

### **Multiple NIC Support**

OmniVista now supports the configuration of multiple NICs on the OmniVista VM so that different subnets can be created to isolate services. OmniVista supports three (3) IPs: the OmniVista IP, the Captive Portal IP and an additional OmniVista Web Management IP. Captive Portal can now be hosted on its own isolated subnet and assigned to its own NIC, providing more security. And the additional OmniVista Web Management IP address provides you with another way of accessing the OmniVista UI. (The IP address must be configured on a different NIC and different subnet than the OmniVista IP.)

## **1.4 Feature Set Support**

### **1.4.1 Element Manager Integration**

To provide additional support for supported devices with different architectures, OmniVista 2500 NMS can integrate with independent Element Managers to provide direct access to devices. Element Managers enable you to access, configure, and gather statistics from individual devices. The Element Managers currently supported in OmniVista 2500 NMS are listed below.



## OmniVista 2500 NMS Enterprise 4.4R1 Release Notes

Element Managers are platform independent and are interfaced through a web browser. They can be accessed in the **Topology** application by selecting a device in a Topology map and clicking on the **Webpage** operation in the Operations Panel on the right side of the screen.

Element Manager	Supported Devices	Description
WebView	<ul style="list-style-type: none"> <li>All supported AOS OmniSwitch Devices</li> </ul>	WebView
Web UI	<ul style="list-style-type: none"> <li>OS2200</li> </ul>	Web UI Device Management
Web UI	<ul style="list-style-type: none"> <li>All supported Stellar APs</li> </ul>	Web UI Device Management
Wireless Controller	<ul style="list-style-type: none"> <li>OAW-4030, OAW-4604, OAW-4704, IAP-105, IAP-205, IAP-225</li> </ul>	OAW EMS
Third-Party	<ul style="list-style-type: none"> <li>Cisco, OmniAccess ESR, Aruba OS</li> </ul>	Respective EMS

### 1.4.2 Device Feature Support

The following table details OV 2500 NMS-E 4.4R1 feature support by device.

Feature	OS10K 6900	OS6860/ OS6865	Other AOS	OS2220	Stellar APs	OA WLAN	OA ESR	3rd Party Switches
Application Visibility (1)		X			X			
Analytics (2)	X	X	X		X			
Basic MIB-2 Polling and Status Display	X	X	X	X		X	X	X (3)
ClearPass (BYOD) (4)	X	X	X					
CLI Scripting	X	X	X		X(5)	X	X	X
Discovery	X	X	X	X	X	X	X	X (3)
Locator	X	X	X	X	X	X		X (6)
mDNS		X	X (7)					
mDNS Gateway (8)	X	X	X		X			
PolicyView-QoS	X	X	X		X	X		
Premium Service (BYOD)		X	X					
ProActive Lifecycle Mgmt (PALM)	X	X	X	X	X	X		
Quarantine Manager (9)		X	X			X		
Resource Manager BU/Restore/Upgrade	X	X	X		X			
SIP (10)		X	X					
SPB/ERP (11) (12)	X	X	X					
Remote CLI	X	X	X			X	X	X
Topology Links (LLDP) (13)	X	X	X	X	X			
Trap Absorption	X	X	X	X	X	X		X
Trap Display/Trap Responder	X	X	X	X (14)	X	X	X	X
Trap Replay	X	X	X		X			

## OmniVista 2500 NMS Enterprise 4.4R1 Release Notes

Feature	OS10K 6900	OS6860/ OS6865	Other AOS	OS2220	Stellar APs	OA WLAN	OA ESR	3rd Party Switches
UPAM (Guest User, BYOD) (15)	X	X	X		X			
UNP (16)	X	X	X		X			
VLAN Configuration	X	X	X			X		
VM Manager	X	X	X					
VM Snooping	X (17)							
VXLANS	X (18)							
WLAN (SSID)					X			

**1.** The Application Visibility feature is supported on OS6860E Switches (AOS 8.2.1.R01 and later). It is also supported in a virtual chassis of OS6860/OS6860E Switches where at least one OS6860E is present. It is also supported on all Stellar APs models except AP1101, AP1201H.

**2.** The Analytics feature is supported on OS6250/6450 devices (6.7.1.R01 and later), OS6850/6855 devices (6.4.4.R01 and later, OS6860/6860E and OS6865 (8.3.1.R01 and later), OS6900 (8.3.1.R01 and later), OS9900 (8.3.1.R02 and later), and OS10K (7.3.4.R02 and later). It is also supported on Stellar APs (except for Top N Ports, Top N Application and Clients – sFlow, and performance monitoring).

**3.** Third-Party devices, such as Cisco and Extreme are supported; however, you must manually provide OIDs and map the OIDs to the mib-2 directory from the Third-Party Device Support feature in the Discovery application. Refer to online Discovery help for details.

**4.** ClearPass (BYOD) is supported on OS6850E/6855 Switches (AOS 6.4.6.R01 and later), OS6250, and OS6450 (6.7.1.R02 and later), and OS6860 (8.3.1.R01 and later).

**5.** CLI Scripting is not supported on Stellar APs, however you can connect (SSH) to a Stellar AP using the CLI Scripting application.

**6.** Requires MIB-2 support for 3rd-party devices.

**7.** AOS 6.4.6.R01 and later Switches only.

**8.** mDNS Gateway is supported on OS6450 Switches running AOS 6.72.R02 or higher; and OS6860E, OS6865, and OS6900 Switches running 8.4.1.R02 or higher.

**9.** The TAD feature in Quarantine Manager is only supported on OS6850, OS6855, OS9700 Switches running AOS 6.4.6.R01. Quarantine Manager is supported on OS6250, OS 6350, OS6400, OS6450, OS6850, OS 6855, OS 6860, OS6900, and OS10K Switches, as well as OA WLAN Devices.

**10.** The SIP feature is only supported on the following devices running 6.4.6.R01 and later: 6850E (C24/24x/48/48X, P24/24X/48/48X, U24X), 6855 (U24x), 9700E (C-24/48, P24, U2/6/12/24), 9800E (C24/48, P24, U2/6/12/24).

**11.** SPB is supported on OS6855, OS6860, OS6860E, OS6865, OS9000, OS6900, OS9900, and OS10K Switches.

**12.** ERP is supported as “early availability” feature on OS OS6400, OS6465, OS6560, OS6850, OS6855, OS6860, OS6860E, OS6865, OS9000, OS6900 (excluding C32 and V72 models), OS9900, and OS10K Switches.

**13.** OmniVista 2500 NMS does not display LLDP links reported by a single device. For a link to be displayed, both devices must be supported devices and LLDP MIB interface from each must have the Link.

LLDP Links for Third-Party Switches are supported and displayed in Topology maps. However, you must first add the Mibset for the device using the Third-Party Devices Support Feature in the Discovery application (Network – Discovery - Third Party Devices Support). Refer to the Discovery online Help for more details. Links between AOS and Third-Party devices as well as links between Third-Party devices are displayed in Topology maps. For this feature to work, the Third-Party device must support IEEE 802.1AB standard SNMP MIB “lldpMIB”.

**14.** Trap display is supported on OS2220 Switches. However, trap configuration must be performed on the device using the device’s web interface.

**15.** LDAP Role Mapping is supported with 802.1x Authentication only.

**16.** The UNP feature within Unified Access is supported on 6250, 6450, 6560, 6850E, 6855, 6860, OS6865, 6900, OS9900, OS10K devices, and OAW Controller and OAW IAP.

**17.** VM Snooping is supported on OS6900 and OS10K Switches 7.3.4.R02 and later). Note that on OS10K Switches, VM Snooping is only supported on OS10K-XNI-U16E NIs. VM Snooping is supported on a port/linkagg, fixed bridge port, UNP bridge port, service access port, and UNP Service Access Point. VM Snooping is not supported on eVB, SDP, or VXLAN service ports.

**18.** VXLANs are supported on OS6900-Q32/X72/C32/V72 Switches.

### 1.4.3 SSHv2/Telnet Element Management

Many devices provide element management through a user interface accessible through SSHv2/telnet. For example, you can perform element management for most Alcatel-Lucent Enterprise devices via telnet using the device’s CLI (Command Line Interface). You can use OmniVista 2500 NMS to access and configure telnet capable devices. This is generally not recommended if these tasks can also be performed using OmniVista 2500 NMS. If you change device configurations without using OmniVista 2500 NMS, configuration information stored by OmniVista 2500 NMS must then be refreshed to reflect the current device configuration, using manual or automatic polling.

You can telnet to a device using the CLI Scripting application or the Discovery or Topology applications. Refer to the switch documentation for information on how to use the CLI.

**Note:** To connect to Stellar APs, you must enable SSH at the AP Group level. If enabled, you will be able to connect (SSH) to all Stellar APs in the group. Telnet Scripting is not supported on Stellar APs.

## 2.0 System Requirements

The following builds are certified for OV 2500 NMS-E 4.4R1:

### AOS

- OS6250 – 6.7.1.R02, 6.7.1.R03, 6.7.1.R04
- OS6350 – 6.7.2.R04, 6.7.2.R05, 6.7.2.R06
- OS6400 – 6.4.5.R01, 6.4.5.R02 (limited support, restricted to PALM)
- OS6450 – 6.7.2.R04, 6.7.2.R05, 6.7.2.R06
- OS6465 – 8.5R2, 8.5R4, 8.6R1

## OmniVista 2500 NMS Enterprise 4.4R1 Release Notes

- OS6560 – 8.5R2, 8.5R4, 8.6R1
- OS6850 – 6.4.4.R01
- OS6850E – 6.4.6.R01
- OS6855 – 6.4.6 .R01
- OS6860/E – 8.5R2, 8.5R4, 8.6R1
- OS6865 – 8.5R2, 8.5R4, 8.6R1
- OS6900 – 8.5R2, 8.5R4, 8.6R1
- OS6900 C32/V72 - 8.5R2, 8.5R4, 8.6R1
- OS9700E– 6.4.6.R01
- OS9800E– 6.4.6.R01
- OS9900 – 8.5R2, 8.5R4, 8.6R1
- OS10K – 7.3.4.R02, 8.3.1.R01

### WebSmart

- OS2220 – 8.3.1.2, 8.3.1.3

### OmniAccess WLAN

- OAW-4030 – OAW 6.5.1, 6.5.4
- OAW-4704 – OAW 6.5.1, 6.5.4
- OAW-4604 – OAW 6.5.1, 6.5.4
- OAW-4x50 – OAW 6.5.1, 6.5.4

### OmniAccess WLAN IAP

- IAP-105 – OAW 6.5.4, 8.3.0
- IAP-205 – OAW 6.5.4, 8.3.0
- IAP-225 – OAW 6.5.4, 8.3.0
- IAP-325 – OAW 6.5.4, 8.3.0
- IAP-335 – OAW 6.5.4, 8.3.0

### OmniAccess ESR

- OA 5710 – 11.00.00.02.05
- OA 5720 – 11.00.00.02.05
- OA 5725 – 11.00.00.02.05
- OA 5800 – 11.00.00.02.05

### Stellar AP Series Wireless Devices

- OAW-AP1101 – AWOS 3.0.6.28 (only)
- OAW-AP1201 – AWOS 3.0.6.28 (only)
- OAW-AP1201H – AWOS 3.0.6.28 (only)
- OAW-AP1221 – AWOS 3.0.6.28 (only)
- OAW-AP1222 – AWOS 3.0.6.28 (only)
- OAW-AP1231 – AWOS 3.0.6.28 (only)

## OmniVista 2500 NMS Enterprise 4.4R1 Release Notes

- OAW-AP1232 – AWOS 3.0.6.28 (only)
- OAW-AP1251 – AWOS 3.0.6.28 (only)

**Note:** You cannot use an older AWOS with this OmniVista Release. If you are upgrading to OV 4.4R1 OmniVista from a previous release, you must upgrade AWOS devices to AWOS 3.0.6.28 after the OmniVista upgrade.

**Note:** Only the builds listed above are certified for this release.

### OmniVista 2500 NMS-E 4.4R1 Upgrade Paths Certified

- Standalone Upgrade
  - 4.3R3 Standalone to 4.4R1 Standalone
  - To upgrade from older releases, you must first upgrade to 4.3R3.
- High-Availability (HA) Upgrade
  - 4.3R3 HA Installation to 4.4R1 HA Installation
  - To upgrade from 4.3R2 HA, you must first upgrade to 4.3R3 HA.

**Note:** Detailed upgrade instructions are available in the *OmniVista 2500 NMS Enterprise 4.4R1 Installation and Upgrade Guide*.

**Note:** You can only perform a restore using a backup from the same release (e.g., you can only restore a 4.4R1 configuration using a 4.4R1 Backup File). OmniVista will not allow you to perform a restore using a backup from a previous release. Also note that the Backup/Restore function is only supported on a Standalone Installation. It is **not** supported on an HA Installation.

## 2.1 Proxy Requirements

OV 2500 NMS-E 4.4R1 uses external repositories for Application Visibility Signature File updates, ProActive Lifecycle Management (PALM), and the OmniVista 2500 NMS Software Repository, which is used for software updates/upgrades. If the OmniVista 2500 NMS Server has a direct connection to the Internet, a Proxy is not required. Otherwise, a Proxy should be configured to enable OV 2500 NMS-E 4.4R1 to connect to the OmniVista 2500 NMS External Repository.

## 2.2 Firewall Requirements

The OmniVista 2500 NMS Web Client, OmniVista 2500 NMS Server and network devices communicate over an IP network. You must configure the firewall appropriately for OmniVista 2500 NMS to run properly. The following URLs must be allowed to enable communication between the OmniVista Server and the ALE Central Repository, Application Visibility (AV) Signature Repository, and Proactive Lifecycle Management (PALM) Portal:

- **ALE Central Repository** – [ovrepo.fluentnetworking.com](http://ovrepo.fluentnetworking.com)
- **AV Repository** – [ep1.fluentnetworking.com](http://ep1.fluentnetworking.com)
- **PALM** – [palm.enterprise.alcatel-lucent.com](http://palm.enterprise.alcatel-lucent.com)
- **Call Home Backend** - [us.fluentnetworking.com](http://us.fluentnetworking.com)

## 2.2.1 OmniVista 2500 NMS Ports

The following table lists the default ports used to communicate between the OmniVista 2500 NMS Server and Client, and the OmniVista 2500 NMS Server and network devices.

<b>Service</b>	<b>Port</b>	<b>Source/Destination</b>
SFTP/SSHv2	22	OV Server/Net Device
Telnet	23	OV Client/Net Device
SNMP Request	161	OV Server/Net Device
SNMP Trap	162	Net Device OV Server
FTP	21	OV Server/Net Device
TFTP	69	Net Device OV Server
LDAP Server	5389	OV Server/Net Device
sFlow	6343	Net Device/OV Server
Web Server (HTTP)	80	OV Client/OV Server
Web Server (HTTPS)	443	OV Client/OV Server
Secure MQTT	1883	Stellar AP/OV Server
SMTP	25	UPAM/Third-Party Party SMTP Server
Log-MySQL	3306	UPAM/Log Server
Log-MSSQL	1433	UPAM/Log Server
LDAP	389	UPAM/LDAP Server
Active Directory (AD)	389	UPAM/AD Server
Syslog Listener	514	Net Device/OV Server, UPAM/Syslog Server
RADIUS Authentication	1812	Net Device/UPAM, UPAM/External RADIUS
RADIUS Accounting	1813	Net Device/UPAM, UPAM/External RADIUS
RADIUS CoA – UDP Port	3799	UPAM/Net Device
VMM	135	OV Server/Hyper-V Server
	49152-65535 (RPC Dynamic Port)	Hyper-V Server/OV Server
High-Availability	8000, 5405, 7801	Node 1/Node 2 Node 2/Node 1

## 2.3 Recommended System Configurations

The table below provides recommended Hypervisor configurations based on the number of devices being managed by OV 2500 NMS-E 4.4R1 (500, 2,000, 5,000, and 10,000 devices). These configurations should be used as a guide. Specific configurations may vary depending on the network, the number of wired/wireless clients, the number of VLANs, applications open, etc. For more information, contact Customer Support.

Configuration	Network Size			
	Low	Medium	High	Very High
Total Number of Managed Devices (AOS, Third-Party, and Stellar APs)	500	2,000	5,000*	10,000*
Stellar AP Devices	500	2,000	4,000	4,000
Stellar AP Client Association	50,000	200,000	200,000	200,000
UPAM Authentication	15,000	30,000	100,000	100,000
Hypervisor Processor	2.4 GHz 8 Logical Processors	2.4 GHz 8 Logical Processors	2.4 GHz 12 Logical Processors	2.4 GHz 12 Logical Processors
Minimum Reserved OmniVista VA RAM	16GB	32GB	64GB	64GB
HDD Provisioning	HDD1:50GB HDD2:256GB	HDD1:50GB HDD2:512GB	HDD1:50GB HDD2:2048GB	HDD1:50GB HDD2:2048GB

\*If there are 4,000 Stellar AP in a “High” network size, up to 500 AOS Switches can be supported. If there are 4,000 Stellar APs in a “Very High” network size, up to 1,000 AOS Switches can be supported.

### Notes:

- When provisioning RAM for a new VM for OmniVista, never allocate more memory than is available on the Host Server. For example, if you are running a Host Server with 128GB of memory and have already allocated 96GB of memory to your existing VMs, accounting for the Host Server’s own memory use, you are not left with enough memory to run OmniVista without incident. VM RAM is configured from the Hypervisor.
- Allocate the recommended amount of RAM for the OmniVista VM based on your network size as shown in the above table. In addition, it is recommended that you **reserve** that RAM for the OmniVista VM to prevent performance issues. VM RAM, including reserving VM RAM is configured on the Hypervisor.
- Set CPU Shares to “High”.
- Do not exceed the number of Logical Processors recommended for your network size as shown in the above table. Hypervisor Processors are configured from the Hypervisor.
- By default, OV 2500 NMS-E 4.4R1 is partitioned as follows: HDD1:50GB and HDD2:256GB. If you are managing more than 500 devices it is recommended that you go to the Virtual Appliance Menu on the VA to the increase the HDD2 provision.

See the *OmniVista 2500 NMS-E 4.4R1 Installation and Upgrade Guide* for instructions on extending the partition.

- OmniVista can be configured to use SNMPv3 to communicate with devices. When editing this configuration, you can specify which algorithms should be used. A recommended algorithm is AES ("Advanced Encryption Standard"). To get the best performance from your hypervisor, we recommend that you use Intel processors with the AES-NI instruction set enabled.
- AES-NI was introduced by Intel in 2010 in its Westmere family of processors and allows your hypervisor and its VMs to manage AES-related workloads natively. To realize the full benefits of AES-NI, you need to ensure that it is made available to the VM running OmniVista. To do this:
  - Your hypervisor's CPUs must be newer CPUs (> 2010)
  - AES-NI must be enabled in your hypervisor's BIOS
  - The AES-NI feature must not be "masked" by your hypervisor.
- By default, VMWare and HyperV are "pass-through" meaning that OmniVista's VM will be able to use AES acceleration. When using VirtualBox, please verify that "Nested paging" is enabled.

**Important Note:** You must upgrade your Stellar APs to AWOS 3.0.6.28 for OV 2500 NMS-E 4.4R1. **First** upgrade to OV 2500 NMS-E 4.4R1; then upgrade your APs to AWOS 3.0.6.28. Please refer to the *OmniVista 2500 NMS-E 4.4R1 Installation Guide* for details.

Also note that When upgrading Stellar APs in a Mesh Network, you must upgrade them starting from the last node and proceeding hop-by-hop. You cannot use OmniVista Resource Manager for the upgrade since Resource Manager upgrades Stellar APs by AP Group simultaneously. You must use Stellar AP Express Mode for the upgrades.

## 2.4 High-Availability Installation Limitations

The following features are not supported in a High-Availability (HA) Installation:

- Cluster IP configuration in L3 Cluster
- Changing the OmniVista IP address and Hostname after creating the Cluster.
- Memory synchronization. When the active service is not available and failover happens, the data in memory of that service will be lost.
- Hostname in upper case. Also note that the Hostname can have a maximum of 15 characters
- Changing/configuring Timezone
- Configuring an NTP client.
- Failover while re-syncing between nodes.
- Backup/Restore an HA Installation from VA Menu.

## 3.0 Installation

OmniVista 2500 NMS is installed from a download file available on the Customer Support website. Note that you can only directly upgrade to OV 2500 NMS-E 4.4R1 from OV 2500 NMS-E OV 2500 NMS-E 4.3R3. See the *OmniVista 2500 NMS-E 4.4R1 Installation and Upgrade Guide* for upgrade paths from older builds.



### 3.1 Licensing

OmniVista 2500 NMS licensing is based on the license purchased. A user is allowed to manage up to the maximum number of devices allowed for that license. There are two types of licenses that can be purchased - Device Licenses and Service Licenses.

- **Device Licenses** - Licenses a user to manage a specific number of devices.
  - **Alcatel-Lucent Enterprise Devices** - Licenses a specific number of ALE devices (e.g., OS10K, 6900, 6860) that can be managed. OmniVista has been certified to manage up to 10,000 devices (includes AOS and Third-Party Devices).
  - **Third Party Devices** - Licenses third-party devices (e.g., Cisco).
  - **Alcatel Lucent Enterprise OmniAccess Stellar APs** - Licenses OmniAccess Stellar Wireless Devices (e.g., OAW-AP1101, OAW-AP1221). OmniVista has been certified to manage up to 512 Stellar APs.
- **Service Licenses** - Licenses a user to manage a specific number of devices for the following services:
  - **VMs** - Licenses Virtual Machines (VMs). VMs can be deployed on VMware vCenters, Citrix XenServers, and MS Hyper-V Servers; and OmniVista 2500 NMS supports a mixture of Hypervisor types with no limit on the number of Hypervisors. However, the VM Manager application supports a maximum of 5,000 VMs from all Hypervisors. More than 5,000 VMs are allowed, however a warning message will be displayed and an entry will be written to the VMM Log File.
  - **Alcatel Lucent Enterprise Guest Devices** - Licenses Guest Devices authentication through UPAM. The following licenses are available: 20, 50, 100, 500, or 1000 Guest Devices.
  - **Alcatel-Lucent Enterprise On-Boarding Devices** - Licenses BYOD Devices authentication through UPAM. The following licenses are available: 20, 50, 100, 500, or 1000 Guest Devices.
  - **High-Availability** – Licenses the High-Availability Feature.

There are three (3) types of OmniVista Licenses:

- **Starter Pack** - Is free and enables you to use OmniVista on a limited basis without expiration. You can manage up to 30 devices (10 AOS, 10 Third Party, 10 Stellar APs).
- **Evaluation** - Is free and gives you full use of OmniVista, but for a limited time (90 days). You can manage up to 60 devices (20 AOS, 20 Third Party, 20 Stellar APs)
- **Production** - Gives you full use of OmniVista without expiration.

#### Device License Types

	Starter Pack	Evaluation	Production
<b>Device Count</b>	30 (10 AOS, 10 Third Party, 10 Stellar AP)	60 (20 AOS, 20 Third Party, 20 Stellar AP) (full OV functionality)	Chosen at license generation (full OV functionality)
<b>Expires</b>	No	90 Days	No

**Note:** OAW (non-Stellar) Devices are counted as AOS Devices.

## Service License Types

	Starter Pack	Evaluation	Production
<b>VMs</b>	10	100	Chosen at license generation (full VMM functionality)
<b>ALE Guest Devices</b>	10	20	Chosen at license generation (full VMM functionality)
<b>ALE On-Boarding Devices</b>	10	20	Chosen at license generation (full VMM functionality)
<b>Expires</b>	No	90 Days	No

**Note:** The High-Availability License is only available as a Production License. It does not expire.

The maximum number of devices allowed and the current number being managed is displayed in License Application (Administrator – License). This enables the user to determine if more devices can be added for management. Trying to discover new devices after the allowed limit will result in an Audit log and Status message.

**Note:** Licenses are imported/upgraded in the License Application. After installing OV 2500 NMS-E 4.4R1, go to Administrator – License, import the license, then select the license type you want to upgrade/relicense and enter the License Key.

See the *OmniVista 2500 NMS-E 4.4R1 Installation and Upgrade Guide* for instructions on generating an Evaluation License.

### 3.2 Upgrading a Starter Pack or Evaluation License to a Production License

A Starter Pack License of the OmniVista 2500 NMS Application allows you to manage up to 30 devices (10 AOS, 10 Third-Party, 10 Stellar APs) with no expiration date. An Evaluation license of OmniVista 2500 NMS is valid only for a limited period of time. To gain permanent use of the OmniVista 2500 NMS software, you must order a Permanent Node Management License. The following procedure describes how to obtain an OmniVista 2500 NMS license key.

1. Purchase a permanent OmniVista 2500 NMS-E 4.4R1 License. You will receive a “Welcome Kit” e-mail that contains a Customer ID and Order Number.
2. Once you receive your e-mail, log onto the License Generation website at <https://lds.al-enterprise.com/ov25411/enterLicenseData.jsp>.
3. Enter your Customer ID and Order Number.
4. Complete the License Registration Form and click **Submit**. A download prompt will appear.
5. Click **Save** at the confirmation prompt to download the license file to your computer.
6. Go to the **License – Add/Import License Screen** in OmniVista to import the license file you just downloaded.

If you have questions or encounter problems upgrading your OmniVista 2500 NMS License, please contact Alcatel-Lucent Enterprise Customer Support.

## 4.0 Launching OmniVista 2500 NMS

OV 2500 NMS-E 4.4R1 is supported on the following browsers: Internet Explorer 11+ (on Windows client PCs), Chrome 68+ (on Windows and Redhat/SuSE Linux client PCs), and Firefox 62+ (on Windows and Redhat/SuSE Linux client PCs). To launch OmniVista, enter the IP address of the OmniVista 2500 NMS Server (e.g., <https://<OVServerIPaddress>>). The IP address entered depends on the type of installation:

- **Standalone** - Enter the IP address of the OmniVista Server.
- **High-Availability (Layer 2)** - Enter the Virtual Cluster IP address.
- **High-Availability (Layer 3)** - Enter the IP address of the Active Node.

**Note:** If you changed the default HTTPs port (443) during VA configuration, you must enter the port after the IP address (e.g., <https://<OVServerIPaddress>:<HTTPsPort>>).

**Note:** The Watchdog Application, which enables all of the necessary OV 2500 NMS-E 4.4R1 Services must be started to launch OV 2500 NMS-E 4.4R1. By default, Watchdog should start automatically when OV 2500 NMS-E 4.4R1 is installed. However, if you are having trouble launching OmniVista 2500 NMS, check to make sure that the Watchdog Service is enabled. If it is not, enable it. It will launch the remaining OmniVista 2500 NMS Services.

Open a Console on the VA and select the **Run Watchdog Command** option to display the status of Services or launch Services.

### 4.1 Logging Into OmniVista 2500 NMS-E 4.4R1

After launching OV 2500 NMS-E 4.4R1 for the first time, log in using the Default Username and Password:

- **Username:** admin
- **Password:** switch

## 5.0 Known Problems

### 5.1 Known Analytics Problems

#### 5.1.1 Cannot Edit Health Threshold Report for Devices In 4K AP System

If you attempt to configure Network Health Reports for a large number of devices in Analytics – Network Health, the operation takes so long that the page times out.

**Workaround:** Select smaller groups of devices when configuring Health Threshold Reports (approximately 20 at one time). Set Health Thresholds using the Discovery – Managed Devices List. Select 10 – 20 AOS Devices/APs at a time, click on the **Actions** drop-down menu and select **Configure Health Thresholds**.

PR# OVE-1944

#### 5.1.2 Modules Displayed Incorrectly in Performance Monitoring in 6.x Devices

When creating a profile in Performance Monitoring and selecting a module for a device, the modules displayed for 6.x Devices displays incorrectly. For 6x devices, the slot numbering

scheme should be slot/port. However, OmniVista shows the Chassis number as the Slot number with a prefix of “Chassis=0”. That is, Chassis =1 is represented as Chassis 0 Slot 1, rather than “Chassis 1” or “Slot 1”.

**Workaround:** Chassis = 0 value is invalid and can be safely ignored by user when listed in the drop-down. The chassis number (or slot number) value is actually the Slot number.

This issue was fixed in AOS 6.7.2.R06. Upgrade switch to AOS 6.7.2.R06.

PR# OVE-3033

### 5.1.3 Process Stop When Trying to Create Top N Ports Profile

When attempting to create a Top N Ports Profile for a large number of device/ports, OmniVista will occasionally freeze up.

**Workaround:** This is a problem with Chrome 74.x. Use a different browser and start the configuration process over again.

PR# OVE-4946

## 5.2 Known Application Visibility Problems

### 5.2.1 Cannot Apply Signature and Classification to a Large Number of APs

Operation fails when attempting to apply an Application Visibility Profile or Access Classification Roles to a large number of APs at the same time.

**Workaround:** Apply profiles to no more than 500 APs at a time. Create AP Groups of no more than 500 APs and apply the Signature Profile or Access Classification Roles to the group. Create additional AP Groups and apply the Signature Profile or Access Classification Roles as needed.

PR# OVE-2256

## 5.3 Known AP Registration Problems

### 5.3.1 I/E v11 Does Not Work with Stellar AP Web Management Tool

Internet Explorer, Version 11 does not work when connecting to a Stellar AP using the AP Web Management Tool.

**Workaround:** Set another web browser as your default browser.

PR# OV-2096

### 5.3.2 In 2,000 AP Setup, Many APs Cannot Register

When trying to register 2,000 APs at once, many APs do not register with OmniVista and remain in an “Unlicensed” State even though there are enough licenses for all of the APs.

**Workaround:** When registering a large number of APs, register them in AP Groups of 500. Bring up the first group of 500 APs and wait for them to be “Licensed” and “Trusted” before bringing up the next group. Repeat until all APs are registered.

PR# OV-5339

### 5.3.3 When Upgrading Stellar APs in Mesh Network, Start From Last Node

When upgrading Stellar APs in a Mesh Network, you must upgrade them starting from the last node and proceeding hop-by-hop. You cannot use OmniVista Resource Manager for the upgrade since Resource Manager upgrades Stellar APs by AP Group simultaneously. You must use Stellar AP Express Mode for the upgrades.

**Workaround:** Information only.

PR# OVE-4015

## 5.4 Known CLI Scripting Problems

### 5.4.1 Increase Buffer Size of Interactive SSH Terminal in Web UI

When you launch SSH session to a device from OmniVista from "CLI Scripting" application, the screen buffer size is only 300 lines. If the command output is long, then it is difficult to view the results. Also, the previously executed commands cannot be seen.

**Workaround:** Up to 300 lines can be displayed. No workaround at this time.

PR# OVE-998

## 5.5 Known Discovery Problems

### 5.5.1 AP Reason Down Field is Updated Slowly System with 500 APs

The "Reason Down" field is blank if an AP is UP. If an AP goes down and then returns to an UP state, the "Reason Down" field does not return to a blank field.

**Workaround:** If an AP goes down, the "Reason Down" field may not update to "Blank" when the AP returns to an "Up" state. For APs, ignore this field if the AP Status is "Up". No workaround at this time.

PR# OVE-2131

### 5.5.2 "Save to Running" on Large Number of APs Is Slow

Performing a "Save to Running" action on a large number of APs in the Discovery application takes a long time (it takes approximately 10 seconds for each AP).

**Workaround:** No workaround at this time.

PR# OVE-2264

### 5.5.3 Unable to Discover Additional Devices Once 7,000 Devices Is Reached

When performing a discovery on a large network, once approximately 7,000 devices were discovered, OmniVista could not discover additional devices.

**Workaround:** Discover no more than 5,000 devices at a time. Perform additional discoveries as needed to discover remaining devices.

PR# OVE-2198

### 5.5.4 “Last Known Up At” Field in Managed Devices Empty for Down AP

When a Stellar AP goes down, the “Last Known Up” field in the Managed Devices List will go blank.

**Workaround:** No workaround at this time.

PR# OVE-3159

### 5.5.5 Adding Heavily-Configured Device Takes Additional Time

When you add a heavily-configured device (e.g., SPB configuration) to the Managed Devices List, the process can take a long time and OmniVista may display a timeout message after several minutes.

**Workaround:** Ignore the Timeout error message. The device will be added when polling is complete.

PR# OVE-4145

### 5.5.6 OV Allows 2 Devices With Same IP Address If One Device Is Down

If you have a “Down” device and add another device with the same IP address, OmniVista will display both devices in the Managed Devices List and show them as “Up”.

**Workaround:** Delete the device that is “Down”, or delete both devices. Change the IP address of the “Down” device, then add this device or both devices to OmniVista again.

PR# OVE-4424

## 5.6 Known Locator Problems

### 5.6.1 Cannot Locate End Stations Connected to OS2220

Unable to locate end stations connected to OS2200 Switch.

**Workaround:** The Locator application is not supported on OS2200 Switches.

PR# OVE-1226

## 5.7 Known Notifications Problems

### 5.7.1 Backup Failure Trap Not Working on System Upgraded From OV422 MR2 - OV43R2

The Backup Failure Trap (alaOvOperationTrap) does not work properly on a system upgraded from OmniVista 4.2.2.R01 (MR2) to 4.3R2. Trap Severity should be “Major”. It is “Normal”.

**Workaround:** Restart the ovclient service from the Watchdog UI in OmniVista (Administrator – Control Panel – Watchdog); then correct the severity (from Normal to Major) in the Notifications application (Notifications – Trap Definition).

PR# OVE-3031

### **5.7.2 SNMP “Up/Down” Traps Are Not Showing After Upgrade from OV422MR2 to OV43R3**

SNMP “Up/Down” Traps (“alasnmpdown” and “alasnmpup”) are not displayed after upgrading from OV422MR2 to OV43R3 via multiple releases.

**Workaround:** Restart the ovclient service from the Watchdog UI in OmniVista (Administrator – Control Panel – Watchdog); then correct the severity (from Normal to Major) in the Notifications application (Notifications – Trap Definition).

PR# OVE-3759

## **5.8 Known PolicyView Problems**

### **5.8.1 LDAP Policy with 'TCP Flags' Condition Fails in Notify**

LDAP Policy with 'TCP Flags' Condition Fails in Notify because the "tcpflags" attribute is not getting processed in switch properly.

**Workaround:** No workaround at this time.

PR# OVE-3020

### **5.8.2 OS6900-Q32 Does Not Support Port Type in Expert Mode Policy Action**

OS6900-Q32 Does Not Support Port Type in Expert Mode Policy Action.

**Workaround:** No workaround at this time.

PR# 201688

### **5.8.3 Problems Re-Caching When Port Policy Applied to Both OS6900-X32 Switches and Non-OS6900-X32 Switches**

If you mix OS6900-Q32 and other switches in a policy that contains an action on a physical port, the configuration can be applied on the wrong port on some switches. You can mix switches in a policy only if the policy does not contain any physical port in the policy action.

**Workaround:** If you want to create a policy with a Policy Action on a physical slot/port of OS6900-Q32 switches, do not include any switch that is not an OS6900-Q32 switch in the same policy. Create separate policies.

PR# OVE-678

### **5.8.4 Problems When Applying Unsupported Attributes in Policy List to AOS 8.x Switches After Upgrade from OV 4.2.2 GA**

The “Send Trap” attribute is present in default policies but is not supported in AOS 8.x Switches. If you upgrade to OV 4.3R1 from OV 4.2.2 GA and configured policy lists in OV 4.2.2 GA containing this attribute, you will not be able to push that policy list to devices. This is not a problem if you are upgraded from OV 4.2.2 (MR2) or are working with a fresh install of OV 4.3R1.

**Workaround:** Create new policies/policy lists to replace the old policy lists containing the attribute.

PR# OVE-653

## 5.9 Known Report Problems

### 5.9.1 Cannot Add Widget to Report if Current Data is More Than 16 MB

Cannot create a report containing more than 16 MB of data.

**Workaround:** A report can contain a maximum of 16MB of data (for a table report, such as Discovery - Inventory List, this is approximately 1,000 rows of data). If you are unable to generate a larger report, reduce the number of devices/rows in the report.

PR# OV-4463

### 5.9.2 After Changing Languages, Report Still Printed in Previous Language

If you create a report with the UI set to one language (e.g., Chinese), change the language (e.g., English), and then re-print the report (PDF), the report will still be generated in the previous language (e.g., Chinese).

**Workaround:** After changing languages, you must re-create the report to generate it in the current language.

PR# OVE-4960

## 5.10 Known Resource Manager Problems

### 5.10.1 SSH Key and User Table Missing after Full Backup of OS6900 8.3.1

The SSH Key and User Table are missing after performing a full backup of OS6900 Switch running AOS 8.3.1.R01. User Table cannot be backed up.

**Workaround:** No workaround at this time.

PR# 219688

### 5.10.2 “Restore” Must Be From The Same Release

You can only perform a restore using a backup from the same release (e.g., you can only restore a 4.3R2 configuration using a 4.3R2 Backup File). OmniVista will not allow you to perform a restore using a backup from a previous release.

**Workaround:** Informational

PR# CRNOV-675



## 5.11 Known Topology Problems

### 5.11.1 AMAP Entries for ERP-RPL Links Are Not Always Displayed

AMAP is a proprietary protocol and has been deprecated, so AMAP Entries for ERP-RPL Links are not always displayed.

**Workaround:** AMAP Adjacency Protocol functionality on the switch does not work properly with ERPV2 in case of ERP-RPL link, which may affect ERPV2 functionality. Use LLDP as the adjacency protocol when working with ERPV2.

PR# 177202

### 5.11.2 SPT Available Links Are Not Shown When More than 2 Devices Selected

SPT Available links are not shown when more than 2 devices are selected using 'Multiple Selection'.

**Workaround:** SPB Topology will only display SPT links between 2 nodes. If more than 2 nodes are selected, the "Show SPT Available Links" function is disabled.

PR# OVE-1491

## 5.12 Known Unified Access Problems

### 5.12.1 Device Config - Port and Dynamic Service Access Auth Profile Displayed Incorrectly for OS6900-Q32/X72

Device Config - Port and Dynamic Service Access Auth Profile Displayed Incorrectly for OS6900-Q32/X72 Switches.

**Workaround:** Switch issue. No workaround at this time.

PR# 219133

### 5.12.2 Device Config - Cannot View Access Role Profile of AOS 8.2.1 Devices

Cannot view Access Role Profiles on Device Config Screen.

**Workaround:** No workaround at this time.

PR# 220259

### 5.12.3 Cannot Select WPA3 Encryption via Unified Profile Workflow

WPA Encryption is not available when configuring Unified Profile via Unified Profile Workflows.

**Workaround:** Use the WLAN Service (Expert) Template for configuration.

PR# OVE-4950

### 5.12.4 Cannot Notify Policy List with Accept All | Deny All Policy on AOS 6x Devices

A Policy List containing an "Accept All" or "Deny All" Policy cannot be applied to an AOS 6.x Device even though OmniVista message indicates "Success".

**Workaround:** This issue does not exist on AOS 8.x Devices, and will be fixed in AOS 6.7.2.R07. Until then, for AOS 6.x Devices, connect to the device and issue the following CLI commands to apply the configuration:

```
policy condition IPv6-Any destination ipv6 Any
policy action [DenyAction/AcceptAction] disposition [drop/ accept]
policy validity-period AllTheTime days sunday monday tuesday wednesday
thursday friday saturday months january february march april may june
july august september october november december
policy rule [OV-L3-DenyAllPolicy-IPv6/ OV-L3-AcceptAllPolicy-IPv6]
precedence 100 condition IPv6-Any action [DenyAction/ AcceptAction]
validity-period AllTheTime log no default-list
policy list [list1] rules [ OV-L3-DenyAllPolicy-IPv6/ OV-L3-
AcceptAllPolicy-IPv6]
 qos apply
```

PR# OVC-6133

## 5.13 Known UPAM Problems

### 5.13.1 Authentication Fails with Secret Key as "alcatel" Instead of "123456"

MAC and 1x authentication may fail if the NAS Client is using a different IP address than the Management IP address for RADIUS authentication.

**Workaround:** Configure the NAS Client to use the Management IP address for RADIUS authentication

PR# OVE-2025

### 5.13.2 Cannot Fully Customize UPAM Captive Portal Page

Full HTML customization is not available when creating UPAM Captive Portal Page in OmniVista.

**Workaround:** No workaround at this time. OmniVista does not support HTML-level customization.

PR# OVE-834

### 5.13.3 UPAM Authentication with an External LDAP Server Does Not Work with an Encryption Password Configured for the User

UPAM authentication does not work if you are using an external LDAP with an Encryption Password (e.g., MD5, SHA) configured for the user.

**Workaround:** If using an external LDAP Server for UPAM authentication, use a plain text password.

PR# OVE-818

### 5.13.4 Unable to Activate Old Certificate After Upgrade to OV Build 115

If you uploaded and activated a new certificate for UPAM RADIUS on the OV 422R01 GA build, after upgrading to 422R01 MR 2, OmniVista falls back to the default certificate. The new certificate is displayed in UPAM – Settings - RADIUS Server Certificate, but it is not activated.

This was only observed when upgrading from OV 422R01 GA to OV 422R01 MR 2. It did not occur when upgrading from OV 422R01 MR 1 to OV 422R01 MR 2.

**Workaround:** After the upgrade, go to UPAM- Settings - RADIUS Server Certificate. Remove the certificate that you used earlier, upload it again, and activate it.

PR# OVE-833

### 5.13.5 CP/Guest-Authentication Fails with UPAM as RADIUS Server

CP/Guest-Authentication fails with UPAM as RADIUS Server. Client is unable to open redirect-url portal because 'hotspot login cannot open the page because it is not connected to internet'.

**Workaround:** There must be a DNS Server in the Customer Network for Captive Portal user authentication for wired devices if AOS is the network authenticating device. The DNS must resolve to the secondary OV IP address (UPAM address). This is not required for wireless devices authenticating through an AP.

PR # OVE-1693

### 5.13.6 802.1X Authentication with External Windows LDAP Failed When Logging in with User Credential

802.1X Authentication using an external Windows LDAP Server fails when Logging in with user credentials.

**Workaround:** Currently, UPAM does not work when using a Windows LDAP server for external LDAP Authentication. Use OpenLDAP on a Linux machine or AD on Windows Server.

PR # OVE-3000

### 5.13.7 HTTPs Traffic is Not Redirected to Portal Page for an HSTS Website

The first time a user opens an HSTS website, they are redirected to the portal page, as expected. The second time a user opens an HSTS website, the redirection will not work. If the user clears browser cache and retries connecting to the HSTS website, it will work. The behavior depends on the browser used. Chrome is very strict, so the problem is always seen, Firefox is not as strict; the problem will still happen but not as frequently.

Workaround: There is no workaround at this time.

PR # OVE-779

### **5.13.8 Guest User Account Names Are Not Case-Sensitive in OVE 4.4R1**

In previous OVE releases, the Guest Account Name in UPAM was case-sensitive (e.g., “Account1” and “account1” are seen as two different accounts). In OVE 4.4R1 Guest Accounts are not case-sensitive (e.g., “Account1” and “account1” are seen as the same account by OmniVista). In OVE 4.4R1, if two accounts have the same name (e.g., “Account1 and “account1”), UPAM will authenticate the first account received for authentication. The other account will not be authenticated.

**Workaround:** Guest Account names must be different in OVE4.4R1. If necessary, change any existing account names to avoid this problem.

PR # OVE-4999

### **5.13.9 Switch responding “Unsupported-Attribute” After Successful Guest/BYOD Authentication on 8.5R2 Switch**

“Unsupported-Attribute” Error occurs when session timeout is enabled in Guest Access post portal authentication on switches running AOS 8.5R2.

**Workaround:** This problem has been fixed in AOS 8.5R4. Upgrade switch to AOS 8.5R4.

PR # OVE-4189

## **5.14 Known Users and User Groups Problems**

### **5.14.1 When You Configure the Analytics Application for a Role, the Performance Monitoring Application is Also Configured**

In OV 4.3R1, Performance Monitoring is a new feature and you can configure permissions of Analytics and Performance Monitoring application separately. However, if you upgrade to OV 4.3R1 from OV 422 MR2, the default permissions for the Performance Monitoring application are automatically derived from Analytics application permissions because the Performance Monitoring application is a sub-application of the Analytics application. This is expected behavior.

Workaround: NA

PR # OVE-1847

## **5.15 Known VM Manager Problems**

### **5.15.1 VLAN Notification Does Not Generate a Notification When Default UNP of LAG Port Is Deleted**

VLAN notification does not come up when the default UNP of a Link Agg Port is deleted

**Workaround:** This is a switch issue. When the default UNP is taken away from the LAG, the switch takes longer than usual to populate the MAC Learning Table. For a period of time, the MAC Address belong to the VM disappears and hence cannot even be located. Both commands 'show unip user' and 'show mac-learning' have no entry of the VM's MAC address. This behavior is not observed on the standard port. Notification eventually gets raised as the switch populates its table.

PR# 174181

### **5.15.2 VMM Locator VM Count Can Be Greater Than VMM License VM Count or Reported by vCenter**

If VMs are using multiple Physical NIC Interfaces, the same VM will be bound to different MAC Addresses and OmniVista 2500 NMS will display multiple rows for the VM in VMM Locator search and browse applications. However, this will not affect VM Manager Licensing. The VMM License Manager will count multiple references as single Virtual Machine its UUID and the count will match the number of Virtual Machines reflected in vCenter.

**Workaround:** N/A

PR# 163885

### **5.15.3 OmniVista 2500 NMS Treats a VM Template as a Virtual Appliance**

This is working as designed. vCenter treats Virtual Machine Templates and Virtual Machines in a similar manner. A MAC address is assigned to templates and they can be converted to a Virtual Machine in a single click. vCenter returns VM Template in the list of Virtual Machines like any other VM, and OmniVista 2500 NMS treats VM Templates like any other Virtual Machine.

**Workaround:** N/A

PR# 163314

## **5.16 Known WLAN Problems**

### **5.16.1 Unable to Create a Floor Plan in OVE 4.4R1**

When a user attempts to create a Floor Plan in OVE 4.4R1, the user receives a “Failed to Add Floor Plan” error message. This error occurs if a user upgrades to 4.4R1 and did **not** create any Floorplans in their previous version of OmniVista. In this case, the Floor Plan Folder is not created in OV 4.4R1 and the user will be unable to create any new Floor Plans.

**Workaround:** SSH to the OmniVista Sever, login with the cliadmin credentials and create the Floor Plan Folder:

```
/opt/OmniVista_2500_NMS/data/wma_shared/heatmapImage/upload/
```

This problem will not occur if the user has created Floor Plans in a previous version of OmniVista.

PR# OVE-5414

## **5.17 Known Other Problems**

### **5.17.1 Apostrophe Is an Invalid Character in SNMP Community String**

Apostrophe Is an Invalid Character in SNMP Community String.

**Workaround:** Remove Apostrophe from the SNMP community string.

PR# 195715

### 5.17.2 Unable to Access Web UI Using IP Address on I/E

Unable to access Web UI using IP address on Internet Explorer browser, locally on a Windows 2012 R2 system.

**Workaround:** Have the correct mapping for 'localhost' in the hosts file and use 'localhost' instead of IP address to access the Web UI locally.

PR# 194913

### 5.17.3 U-Boot Version for OS6450 Devices Shows as "NA" in Inventory Report

U-Boot Version for OS6450 Devices Shows as "NA" in OmniVista 2500 NMS Inventory Report.

**Workaround:** This is a hardware issue with the OS6450. No workaround at this time.

PR# 181085

### 5.17.4 Some OmniVista Features Do Not Work if the System Port is Changed

If a user changes the System Port using the VA Menu on a system that has been running, the system will not be able to reach the internet (for PALM, upgrades, etc.) via the network proxy since the port has been changed.

**Workaround:** Change the Proxy Port back to correct network Proxy Port. Go to Preferences - System Settings - Proxy.

PR# OVE-2127

### 5.17.5 OmniVista Cannot be Accessed by Web Client

OmniVista became unavailable to web clients, displaying the following error message on the browser: "OmniVista Error Fail to get current user".

**Workaround:** Restart ovclient or tomcat service.

PR# OVE-2220

### 5.17.6 Packet Drops When Roaming with OKC Enabled

When a client roams between APs with OKC enabled, some packets are lost. However, there is no disconnection or re-authentication.

**Workaround:** No workaround at this time.

PR# OVE-2218

### 5.17.7 WMA/UPAM Memory Not Updated After Upgrade

If you are upgrading from a previous build (not a fresh installation), the VA memory settings will not be upgraded for OV 2500 NMS-E 4.2.2.R01 (MR 2). This can cause problems in installations with more than 256 Stellar APs.

**Workaround:** If you are upgrading from a previous build and your network has more than 256 Stellar APs, you must re-apply the VA memory settings. Go to the VA Menu, re-apply the memory settings, and reboot the VA.

This is not required if you have fewer than 256 Stellar APs, or if you are performing a fresh installation.

PR# OVE-1993/2048

### 5.17.8 Update Firewall Rules and Script to Enable DCOM When Creating Hyper V Profile

Error messages are displayed when trying to add a Hyper-V Hypervisor in the VM Manager Hypervisor Systems Screen.

**Workaround:** Make sure that the VMM Ports are configured as shown in [Section 2.2.1 OmniVista 2500 NMS Ports](#). If the problem persists, follow the applicable DCOM procedure as detailed in [Appendix A](#).

PR # OVE-1568

### 5.17.9 OV Nginx Service Does Not Start After Updating OmniVista Web Server SSL Certificate (OV 4.2.2 Build 115 MR-2)

If you update the OmniVista SSL Web Certificate using the VA Menu option, The OmniVista Nginx Service does not start up even if the VM is restarted.

**Workaround:** OmniVista does not support importing a Web Server SSL certificate with private key that was encrypted with password. Import a new SSL certificate with a private key not protected with a password and reboot OmniVista.

PR # OVE-1776

### 5.17.10 Unsupported Features in High-Availability (HA) Installation

The following features are not supported in a High-Availability (HA) Installation:

- Cluster IP configuration in L3 Cluster
- Upgrade from 4.3R1 HA to 4.3R2 HA
- Changing the OmniVista IP address and Hostname after creating the Cluster.
- Memory synchronization. When the active service is not available and failover happens, the data in memory of that service will be lost.
- Hostname in upper case
- Changing/configuring Timezone
- Configuring an NTP client.
- Failover while re-syncing between nodes.
- Backup/Restore an HA Installation from VA Menu.

Workaround: NA

PR # OVE-2327

### 5.17.11 Failover Banner Warning Redirects User to Inoperable Standby Node

If a user manually stops/restarts all services on the Active Node in an HA Installation, the Failover Banner will appear, directing the user to the Standby Node. Since a failover did not actually occur, the Standby Node will be inoperable.

**Workaround:** Ignore the Banner Warning. The Active Node will return once all services are restarted.

PR # OVE-3313

### 5.17.12 OVUPAM and OVRADIUS Services Do Not Start After OV Restore

When you perform a restore of OmniVista using the VA Menu, the ovupam and ovradius services may not start.

**Workaround:** After the restore is complete, reboot the VM.

PR # OVE-3142

### 5.17.13 Failover During VM Sync in HA Installation

Although extremely rare, there could be a case when a failover occurs during a sync between the Active and Standby Nodes in a High-Availability Installation. Since the failover interrupts the data sync, the Standby Node will not come up as the Active Node because it does not have the latest data.

**Workaround:** If it was a temporary problem with the Active Node that caused the failover, the Active Node may come up again and complete the sync. If the Active Node is permanently down, SSH to the Standby Node. On the HA Virtual Appliance Menu select **3 – Configure Cluster**, then select **14 – Cluster Error Check**. When the error check is complete, the Standby Node will come up as the Active Node. Note that it may not have the most recent data since the sync was interrupted.

PR # OVE-1629

### 5.17.14 OV Hostname Cannot Be More than 15 Characters

When configuring the OmniVista Hostname in the VA Menu, the name can contain a maximum of 15 characters.

**Workaround:** Informational

PR # CRNOV-793

### 5.17.15 Failover Banner Directs User to Inoperable HA Standby Node

If you are restarting services on the Active Node in an HA Installation, the Failover Banner will appear informing the user to redirect to the Standby Node. Failover does not occur when services are manually restarted, only when the Active Node is unreachable. Ignore the message when it appears due to services being manually restarted. The Active Node should become available again when all of the services are “Up”.

**Workaround:** Informational

PR # OVE-3113



### 5.17.16 Offline Upgrade from 4.3R3 to 4.4R1 Failed

Offline Upgrade from 4.3R3 to 4.4R1 Failed due to invalid upgrade location.

**Workaround:** Contact Customer Support for Offline Upgrades

PR # OVE-5006

## 6.0 Release Notes PRs Fixed

### 6.1 PRs Fixed Since 4.3R3

#### 6.1.1 Customer PRs

CR/PR Number	Description
<b>Case:</b> <b>379841</b> <i>CRNOV-1000</i>	<b>Summary:</b> UPAM LDAP / AD AUTH No UPN support.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>372065</b> <i>CRNOV-913</i>	<b>Summary:</b> Custom Radius Server certificate ineffective after upgrade to OV 4.3.R3 or service restart.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>292909</b> <i>OVE-1777</i>	<b>Summary:</b> OmniVista should allow importing Web Server SSL Certificate with encrypted private key.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>314628</b> <i>OVE-2529</i>	<b>Summary:</b> Increase "Max Open Files" to limit the error "too many open files" of influxdb.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>314452</b> <i>OVE-2549</i>	<b>Summary:</b> METRA SPA:OV2500:Unable to add the license.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>346874</b> <i>OVE-2583</i>	<b>Summary:</b> Conflicting AP's IP.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>322701</b> <i>OVE-2740</i>	<b>Summary:</b> Email trap responder is not working properly.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>331841</b> <i>OVE-2941</i>	<b>Summary:</b> IAP-215 Management Login via UPAM Radius Proxy not possible.  <a href="#">Click for Additional Information</a>
<b>Case:</b> NA	<b>Summary:</b>

**OmniVista 2500 NMS Enterprise 4.4R1 Release Notes**

<b>CR/PR Number</b>	<b>Description</b>
<i>OVE-3182</i>	The "Device DNS Name" on Netforward Result and "End station Name" on ARP Results are missed in OV 4.3R2.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>345626</b> <i>OVE-3277</i>	<b>Summary:</b> OV2500 - Need API for Guest & BYOD users for UPAM.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>356522</b> <i>OVE-3905</i>	<b>Summary:</b> Traps should be displayed consecutively from the first page when searching by trap name.  <a href="#">Click for Additional Information</a>
<b>Case:</b> 379239 <i>OVE-3925</i>	<b>Summary:</b> OmniVista kept the old Memory values (Xms, Xmx) of wrapper.conf.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>356499</b> <i>OVE-4229</i>	<b>Summary:</b> Update help info about audit settings.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>363763</b> <i>OVE-4351</i>	<b>Summary:</b> The template of browser page works incorrectly when changing the order of columns.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>371694</b> <i>OVE-4385</i>	<b>Summary:</b> Add a note in discovery online help that LLDP links cannot be manually edited/delete.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>322800</b> <i>OVE-4466</i>	<b>Summary:</b> Settings of Managed Devices are not saved.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>375237</b> <i>OVE-4513</i>	<b>Summary:</b> DNS configuration missing after changes to hostname in OmniVista.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>375760</b> <i>OVE-4539</i>	<b>Summary:</b> In Topology page, the map node missed the IP address information.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>372645</b> <i>OVE-4567</i>	<b>Summary:</b> OmniVista terminal command output is misaligned for the command 'ssudo sta_list'.  <a href="#">Click for Additional Information</a>

## OmniVista 2500 NMS Enterprise 4.4R1 Release Notes

CR/PR Number	Description
<b>Case:</b> <b>372645</b> <i>OVE-4567</i>	<b>Summary:</b> OmniVista terminal command output is misaligned for the command 'ssudo sta_list'.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>358719</b> <i>OVE-4667</i>	<b>Summary:</b> OmniVista needs to push Trust-tag configuration to AP.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>NA</b> <i>OVE-4708</i>	<b>Summary:</b> Some code flows of Application Visibility did not close connection after using.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>380331</b> <i>OVE-4712</i>	<b>Summary:</b> Update Help document: Failure Policy - The authentication method used for 802.1X authentication is not supported on AOS 6.x devices.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>380433</b> <i>OVE-4808</i>	<b>Summary:</b> Trap Responder - Email notification is not functioning.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>381830</b> <i>OVE-4829</i>	<b>Summary:</b> Error in plugin [inputs.snmp]: agent 10.1.20.95:161: performing get on field healthDeviceRxTxLatest: Request timeout.  <a href="#">Click for Additional Information</a>
<b>Case:</b> 385881 <i>OVE-5056</i>	<b>Summary:</b> Topology map with background image does not save device's position.  <a href="#">Click for Additional Information</a>
<b>Case:</b> <b>386993</b> <i>OVE-5109</i>	<b>Summary:</b> Update the help-on-line page - Widget WLAN Client Health, what are the defined thresholds to determine Best/Good/Fair client health.  <a href="#">Click for Additional Information</a>
<b>Case:</b> 391867 <i>OVE-5292</i>	<b>Summary:</b> Resource Manager Backup/Restore page stuck at Loading due to corrupted data in MongoDB.  <a href="#">Click for Additional Information</a>

### 6.1.2 Release Note PRs

- No Tier 2 DFS Channel Support for US Domain (OVE-819)
- Live Search Does Not Work for VM IP Address/Switch IP Address (OVE-1908)
- During OV Upgrade, User Must “Press Any Key” When Prompted (OVE-2291)

- Layer 3 “Accept All” and “Deny All” Policies Fail (OVE-2753)
- UPAM Web Portal Is Not Updated on OV After Changing (OVE-2973)
- Missing Device Info After Re-Discovering Multiple APs (OVE-2978)
- Upgraded Stellar APs Display Incorrect Error Message (OVE-3018)
- Slow Discovery of Links of Newly Discovered Devices (OVE-3147)
- Switch Responding “Unsupported-Attribute” After Successful Guest/BYOD Authentication on 8.5R2 Switch (OVE-4189)

## 6.2 PRs Fixed Since 4.3R2

- Using “show log swlog” in OV Client Window Causes Window to Crash (CRNOV-645)
- OV Should Allow to Reset AP to Factory Settings (OVE-2162)
- AP Records Are Not Received by OmniVista in L2 HA Mode (OVE-2292)
- UPAM Authentication Log Issue with External Syslog Log Server (OVE-2699)
- Issue No Auth Radius Possible Between UPAM and RADIUS (OVE-3041)
- Stellar Clients Connected to AP1231 in Enterprise Mode Are Mapped to the Wrong VLAN (OVE-3042)
- Trap Description Does Not Show In OmniVista If Trap Is Defined as a V2 trap (OVE-3105)
- Cannot Upgrade from 4.3R1 Download Package After Selecting the “Download Only” Option (OVE-3112)
- Performance Monitoring Does Not Support OS9900 (OVE-3151)
- Resource Manager Failed to Upgrade OS6350/6450 Switches (OVE-3160)
- Edit RADIUS shared key it automatically synchronizes to all the switch – no way to revert (OVE-3166)
- “Synchronized status” field in OV 2500 under “managed devices” is not correct for switches on R8 (OVE-3181)
- Topology child maps order (OVE-3347)
- OV fails to create policy conditions of MAC group along with service group (OVE-3359)
- Need to improve the work flow to limit the error “failed to stop all services, proceed to exit ov restore flow” (OVE-3537)
- If Data Migration process is failed, OV needs to have a mechanism to inform the result of upgrade to the user (OVE-3538)
- If Backup/restore operation is failed, OV needs to have a mechanism to inform exactly the result to the user (OVE-3862)
- Authentication Server doesn’t support RADIUS Server that has Shared Secret > 16 characters (OVE-3878)
- Unable to change Discovery polling frequencies in OV 4.3R2 (OVE-3909)
- Add more some info of OV system when collecting OV log via VA Menu (OVE-3934)
- CLI Scripting’s Scheduler jobs have wrong start time when schedule the same script in the second time (OVE-3935)
- Guest can register account with long mail-address (OVE-3994)
- AP Registration - Access Point: Cannot change AP name + RF Profile at the same time (OVE-4005)

## 6.3 PRs Fixed Since 4.3R1

- IAP SSID Generated a Default Role with the Same Name (OVE-795)
- Configure Traps for Multiple Devices Failed on Some Devices (OVE-838)
- Stellar APs do not show up after upgrade of OV from 4.2.1 to 4.2.2-build 115 (OVE-1023)
- Cannot Apply Policy List to VC of 8 or VC of 5 Devices for AOS 8.5R1 (OVE-1469)
- Cannot Collect Top N Clients Data for 6860 Switches Running AOS 8.5R1 (OVE-1742)
- "Cannot topology.msg.getMap" OmniVista 2500 NMS 4.2.2.R01 MR-2 (Build 115, 01/22/2018) (OVE-1783)
- Sorting Report List by Date does not sort by chronological order (OVE-1789)
- Some Stellar APs upgrade via OV failed (OVE-1806)
- OmniVista Not Displaying OS6560, OS9900 Switches When Mapping Tunnels in Unified Profile application (OVE-1816)
- OV server time (time zone) is not getting updated properly (OVE-1834)
- Unable to re-discover the switches after deleting them in Managed Devices using IP range (OVE-1872)
- OV doesn't display Trap Name for alaLldpTrustViolation of OS 6860 (OVE-1909)
- Group permission is changed when the user add/remove the user in Administrators group (OVE-1938)
- Monitoring Band Widget do not show up in the WLAN Dashboard (OVE-1943)
- OV Should allow SSH/Telnet to a Newly Added Device That Is Unreachable by SNMP (OVE-1949)
- OV2500: Unable to update the CLI/FTP user name and password for existing discovered switches. (OVE-1966)
- Error when sending test email with SMTP Authentication in Home > UPAM > Settings > Email Server (OVE-1973)
- Remove quota option in mongodb.cfg (OVE-2000)
- OV2500 SMTP/ Mail server communication issue port 25 (OVE-2288)
- Link between the Stellar AP and OS6860 switch is missing in the Topology tab (OVE-2294)
- Registration Status message on AP Registration Page is not descriptive of the underlying issue (OVE-2305)
- Topology Search Map Is Case Sensitive (OVE-2308)
- SSH Terminals in New Browser Tabs Do Not Show Device Name (OVE-2309)
- The list port of Access Auth Profile does not sort (OVE-2310)
- The item "OmniAccess Stellar APs" in Device Type in Topology should be changed as "WLAN" (OVE-2318)
- OV 4.3.51.R1 UPAM Captive Portal Authentication. Switch responding CoA NAK Unsupported attribute (OVE-2321)
- Don't allow the user to perform a restore using a backup from a previous release. (OVE-2326)
- The password is showed on the Captive Portal page after register the guest user by Phone Number (OVE-2336)

## OmniVista 2500 NMS Enterprise 4.4R1 Release Notes

- CLI Scripting: Parameter should be moved "\$" to display friendly at the last step when sending a scripting file (OVE-2426)
- OV 4.3.51.R1/UPAM Guest Access with Self-Registration, receipt contains some errors (OVE-2436)
- Resource Manager does not recognize OS6560\_8.5.164.R01 ISSU zip package as an ISSU image set (OVE-2456)
- Resource Manager can't run backup after upgrading OV to 4.3R1 (OVE-2480)
- OV2500 4.3 Trap responder issue (OVE-2535)
- Settings of Managed Devices are not saved (OVE-2571 )
- Need to customize the captive portal login page (OVE-2591)
- OV2500 sees OAW-AP1251 as down; device is reachable from OV via ICMP (OVE-2600)
- Resource Manager page is stuck and does not response (OVE-2647)
- Guest Account table content removed by the system all 2 hours (OVE-2735)
- KEC international. ; OV 2500 integrated with stellar AP (OVE-2749)
- [Locator] Change column headers of Netforward results (OVE-2895)
- [Locator] Allow Copy function in the MAC address field of the locator result (OVE-2896)
- [Locator] Should persist the sort setting in the locator result (OVE-2897)
- Support one new command "Show tech-support eng complete" in Collect Support Info app (OVE-2907)
- OV2500 unable to discover complete VM machines by the VM manager and license issue (OVE-2938)
- Remove auto trap config feature when discovering a new device in OV Enterprise (OVE-2945)
- AP coverage from Floor Plan application is very different from the actual coverage. (OVE-2948)
- The Compare page of Resource Manager could not load switch snapshots (OVE-2968)
- Operator available in OV2500 UPAM (OVE-2970)
- OV 2500 - display issue regarding the "changes" status of Stellar AP which is seen as « unsaved (OVE-2971)
- Cannot Use UTF8 Characters in Unified Profile Name (OV-4404)
- Errors Displayed During OmniVista Upgrade (OV-4752)
- Expired Guest/BYOD Devices Not Removed from Remember Devices Tab (OV-5104)
- Guest Access Approval Setting Is Reset After Upgrade to OV 422-MR 1 (OV-5182)
- OmniVista 2500 NMS 4.3 Extend Data Partition Issue and High CPU Usage (CRNOV-534)
- Customer OV2500 4.3R1 Issue with High CPU on the VM (CRNOV-561)
- Authenticating Record Module Is Not Responding on OV2500 4.3R01 B51 (CRNOV-572)
- Cannot delete a map in Topology, Button is Greyed Out (CRNOV-575)
- BMF Upgrade Fails on OS6250 Switch (210056)

## 6.4 PRs Fixed Since 4.2.2.R01 (MR 2)

- OV makes SSH connections to OS6860 switches every 15 minutes even though no AV profiles have been assigned to those switches (OVE-679)
- AP Stellar - Up Time received in the trap from AP is incorrect (OVE-727)
- IAP SSID generated a default role with the same name (OVE-795)
- Add a Serial Number column in Managed Devices table (OVE-829)
- LAG member ports: No way to know which are members of a given LAG (OVE-843)
- Guest username does not support hyphen (OVE-845)
- Error message "Fail to load data from server" after waiting a long time to get the data in Top N port report (OVE-846)
- Backup Files table should show backup files by device and by latest time periods (OVE-856)
- OV does not support showing a serial number with the prefix 00 in Configuration > Resource Manager > Inventory (OVE-879)
- The associated time in WLAN Client list shows the incorrect time (OVE-989)
- User-installed OV Web Server SSL certificate was lost after upgrading from OV422GA to OV422 MR-2 (OVE-1065)
- Enhance TTS template configuration to input arbitrary IP (OVE-1151)
- 4.2.2.115.R01 – Vulnerabilities (OVE-1157)
- Initializing OV Cluster stops at "Synchronizing activemq data". Cannot go further because of unstable network (OVE-1302)
- CRAOS8X-1165 Notifying "one touch data" policy fails on OS6465 8.5R01 (OVE-1457)
- Copy-Paste on Terminal (OVE-1482)
- The "Device DNS Name" on Netforward Result and "End station Name" on ARP Results are missing in OV 4.3R1 (OVE-1552)
- Analytics for AV (App count) is not showing data for Top User per application and Top Application per user after upgrade from OV42 MR2 (OVE-1593)
- Script triggering without considering the scheduled start time (OVE-1633)
- OV2500: Read and Write community strings are the same after OV discovers the switches (OVE-1762)
- The Locator polling was broken when receiving "disposition=null" from the switch (OVE-1785)
- Update Help pages/Release Notes for Preferred Node in HA configuration (OVE-1875)
- Upgrade from 422\_115\_MR to 431\_42R1 failed during OV43R1 FAT (OVE-1886)
- Users are unable to authenticate after OV2500 reboot (ALEISSUE-156)
- UPAM/ Updated Guest/BYOD Device Validity Period options (ALEISSUE-166)
- Not able to manage the right side of the map/image when running "Heat Map" (ALEISSUE-168)
- Latvia country not configurable in the RF profile in OV enterprise (ALEISSUE-194)

## 6.5 PRs Fixed Since 4.2.2.R01 (MR 1)

- OmniVista Takes More Than One Hour to Boot Up (227970)
- UPAM authentication with and External RADIUS server will fail if the shared secret between UPAM and AP are different than the shared secret between UPAM and the External RADIUS server (OV-4242)
- UPAM External RADIUS Server Certificate Fails When Importing .der, .pfx Certificates (OV-4490)
- LLDP Link disappeared between OS6450 and Stellar AP (OV-4706)
- Monitoring and Enforcement CSV Files are not Getting Populated in OmniVista (OV-4751)
- Errors Displayed During OmniVista Upgrade (OV-4752)
- Unsecure Host Key Algorithm Used in VA for SFTP on Port 22 (OV-4765)
- UPAM Does Not Support NAS Clients with Different Keys (OV-4786)
- OmniVista Does Not Show Correct LLDP Port Numbers for 9900 Devices (OV-4886)
- Unable to Create Multiple Manual Links to the Same Port (OV-4913)
- SSH/SSL Security Vulnerabilities - CVE-2016-2183, CVE-2016-2183 (OV-5003)
- Application Visibility Stats in Summary View and Details View Not Updated Though There Are Flows (OV-5056)
- Account and Device Validity Period Set to 1 Day, But Device Displayed in Remembered Devices After 2 Days. Client Can Still Connect after 24 Hours (OV-5062)
- Not able to modify the Guest Access Strategy (OV-5063)
- Unable to Delete Expired Blacklist Client (OV-5084)
- UPAM External Log Server configuration is not saved (OV-5123)
- Guest username does not support hyphen ("-") (OV-5146)
- UPAM Does Not Validate AOS Device Shared Secret (OV-5159)
- AOS Switches Frequently Show as "Down" (OV-5197)
- Issue with "Associated time" with WLAN Client – AM/PM Not Displayed (OV-5328)

## 6.6 PRs Fixed Since 4.2.2.R01 GA

- External RADIUS Users Cannot Utilize the Template Function (228018)
- Imported Floor Plan Does Not Display in Heat Map (OV-4640)

## 6.7 PRs Fixed Since 4.2.1.R01 (MR 2)

- Backup files are disordered by date (226863)
- Backup fail\_operation failed on the device (226999)
- Some Switches are missing from PALM summary reports (227209)
- Boot up takes more than an hour (227704)
- Two folders switchbackups and switchBackups are displayed in cliadmin folder (228220)
- Update MIB for OS9900 from OV because this device displays type incorrectly as OS9907 (OV-2142)
- The value of " Last Known Up At" field between 2 features (Discovery and Topology) is mismatched (OV-2808)



## OmniVista 2500 NMS Enterprise 4.4R1 Release Notes

- CLI Scheduled CLI Script Fails to Run (OV-2883)
- Report file for Discovery is empty (OV-2961)
- Display serial number in topology view (OV-3066)
- Support send scripts for Cisco devices (OV-3248)
- Hardware Inventory does not show Miniboot version and Firmware Version correctly for OS6450 device (OV-3283)
- OS6860 8.4.1.R02 cannot get IP from DHCP Server (Auto Configuration) (OV-3853)
- Topology does not react to link down trap sent from switches (OV-4007)
- New switches within the discovery range are not being discovered when full auto discovery polling is run (OV-4133)
- OV cannot get statistics if the devices are using SNMPv3 except MD5+DES (OV-4144)
- OV cannot send the script with long command (OV-4321)
- OV shouldn't use OID to display the info of Module-name and Description for OS6350 (OV-4557)
- Schedule reload the switch does not work (OV-4605)
- Failed to login to OV after upgrade if the previous system using external radius server (OV-4660)
- Schedule Configuration backup device with Incremental ON does not work (OV-4664)
- SNMP settings revert to default value if users provide FTP user/password at CLI scripting terminal (OV-4676)
- Filtering doesn't work for the List view in Discovery/Range List (OV-4681)
- Cannot see Alarm widget data if OV using external radius server and users belongs to groups "Network Administrator", "Writers" and "Default" (OV-4683)
- Got the error "Failed to load data" from server when sending a long script to the device (OV-4684)
- Auto configuration entries do not display after restoring (OV-4700)

### 6.8 PRs Fixed Since 4.2.1.R01 (MR 1)

- User allowed to use the same Application Group Name for monitoring and enforcement. (PR 221096)
- User cannot navigate to Diagnostic Screen in Locator. (PR 220966)
- Certain Operations in Topology Fail Using I/E Browser (220967)
- OV421 GA to MR 1 upgrade failed the first time, and subsequent attempts to upgrade to MR 1 build were not successful because VA could not detect the new build in the Repository. (OV-2556)
- It takes a long time to load large log files in the Audit application. (OV-2623)
- Topology Map List sort order is not persistent. Sort order is now retained for the current OmniVista login session. (OV-2632)
- Not enough information in the Scheduler application for schedule Resource Manger Backup Jobs. Need job description and list of devices being backed up. (OV-2665)
- It takes a long time to re-discover existing switches in Discovery application. (OV-2672)
- When importing Third Party MIBs, if MIB Files are not sorted in the correct order, some MIB file imports failed because of dependencies on other MIB files. (OV-2680)

- A CLI Script scheduled to run periodically would fail with "STOPPING" status in Scheduler Jobs but show as "Running" in Scheduler History. (OV-2883)
- Analytics Port Utilization job in Scheduler application displays incorrect device list. (OV-2909)
- After performing an image upgrade of multiple devices, the "Install Upgrade Result Wizard" Results Screen is usually very long, forcing the webpage scroll-bar to display. As a result, users might not see the "Go to Topology to Reboot Device" link at the bottom of the screen, and know that they need to reboot the devices to complete the upgrade. The link has been moved to the top of the Results Screen. (OV-2990)
- In the Report application, the Backup Report does not include a Date Column. (OV-3195)
- The Role Based Access Control (RBAC) feature does not work for Discovery - Ports. (OV-3427)

## 6.9 PRs Fixed Since 4.2.1.R01 GA

- OmniVista should display ifAlias in addition to ifDescr in port pickers (PR 214448)
- In the Application Visibility application, the default option for Data Unit should be "Bytes" instead of "MB" for Counter Type/Byte Count (PR 220623) Create ClearPass Roles matching the names of the standard Enforcement Profiles (PR 220825)
- Tomcat shuts down on a system running for a long time (PR 220833)
- OmniVista using 127.0.0.1 as the NAS-IP instead of using the physical address in the RADIUS request sent (PR 221385)
- BYOD Diagnostics - Search for IP address for authenticated endpoint in ClearPass fails (PR 221798)
- BYOD fails to update Access Role Profile if it is associated with an Enforcement Policy (PR 221857)
- Read and Write community string are the same after OV discovers switches (PR 222203)
- OmniVista Scheduled reboot is not working (PR 222520)
- Backup Tab in Resource Manager is not responding. Screen takes a long time to load or never responds when there are a large number of backups. (PR 222706)
- Repetitive proxy message displayed when YouTube is not reachable from the OmniVista Server (PR N/A)

## 6.10 PRs Fixed Since 4.1.2.R03

- The Modules tab in the Topology application is displaying incorrect information for transceivers connected to OS-XNI-U12E daughter cards on OS6900-X20 devices (PR 187119)
- SIP does not display Active Call Records on devices running AOS 6.4.6.R01 even when SIP call is running successfully on device (PR 189041)
- Cannot find end station using upper case MAC address when trying to locate a device on the Diagnostics Screen (PR 205365)
- If the sFlow Receiver is configured on a switch in the CLI as Receiver "1" and a user applies an Analytics Profile to the switch OmniVista 2500 NMS overwrites the CLI-configured sFlow receiver with its own IP address as Receiver "1" (PR 205843)

- "Failed to activate signature file" error on OS6860E-P48 (AOS 8.2.1.256.R01 GA) (PR 211504)

### **6.11 PRs Fixed Since 4.1.2.R02**

- No Traps Generated on 7.x/8.x when Trap Port Set to Number Other Than 162 (PR 198919)
- UA Policy Re-Caches Incorrectly with Policies on AOS Switch (PR 205481)

### **6.12 PRs Fixed Since 4.1.2.R01 Maintenance Release**

- When linkagg removed via CLI, UNP linkagg is deleted on switch, but not in OmniVista 2500 NMS (PR 195702)
- Installation of OmniVista 2500 NMS Fails with "Error: Mongo couldn't be started" and the installation rolls back (PR 197900)

### **6.13 PRs Fixed Since 4.1.2.R01**

- VA Upgrade - Error "The SNMP trap listener could not be created on port 162" when notification app opened (PR 201406)
- OmniVista 2500 NMS Discovery issue for Juniper switches in VC configuration (PR 190524)
- Clarification in color status change for Link Aggregate link status (PR 196909)
- Issue with the SPB One Touch Feature (PR 197937)
- "Max Timeout" script error seen when sending SPB Configuration Telnet Script through OmniVista 2500 NMS (PR 199393)
- Unable to assign ClearPass Server for AOS device (6.4.4.R01) (PR 199978)
- OmniVista 2500 NMS Tomcat Service does not start if database backup is imported from 3.5.7 through a RADIUS Server (PR 200009)
- SSLv3 vulnerability issue (PR 200391)
- OmniVista 2500 NMS Server in a VA installation should be able to bind to a port lower than 1024 (e.g., 162, 514) (PR 201007)
- OmniVista 2500 NMS should not show stack split warning icon when the stack does not support SSP and is not in loop (PR 201483)

### **6.14 PRs Fixed Since Release 4.1.1**

- Even if GetBulk is disabled in the SNMP Settings of the java UI, OmniVista 2500 NMS 411 services such as Unified Access, Application Visibility, and BYOD ignore this setting and still use GetBulk (PR 196768)

### **6.15 PRs Fixed Since 3.5.7 Maintenance Build**

- Live Search for IP Phones Issue (PR 187956)

### **6.16 PRs Fixed Since Release 3.5.7 GA**

- "Set Row" displays error when user logs into OV Server with multiple browser windows (PR 188220)

## OmniVista 2500 NMS Enterprise 4.4R1 Release Notes

- Status "In Active" of Statistics profile is not correct; and the Calendar does not work when scheduling a Statistics profile (PR 188827)
- Error in vmm.log if the VM name contains "/" character and the VM name in VM Manager is not correct (PR 188876)
- Unable to start OV Server if LDAP server is not running (PR 191084)
- 64-bit OmniVista 2500 NMS 3.5.7 does not detect the previously installed version during upgrade (PR 192354)

## Appendix A – Enabling DCOM on Hyper-V

Follow the applicable procedures below to enable DCOM on a [Standalone](#) or [High-Availability](#) installation.

### Enable DCOM on Hyper-V (Standalone Installation)


The following steps are specific to Windows 64 bit only.

1. Log in Hyper-V Server.
2. Get the Powershell script from attachment: HyperV\_Enable\_DCOM\_x64.ps1.




HyperV\_Enable\_DCOM\_x64.ps1

3. Run Powershell.




4. Run Set-ExecutionPolicy -Scope Process - ExecutionPolicy Bypass.




5. Change to the directory that contains the downloaded script from Step 2.



3. Run Powershell.



4. Change to the directory that contains the downloaded scripts from Step 2.



5. Open Registry Editor (regedit.exe) > create a backup by using Export.

6. Execute HyperV\_Cluster\_Enable\_DCOM\_x64.ps1.

