

OmniVista 3600 Air Manager provides a range of features to manage network infrastructure devices from Alcatel-Lucent and other vendors. This document describes the supported product families, software versions, and feature set for the following product sets:

- [Alcatel-Lucent Devices](#)
- [Other Third-Party Vendor Devices](#)
 - [Cisco® Devices](#)
 - [Hewlett Packard Enterprise Devices](#)
 - [Juniper® Devices](#)
 - [Meru® Devices](#)
 - [Motorola® Devices](#)
 - [Other Third-Party Devices with Monitoring Support](#)
- [Other Switches](#)

Alcatel-Lucent Devices

This release of OV3600 supports management of global configuration profiles or settings, monitoring, and software upgrades on the Alcatel-Lucent devices and software described in the following sections.

Alcatel-Lucent AOS-W

OV3600 supports all Alcatel-Lucent switches and most access points (APs) that are running the following Alcatel-Lucent AOS-W versions:

- 6.4.4.0
- 6.5.0.0, 6.5.1.0, 6.5.2.0, 6.5.3.0, 6.5.4.0, 6.5.4.18, and 6.5.4.20
- 8.0.0.0 and 8.0.1.0
- 8.1.0.x
- 8.2.0.x and 8.2.1.x
- 8.3.0.x
- 8.4.0.x
- 8.5.0.x
- 8.6.0.x
- 8.7.0.x
- 8.7.1.x
- 8.8.0.x
- 8.9.0.x
- 8.10.0.x

OV3600 also supports Alcatel-Lucent unified APs, which are APs factory-installed with Alcatel-Lucent AOS-W 6.5.2.0 or a later. A unified AP can be configured to operate as either a campus AP or a remote AP when that device is first provisioned. For more information on unified APs, refer to the *Alcatel-Lucent AOS-W 6.5.2.0 Release Notes*.

FIPS Support

Alcatel-Lucent AOS-W 6.x supports FIPS for Alcatel-Lucent switches, OAW-4000/4650/4750 Series Series, OAW-4550/4650/4750 Series, and 7280 models for Alcatel-Lucent AOS-W version 6.5.4.20-FIPS_80110.

Alcatel-Lucent AOS-W 8.x supports FIPS for Alcatel-Lucent switches, OAW-4000/4650/4750 Series Series, OAW-4550/4650/4750 Series, 7280, and 9000 Series models for below Alcatel-Lucent AOS-W versions.

- 8.5.0.13-FIPS_80141
- 8.6.0.9-FIPS_79814
- 8.7.1.4-FIPS_80407
- 8.8.0.1-FIPS_80394

For the complete list of products that have reached the end of life milestone and are not supported, refer to <https://businessportal2.alcatel-lucent.com>

[Table 1](#) lists the supported devices and the tested AOS-W firmware versions.

Table 1: Supported Alcatel-Lucent AOS-W Devices

| Device | Validated Up To |
|--|-------------------|
| OAW-AP534, OAW-AP535 | 8.8.0.0 |
| OAW-AP515 | 8.7.0.0 |
| OAW-AP374, OAW-AP375, and OAW-AP377 | 6.5.4.16, 8.8.0.0 |
| OAW-AP365 and OAW-AP367 | 6.5.4.16, 8.8.0.0 |
| OAW-AP344 and OAW-AP345 with Dual 5-GHz Mode | 8.8.0.0 |
| OAW-AP334 and OAW-AP335 | 6.5.4.16, 8.8.0.0 |
| OAW-AP324 and OAW-AP325 | 6.5.4.16, 8.8.0.0 |
| OAW-AP318 | 8.8.0.0 |
| OAW-AP314 and OAW-AP315 | 6.5.4.16, 8.8.0.0 |
| OAW-AP304 and OAW-AP305 | 6.5.4.16, 8.7.0.0 |
| OAW-AP303 | 8.8.0.0 |
| OAW-AP303H | 6.5.4.16, 8.8.0.0 |
| OAW-AP277 | 6.5.4.16, 8.7.0.0 |
| OAW-AP274 and OAW-AP275 | 6.5.4.16, 8.7.0.0 |
| OAW-AP228 | 6.5.4.16, 8.7.0.0 |
| OAW-AP224 and OAW-AP225 | 6.5.4.16, 8.7.0.0 |
| OAW-AP214 and OAW-AP215 | 6.5.4.16, 8.7.0.0 |
| OAW-AP207 | 6.5.4.16, 8.7.0.0 |

| Device | Validated Up To |
|--------------------------|-------------------|
| OAW-AP205H | 6.5.4.16, 8.7.0.0 |
| OAW-AP204 and OAW-AP205 | 6.5.4.16, 8.7.0.0 |
| OAW-AP203H | 6.5.4.16, 8.8.0.0 |
| OAW-AP203R and OAW-203RP | 6.5.4.16, 8.8.0.0 |
| OAW-AP175 | 6.5.4.16, 8.6.0.0 |
| OAW-AP134 and OAW-AP135 | 6.5.4.16, 8.6.0.0 |
| OAW-AP124 and OAW-AP125 | 6.5.4.16, 6.4.0.0 |
| OAW-AP114 and OAW-AP115 | 6.5.4.16, 8.6.0.0 |
| OAW-AP104 and OAW-AP105 | 6.5.4.16, 8.6.0.0 |
| OAW-AP103 | 6.5.4.16, 8.6.0.0 |
| OAW-AP103H | 6.5.4.16, 8.3.0.0 |
| OAW-AP92 and OAW-AP93 | 6.5.4.16, 8.2.0.0 |
| OAW-AP93H | 6.5.4.16, 8.2.0.0 |
| OAW-AP68 | 6.5.4.16, 8.7.0.0 |
| OAW-AP120 | 6.5.4.16, 8.6.0.0 |
| OAW-AP121 | 6.5.4.16, 8.6.0.0 |
| OAW-AP40 and OAW-AP41 | 6.5.4.16, 8.6.0.0 |
| OAW-AP4306INT | 6.5.4.16, 8.6.0.0 |
| OAW-AP60 | 6.5.4.16, 8.6.0.0 |
| OAW-AP61 | 6.5.4.16, 8.6.0.0 |
| OAW-AP65 | 6.5.4.16, 8.6.0.0 |
| OAW-AP68P | 6.5.4.16, 8.6.0.0 |
| OAW-AP70 | 6.5.4.16, 8.6.0.0 |
| OAW-AP80M | 6.5.4.16, 8.6.0.0 |
| OAW-AP80S | 6.5.4.16, 8.6.0.0 |
| OAW-AP85 | 6.5.4.16, 8.6.0.0 |
| OAW-4008 | 6.5.4.16, 8.7.0.0 |
| OAW-4104 | 6.5.4.16, 8.7.0.0 |

| Device | Validated Up To |
|---|-------------------|
| OAW-4302, OAW-4304, OAW-4306G, OAW-4306GW, OAW-4306, OAW-4308, OAW-4324 | 6.5.4.16, 8.7.0.0 |
| OAW-4450 | 6.5.4.16, 8.7.0.0 |
| OAW-4750XM | 6.5.4.16, 8.7.0.0 |
| OAW-4850 | 6.5.4.16, 8.7.0.0 |
| OAW-5000 | 6.5.4.16, 8.7.0.0 |
| OAW-6000 | 6.5.4.16, 8.7.0.0 |
| OAW-MM-HW-10K | 8.6.0.0 |
| OAW-MM-HW-5K | 8.6.0.0 |
| OAW-MM-HW-1K | 8.6.0.0 |
| OAW-MC-VA | 8.6.0.0 |
| OAW-MM-VA | 8.6.0.0 |
| OAW-4504/4604/4704 Series switch | 6.4.4.22 |
| OAW-4005 switch | 6.5.4.16, 8.7.0.0 |
| OAW-4010 switch | 6.5.4.16, 8.7.0.0 |
| OAW-4024 switch | 6.5.4.16, 8.7.0.0 |
| OAW-4030 switch | 6.5.4.16, 8.7.0.0 |
| OAW-4550/4650/4750 Series switch | 6.5.4.16, 8.7.0.0 |



The End-Of-Life devices and Alcatel-Lucent AOS-W versions listed on the EOL page <https://businessportal2.alcatel-lucent.com> are not tested or supported by OV3600. Alcatel-Lucent recommends deploying the devices only with the supported platforms and Alcatel-Lucent AOS-W versions.

Alcatel-Lucent Instant

Table 2 lists the Instant firmware versions and functions supported by OV3600. OV3600 also supports the Alcatel-Lucent RAP-100 Series and RAP-3 Series remote access points.

Table 2: Supported Alcatel-Lucent Instant Firmware Versions and Functions

| Instant Version | Support for | |
|------------------|-----------------|--------------------|
| | Template Config | Instant GUI Config |
| Instant 8.10.0.0 | OV3600 8.2.14.1 | OV3600 8.2.14.1 |

| Instant Version | Support for | |
|-----------------|-----------------|--------------------|
| | Template Config | Instant GUI Config |
| Instant 8.9.0.0 | OV3600 8.2.14.0 | OV3600 8.2.14.0 |
| Instant 8.9.0.0 | OV3600 8.2.13.1 | OV3600 8.2.13.1 |
| Instant 8.8.0.0 | OV3600 8.2.13.0 | OV3600 8.2.13.0 |
| Instant 8.8.0.0 | OV3600 8.2.12.1 | OV3600 8.2.12.1 |
| Instant 8.7.1.0 | OV3600 8.2.12.0 | OV3600 8.2.12.0 |
| Instant 8.7.0.0 | OV3600 8.2.11.2 | OV3600 8.2.11.2 |
| Instant 8.7.0.0 | OV3600 8.2.11.1 | OV3600 8.2.11.1 |
| Instant 8.6.0.4 | OV3600 8.2.11.0 | OV3600 8.2.11.0 |
| Instant 8.6.0.0 | OV3600 8.2.10.1 | OV3600 8.2.10.1 |
| Instant 8.5.0.2 | OV3600 8.2.10.0 | OV3600 8.2.10.0 |
| Instant 8.5.0.0 | OV3600 8.2.9.1 | OV3600 8.2.9.1 |
| Instant 8.5.0.0 | OV3600 8.2.9.0 | OV3600 8.2.9.0 |
| Instant 8.4.0.1 | OV3600 8.2.8.2 | OV3600 8.2.8.2 |
| Instant 8.4.0.0 | OV3600 8.2.8.1 | OV3600 8.2.8.1 |
| Instant 8.3.0.0 | OV3600 8.2.7.1 | OV3600 8.2.7.1 |
| Instant 8.3.0.0 | OV3600 8.2.6.1 | OV3600 8.2.6.1 |
| Instant 6.5.4.0 | OV3600 8.2.5.1 | OV3600 8.2.5.1 |
| Instant 6.5.4.0 | OV3600 8.2.5.0 | OV3600 8.2.5.0 |
| Instant 6.5.3.0 | OV3600 8.2.4.1 | OV3600 8.2.4.1 |
| Instant 6.5.2.0 | OV3600 8.2.4.0 | OV3600 8.2.4.0 |
| Instant 4.3.1.0 | OV3600 8.2.3.1 | OV3600 8.2.3.1 |
| Instant 4.3.0.0 | OV3600 8.2.3.0 | OV3600 8.2.3.0 |
| Instant 4.2.4.0 | OV3600 8.2.1.0 | OV3600 8.2.2.0 |
| Instant 4.2.3.0 | OV3600 8.2.0.0 | OV3600 8.2.2.0 |



- Starting with 6.4.3.x-4.2, Instant software does not support OAW-IAP92 and OAW-IAP93.
- Management of FIPS-enabled OAW-IAP is not supported on both non-FIPS & FIPS-enabled OV3600 servers.

Aruba Switches

OV3600 supports monitoring, template configuration, and firmware changes on the Aruba switches listed in [Table 3](#). On these switches, you can set up device-specific triggers and alerts and designate them as trap receivers. If you want to see the SNMP traps, go to the **System > Syslog & Traps** page.

In addition, you can push a complete configuration profile using templates to Aruba switches that have a factory-default configuration, or you can send configuration jobs using switch CLI commands and snippets to switches in a device group.



In VisualRF, these Alcatel-Lucent switches appear in the VisualRF product catalog. However, their utilization values will be 0 because OV3600 does not get utilization values for these devices.

Table 3: Supported Aruba Switches

| Device | Monitoring | Configuration | Firmware Upgrade | Validated Up To |
|-------------------------------|------------|---------------|------------------|-----------------|
| Aruba 2530YA Switch Series | Yes | Yes | Yes | YA.16.11.0003 |
| Aruba 2530YB Switch Series | Yes | Yes | Yes | YB.16.11.0003 |
| Aruba 2540 Switch Series | Yes | Yes | Yes | YC.16.11.0003 |
| Aruba 2620 Switch Series | Yes | Yes | Yes | RA.16.11.0003 |
| Aruba 2920 Switch Series | Yes | Yes | Yes | WB.16.11.0003 |
| Aruba 2930F Switch Series | Yes | Yes | Yes | WC.16.11.0003 |
| Aruba 2930M Switch Series | Yes | Yes | Yes | WC.16.11.0003 |
| Aruba 3800 Switch Series | Yes | Yes | Yes | KA.16.11.0003 |
| Aruba 3810 Switch Series | Yes | Yes | Yes | KB.16.11.0003 |
| Aruba 5400Rzl2 Switch Series | Yes | Yes | Yes | KB.16.11.0003 |
| ArubaOS-CX 4100 Switch Series | Yes | No | No | RL.10.09.1000 |
| ArubaOS-CX 6000 Switch Series | Yes | No | No | PL.10.09.1000 |
| ArubaOS-CX 6100 Switch Series | Yes | No | No | PL.10.09.1000 |
| ArubaOS-CX 6200 Switch Series | Yes | No | No | ML.10.09.1000 |

| Device | Monitoring | Configuration | Firmware Upgrade | Validated Up To |
|---------------------------------|------------|---------------|------------------|-----------------|
| ArubaOS-CX 6300 Switch Series | Yes | No | No | FL.10.09.1000 |
| ArubaOS-CX 6300M Switch Series | Yes | No | No | FL.10.09.1000 |
| ArubaOS-CX 6400 Switch Series | Yes | No | No | FL.10.09.1000 |
| ArubaOS-CX 8320 Switch Series | Yes | No | No | TL.10.09.1000 |
| ArubaOS-CX 8325 Switch Series | Yes | No | No | GL.10.09.1000 |
| Aruba OS-CX 8360 Switch Series | Yes | No | No | LL.10.09.1000 |
| Aruba OS-CX 8400 Switch Series | Yes | No | No | XL.10.09.1000 |
| Aruba OS-CX 10000 Switch Series | Yes | No | No | DL.10.09.1000 |

Aruba Mobility Conductor Appliances

OV3600 supports the following devices running ArubaOS 8.0.0.0 and later:

- Mobility Conductor Hardware Appliance MM-HW-1K, MM-HW-5K, and MM-HW-10K
- Mobility Conductor Virtual Appliance MM-VA

Aruba Mobility Access Switches

OmniVista 3600 Air Manager supports profile configuration, monitoring, and software upgrades on the Aruba Mobility Access Switches. In addition to the port statistics supported for most Ethernet switches with the supported firmware described below, OV3600 also tracks the activity of authenticated wired clients on Aruba switches.

Table 4: *Supported Aruba Mobility Access Switches*

| Device | Validated up to |
|--------|-----------------|
| S1500 | 7.4.0.0 |
| S2500 | 7.4.0.0 |
| S3500 | 7.4.0.0 |

Aruba AirMesh

Aruba AirMesh outdoor products running MeshOS 4.2 are supported for monitoring and software upgrades.

Table 5: *Supported Aruba MeshOS Devices*

| Device | Validated up to |
|---------|-----------------|
| MSR1200 | MeshOS 4.2 |
| MSR2000 | MeshOS 4.2 |
| MSR4000 | MeshOS 4.2 |
| MST200 | MeshOS 4.2 |

Other Third-Party Vendor Devices

OV3600 supports the following monitoring features for other third party devices:

- User monitoring data such as connection time, user name, SSID, and bandwidth
- Network monitoring data, including real-time and historical bandwidth and user count metrics
- Rogue detection and classification using OV3600customizable rules
- VisualRF heatmaps and user/rogue location
- Reports
- Triggers and alerts

In some cases, you can do basic configuration and firmware upgrades, as well as discover third-party controller and APs.

Cisco® Devices

OV3600 supports Cisco devices that are running the latest verified firmware versions and have not reached the end of life milestone. Informal testing shows that OV3600 supports devices running more recent versions of firmware, but full support for these later versions is not validated.

Cisco Autonomous Access Points

OV3600 provides monitoring, management, and software upgrade support for the devices listed in [Table 6](#).

Table 6: *Supported Cisco Autonomous Access Points*

| Model | Validated up to |
|---------------------------------------|-------------------------------------|
| 350 Series Access Points | IOS 12.3(11)JA and IOS 12.4(21a)JA1 |
| 702 Series Access Points | IOS: 15.3(3)D |
| 801 Series Integrated Access Points | IOS 12.4(25d)JA2 and IOS 15.(22)B |
| 819 Series Integrated Service Routers | IOS 15.6.3M5 |
| 860 Series Access Points | IOS 12.4(15)XZ, 12.4(20)T |
| 881 Series Access Points | IOS 12.4(21a)JA1 |
| 881W Series Access Points | IOS 12.4(21a)JA1 and IOS 15.0(1)M7 |
| 881GW Series Access Points | IOS 12.4(21a)JA1 and IOS 15.1(4)M3 |
| 891 Series Access Points | IOS 12.4(21a)JA1 and IOS 15.0(1)M7 |
| 1040 Series Access Points | IOS 12.4(21a)JA1 |
| 1100 Series Access Points | IOS 12.4(21a)JA1 |
| 1110 Series Access Points | IOS 12.4(21a)JA1 and IOS 12.3(11)JA |
| 1130 Series Access Points | IOS 12.4(21a)JA1 |
| 1140 Series Access Points | IOS 12.4(21a)JA1 and IOS 12.3(11)JA |

| Model | Validated up to |
|----------------------------|-------------------------------------|
| 1200 Series Access Points | IOS 12.4(21a)JA1 and IOS 12.3(11)JA |
| 1210 Series Access Points | IOS 12.4(21a)JA1 |
| 1230 Series Access Points | IOS 12.4(21a)JA1 |
| 1240 Series Access Points | IOS 12.4(21a)JA1 |
| 1250 Series Access Points | IOS 12.4(21a)JA1 |
| 1260 Series Access Points | IOS 12.4(21a)JA1 |
| 1300/1400 Series Bridges | IOS 12.4(21a)JA1 |
| 1700 Series Access Points | IOS 10.2.111.0 (IOS: 15.3(3)JN3) |
| 1941W Series Access Points | IOS 15.2(3)T |
| 2700 Series Access Points | IOS 10.2.111.0 (IOS: 15.3(3)JN3) |

Cisco Wireless Controllers and Access Points

OV3600 supports monitoring, RAPIDS, device discovery, and VisualRF for these devices, as well as configuration, firmware identification, AMP upgrade, and client monitoring-diagnostics for wireless controllers.

[Table 7](#) lists the Cisco wireless controllers and access point platforms that are supported in this release.

Table 7: *Supported Cisco Wireless Controllers and Access Points*

| Model | Validated up to |
|---------------------------|-----------------------------------|
| 1040 Series Access Points | 8.3.102.0 |
| 1130 Series Access Points | 7.6.110.0 (Bootloader: 7.0.116.0) |
| 1140 Series Access Points | 8.3.102.0 |
| 1200 Series Access Points | 8.3.102.0 |
| 1550 Series Access Points | 8.3.102.0 |

| Model | Validated up to |
|--|-----------------------------------|
| 1600 Series Access Points | 8.3.102.0 |
| 1700 Series Access Points | 8.3.102.0 |
| 1800 Series Access Points | 8.3.102.0 |
| 2600 Series Access Points | 8.3.102.0 |
| 2700 Series Access Points | 8.3.102.0 |
| 2802 Series Access Points | 8.5.110.0 |
| 3500 Series Access Points | 8.3.102.0 |
| 3600 Series Access Points | 8.3.102.0 |
| 3700 Series Access Points | 8.3.102.0 |
| 3800 Series Access Points | 8.3.102.0 |
| 2100 Series Wireless Controllers | 7.0.235.0 (Bootloader: 7.0.235.0) |
| 2500 Series Wireless Controllers | 8.3.102.0 |
| 4400 Series Wireless Controllers | 7.0.235.0 (Bootloader: 7.0.235.0) |
| Aironet 4800 Series Bridges (pre-VxWorks, monitoring only) | 8.65_2 |
| 5508 Wireless Controllers | 8.5.110.0 |
| 5520 Wireless Controllers | 8.1.131.0 |
| 5760 Wireless Controllers | 3.2.0 |

| Model | Validated up to |
|--|--------------------------------------|
| Flex 7500 Controllers | 8.3.102.0 |
| 8510 Controllers | 8.5.110.0 |
| 3504 Wireless switches | 8.10.130.0 (Bootloader: 8.5.103.0) |
| Catalyst 9800-40 Series | 16.12.4a |
| Cisco Catalyst 9800-80 | Limited testing done with simulator. |
| Cisco Catalyst 9800-CL Wireless Controller for Private Cloud | Limited testing done with simulator. |
| Cisco Catalyst 9800-L-C | Limited testing done with simulator. |
| Cisco Catalyst 9120 AXI | 8.10.151.0 |
| Cisco Catalyst 9120 AXE | 8.10.151.0 |
| Cisco Catalyst 9130 AXI | Limited testing done with simulator. |
| Cisco Catalyst 9130 AXE | Limited testing done with simulator. |



Cisco Mobility Services Engine and 500 Series Access Points are not supported.

Cisco Switches

OV3600 supports automated discovery through SNMP, model and firmware version identification, and displays CDP neighbor information and extended port error statistics for the Cisco switches listed in [Table 8](#).

Table 8: Supported Cisco Switches

| Model | Validated up to |
|---|-----------------|
| C9800-L-F-K9 | 16.12.3 |
| Catalyst 9400 Series Switches | 16.06.03 |
| Catalyst 2900 Series Switches (monitoring only) | 15.0(2)SE11 |
| Catalyst 3650 Series Switches | 03.06.06E |

| Model | Validated up to |
|--|-----------------|
| Catalyst 3750 Series Switches | 12.2(55)SE11 |
| Catalyst 3850 Series Switches | 03.06.06E |
| Industrial Ethernet 4000 Series Switches | 15.2(4)EA5 |

OV3600 doesn't update the upstream device information for access points connected to Cisco switches when Cisco switches are polled when using SNMPv3. Cisco has restricted access to the BRIDGE-MIB when using SNMPv3. When you access a Cisco switch using SNMPv3, APs connected to that switch may not be able to show upstream device info. As a workaround to this issue, add SNMPv3 bridge commands to the Cisco switches in order to expose VLAN values for the MIB polled by UDT. If there are devices on a switch, add the following command for each VLAN-#:

```
snmp-server group <GroupName> v3 priv context
```

You may need to append views to the command, as follows:

```
snmp-server group <GroupName> v3 priv context <VLAN-#> read <ViewName>
```

Use the **match prefix** parameter to all existing VLANs:

- `snmp-server group <GroupName> v3 priv context vlan- match prefix`
- `snmp-server group <GroupName> v3 priv context vlan- match prefix access`

Hewlett Packard Enterprise Devices

The firmware versions for the HPE devices listed in [Table 9](#) represent the latest firmware version verified as fully supported by OmniVista 3600 Air Manager 8.2.14.1. You can select these supported devices in the VisualRF product catalog when you configure device-specific triggers and alerts. You can set up these devices as trap receivers and view the SNMP traps on the **System > Syslog & Traps** page.



- OV3600 does not support MSM APs running in autonomous mode.
- Informal testing shows that OV3600 supports some devices running more recent versions of firmware, but full support for these later versions is not guaranteed.

For more information on configuring and managing and HPE switches via OV3600, refer to the *OV3600 Switch Configuration Guide*.

Table 9: HPE Device Support

| Model | Firmware Validated Up To |
|--------------------|--------------------------|
| MSM310 and MSM310R | 6.5.1.0 |
| MSM313 and MSM313R | 6.5.10 |
| MSM317 | 6.5.1.0 |
| MSM318 | 6.5.1.0 |

| Model | Firmware Validated Up To |
|--------------------------------|----------------------------|
| MSM320 and MSM320R | 6.5.1.0 |
| MSM323 and MSM323R | 6.5.1.0 |
| MSM325 | 6.5.1.0 |
| MSM335 | 6.5.1.0 |
| MSM410 | 6.5.1.0 |
| MSM417* | 6.5.1.0 |
| MSM422 | 6.5.1.0 |
| MSM425* | 6.5.1.0 |
| MSM430 | 6.5.1.0 |
| MSM460 | 6.5.1.0 |
| MSM466 and 466R | 6.5.1.0 |
| MSM525* | 6.5.1.0 |
| MSM527* | 6.5.1.0 |
| MSM560* | 6.5.1.0 |
| MSM710 Controller | 6.5.1.0 |
| MSM720 Controller | 6.5.1.0 |
| MSM730 Controller | 6.5.1.0 |
| MSM750 Controller | 6.5.1.0 |
| MSM760 Controller | 6.5.1.0 |
| MSM765 Controller | 6.5.1.0 |
| ProCurve 420 | 2.0.38 - 2.2.5 |
| ProCurve 530 | WA.01.16-WA.02.19 |
| ProCurve 2626-PWR | H.10.35 (ROM H.08.02) |
| 830 Unified Wired-WLAN Switch* | 5.20.109 (Release 2607P39) |
| 850 Unified Wired-WLAN Switch* | 5.20.109 (Release 2607P39) |
| 870 Unified Wired-WLAN Switch* | 5.20.109 (Release 2607P39) |
| HPE WESM controllers & APs xl | WS.01.05 – WS.02.19 |
| HPE WESM controllers & APs zl | WT.01.03 – WT.01.28 |

| Model | Firmware Validated Up To |
|--|---------------------------|
| HPE 1405 Switch Series | ** |
| HPE 1420 Switch Series | ** |
| HPE 1620 Switch Series | ** |
| HPE 1820 Switch Series | ** |
| HPE 1850 Switch Series | ** |
| HPE 1910 Switch Series | ** |
| HPE 1920 Switch Series | ** |
| HPE 1950 Switch Series | 2220P02 (Comware 7) |
| HPE 3100 Switch Series | 2220P02 (Comware 7) |
| HPE 3600 Switch Series | 2220P02 (Comware 7) |
| HPE 5120 Switch Series | 2220P02 (Comware 5) |
| HPE 5130 Switch Series | 2220P02 (Comware 7) |
| HPE 5500 Switch Series | 2220P02 (Comware 5) |
| HPE 5510 HI Switch Series | ** |
| HPE 5700 Switch Series | ** |
| HPE 5710 Switch Series | 7.1.070 (Release 2612P08) |
| HPE 5800 Switch Series | ** |
| HPE 5820 Switch Series | 1810P13 (Comware 7) |
| HPE 5900 Switch Series | 2220P02 (Comware 7) |
| HPE 5945 Switch Series | 7.1.070 (Release 6555P01) |
| HPE 7500 Switch Series | 2220P02 (Comware 7) |
| HPE 7900 Switch Series | ** |
| HPE 10500 Switch Series | 2220P02 (Comware 7) |
| HPE 12900E Switch Series | ** |
| * Not supported in VisualRF. ** Limited testing done. Contact Technical Support for help with any issues. | |

High Availability Support

OV3600 8.2 introduces support for pairs of HP Unified Wired-WLAN (UWW) devices operating in HA mode. OV3600 monitors the status of each controller. After OV3600 detects that a failover occurred and the APs failed over to the backup controller, OV3600 displays the current status of the APs.

Monitoring Support

OV3600 provides monitoring through SNMP polling with the OIDs listed in the following table.

Table 10: Monitoring Support

| Model | SNMP Object ID | SysOID |
|---------------------|---------------------------|-----------------------------|
| HPE 7502 Switch | 1.3.6.1.4.1.25506.11.1.1 | .1.3.6.1.4.1.25506.11.1.269 |
| HPE 7503S Switch | 1.3.6.1.4.1.25506.11.1.2 | .1.3.6.1.4.1.25506.11.1.268 |
| HPE 7503 Switch | 1.3.6.1.4.1.25506.11.1.3 | .1.3.6.1.4.1.25506.11.1.270 |
| HPE 7506 Switch | 1.3.6.1.4.1.25506.11.1.4 | .1.3.6.1.4.1.25506.11.1.267 |
| HPE 7506-V Switch | 1.3.6.1.4.1.25506.11.1.5 | .1.3.6.1.4.1.25506.11.1.264 |
| HPE 7510 Switch | 1.3.6.1.4.1.25506.11.1.6 | .1.3.6.1.4.1.25506.11.1.271 |
| HPE 9505 Switch | 1.3.6.1.4.1.25506.11.1.39 | .1.3.6.1.4.1.25506.11.1.266 |
| HPE 9508-V Switch | 1.3.6.1.4.1.25506.11.1.40 | .1.3.6.1.4.1.25506.11.1.265 |
| HPE 9508 Switch | 1.3.6.1.4.1.25506.11.1.41 | .1.3.6.1.4.1.25506.11.1.272 |
| HPE 9512 Switch | 1.3.6.1.4.1.25506.11.1.43 | .1.3.6.1.4.1.25506.11.1.144 |
| HPE 10504 Switch | 1.3.6.1.4.1.25506.11.1.86 | .1.3.6.1.4.1.25506.11.1.229 |
| HPE 10508 Switch | 1.3.6.1.4.1.25506.11.1.87 | .1.3.6.1.4.1.25506.11.1.230 |
| HPE 10508-V Switch | 1.3.6.1.4.1.25506.11.1.88 | .1.3.6.1.4.1.25506.11.1.145 |
| HPE 10512 Switch | 1.3.6.1.4.1.25506.11.1.89 | .1.3.6.1.4.1.25506.11.1.231 |
| HPE Switches | *.25506.11.1 * | .1.3.6.1.4.1.25506.11.1.232 |
| HPE Routers | *.25506.11.2 * | NA |
| HPE Wireless | *.25506.11.3* | NA |
| HPE Security | *.25506.11.4 * | NA |
| HPE (3Com) S7503E-M | 1.3.6.1.4.1.25506.1.1504 | NA |
| HPE (3Com) S7502 | 1.3.6.1.4.1.25506.1.52 | NA |
| HPE (3Com) S7502E | 1.3.6.1.4.1.25506.1.207 | NA |
| HPE (3Com) S7502ESX | 1.3.6.1.4.1.25506.1.1309 | NA |
| HPE (3Com) S7503 | 1.3.6.1.4.1.25506.1.53 | NA |
| HPE (3Com) S7503E | 1.3.6.1.4.1.25506.1.208 | NA |
| HPE (3Com) S7503E-S | 1.3.6.1.4.1.25506.1.370 | NA |
| HPE (3Com) S7503X | 1.3.6.1.4.1.25506.1.1560 | NA |

| Model | SNMP Object ID | SysOID |
|---------------------|--------------------------|--------|
| HPE (3Com) S7503X-G | 1.3.6.1.4.1.25506.1.1836 | NA |
| HPE (3Com) S7504EXS | 1.3.6.1.4.1.25506.1.1308 | NA |
| HPE (3Com) S7506 | 1.3.6.1.4.1.25506.1.54 | NA |
| HPE (3Com) S7506E | 1.3.6.1.4.1.25506.1.209 | NA |
| HPE (3Com) S7506E-S | 1.3.6.1.4.1.25506.1.469 | NA |
| HPE (3Com) S7506E-V | 1.3.6.1.4.1.25506.1.210 | NA |
| HPE (3Com) S7506E-X | 1.3.6.1.4.1.25506.1.1306 | NA |
| HPE (3Com) S7506X-G | 1.3.6.1.4.1.25506.1.1837 | NA |
| HPE (3Com) S7506X-R | 1.3.6.1.4.1.25506.1.55 | NA |
| HPE (3Com) S7508E-X | 1.3.6.1.4.1.25506.1.636 | NA |
| HPE (3Com) S7510E | 1.3.6.1.4.1.25506.1.159 | NA |
| HPE (3Com) S7510E-X | 1.3.6.1.4.1.25506.1.1307 | NA |
| HPE (3Com) S7510X | 1.3.6.1.4.1.25506.1.1562 | NA |

HPE ProCurve

HPE ProCurve switches have the following additional support through OV3600:

- Automated discovery through SNMP
- Model & software version identification

Juniper® Devices

The following Juniper controllers and APs are supported for monitoring, configuration, and software upgrades.



The firmware versions listed in the table below represents the latest firmware version verified as fully supported by OV3600 8.2.14.1. Informal testing shows that OV3600 supports devices running more recent versions of firmware, but full support for these later versions is not guaranteed.

Table 11: Supported Juniper Access Points and Wireless LAN Controllers

| Model | Validated up to |
|-------------------------|-----------------|
| WLA321 Access Points | 9.1.0.6.0 |
| WLA322 Access Points | 9.1.0.6.0 |
| WLA522 Access Points | 9.1.0.6.0 |

| Model | Validated up to |
|---|-----------------|
| WLA532 Access Points | 9.1.0.6.0 |
| WLA632 Access Points | 9.1.0.6.0 |
| WLC100 Wireless LAN Controllers | 9.1.0.6.0 |
| WLC2 Wireless LAN Controllers | 9.1.0.6.0 |
| WLC2800 Wireless LAN Controllers | 9.1.0.6.0 |
| WLC8 Wireless LAN Controllers | 9.1.0.6.0 |
| WLC800 Wireless LAN Controllers | 9.1.0.6.0 |
| WLC880 Wireless LAN Controllers | 9.1.0.6.0 |
| WLC JunosV Wireless LAN Controllers | 9.1.0.6.0 |
| Juniper Switch | 12.3R6.6 |

Juniper®

Juniper switches have the following additional support through OV3600:

- Automated discovery through SNMP
- Model & software version identification
- Rogue AP detection is supported using the Q-BRIDGE MIB

Meru® Devices

The following Meru controllers and APs are now supported in VisualRF.



The firmware versions listed in the table below represents the latest firmware version verified as fully supported by OV3600 8.2.14.1. Informal testing shows that OV3600 supports devices running more recent versions of firmware, but full support for these later versions is not guaranteed.

Table 12: Meru Device Support

| Model | Validated up to |
|---|-----------------|
| AP302 | 6.1.1-25 |
| AP320i | 6.1.1-25 |
| AP332i | 6.1.1-25 |
| AP433i | 6.1.1-25 |
| AP433is | 6.1.1-25 |
| AP822e | 6.1.1-25 |
| AP822i | 6.1.1-25 |
| AP832e | 6.1.1-25 |
| AP832i | 6.1.1-25 |
| RS4000 | 6.1.1-25 |
| MC1000* | 3.6.1-49 |
| MC1550 | 6.1.1-25 |
| MC3000* | 3.6.1-49 |
| MC3200 | 6.1.1-25 |
| MC4200 | 6.1.1-25 |
| MC5000* | 3.6.1-49 |
| FWC-200D | 3.6.1-49 |
| FWC-500D | 3.6.1-49 |
| * This version of OV3600 supports monitoring for these devices. | |



VisualRF support for the for the AP433i, AP433e, AP433is, AP822i, and AP822e is not included in this release of OV3600.

Motorola® Devices

The following Motorola (formerly Symbol) controllers and autonomous APs are supported for monitoring, configuration, and software upgrades.



The firmware versions listed in the table below represents the latest firmware version verified as fully supported by OV3600 8.2.14.1. Informal testing shows that OV3600 supports devices running more recent versions of firmware, but full support for these later versions is not guaranteed.

Table 13: Motorola Autonomous AP, Wireless LAN Controller, and AP Support

| Model | Validated up to |
|--|-----------------|
| AP621 | 5.4.2.0-030R |
| AP622 | 5.4.2.0-030R |
| AP650 | 5.4.2.0-030R |
| AP5131 | 5.4.2.0-030R |
| AP5181 | 5.4.2.0-030R |
| AP6521* | 5.4.2.0-030R |
| AP6522* | 5.4.2.0-030R |
| AP6532* | 5.7.0.0-057R |
| AP7131 | 5.4.2.0-030R |
| AP7161 | 5.4.2.0-030R |
| AP7532 | 5.8.1.0-012R |
| NX9600 | 5.8.6.0-011R |
| RFS4000 | 5.4.2.0-030R |
| RFS6000 | 5.4.2.0-030R |
| RFS7000 | 5.4.2.0-030R |
| WS2000 | 2.4.5 |
| WS5100 | 3.3.4 |
| Wing5 RFS controllers | 5.4.2.0-030R |
| * These AP and controller models may require adjustments to the OV3600 SNMP timeouts to compensate for known SNMP issues on these devices. | |

Other Third-Party Devices with Monitoring Support

This version of OV3600 supports monitoring for a variety of devices with software versions listed in the table below.



The firmware versions listed in the table below represents the latest firmware version verified as fully supported by OV3600 8.2.14.1. Informal testing shows that OV3600 supports devices running more recent versions of firmware, but full support for these later versions is not guaranteed.

Table 14: Other Supported Devices

| Device | Validated up to |
|---|------------------------------|
| Arista DCS-7504N and DCS-7280SRAM-48C6 switches | 4.21.7M |
| BelAir 200 | main.2005.03.29 |
| Brocade ICX switches | 08.0.20T211 and 08.0.30aT213 |
| Ericsson APM-210 Access Point Modules | 6.4.4.0-sp |
| Proxim AP-600/700 | 2.0 – 4.0.2 |
| Proxim AP 2000/4000 | 2.0 – 4.0.2 |
| Proxim Tsunami MP.11 QB 954-x, 2454-x, 4954-x, 5054-x | 2.3.0 – 4.0.0 |
| Siemens SCALANCE W1750D | 6.5.0.0 - 4.3.0 |
| Siemens SCALANCE XC208G switches | 4.1 |
| Siemens SCALANCE XR500 switches | 6.1.3 |
| Siemens SCALANCE XR300 switches | 3.2.1 |
| Symbol 3021 | 04.01-23 – 04.02-19 |
| Symbol 4121 and 4131 | 3.51-20 – 3.95-04 |
| Symbol 5131/5181 | 1.1.0.0.045R – 2.5.0.0 |
| Trapeze MXR-2, MXR-8, MXR-20, MXR-2xx, MX-400, MP-3x2, and MP-422 | 5.0.12.2 – 7.0.5.6 |
| Tropos 3/4/5210/5320/9422/9532 | 5.1.4.7 – 6.6.1.3 |

Other Switches

Some switches have additional support in OV3600:

Alcatel-Lucent OmniSwitch™(6250 and 6450)

- Automated discovery through SNMP
- Model & software version identification
- Stack information
- Firmware version 6.6.1.859.R01

Brocade

- Automated discovery through SNMP
- Model & software version identification
- Firmware version 08.0.20T211 and 08.0.30aT213
- Stacking

Force10

- Model & software version identification
- Firmware version 8.4.2.9

Siemens Ruggedcom

- Zero Packet Loss Technology
- Robust and Reliable
- Model & software version identification

OV3600 8.2.12.1 supports the following Siemens Ruggedcom models:

Layer 2 Rack Switches

- RSG2100
- RSG2100P
- RST2228
- RST2228P

Layer 2 Compact Switches

- RS900GP
- RSG920P
- RSG908C
- RSG910C
- RSG907R
- RSG909R
- RST916P
- RST916C

Layer 3 Multi-service Platform

RX 1500/1501/1510/1511/1512/1524/1536

RX 5000

Layer 3 Edge Router

RX1400

Firmware Version Boot

- v4.3.0
- ROS v5.4.2

- ROX v2.13.3



Only limited testing has been performed on Seimens Ruggedcom devices.

Contacting Support

| Contact Center Online | |
|--|--|
| Main Site | https://www.al-enterprise.com/ |
| Support Site | https://businessportal2.alcatel-lucent.com |
| Email | ebg_global_supportcenter@al-enterprise.com |
| Service & Support Contact Center Telephone | |
| North America | 1-800-995-2696 |
| Latin America | 1-877-919-9526 |
| EMEA | +800 00200100 (Toll Free) or +1 (650) 385-2193 |
| Asia Pacific | +65 6240 8484 |
| Worldwide | 1-818-878-4507 |