

AOS-W 8.6.0.15 Release Notes



Copyright Information

Alcatel-Lucent and the Alcatel-Lucent Enterprise logo are trademarks of Alcatel-Lucent. To view other trademarks used by affiliated companies of ALE Holding, visit:

<https://www.al-enterprise.com/en/legal/trademarks-copyright>

All other trademarks are the property of their respective owners. The information presented is subject to change without notice. Neither ALE Holding nor any of its affiliates assumes any responsibility for inaccuracies contained herein. (2021)

Open Source Code

This product includes code licensed under the GNU General Public License, the GNU Lesser General Public License, and/or certain other open source licenses.

Contents	3
Revision History	4
Release Overview	5
Related Documents	5
Supported Browsers	5
Terminology Change	5
Contacting Support	6
New Features and Enhancements in AOS-W 8.6.0.15	7
Supported Platforms in AOS-W 8.6.0.15	8
Mobility Master Platforms	8
OmniAccess Mobility Controller Platforms	8
AP Platforms	8
Regulatory Updates in AOS-W 8.6.0.15	11
Resolved Issues in AOS-W 8.6.0.15	12
Known Issues in AOS-W 8.6.0.15	17
Limitation	17
Known Issues	17
Upgrade Procedure	31
Important Points to Remember	31
Memory Requirements	31
Backing up Critical Data	32
Upgrading AOS-W	33
Verifying the AOS-W Upgrade	35
Downgrading AOS-W	36
Before Calling Technical Support	38

The following table provides the revision history of this document.

Table 1: *Revision History*

Revision	Change Description
Revision 01	Initial release.

This AOS-W release notes includes the following topics:

- New Features and Enhancements
- Supported Platforms
- Regulatory Updates
- Resolved Issues
- Known Issues and Limitations
- Upgrade Procedure

For a list of terms, refer [Glossary](#).

Related Documents

The following guides are part of the complete documentation for the Alcatel-Lucent user-centric network:

- *AOS-W Getting Started Guide*
- *AOS-W User Guide*
- *AOS-W CLI Reference Guide*
- *AOS-W API Guide*
- *Alcatel-Lucent Mobility Conductor Licensing Guide*
- *Alcatel-Lucent Virtual Appliance Installation Guide*
- *Alcatel-Lucent AP Software Quick Start Guide*

Supported Browsers

The following browsers are officially supported for use with the AOS-W WebUI:

- Microsoft Internet Explorer 11 on Windows 7 and Windows 8
- Microsoft Edge (Microsoft Edge 38.14393.0.0 and Microsoft EdgeHTML 14.14393) on Windows 10
- Mozilla Firefox 48 or later on Windows 7, Windows 8, Windows 10, and macOS
- Apple Safari 9.0 or later on macOS
- Google Chrome 67 on Windows 7, Windows 8, Windows 10, and macOS

Terminology Change

As part of advancing Alcatel-Lucent Enterprise's commitment to racial justice, we are taking a much-needed step in overhauling ALE engineering terminology to reflect our belief system of diversity and inclusion. Some legacy products and publications may continue to include terminology that seemingly evokes bias against specific groups of people. Such content is not representative of our ALE culture and moving forward, ALE will replace racially insensitive terms and instead use the following new language:

Usage	Old Language	New Language
Campus Access Points + Controllers	Master-Slave	Conductor-Member
Instant Access Points	Master-Slave	Conductor-Member
Switch Stack	Master-Slave	Conductor-Member
Wireless LAN Controller	Mobility Master	Mobility Conductor
Firewall Configuration	Blacklist, Whitelist	Denylist, Allowlist
Types of Hackers	Black Hat, White Hat	Unethical, Ethical

Contacting Support

Table 2: *Contact Information*

Contact Center Online	
Main Site	https://www.al-enterprise.com
Support Site	https://businessportal.al-enterprise.com
Email	ebg_global_supportcenter@al-enterprise.com
Service & Support Contact Center Telephone	
North America	1-800-995-2696
Latin America	1-877-919-9526
EMEA	+800 00200100 (Toll Free) or +1(650)385-2193
Asia Pacific	+65 6240 8484
Worldwide	1-818-878-4507

Chapter 3

New Features and Enhancements in AOS-W 8.6.0.15

There are no new features or enhancements introduced in this release.

This chapter describes the platforms supported in this release.

Mobility Master Platforms

The following table displays the Mobility Master platforms that are supported in this release:

Table 3: Supported Mobility Master Platforms in AOS-W 8.6.0.15

Mobility Master Family	Mobility Master Model
Hardware Mobility Master	MM-HW-1K, MM-HW-5K, MM-HW-10K
Virtual Mobility Master	MM-VA-50, MM-VA-500, MM-VA-1K, MM-VA-5K, MM-VA-10K

OmniAccess Mobility Controller Platforms

The following table displays the OmniAccess Mobility Controller platforms that are supported in this release:

Table 4: Supported OmniAccess Mobility Controller Platforms in AOS-W 8.6.0.15

OmniAccess Mobility Controller Family	OmniAccess Mobility Controller Model
OAW-40xx Series Hardware OmniAccess Mobility Controllers	OAW-4005, OAW-4008, OAW-4010, OAW-4024, OAW-4030
OAW-4x50 Series Hardware OmniAccess Mobility Controllers	OAW-4450, OAW-4550, OAW-4650, OAW-4750, OAW-4750XM, OAW-4850
OAW-41xx Series Hardware OmniAccess Mobility Controllers	OAW-4104
MC-VA-xxx Virtual OmniAccess Mobility Controllers	MC-VA-50, MC-VA-250, MC-VA-1K

AP Platforms

The following table displays the AP platforms that are supported in this release:

Table 5: Supported AP Platforms in AOS-W 8.6.0.15

AP Family	AP Model
OAW-AP100 Series	OAW-AP104, OAW-AP105

Table 5: Supported AP Platforms in AOS-W 8.6.0.15

AP Family	AP Model
OAW-AP103 Series	OAW-AP103
OAW-AP110 Series	OAW-AP114, OAW-AP115
OAW-AP130 Series	OAW-AP134, OAW-AP135
OAW-AP 170 Series	OAW-AP175AC, OAW-AP175AC-F1, OAW-AP175DC, OAW-AP175DC-F1, OAW-AP175P, OAW-AP175P-F1
OAW-AP200 Series	OAW-AP204, OAW-AP205
OAW-AP203H Series	OAW-AP203H
OAW-AP205H Series	OAW-AP205H
OAW-AP207 Series	OAW-AP207
OAW-AP203R Series	OAW-AP203R, OAW-AP203RP
OAW-AP210 Series	OAW-AP214, OAW-AP215
OAW-AP 220 Series	OAW-AP224, OAW-AP225
OAW-AP228 Series	OAW-AP228
OAW-AP270 Series	OAW-AP274, OAW-AP275, OAW-AP277
OAW-AP300 Series	OAW-AP304, OAW-AP305
OAW-AP303 Series	OAW-AP303, OAW-AP303P
OAW-AP303H Series	OAW-AP303H
OAW-AP310 Series	OAW-AP314, OAW-AP315
OAW-AP318 Series	OAW-AP210AP-318
OAW-AP320 Series	OAW-APAP-324, OAW-AP325
OAW-AP330 Series	OAW-AP334, OAW-AP335
OAW-AP340 Series	OAW-AP344, OAW-AP345
OAW-AP360 Series	OAW-AP365, OAW-AP367
OAW-AP370 Series	OAW-AP374, OAW-AP375, OAW-AP377
OAW-AP387	OAW-AP387
500 Series	OAW-AP504, OAW-AP505

Table 5: Supported AP Platforms in AOS-W 8.6.0.15

AP Family	AP Model
510 Series	OAW-AP514, OAW-AP515
530 Series	OAW-AP534, OAW-AP535
550 Series	OAW-AP555
OAW-RAP3 Series	OAW-RAP3WN, OAW-RAP3WNP
OAW-RAP100 Series	OAW-RAP108, OAW-RAP109
OAW-RAP155 Series	OAW-RAP155, OAW-RAP155P

This chapter contains the Downloadable Regulatory Table (DRT) file version introduced in this release.

Periodic regulatory changes may require modifications to the list of channels supported by an AP. For a complete list of channels supported by an AP using a specific country domain, access the switch Command Line Interface (CLI) and execute the **show ap allowed-channels country-code <country-code> ap-type <ap-model>** command.

For a complete list of countries and the regulatory domains in which the APs are certified for operation, refer to the Downloadable Regulatory Table or the DRT Release Notes at businessportal2.alcatel-lucent.com.

The following DRT file version is part of this release:

- DRT-1.0_81806

This chapter describes the issues resolved in this release.

Table 6: Resolved Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-141541 AOS-146008	172320 178130	VRRP flaps were observed between the Mobility Master and managed devices. The fix ensures that there is no unnecessary VRRP flapping. This issue was observed in Mobility Masters running AOS-W 8.0.0.0 or later versions.	AOS-W 8.0.0.0
AOS-198988	—	Mobility Masters running AOS-W 8.5.0.0 or later versions generated multiple DHCP option 82 warning messages even when the DHCP option 82 configuration was disabled. The fix ensures that the Mobility Masters work as expected.	AOS-W 8.3.0.0
AOS-209315	—	The IDS unauthorized device profile incorrectly sent deauthentication frames to APs. This issue occurred when protect-misconfigured-ap parameter was enabled in the ids unauthorized-device-profile . The fix ensures that the APs work as expected. This issue was observed in APs running AOS-W 8.6.0.9 or later versions	AOS-W 8.6.0.9
AOS-210688 AOS-227065	—	Apple devices were unable to connect to AP-225 access points in mesh deployments. This issue occurred when the AP advertised a Channel Switch Announcement but remained in the same channel. The fix ensures that Apple devices are able to connect to the AP-225 access points. This issue was observed in AP-225 access points running AOS-W 8.6.0.5 or later versions.	AOS-W 8.6.0.5
AOS-212552 AOS-221507	—	Some OAW-AP515 access points running AOS-W 8.6.0.6 or later versions crashed unexpectedly. The log files listed the reason for the event as BadAddr:fffffc12c30ca80 PC:_alloc_skb+0x110/0x1c8 Warm-reset . The fix ensures that the APs work as expected.	AOS-W 8.6.0.6
AOS-215303	—	Users were unable to view file names in the Diagnostic > Technical Support > Copy Files page of the WebUI. This issue occurred when Flash file system was selected as the source file. The fix ensures that the users are able to view the file names. This issue was observed in managed devices running AOS-W 8.5.0.11 or later versions.	AOS-W 8.5.0.11

Table 6: Resolved Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-215712	—	Mobility Masters running AOS-W 8.6.0.13 forwarded all syslog messages with severity level marked as debug. This issue occurred when CEF format was enabled on the Mobility Master. The fix ensures that the Mobility Masters do not forward all syslog messages with severity level marked as debug.	AOS-W 8.7.0.0
AOS-216536 AOS-220630	—	Some managed devices running AOS-W 8.5.0.11 or later versions were unable to come up on the Mobility Master. This issue occurred when the managed devices received the branch IP address as the switch IP address in a VPNC deployment. The fix ensures that the managed devices are able to come up on the Mobility Master.	AOS-W 8.5.0.11
AOS-217628 AOS-221178	—	Some managed devices running AOS-W 8.5.0.11 or later versions crashed and rebooted unexpectedly. The log file lists the reason for the event as, Reboot Cause: Kernel Panic (Intent:cause:register 12:86:f0:2) fib6_clean_node . The fix ensures that the managed devices work as expected	AOS-W 8.5.0.11
AOS-217689	—	Some managed devices running AOS-W 8.6.0.9 or later versions did not generate the AP reboot logs during an AP reboot. The fix ensures that the managed devices generate the AP reboot logs during an AP reboot.	AOS-W 8.6.0.9
AOS-218621	—	Some APs running AOS-W 8.6.0.7 or later versions crashed unexpectedly. The log files listed the reason for the event as AP Reboot reason: BadAddr:6c0094119461 PC:wlc_ampdu_rcv_addba_resp+0x240/0x838 [wl_v6] Warm-reset . The fix ensures that the APs work as expected.	AOS-W 8.7.1.1
AOS-218642	—	A few iPads and other clients were unable to access the Internet. This issue occurred when the client entries were not removed by the managed devices even when CoA disconnect was triggered for the clients. The fix ensures seamless connectivity. This issue was observed in managed devices running AOS-W 8.5.0.11 or later versions.	AOS-W 8.5.0.11
AOS-219112	—	A few UBT clients hopped between VLANs. The fix ensures that the UBT clients do not between VLANs. This issue was observed in managed devices running AOS-W 8.7.1.1 or later versions.	AOS-W 8.7.1.1
AOS-219383	—	The Configuration > License > License Usage tab did not display the license details. The fix ensures that the WebUI displays the license details. This issue was observed in stand-alone controllers running AOS-W 8.5.0.12 or later versions.	AOS-W 8.5.0.12

Table 6: Resolved Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-219725	—	Some APs running AOS-W 8.6.0.7 or later versions crashed unexpectedly. The log files listed the reason for the event as PC is at wlc_nar_detach+0x8c . The fix ensures that the APs work as expected.	AOS-W 8.7.1.1
AOS-219879	—	The show iap subnet command did not display the Allocated BID Branch List . The fix ensures that the command displays the Allocated BID Branch List . This issue was observed in Mobility Masters running AOS-W 8.3.0.0 or later versions.	AOS-W 8.3.0.0
AOS-220053	—	Some OAW-RAPs went down on managed devices running AOS-W 8.6.0.5 or later versions. This issue occurred after a failover. The fix ensures that the OAW-RAPs work as expected.	AOS-W 8.6.0.5
AOS-220251	—	Some users experienced connectivity issue. This issue occurred when APs did not respond to the authentication frames in MultiZone networks that had non-cluster zones and 802.11r enabled Virtual APs. The fix ensures seamless connectivity. This issue was observed in stand-alone switches running AOS-W 8.5.0.4 or later versions.	AOS-W 8.5.0.4
AOS-220293	—	Some APs running AOS-W 8.6.0.10 or later versions crashed unexpectedly. The log files listed the reason for the event as aruba_wlc_ratesel_getmaxrate+0x34 . The fix ensures that the APs work as expected.	AOS-W 8.6.0.10
AOS-220552	—	The Configuration > Services > Clusters page of the WebUI did not display the status of the live upgrade. This issue occurred when the cluster profile name had blank spaces. The fix ensures that the WebUI displays the status for all live upgrades. This issue was observed in Mobility Masters running AOS-W 8.6.0.9 or later versions.	AOS-W 8.6.0.9
AOS-220595	—	Some VIA users experienced connectivity issues and an error message, Invalid auth algo 0 was displayed. This issue occurred when default-gcm128 or default-gcm256 was configured as transform-set value. The fix ensures seamless connectivity. This issue was observed in Mobility Masters running AOS-W 8.6.0.9 or later versions.	AOS-W 8.6.0.9
AOS-221064	—	Some OAW-AP515 access points running AOS-W 8.6.0.0 or later versions crashed unexpectedly. The log files listed the reason for the event as, AP Reboot reason: InternalError: : 96000210 1 SMP PC:phy_utils_write_phyreg_nopi+0x70/0x130 [w1_v6] Warm-reset . The fix ensures that the APs work as expected.	AOS-W 8.7.1.3

Table 6: Resolved Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-221222	—	Some APs came up with IDe flag and the show ap database command displayed the e flag even when EST was not configured. This issue occurred when external whitelist authentication was configured on the managed devices and CPsec enabled APs were brought up on the managed devices. The fix ensures that the APs work as expected. This issue was observed in managed devices running AOS-W 8.8.0.0.	AOS-W 8.8.0.0
AOS-221352	—	Some mesh links reported incorrect RSSI values. The fix ensures that the mesh links report correct RSSI values. This issue was observed in APs running AOS-W 8.7.0.0 or later versions.	AOS-W 8.7.0.0
AOS-222051	—	The IAPMGR process crashed on managed devices running AOS-W 8.6.0.4 or later versions. The fix ensures that the managed devices work as expected.	AOS-W 8.6.0.4
AOS-222267 AOS-212114 AOS-217474 AOS-219497 AOS-225306	—	A few managed devices went down intermittently. This issue occurred when the traffic between Mobility Master and managed devices was transmitted without IPsec encryption. The fix ensures that the traffic between the Mobility Master and managed devices is encrypted. This issue was observed in managed devices running AOS-W 8.6.0.8 or later versions.	AOS-W 8.6.0.8
AOS-222540 AOS-224221	—	Some APs dropped EAPOL packets from the bridge-mode wired port. The fix ensures that the APs do not drop the EAPOL packets. This issue was observed in APs running AOS-W 8.6.0.9 or later versions.	AOS-W 8.6.0.9
AOS-222754	—	The SNMP walk to managed devices failed when the SNMP requests had the IPv6 address of the switch. This issue occurred when the primary managed device had a VRRP IPv6 address configured. The fix ensures that the SNMP walk to managed devices does not fail. This issue was observed in managed devices running AOS-W 8.4.0.1 or later versions.	AOS-W 8.4.0.1
AOS-222787 AOS-225503	—	Some OAW-AP535 access points running AOS-W 8.6.0.9 or later versions rebooted unexpectedly. The log file listed the reason for the event as, kernel panic: Fatal exception . The fix ensures that the APs work as expected.	AOS-W 8.6.0.9
AOS-222895 AOS-227006	—	The STM process was stuck on a few managed devices running AOS-W 8.6.0.9 or later versions. The fix ensures that the managed devices work as expected.	AOS-W 8.6.0.9
AOS-223577	—	The user table entries displayed only the IPv6 link local address. The fix ensures that the user table displays the correct entries. This issue was observed in stand-alone switches running AOS-W 8.2.0.0 or later versions.	AOS-W 8.6.0.5

Table 6: Resolved Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-223724 AOS-222270	—	Some OAW-RAPs running AOS-W 8.3.0.0 or later versions were unable to perform 802.1X authentication. The fix ensures that the OAW-RAPs are able to perform 802.1X authentication.	AOS-W 8.3.0.0
AOS-224090 AOS-225043	—	Some managed devices running AOS-W 8.6.0.10 or later versions were stuck in the Last Snapshot state. This issue occurred when tunnel MTU was set to a value lesser than 1500. The fix ensures that the managed devices work as expected.	AOS-W 8.6.0.10
AOS-224110 AOS-224287	—	A few APs running AOS-W 8.6.0.9 or later versions were stuck in the BLE upgrade loop after an upgrade. The fix ensures that the APs work as expected.	AOS-W 8.6.0.9

This chapter describes the known issues and limitations observed in this release.

Limitation

Following are the limitations observed in this release:

Port-Channel Limitation in OAW-4850 switches

On OAW-4850 switches with all the member ports of each port-channel configured from the same NAE (Network Acceleration Engine), if one of the member ports experiences link flap either due to a network event or a user driven action, the rest of the port-channels also observe the link flap for less than a second.

No Support for Unique Local Address over IPv6 Network

The IPv6 addresses for interface tunnels do not accept unique local addresses.

Known Issues

Following are the known issues observed in this release.

Table 7: *Known Issues in AOS-W 8.6.0.15*

New Bug ID	Old Bug ID	Description	Reported Version
AOS-151022 AOS-188417	185176	The output of the show datapath uplink command displays incorrect session count. This issue is observed in managed devices running AOS-W 8.1.0.0 or later versions.	AOS-W 8.1.0.0
AOS-151355	185602	A few managed devices are unable to pass traffic to the nexthop VPN concentrator (VPNC) using policy-based routing. This issue is observed in managed devices running AOS-W 8.0.1.0 or later versions.	AOS-W 8.0.1.0
AOS-153742 AOS-194948	188871	A stand-alone switch crashes and reboots unexpectedly. The log files list the reason for the event as Hardware Watchdog Reset (Intent:cause:register 51:86:0:8) . This issue is observed in OAW-4010 switches running AOS-W 8.5.0.1 or later versions in a Mobility Master-Managed Device topology.	AOS-W 8.5.0.1
AOS-155404 AOS-207878	191106	An AP is unable to establish IKE/IPsec tunnel with the managed device. This issue occurs when the AP is enrolled with EST certificates. This issue is observed in OAW-AP515 access points running AOS-W 8.5.0.0 or later versions in a Mobility Master-Managed Device topology.	AOS-W 8.6.0.4

Table 7: Known Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-156068	192100	The DDS process in a managed device running AOS-W 8.2.1.1 or later versions crashes unexpectedly.	AOS-W 8.2.1.1
AOS-157472 AOS-209050	—	The MAC address of the AP is not present in the called-station-ID of RADIUS accounting messages. This issue is observed in APs running AOS-W 8.5.0.8 or later versions.	AOS-W 8.5.0.8
AOS-182847	—	A few users are unable to copy the WPA Passphrase field and High-throughput profile to a new SSID profile in the Configuration > System > Profiles > Wireless LAN > SSID > <SSID_Profile> option of the WebUI. This issue occurs when a new SSID profile is created from an existing SSID profile using WebUI. This issue is observed in managed devices running AOS-W 8.4.0.0 or later versions in a Mobility Master-Managed Device topology.	AOS-W 8.4.0.0
AOS-183706	—	The TX radio power of a few APs are lesser than the TX radio power of other APs in the same network. This issue is observed in APs running AOS-W 8.3.0.6 or later versions.	AOS-W 8.3.0.6
AOS-184947 AOS-192737	—	The jitter and health score data are missing from the Dashboard > Infrastructure > Uplink > Health page in the WebUI. This issue is observed in Mobility Masters running AOS-W 8.4.0.4 or later versions.	AOS-W 8.4.0.4
AOS-185538 AOS-195334	—	High number of EAP-TLS timeouts are observed in a managed device. This issue occurs when multiple IP addresses are assigned to each client. This issue is observed in managed devices running AOS-W 8.3.0.8 or later versions.	AOS-W 8.3.0.8
AOS-188972 AOS-194746 AOS-208631 AOS-213627	—	Mobility Master displays the blacklisted clients although the clients were removed from the managed device. This issue is observed in Mobility Masters running AOS-W 8.4.0.4 or later versions in a cluster setup.	AOS-W 8.4.0.4
AOS-190071 AOS-190372	—	A few users are unable to access websites when WebCC is enabled on the user role. This issue occurs in a Per-User Tunnel Node (PUTN) setup when the VLAN of user role is in trunk mode. This issue is observed in OAW-4005 switches running AOS-W 8.4.0.0. Workaround: Perform the following steps to resolve the issue: 1. Remove web category from the ACL rules and apply any any any permit policy. 2. Disable WebCC on the user role. 3. Change the VLAN of user role from trunk mode to access mode.	AOS-W 8.4.0.0

Table 7: Known Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-190621	—	WebUI does not filter the names of the APs that begin with the special characters, + and %. This issue is observed in managed devices running AOS-W 8.4.0.2 or later versions.	AOS-W 8.4.0.2
AOS-192725	—	The Dashboard > Overview page of the WebUI displays incorrect number of users intermittently. This issue is observed in Mobility Masters running AOS-W 8.3.0.8 or later versions. Duplicates: AOS-188255, AOS-190476, AOS-190946, AOS-193586, AOS-194784, AOS-196004, AOS-200375, and AOS-210787	AOS-W 8.3.0.8
AOS-193184	—	All L2 connected managed devices move to L3 connected state after an upgrade. This issue is observed in managed devices running AOS-W 8.5.0.2 or later versions.	AOS-W 8.5.0.2
AOS-193231 AOS-200101 AOS-207456	—	The Dashboard > Infrastructure > Access Devices page of the WebUI displays an error message, Error retrieving information . This issue is observed in Mobility Masters running AOS-W 8.5.0.3 or later versions.	AOS-W 8.5.0.3
AOS-193560	—	The number of APs that are DOWN are incorrectly displayed in the Dashboard > Overview page of the WebUI. However, the CLI displays the correct status of APs. This issue is observed in Mobility Masters running AOS-W 8.4.0.4 or later versions. Duplicates: AOS-198565, AOS-200262, AOS-204794, AOS-212249, AOS-208110, AOS-209989, and AOS-212249	AOS-W 8.4.0.4
AOS-193775 AOS-194581 AOS-197372	—	A mismatch of AP count and client count is observed between the Mobility Master and the managed device. This issue is observed in Mobility Masters running AOS-W 8.3.0.0 or later versions.	AOS-W 8.5.0.2
AOS-193883 AOS-197756	—	A few APs are unable to use DHCP IPv6 addresses and option 52 for master discovery. This issue occurs when APs did not clear the previous LMS entries after an upgrade. This issue is observed in access points running AOS-W 8.3.0.8 or later versions. Workaround: Delete the IPv4 addresses from ap system profile using the command, ap system-profile and from high availability profiles using the command, ha .	AOS-W 8.3.0.8
AOS-194080	—	Some managed devices display the error log, Deleting a user IP=fe80::1c4d:d31f:a935:2107 with flags=0x0 from the datapath that does not exist in auth even if IPv6 is disabled on the managed devices. This issue is observed in stand-alone switches running AOS-W 8.2.2.10 or later versions.	AOS-W 8.2.2.10

Table 7: Known Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-194381	—	Some managed devices lose the route-cache entries and drop the VRRP IP addresses sporadically. This issue is observed in managed devices running AOS-W 8.3.0.7 or later versions.	AOS-W 8.3.0.7
AOS-194911	—	Incorrect flag output is displayed for APs configured with 802.1X authentication when the show ap database command is executed. This issue is observed in APs running AOS-W 8.5.0.2 or later versions.	AOS-W 8.5.0.2
AOS-194964	—	A few users are unable to clone configurations from an existing group to a new group in a Mobility Master. This issue is observed in Mobility Masters running AOS-W 8.4.0.1 or later versions. Workaround: Execute the rf dot11a-radio-profile <profile name> command to change the operating mode of the AP from am-mode to ap-mode.	AOS-W 8.5.0.2
AOS-195089	—	The DNS traffic is incorrectly getting classified as Thunder and is getting blocked. This issue occurs when the DNS traffic is blocked and peer-peer ACL is denied for users. This issue is observed in managed devices running AOS-W 8.3.0.7 or later versions.	AOS-W 8.3.0.7
AOS-195100 AOS-198302 AOS-204455 AOS-206735	—	The health status of a managed device is incorrectly displayed as Poor in the Dashboard > Infrastructure page of the Mobility Master's WebUI. This issue is observed in Mobility Masters running AOS-W 8.3.0.7 or later versions.	AOS-W 8.3.0.7
AOS-195177	—	Some managed devices frequently generate internal system error logs. This issue occurs when the sapd process reads a non-existent interface. This issue is observed in OAW-4650 switches running AOS-W 8.3.0.7 or later versions.	AOS-W 8.3.0.7
AOS-195434	—	An AP crashes and reboots unexpectedly. The log files list the reason for the event as Reboot caused by kernel panic: Fatal exception . This issue is observed in APs running AOS-W 8.5.0.0 or later versions in a Mobility Master-Managed Device topology.	AOS-W 8.5.0.2
AOS-196042 AOS-217995 AOS-221263	—	The show ucc dns-ip-learning command displays Unknown for Service Provider . This issue is observed in managed devices running AOS-W 8.6.0.9 or later versions.	AOS-W 8.6.0.9
AOS-196457	—	High radio noise floor is observed on APs. This issue is observed in OAW-AP515 access points running AOS-W 8.5.0.2 or later versions.	AOS-W 8.5.0.2

Table 7: Known Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-196864	—	Although a new VLAN ID is successfully connected, the managed device displays that the VLAN ID fails with a different ID. This issue is observed when new VLANs are added and the total number of VLANs are 100/101, 200/201, 300/301 and so on. This issue is observed in managed devices running AOS-W 8.5.0.3 or later versions.	AOS-W 8.5.0.3
AOS-196878 AOS-197216	—	The Datapath process crashes on a managed device. The log file lists the reason for the event as wlan-n09-nc1.gw.illinois.edu . This issue is observed in managed devices running AOS-W 8.5.0.2 or later versions.	AOS-W 8.5.0.2
AOS-197023	—	Mobility Master sends incorrect AP regulatory-domain-profile channel changes to the managed device during the initial configuration propagation. This issue is observed in Mobility Masters running AOS-W 8.0.0.0 or later versions. Workaround: Perform one of the following steps to resolve the issue: <ul style="list-style-type: none"> ■ In the CLI, execute the ap regulatory-domain-profile command to create an AP regulatory-domain-profile without any channel configuration, save the changes, and later add or delete channels as desired. ■ In the WebUI, create an AP regulatory-domain-profile with default channel selected, save the changes, and later add or delete channels as desired in the Configuration > AP Groups page. 	AOS-W 8.5.0.4
AOS-197497	—	AirMatch selects the same channel for two neighboring APs even after radar detection. This issue is observed in managed devices running AOS-W 8.5.0.3 or later versions.	AOS-W 8.5.0.3
AOS-197812	—	A mismatch of user roles is observed in the WebUI and the CLI of the Mobility Master and managed device. This issue occurs when UDR is configured to assign user roles to clients. This issue is observed in Mobility Masters and managed devices running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.0
AOS-198024	—	Users are unable to access any page after the fifth page using the Maintenance > Access Point page in the WebUI. This issue is observed in stand-alone switches running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.0
AOS-198281	—	The details of the Up time in Managed network > Dashboard > Access Points > Access Points table does not get updated correctly. This issue is observed in Mobility Masters running AOS-W 8.2.2.6 or later versions.	AOS-W 8.2.2.6

Table 7: Known Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-198483	—	WebUI does not have an option to map the rf dot11-60GHz-radio-profile to an AP group. This issue is observed in Mobility Masters running AOS-W 8.5.0.4 or later versions.	AOS-W 8.5.0.4
AOS-198849 AOS-198850	—	Users are unable to configure 2.4 GHz radio profile in the Configuration > System > Profiles > 2.4 GHz radio profile page and the WebUI displays an error message, Feature is not enabled in the license . This issue is observed in stand-alone switches running AOS-W 8.5.0.3 or later versions.	AOS-W 8.5.0.3
AOS-198991	—	Users are unable to add a VLAN to an existing trunk port using the Configuration > Interfaces > VLANs page of the WebUI. This issue is observed in Mobility Masters running AOS-W 8.6.0.1 or later versions.	AOS-W 8.6.0.2
AOS-199492	—	Some APs do not get displayed in the show airgroup aps command output and the auto-associate policy does not work as expected. This issue occurs when the AirGroup domain is in distributed mode and is not validated in a cluster deployment. This issue is observed in managed devices running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.0
AOS-200515 AOS-219987	—	The DDS process crashes on managed devices running AOS-W 8.3.0.10 or later versions.	AOS-W 8.3.0.10
AOS-200733	—	Some APs running AOS-W 8.5.0.3 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as kernel page fault at virtual address 00005654, epc == c0bd7dd4, ra == c0bf95f8 .	AOS-W 8.5.0.3
AOS-200765	—	Some managed devices running AOS-W 8.3.0.7 or later versions in a cluster setup log the error message, <199804> <4844> authmgr cluster gsm_auth.c, auth_gsm_publish_ip_user_local_section:1011: auth_gsm_publish_ip_user_local_section: ip_user_local_flags .	AOS-W 8.3.0.7
AOS-201042	—	A large number of packet drops are observed in a few APs running AOS-W 8.3.0.6 or later versions. This issue occurs when the AP SAP MTU datapath tunnel is set to 1514.	AOS-W 8.3.0.6
AOS-201376	—	The measured power, Meas. Pow column in the show ap debug ble-table command does not get updated when the TX power of an AP is changed. This issue is observed in APs running AOS-W 8.5.0.6 or later versions.	AOS-W 8.5.0.6
AOS-201428	—	The show log all command does not display output in a chronological order. This issue is observed in Mobility Masters running AOS-W 8.3.0.0 or later versions.	AOS-W 8.3.0.0

Table 7: Known Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-201439 AOS-201448	—	Some OAW-AP303H access points running AOS-W 8.5.0.5 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as PC is at skb_panic+0x5c/0x68 .	AOS-W 8.5.0.5
AOS-202129 AOS-204127	—	The Configuration > AP groups page does not have the Split radio toggle button to enable the tri-radio feature. This issue is observed in stand-alone switches running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.0
AOS-202426 AOS-203652	—	Some 510 Series access points running AOS-W 8.6.0.4 crash and reboot unexpectedly. The log files list the reason for the event as PC is at: wlc_phy_enable_hwaci_28nm+0x938 - undefined instruction: 0 [#1] .	AOS-W 8.6.0.4
AOS-202552 AOS-203990	—	The Dashboard > Traffic Analysis > AppRF page of the WebUI displays Unknown for WLANs, Roles, and Devices. This issue is observed in Mobility Masters running AOS-W 8.3.0.0 or later versions.	AOS-W 8.3.0.0
AOS-203025 AOS-224678	—	A few mesh point APs are Down in the AP database. This issue occurs when CPsec is disabled. This issue is observed in managed devices running AOS-W 8.5.0.6 or later versions in a cluster setup.	AOS-W 8.5.0.6
AOS-203201	—	A managed device is unable to download configurations from the Mobility Master using VPNC. This issue is observed in managed devices running AOS-W 8.2.2.6 or later versions.	AOS-W 8.2.2.6
AOS-203336	—	The Dashboard > Infrastructure > Access Points page of the WebUI and the show log command display different values for the last AP reboot time. This issue is observed in stand-alone switches running AOS-W 8.5.0.5 or later versions.	AOS-W 8.5.0.5
AOS-203438	—	The configuration for EIRP made using the WebUI is not visible in stand-alone switches running AOS-W 8.6.0.3 or later versions.	AOS-W 8.6.0.3
AOS-203614 AOS-209261	—	The Mobility Master dashboard does not display the number of APs and clients present in the network. This issue is observed in Mobility Masters running AOS-W 8.6.0.2 or later versions.	AOS-W 8.6.0.2
AOS-203910 AOS-209692	—	The stand-alone switches running AOS-W 8.6.0.3 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as, Datapath timeout (Heartbeat Initiated) (Intent:cause:register 53:86:0:2c) .	AOS-W 8.6.0.3

Table 7: Known Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-204414	—	The VLAN range configured using the ntp-standalone vlan-range command is not correctly sent to the managed devices. This issue occurs when the user repeatedly modifies the VLAN range. This issue occurs in Mobility Masters running AOS-W 8.0.1.0 or later versions. Workaround: Delete the VLAN range configured on the Mobility Master and re-configure the ntp-standalone vlan-range .	AOS-W 8.3.0.8
AOS-205140	—	The AppRF ACLs using a voice role block WebRTC calls. This issue occurs when WebRTC audio and video ACLs are not part of the default voip-applications-acl . This issue is observed in Mobility Masters running AOS-W 8.6.0.8 or later versions. Workaround: Add WebRTC audio and video ACLs to the user role using the following command: ip access-list session webrtc any any app alg-webrtc-audio permit any any app alg-webrtc-video permit	AOS-W 8.6.0.8
AOS-205284 AOS-226338	—	Some OAW-AP515 access points running AOS-W 8.6.0.10 or later versions crash unexpectedly. The log files list the reason for the event as Warm-reset PC is at txq_hw_fill+0x13bc/0x21b8 [wl_v6] .	AOS-W 8.6.0.10
AOS-205319 AOS-206993 AOS-216577 AOS-218524	—	Some APs running AOS-W 8.6.0.5 or later versions crash and reboot unexpectedly. The log file lists the reason as Reboot caused by kernel panic: Fatal exception in interrupt .	AOS-W 8.6.0.5
AOS-206178	—	System logs do not display the reason why an AP has shut down. This issue is observed in Mobility Masters running AOS-W 8.6.0.4 or later versions.	AOS-W 8.6.0.4
AOS-206541	—	The Maintenance > Software Management page does not display the list of all managed devices that are part of a cluster. This issue is observed in Mobility Masters running AOS-W 8.5.0.8 or later versions.	AOS-W 8.5.0.8
AOS-206752	—	The console log of OAW-4450 switches running AOS-W 8.5.0.9 or later versions displays the ofald sdn ERRS ofconn_rx:476 <10.50.1.26:6633> socket read failed, err:Resource temporarily unavailable(11) message.	AOS-W 8.5.0.9
AOS-206795	—	A user is unable to rename a node from the Mobility Master node hierarchy. This issue is observed in Mobility Masters running AOS-W 8.3.0.7 or later versions. Workaround: Restart profmgr process to rename the node.	AOS-W 8.3.0.7

Table 7: Known Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-206890	—	The body field in the Configuration > Services > Guest Provisioning page of the WebUI does not allow users to add multiple paragraphs for email messages. This issue is observed in Mobility Masters running AOS-W 8.6.0.4 or later versions.	AOS-W 8.6.0.4
AOS-206902 AOS-208241	—	AirGroup users are unable to connect to Sonos speakers. This issue is observed in managed devices running AOS-W 8.5.0.9 or later versions.	AOS-W 8.5.0.9
AOS-207006 AOS-215138	—	APs go down and UDP 8209 traffic is sent without UDP 4500 traffic. This issue is observed in managed devices running AOS-W 8.6.0.4 or later versions.	AOS-W 8.6.0.4
AOS-207245	—	Some managed devices running AOS-W 8.5.0.8 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as Hardware Watchdog Reset (Intent:cause:register 53:86:0:802c) .	AOS-W 8.5.0.8
AOS-207366	—	The show advanced options menu is not available in the Configuration > Access Points > Campus APs page of the WebUI. This issue occurs when more than one AP is selected. This issue is observed in Mobility Masters running AOS-W 8.3.0.13.	AOS-W 8.3.0.13
AOS-207692	—	Some managed devices running AOS-W 8.6.0.4 or later versions log multiple authentication error messages.	AOS-W 8.6.0.4
AOS-209276	—	The show datapath crypto counters command displays the same output parameter, AESCCM Decryption Invalid Replay Co twice. This issue is observed in Mobility Masters running AOS-W 8.5.0.0 or later versions.	AOS-W 8.5.0.10
AOS-209912	—	A few managed devices fail to filter and drop spoofed ARP responses from the clients. The user entry for the other IP address was present on the managed devices but not in the route cache table. This issue is observed in managed devices running AOS-W 8.6.0.5 or later versions.	AOS-W 8.6.0.5
AOS-209977	—	SNMP query with an incorrect string fails to record the offending IP address. This issue is observed in managed devices running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10
AOS-210198	—	The Dashboard > Security > Detected Radio page of the WebUI displays incorrect number of Clients . This issue is observed in Mobility Masters running AOS-W 8.6.0.5 or later versions.	AOS-W 8.6.0.5
AOS-210482	—	Some managed devices running AOS-W 8.3.0.6 or later versions display the error message, Invalid set request while configuring ESSID for a Beacon Report Request profile.	AOS-W 8.3.0.6

Table 7: Known Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-210490	—	Some managed devices running AOS-W 8.5.0.8 or later versions display the error message, Error: Tunnel is part of a tunnel-group while deleting an L2 GRE tunnel which is not a part of any tunnel group.	AOS-W 8.5.0.8
AOS-210992	—	The Mobility Master displays an error message, Flow Group delete: id not found after an upgrade. This issue occurs when logging levels are not configured correctly. This issue is observed in Mobility Masters running AOS-W 8.6.0.5 or later versions.	AOS-W 8.6.0.5
AOS-211658	—	A few clients are unable to connect to OAW-AP535 access points running AOS-W 8.6.0.5 or later versions in a cluster setup. This issue occurs when WMM and HT configurations are enabled.	AOS-W 8.6.0.5
AOS-211720	—	The STM process crashes on managed devices and hence, APs failover to another cluster. This issue is observed in managed devices running AOS-W 8.5.0.5 or later versions.	AOS-W 8.5.0.5
AOS-211863	—	Some APs do not come up on managed devices. This issue occurs when <ul style="list-style-type: none"> ■ the forwarding mode is changed to bridge mode. ■ the name of the ACL is 64 bytes. This issue is observed in managed devices running AOS-W 8.6.0.5 or later versions.	AOS-W 8.6.0.5
AOS-212038	—	The show memory <process-name> command does not display information related to the dpagent process. This issue is observed in managed devices running AOS-W 8.6.0.5 or later versions.	AOS-W 8.6.0.5
AOS-212255	—	Some APs are stuck in Not in Progress state during cluster live upgrade. This issue is observed in managed devices running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10
AOS-215461 AOS-220709	—	Database synchronization fails between standby and stand-alone switches running AOS-W 8.6.0.9 or later versions. The log files list the reason for the event as Standby switch did not acknowledge the WMS database restore request.	AOS-W 8.6.0.9
AOS-215669	—	Some managed devices running AOS-W 8.6.0.7 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as Datapath timeout (Heartbeat Initiated) (Intent:cause:register 53:86:50:4).	AOS-W 8.6.0.7

Table 7: Known Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-215852	—	Mobility Masters running AOS-W 8.6.0.6 or later versions log the error message, ofa: 07765 ofproto INFO Aruba-SDN: 1 flow_mods 28 s ago (1 modifications) . This issue occurs when openflow is enabled and when 35 seconds is configured as UCC session idle timeout.	AOS-W 8.6.0.6
AOS-216145	—	Mobility Masters running AOS-W 8.5.0.8 or later versions send continuous DNS requests to the managed devices. This issue occurs when a folder that is not available on the /mm node is trying to get synchronized on the managed devices. Workaround: Perform the following steps to resolve the issue: 1. Issue the show memory debug include rsync command to identify the name of the folder that is trying to get synchronized on the managed devices. 2. Ensure that the folder is not present in the /flash/upload/custom/ path of the Mobility Master and then issue the no sync files <folder name> command to stop synchronization.	AOS-W 8.5.0.8
AOS-216874 AOS-219841	—	The virtual MAC address of VLAN gets deleted from the bridge table and results in a network outage. This issue is observed in managed devices running AOS-W 8.5.0.11 or later versions.	AOS-W 8.5.0.11
AOS-217890	—	Some managed devices running AOS-W 8.5.0.10 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as, Datapath timeout (SOS Assert) .	AOS-W 8.5.0.10
AOS-218328 AOS-220026	—	VRRP flapping is observed on managed devices running AOS-W 8.6.0.4 or later versions and hence, clients face connectivity issues.	AOS-W 8.6.0.4
AOS-218519	—	A few mesh APs detect its own BSSIDs as phony BSSIDs. This issue is observed in APs running AOS-W 8.6.0.7 or later versions.	AOS-W 8.6.0.7
AOS-219385	—	Some APs take a long time to come up on the backup data center after primary data center failover. This issue is observed in APs running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10
AOS-219619	—	Configurations inherited from the Mobility Master are incorrectly displayed as local/mm indicating that the configurations are locally enabled on the managed devices. This issue is observed in managed devices running AOS-W 8.5.0.8 or later versions.	AOS-W 8.5.0.8
AOS-219702	—	A few APs incorrectly report a hotspotter attack. This issue is observed in APs running AOS-W 8.6.0.7 or later versions.	AOS-W 8.6.0.7

Table 7: Known Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-220108	—	The OFA process crashes on Mobility Master Virtual Appliances running AOS-W 8.6.0.6 or later versions. This issue occurs when the show openflow debug ports command is executed.	AOS-W 8.6.0.6
AOS-220374	—	The authentication server load balancing does not work as expected. This issue is observed in managed devices running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10
AOS-220515	—	Some managed devices running AOS-W 8.0.0.0 or later versions display the error message, fpapps filling up the default gateway configuration.	AOS-W 8.5.0.12
AOS-220704	—	Some APs are incorrectly displayed under different clusters. This issue is observed in managed devices running AOS-W 8.5.0.11 or later versions.	AOS-W 8.5.0.11
AOS-220903	—	The s flag indicating LACP striping is not displayed in the output of the show ap database long command even if LLDP is enabled on two uplinks. This issue is observed in APs running AOS-W 8.6.0.8 or later versions.	AOS-W 8.6.0.8
AOS-220982	—	A few wireless clients are unable to pass traffic during a cluster failover. This issue is observed in managed devices managed devices	AOS-W 8.5.0.13
AOS-221018 AOS-220919	—	Some users are unable to connect to SSIDs. This issue occurs in 802.11r and MultiZone enabled configurations. This issue is observed in APs running AOS-W 8.5.0.11 or later versions.	AOS-W 8.5.0.11
AOS-221144	—	ARP packets are not forwarded to the uplink switch when bmc-optimization is enabled on the switches. This issue is observed in Mobility Masters and managed devices running AOS-W 8.5.0.9 or later versions.	AOS-W 8.5.0.9
AOS-221307	—	Adding a new VLAN removes all the existing VLANs on the port channel. This issue occurs when the existing VLAN list exceeds 256 characters. This issue is observed in managed devices running AOS-W 8.5.0.8 or later versions.	AOS-W 8.5.0.8
AOS-221429	—	Downloadable user roles are not applied correctly in the split tunnel mode. This issue is observed in stand-alone switches running AOS-W 8.6.0.9 or later versions.	AOS-W 8.6.0.9
AOS-221666 AOS-222708	—	Some OAW-RAPs running AOS-W 8.6.0.9 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as, Kernel panic - not syncing.	AOS-W 8.6.0.9

Table 7: Known Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-221743 AOS-212229	—	Some APs running AOS-W 8.5.0.10 or later versions reboot unexpectedly. The log files list the reason for the events as, skb_release_data+0xa0/0xc8/neighbor_flush_dev+0x60 .	AOS-W 8.5.0.10
AOS-221789 AOS-223052	—	The 802.1X authentication is initiated twice. This issue is observed in APs running AOS-W 8.6.0.3 or later versions.	AOS-W 8.6.0.9
AOS-222469	—	The number of APs in a network are higher than the number of licenses installed. This issue is observed in stand-alone switches running AOS-W 8.5.0.12 or later versions.	AOS-W 8.5.0.12
AOS-222499	—	Clients that perform only four-way handshake are unable to update their VSA role derived after machine and user authentication. This issue is observed in managed devices running AOS-W 8.6.0.6 or later versions.	AOS-W 8.6.0.6
AOS-222771	—	Some managed devices running AOS-W 8.5.0.12 or later versions do not send SNMPv3 information to the OmniVista 3600 Air Manager server.	AOS-W 8.5.0.12
AOS-223094 AOS-224240 AOS-224792	—	The net destination ID value in ACEs is incorrectly set to 0 after a reboot. This issue is observed in managed devices running AOS-W 8.2.0.0 or later versions.	AOS-W 8.6.0.9
AOS-223337	—	The clients added to the client match unsupported list are still considered for client match steers. This issue is observed in managed devices running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10
AOS-223669	—	Some users are unable to complete captive portal authentication. This issue occurs when ipv6-user snmpwalk populates IPv4 user details. This issue is observed in managed devices running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.4
AOS-223797	—	The show ap remote auth-trace-buf command does not display any output. This issue is observed in stand-alone switches and managed devices running AOS-W 8.6.0.9 or later versions.	AOS-W 8.6.0.9
AOS-223839	—	The output of the show ap active command does not display any value for Outer IP . This issue is observed in Mobility Masters running AOS-W 8.6.0.9 or later versions.	AOS-W 8.6.0.9
AOS-224019 AOS-226123	—	High controlpath memory utilization is observed and an error message, Resource 'Controlpath Memory' has dropped below 85% threshold is displayed. This issue is observed in managed devices running AOS-W 8.6.0.9 or later versions.	AOS-W 8.6.0.9

Table 7: Known Issues in AOS-W 8.6.0.15

New Bug ID	Old Bug ID	Description	Reported Version
AOS-224186	—	The show tech-support command does not display any information about the kernel crash and displays the message, No kernel crash information available . This issue is observed in stand-alone switches running AOS-W 8.6.0.9 or later versions.	AOS-W 8.6.0.9
AOS-224275 AOS-215206	—	The predefined v6-control policy does not allow DHCPv6 traffic. This issue is observed in managed devices running AOS-W 8.0.0.0 or later versions.	AOS-W 8.6.0.9
AOS-224538	—	A few APs running AOS-W 8.5.0.11 or later versions incorrectly fall back to the default AP group.	AOS-W 8.5.0.11
AOS-224767 AOS-221486	—	A few clients are disconnected from the network. The log file lists the reason for the event as Wlan driver excessive tx fail quick kickout . This issue is observed in OAW-AP535 and OAW-AP555 access points running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.8
AOS-224901	—	A few APs terminating in the backup LMS cluster do not move to the LMS cluster after a reboot. This issue is observed in managed devices running AOS-W 8.6.0.9 or later versions.	AOS-W 8.6.0.9
AOS-225135	—	Clients connected to APs are unable to send or receive data packets from APs. This issue occurs when the ACL changes are not updated on APs. This issue is observed in APs running AOS-W 8.6.0.9 or later versions.	AOS-W 8.6.0.9
AOS-226075	—	The logs generated by the stand-alone switch do not have source and destination port details and the logs also indicate that all TCP packets are fragmented. This issue is observed in stand-alone switches running AOS-W 8.6.0.12 or later versions.	AOS-W 8.6.0.12
AOS-226306		The show crypto isakmp command displays the output in an incorrect format. This issue is observed in Mobility Masters running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.10

This chapter details software upgrade procedures. It is recommended that you schedule a maintenance window for the upgrade.



Read all the information in this chapter before upgrading your Mobility Conductor, managed device, or stand-alone switch.

Important Points to Remember

To upgrade your managed device or Mobility Conductor:

- Schedule the upgrade during a maintenance window and notify your community of the planned upgrade. This prevents users from being surprised by a brief wireless network outage during the upgrade.
- Avoid making any changes to your network, such as configuration changes, hardware upgrades, or changes to the rest of the network during the upgrade. This simplifies troubleshooting.
- Know your network and verify the state of the network by answering the following questions:
 - How many APs are assigned to each managed device? Verify this information by navigating to the **Dashboard > Access Points** page in the WebUI, or by executing the **show ap active** or **show ap database** commands.
 - How are those APs discovering the managed device (DNS, DHCP Option, Broadcast)?
 - What version of AOS-W runs on your managed device?
 - Are all managed devices running the same version of AOS-W?
 - What services are used on your managed device (employee wireless, guest access, OAW-RAP, wireless voice)?
- Resolve any existing issues (consistent or intermittent) before you upgrade.
- If possible, use FTP to load AOS-W images to the managed device. FTP is faster than TFTP and offers more resilience over slow links. If you must use TFTP, ensure the TFTP server can send over 30 MB of data.
- Always upgrade the non-boot partition first. If you encounter any issue during the upgrade, you can restore the flash, and switch back to the boot partition. Upgrading the non-boot partition gives you a smoother downgrade path, if required.
- Before you upgrade to this version of AOS-W, assess your software license requirements and load any new or expanded licenses that you might require. For a detailed description of these new license modules, refer the *Alcatel-Lucent Mobility Conductor Licensing Guide*.
- Multiversion is supported in a topology where the managed devices are running the same version as the Mobility Conductor, or two versions lower. For example multiversion is supported if a Mobility Conductor is running AOS-W 8.5.0.0 and the managed devices are running AOS-W 8.5.0.0, AOS-W 8.4.0.0, or AOS-W 8.3.0.0.

Memory Requirements

All Alcatel-Lucent managed devices store critical configuration data on an onboard compact flash memory module. Ensure that there is always free flash space on the managed device. Loading multiple large files such as JPEG images for RF Plan can consume flash space quickly. Following are best practices for memory management:

- Do not proceed with an upgrade unless 100 MB of free memory is available. Execute the **show memory** command to identify the available free memory. To recover memory, reboot the managed device. After the managed device comes up, upgrade immediately.
- Do not proceed with an upgrade unless the minimum flash space is available. Execute the **show storage** command to identify the available flash space. If the output of the **show storage** command indicates that there is insufficient flash memory, free some used memory. Copy any log files, crash data, or flash backups from your the managed device to a desired location. Delete the following files from the managed device to free some memory:
 - **Crash data:** Execute the **tar crash** command to compress crash files to a file named **crash.tar**. Use the procedures described in [Backing up Critical Data on page 32](#) to copy the **crash.tar** file to an external server. Execute the **tar clean crash** command to delete the file from the managed device.
 - **Flash backups:** Use the procedures described in [Backing up Critical Data on page 32](#) to back up the flash directory to a file named **flash.tar.gz**. Execute the **tar clean flash** command to delete the file from the managed device.
 - **Log files:** Execute the **tar logs** command to compress log files to a file named **logs.tar**. Use the procedures described in [Backing up Critical Data on page 32](#) to copy the **logs.tar** file to an external server. Execute the **tar clean logs** command to delete the file from the managed device.



In certain situations, a reboot or a shutdown could cause the managed device to lose the information stored in its flash memory. To avoid such issues, it is recommended that you execute the **halt** command before power cycling.

Deleting a File

You can delete a file using the WebUI or CLI.

In the WebUI

From the Mobility Conductor, navigate to **Diagnostic > Technical Support > Delete Files** and remove any aging log files or redundant backups.

In the CLI

```
(host) #delete filename <filename>
```

Backing up Critical Data

It is important to frequently back up all critical configuration data and files on the flash memory to an external server or mass storage device. You should include the following files in these frequent backups:

- Configuration data
- WMS database
- Local user database
- Licensing database
- Custom captive portal pages
- x.509 certificates
- Log files
- Flash backup

Backing up and Restoring Flash Memory

You can backup and restore the flash memory using the WebUI or CLI.

In the WebUI

The following steps describe how to back up and restore the flash memory:

1. In the Mobility Conductor node hierarchy, navigate to the **Maintenance > Configuration Management > Backup** page.
2. Click **Create Backup** to backup the contents of the flash memory to the **flashbackup.tar.gz** file.
3. Click **Copy Backup** to copy the file to an external server.

You can copy the backup file from the external server to the flash memory using the file utility in the **Diagnostics > Technical Support > Copy Files** page.

4. To restore the backup file to the flash memory, navigate to the **Maintenance > Configuration Management > Restore** page and click **Restore**.

In the CLI

The following steps describe how to back up and restore the flash memory:

1. Execute the following command in the **enable** mode:

```
(host) #write memory
```

2. Execute the following command to back up the contents of the flash memory to the **flashbackup.tar.gz** file.

```
(host) #backup flash
Please wait while we take the flash backup.....
File flashbackup.tar.gz created successfully on flash.
Please copy it out of the controller and delete it when done.
```

3. Execute either of the following command to transfer the flash backup file to an external server or storage device.

```
(host) #copy flash: flashbackup.tar.gz ftp: <ftphost> <ftpusername> <ftpuserpassword>
<remote directory>
```

```
(host) #copy flash: flashbackup.tar.gz usb: partition <partition-number>
```

You can transfer the flash backup file from the external server or storage device to the flash memory by executing either of the following command:

```
(host) #copy tftp: <tftphost> <filename> flash: flashbackup.tar.gz
```

```
(host) #copy usb: partition <partition-number> <filename> flash: flashbackup.tar.gz
```

4. Execute the following command to untar and extract the **flashbackup.tar.gz** file to the flash memory.

```
(host) #restore flash
Please wait while we restore the flash backup.....
Flash restored successfully.
Please reload (reboot) the controller for the new files to take effect.
```

Upgrading AOS-W

Upgrade AOS-W using the WebUI or CLI.



Ensure that there is enough free memory and flash space on your Mobility Conductor or managed device. For details, see [Memory Requirements on page 31](#).



When you navigate to the **Configuration** tab in the WebUI, the managed device might display the **Error getting information: command is not supported on this platform** message. This message is displayed occurs when you upgrade using the WebUI and navigate to the **Configuration** tab after the managed device reboots. This message disappears after clearing the Web browser cache.

In the WebUI

The following steps describe how to upgrade AOS-W from a TFTP server, FTP server, or local file.

1. Download the AOS-W image from the customer support site.
2. Upload the AOS-W image to a PC or workstation on your network.
3. Validate the SHA hash for the AOS-W image:
 - a. Download the **Alcatel.sha256** file from the download directory.
 - b. Load the AOS-W image to a Linux system and execute the **sha256sum <filename>** command. Alternatively, use a suitable tool for your operating system that can generate a **SHA256** hash of a file.
 - c. Verify that the output produced by this command matches the hash value found on the customer support site.



The AOS-W image file is digitally signed and is verified using RSA2048 certificates preloaded at the factory. The Mobility Conductor or managed device will not load a corrupted AOS-W image.

4. Log in to the AOS-W WebUI from the Mobility Conductor.
5. Navigate to the **Maintenance > Software Management > Upgrade** page.
 - a. Select the **Local File** option from the **Upgrade using** drop-down list.
 - b. Click **Browse** from the **Image file name** to navigate to the saved image file on your PC or workstation.
6. Select the downloaded image file.
7. Choose the partition from the **Partition to Upgrade** option.
8. Enable the **Reboot Controller After Upgrade** toggle switch to automatically reboot after upgrading. If you do not want to reboot immediately, disable this option.



The upgrade does not take effect until reboot. If you chose to reboot after upgrade, the Mobility Conductor or managed device reboots automatically.

9. Select **Save Current Configuration**.
10. Click **Upgrade**.
11. Click **OK**, when the **Changes were written to flash successfully** message is displayed.

In the CLI

The following steps describe how to upgrade AOS-W from a TFTP server, FTP server, or local file.

1. Download the AOS-W image from the customer support site.
2. Open an SSH session to your Mobility Conductor.
3. Execute the **ping** command to verify the network connection between the Mobility Conductor and the SCP server, FTP server, or TFTP server.

```
(host)# ping <ftphost>
```

or

```
(host)# ping <tftphost>
```

or

```
(host)# ping <scphost>
```

4. Execute the **show image version** command to check if the AOS-W image is loaded on the flash partition. The partition number appears in the **Partition** row; **0:0** is partition 0, and **0:1** is partition 1. The active boot partition is marked as **Default boot**.

```
(host) #show image version
```

5. Execute the **copy** command to load the new image to the non-boot partition.

```
(host)# copy ftp: <ftphost> <ftpusername> <image filename> system: partition <0|1>
```

or

```
(host)# copy tftp: <tftphost> <image filename> system: partition <0|1>
```

or

```
(host)# copy scp: <scphost> <scpusername> <image filename> system: partition <0|1>
```

or

```
(host)# copy usb: partition <partition-number> <image filename> system: partition <0|1>
```

6. Execute the **show image version** command to verify that the new image is loaded.

```
(host)# show image version
```

7. Reboot the Mobility Conductor.

```
(host)#reload
```

8. Execute the **show version** command to verify that the upgrade is complete.

```
(host)#show version
```

Verifying the AOS-W Upgrade

Verify the AOS-W upgrade in the WebUI or CLI.

In the WebUI

The following steps describe how to verify that the Mobility Conductor is functioning as expected:

1. Log in to the WebUI and navigate to the **Dashboard > WLANs** page to verify the AOS-W image version.
2. Verify if all the managed devices are up after the reboot.
3. Navigate to the **Dashboard > Access Points** page to determine if your APs are up and ready to accept clients.
4. Verify that the number of APs and clients are as expected.
5. Test a different type of client in different locations, for each access method used.
6. Complete a backup of all critical configuration data and files on the flash memory to an external server or mass storage facility. See [Backing up Critical Data on page 32](#) for information on creating a backup.

In the CLI

The following steps describe how to verify that the Mobility Conductor is functioning as expected:

1. Log in to the CLI to verify that all your managed devices are up after the reboot.
2. Execute the **show version** command to verify the AOS-W image version.
3. Execute the **show ap active** command to determine if your APs are up and ready to accept clients.
4. Execute the **show ap database** command to verify that the number of APs and clients are as expected.
5. Test a different type of client in different locations, for each access method used.
6. Complete a backup of all critical configuration data and files on the flash memory to an external server or mass storage facility. See [Backing up Critical Data on page 32](#) for information on creating a backup.

Downgrading AOS-W

A Mobility Conductor or managed device has two partitions, 0 and 1. If the upgrade fails on one of the partitions, you can reboot the Mobility Conductor or managed device from the other partition.

Pre-requisites

Before you reboot the Mobility Conductor or managed device with the pre-upgrade AOS-W version, perform the following steps:

1. Back up your Mobility Conductor or managed device. For details, see [Backing up Critical Data on page 32](#).
2. Verify that the control plane security is disabled.
3. Set the Mobility Conductor or managed device to boot with the previously saved configuration file.
4. Set the Mobility Conductor or managed device to boot from the partition that contains the pre-upgrade AOS-W version.

When you specify a boot partition or copy an image file to a system partition, Mobility Conductor or managed device checks if the AOS-W version is compatible with the configuration file. An error message is displayed if the boot parameters are incompatible with the AOS-W version and configuration files.

5. After switching the boot partition, perform the following steps:
 - Restore the pre-upgrade flash backup from the file stored on the Mobility Conductor or managed device. Do not restore the AOS-W flash backup file.
 - Do not import the WMS database.
 - If the RF plan is unchanged, do not import it. If the RF plan was changed before switching the boot partition, the changed RF plan does not appear in the downgraded AOS-W version.
 - If any new certificates were added in the upgraded AOS-W version, reinstall these certificates in the downgraded AOS-W version.

Downgrade AOS-W version using the WebUI or CLI.

In the WebUI

The following steps describe how to downgrade the AOS-W version:

1. If the saved pre-upgrade configuration file is on an external FTP or TFTP server, copy the file to the Mobility Conductor or managed device by navigating to the **Diagnostics > Technical Support > Copy Files** page.
 - a. From **Select source file** drop-down list, select FTP or TFTP server, and enter the IP address of the FTP or TFTP server and the name of the pre-upgrade configuration file.

- b. From **Select destination file** drop-down list, select **Flash file system**, and enter a file name (other than default.cfg).
 - c. Click **Copy**.
2. Determine the partition on which your pre-upgrade AOS-W version is stored by navigating to the **Maintenance > Software Management > Upgrade** page. If a pre-upgrade AOS-W version is not stored on your system partition, load it into the backup system partition by performing the following steps:



You cannot load a new image into the active system partition.

- a. Enter the FTP or TFTP server address and image file name.
 - b. Select the backup system partition.
 - c. Enable **Reboot Controller after upgrade**.
 - d. Click **Upgrade**.
3. Navigate to the **Maintenance > Software Management > Reboot** page, select **Save configuration before reboot**, and click **Reboot**.
The Mobility Conductor or managed device reboots after the countdown period.
4. When the boot process is complete, verify that the Mobility Conductor or managed device is using the correct AOS-W version by navigating to the **Maintenance > Software Management > About** page.

In the CLI

The following steps describe how to downgrade the AOS-W version:

1. If the saved pre-upgrade configuration file is on an external FTP or TFTP server, use the following command to copy it to the Mobility Conductor or managed device:

```
(host) # copy ftp: <ftphost> <ftpusername> <image filename> system: partition 1
```

or

```
(host) # copy tftp: <tftphost> <image filename> system: partition 1
```
2. Set the Mobility Conductor or managed device to boot with your pre-upgrade configuration file.

```
(host) # boot config-file <backup configuration filename>
```
3. Execute the **show image version** command to view the partition on which your pre-upgrade AOS-W version is stored.

```
(host) #show image version
```



You cannot load a new image into the active system partition.

4. Set the backup system partition as the new boot partition.

```
(host) # boot system partition 1
```
 5. Reboot the Mobility Conductor or managed device.

```
(host) # reload
```
 6. When the boot process is complete, verify that the Mobility Conductor or managed device is using the correct AOS-W version.

```
(host) # show image version
```

Before Calling Technical Support

Provide the following information when you call the Technical Support:

- The status of installation (new or existing) and recent changes to network, device, or AP configuration. If there was a configuration change, list the exact configuration steps and commands used.
- A detailed network topology including all the devices in the network with IP addresses and interface numbers.
- The make and model number of the wireless device and NIC, driver date, version, and configuration of the NIC, and the OS version including any service packs or patches.
- The logs and output of the **show tech-support** command.
- The syslog file at the time of the problem.
- The date and time when the problem first occurred. If the problem is reproducible, list the exact steps taken to re-create the problem.
- Any wired or wireless sniffer traces taken during the time of the problem.
- The device site access information.