

AOS-W 8.11.2.2 Release Notes



Copyright Information

The Alcatel-Lucent name and logo are trademarks of Nokia used under license by ALE. To view other trademarks used by affiliated companies of ALE Holding, visit: www.al-enterprise.com/en/legal/trademarks-copyright. All other trademarks are the property of their respective owners. The information presented is subject to change without notice. Neither ALE Holding nor any of its affiliates assumes any responsibility for inaccuracies contained herein.

© Copyright 2024 ALE International, ALE USA Inc. All rights reserved in all countries.

Open Source Code

This product includes code licensed under the GNU General Public License, the GNU Lesser General Public License, and/or certain other open source licenses.

Contents	3
Revision History	4
Overview	5
Important Upgrade Information for OAW-41xx Series and 9200 Series switches	5
Related Documents	5
Supported Browsers	5
Terminology Change	6
Contacting Support	6
What's New in AOS-W 8.11.2.2	8
New Features and Enhancements	8
Behavioral Changes	8
Supported Platforms in AOS-W 8.11.2.2	9
Mobility Conductor Platforms	9
OmniAccess Mobility Controller Platforms	9
AP Platforms	9
Regulatory Updates in AOS-W 8.11.2.2	11
Resolved Issues in AOS-W 8.11.2.2	12
Known Issues in AOS-W 8.11.2.2	20
Limitations	20
Known Issues	20
Upgrade Procedure	25
Important Points to Remember	25
Memory Requirements	26
Low Free Flash Memory	26
Backing up Critical Data	29
Upgrading AOS-W	30
Verifying the AOS-W Upgrade	32
Downgrading AOS-W	32
Before Calling Technical Support	34

The following table lists the revision numbers and the corresponding changes that were made in this release:

Table 1: *Revision History*

Revision	Change Description
Revision 01	Initial release.

This release includes new features, enhancements, bug fixes, and a regulatory update.

Important Upgrade Information for OAW-41xx Series and 9200 Series switches

Upgrading from AOS-W 8.11.1.0 or earlier versions on OAW-41xx Series and 9200 Series switches will take longer than usual as we will be automatically upgrading the BIOS version to support additional functionality in the future. This upgrade is estimated to take up to 15 minutes and should not be interrupted for any reason. Power failures and interruptions during the upgrade may make the switch unusable. Please use caution and plan accordingly.



Cluster Rolling Upgrade is not supported when a BIOS upgrade is required. AOS-W 8.11.2.2 must be manually upgraded for these controllers.

Release Date: February 2024

[Upgrade Procedure](#)

[Supported Platforms](#)

Related Documents

The following guides are part of the complete documentation for the Alcatel-Lucent user-centric network:

- *AOS-W Getting Started Guide*
- *AOS-W User Guide*
- *AOS-W CLI Reference Guide*
- *AOS-W API Guide*
- *Alcatel-Lucent Mobility Conductor Licensing Guide*
- *Alcatel-Lucent Virtual Appliance Installation Guide*
- *Alcatel-Lucent AP Software Quick Start Guide*

Supported Browsers

The following browsers are officially supported for use with the AOS-W WebUI:

Web Browser	Operating System
Microsoft Edge (Microsoft Edge 92.0.902.62 and Microsoft EdgeHTML 18.19041) or later	<ul style="list-style-type: none">■ Windows 10 or later■ macOS

Web Browser	Operating System
Firefox 107.0.1 or later	<ul style="list-style-type: none"> ▪ Windows 10 or later ▪ macOS
Apple Safari 15.4 (17613.17.1.13) or later	<ul style="list-style-type: none"> ▪ macOS
Google Chrome 108.0.5359.71 or later	<ul style="list-style-type: none"> ▪ Windows 10 or later ▪ macOS

Terminology Change

As part of advancing Alcatel-Lucent Enterprise's commitment to racial justice, we are taking a much-needed step in overhauling ALE engineering terminology to reflect our belief system of diversity and inclusion. Some legacy products and publications may continue to include terminology that seemingly evokes bias against specific groups of people. Such content is not representative of our ALE culture and moving forward, ALE will replace racially insensitive terms and instead use the following new language:

Usage	Old Language	New Language
Campus Access Points + Controllers	Master-Slave	Conductor-Member
Instant Access Points	Master-Slave	Conductor-Member
Switch Stack	Master-Slave	Conductor-Member
Wireless LAN Controller	Mobility Master	Mobility Conductor
Firewall Configuration	Blacklist, Whitelist	Denylist, Allowlist
Types of Hackers	Black Hat, White Hat	Unethical, Ethical

Contacting Support

Table 2: *Contact Information*

Contact Center Online	
Main Site	https://www.al-enterprise.com
Support Site	https://myportal.al-enterprise.com
Email	ebg_global_supportcenter@al-enterprise.com
Service & Support Contact Center Telephone	
North America	1-800-995-2696
Latin America	1-877-919-9526
EMEA	+800 00200100 (Toll Free) or +1(650)385-2193

Contact Center Online

Asia Pacific	+65 6240 8484
Worldwide	1-818-878-4507

This chapter describes the features, enhancements, and behavioral changes introduced in this release.

New Features and Enhancements

This topic describes the features and enhancements introduced in this release.

RADIUS Authentication Server Profile Configurations Added to AirGroup Version 2

The AirGroup version 2 module now accepts RADIUS authentication profile changes such as **nas-IP** and **source-interface** through the **aaa authentication-server radius** command. Rather than depending on the Mobility Conductor's settings, this feature allows for specific authentication-related configurations to be applied to managed devices.

The configuration varies depending on the AirGroup mode used:

- **Centralized mode** requires configurations to be applied on both the Mobility Conductor and managed device. In the case of having different profiles configured, the managed device's profile will take priority.
- **Distributed mode** requires node-specific configuration. In the case of having governing managed devices, the configuration will apply to all member nodes. However, node-specific configuration can still be applied to member nodes if needed.

Enhancement to VAPs

The processing time for manually created VAPs to transition from **interfering** to **valid** has been enhanced.

Behavioral Changes

This release does not introduce any changes in AOS-W behaviors, resources, or support that would require you to modify your existing system configurations after updating to 8.11.2.2.

Removal of ssh-rsa Signature Scheme from SSH Cryptographic Settings

The **ssh-rsa** parameter has been removed to eliminate any security concerns with the SHA-1 hash algorithm and RSA public key algorithm.

This chapter describes the platforms supported in this release.

Mobility Conductor Platforms

The following table displays the Mobility Conductor platforms that are supported in this release:

Table 3: *Supported Mobility Conductor Platforms*

Mobility Conductor Family	Mobility Conductor Model
Hardware Mobility Conductor	MCR-HW-1K, MCR-HW-5K, MCR-HW-10K
Virtual Mobility Conductor	MCR-VA-50, MCR-VA-500, MCR-VA-1K, MCR-VA-5K, MCR-VA-10K

OmniAccess Mobility Controller Platforms

The following table displays the OmniAccess Mobility Controller platforms that are supported in this release:

Table 4: *Supported OmniAccess Mobility Controller Platforms*

OmniAccess Mobility Controller Family	OmniAccess Mobility Controller Model
OAW-40xx Series OmniAccess Mobility Controllers	OAW-4005, OAW-4008, OAW-4010, OAW-4024, OAW-4030
OAW-4x50 Series OmniAccess Mobility Controllers	OAW-4450, OAW-4550, OAW-4650, OAW-4750, OAW-4750XM, OAW-4850
OAW-41xx Series OmniAccess Mobility Controllers	OAW-4104, 9012
9200 Series OmniAccess Mobility Controllers	9240
MC-VA-xxx Virtual OmniAccess Mobility Controllers	MC-VA-10, MC-VA-50, MC-VA-250, MC-VA-1K

AP Platforms

The following table displays the AP platforms that are supported in this release:

Table 5: *Supported AP Platforms*

AP Family	AP Model
OAW-AP300 Series	OAW-AP304, OAW-AP305

Table 5: Supported AP Platforms

AP Family	AP Model
OAW-AP303 Series	OAW-AP303, OAW-AP303P
OAW-AP303H Series	OAW-AP303H, OAW-303HR
OAW-AP310 Series	OAW-AP314, OAW-AP315
OAW-AP318 Series	OAW-AP318
OAW-AP360 Series	OAW-AP365, OAW-AP367
OAW-AP370 Series	OAW-AP374, OAW-AP375, OAW-AP377
OAW-AP370EX Series	OAW-AP375EX, OAW-AP377EX, OAW-AP375ATEX
OAW-AP500 Series	OAW-AP504, OAW-AP505
OAW-AP503 Series	OAW-AP503
OAW-AP500H Series	OAW-AP503H, OAW-AP503HR, OAW-AP505H, OAW-AP505HR
OAW-AP510 Series	OAW-AP514, OAW-AP515, OAW-AP518
OAW-AP518 Series	OAW-AP518
OAW-AP530 Series	OAW-AP534, OAW-AP535
OAW-AP550 Series	OAW-AP555
OAW-AP560 Series	OAW-AP565, OAW-AP567
OAW-AP570 Series	OAW-AP574, OAW-AP575, OAW-AP577
OAW-AP580 Series	OAW-AP584, OAW-AP585, OAW-AP585EX, OAW-AP587, OAW-AP587EX
OAW-AP610 Series	OAW-AP615
OAW-AP630 Series	OAW-AP635, AP-634
OAW-AP650 Series	OAW-AP655, AP-654



Chapter 5

Regulatory Updates in AOS-W 8.11.2.2

This chapter contains the Downloadable Regulatory Table (DRT) file version introduced in this release. Periodic regulatory changes may require modifications to the list of channels supported by an AP. For a complete list of channels supported by an AP using a specific country domain, access the switch Command Line Interface (CLI) and execute the **show ap allowed-channels country-code <country-code> ap-type <ap-model>** command.

For a complete list of countries and the regulatory domains in which the APs are certified for operation, refer to the Downloadable Regulatory Table or the DRT Release Notes at <https://myportal.al-enterprise.com>.

The following DRT file version is part of this release:

- DRT-1.0_89073

Chapter 6

Resolved Issues in AOS-W 8.11.2.2

This chapter describes the resolved issues in this release.

Table 6: Resolved Issues in AOS-W 8.11.2.2

New Bug ID	Description	Reported Version
AOS-215875	The show ap arm state command displayed deprecated information such as Edge, Relevant Neighbors, Valid Neighbors, Neighbor Density, and Client Density. The fix ensures the deprecated information is no longer displayed. This issue was observed on OmniAccess Mobility Controllers running AOS-W 8.7.1.1 or later versions.	AOS-W 8.7.1.1
AOS-230427	Gateway backup on OmniVista 3600 Air Manager did not work for gateways running AOS-W 8.6.0.23 or later versions. This issue occurred because OmniVista 3600 Air Manager did not support ssh-rsa host key algorithm, but the gateways supported only ssh-rsa as a client. The fix ensures that the gateway backup works as expected since support for rsa-sha2-256 and rsa-sha2-512 was reinstated in OmniVista 3600 Air Manager.	AOS-W 8.6.0.23
AOS-232527	Some users experienced issues when the deletion of an aged-out IPv4 address for a client inadvertently led to the deletion of all associated IPv6 addresses for the same client. This issue was observed when the aaa user fast-age command was enabled. The fix ensures that IPv6 addresses are not idled out when fast-age is enabled. This issue was observed on Mobility Conductors running AOS-W 8.6.0.15 or later versions.	AOS-W 8.6.0.15
AOS-237373 AOS-248873	Some access points crashed unexpectedly when the PMTU value was set up to 1200 or 1300 bytes. The log files listed the reason for the event as PC is at skb_copy_and_csum_bits+0x24/0x274 . The fix ensures the APs work as expected. This issue was observed in OAW-AP655 access points running AOS-W 8.10.0.7 or later versions.	AOS-W 8.7.1.9
AOS-239321 AOS-240598	Some OAW-AP635 access points crashed and rebooted unexpectedly. The log files listed the event as Reboot caused by kernel panic: Take care of the TARGET ASSERT . The crash-info showed that the AP firmware was asserted at whal_rcv.c:1656 . The fix ensures that the APs work as expected. The issue was observed on APs running AOS-W 8.10.0.4 or later versions.	AOS-W 8.10.0.4
AOS-240568 AOS-244716	In some switches, saving the tunnel configuration took longer than expected. The fix ensures the tunnel configurations are saved as expected. This issue was observed in standby switches running AOS-W 8.10.0.2 or later versions.	AOS-W 8.10.0.2

Table 6: Resolved Issues in AOS-W 8.11.2.2

New Bug ID	Description	Reported Version
AOS-241498	A corrupt bridge ACL issue was observed in APs running AOS-W 8.10.0.5 or later versions, where some user roles were either missing or contained a duplicate of the logon role. This issue prevented the AP from passing user traffic. The fix ensures the APs work as expected.	AOS-W 8.10.0.5
AOS-241833	Remote APs operating in a dual-stack environment with an IPv4 IPSEC experienced heartbeat loss after IPSEC re-key when IPv6 was inadvertently used. The fix ensures no heartbeat misses are seen on RAPs when IPSEC re-keying happens. The issue was seen on remote OAW-AP505H access points running AOS-W 8.10.0.5 or later versions.	AOS-W 8.10.0.5
AOS-242970 AOS-251056 AOS-242377 AOS-245036 AOS-249828 AOS-250026 AOS-250893	When running the clear gap-db ap-name and clear gap-db wired-mac commands from a Mobility Conductor, the state AP records were not cleared down on managed devices. As a result, stale AP records were still observed in managed devices. The fix ensures the stale AP records are deleted as expected after running these commands. However, if needed, run the clear gapdb stale-ap ap-name <ap-name> lms lms-ip <lms-ip> command to clear the a stale entry on a particular managed device. This issue was observed in Mobility Conductors running AOS-W 8.10.0.4 or later versions.	AOS-W 8.10.0.4
AOS-243033	In some switches, the associated access points randomly disconnected. This issue occurred in a cluster setup with the Bypass function enabled, where the AP would not try to re-authenticate. The tunnel to Active AP Anchor Controller was maintained, but the tunnel to the Standby Active AP Anchor Controller was dropped. This caused that the client devices were unable to pass traffic. The fix ensures dot1x authentication is restored in this scenario. This issue was observed in switches running AOS-W 8.10.0.5 or later versions.	AOS-W 8.10.0.5
AOS-243720	The WebUI did not display the correct output for the show wms ap list and show wms rogue-ap list commands. The fix ensures the correct information is displayed in the WebUI. This issue was observed in Mobility Conductors running AOS-W 8.10.0.4 or later versions.	AOS-W 8.10.0.4
AOS-244218 AOS-245833 AOS-247849 AOS-248640 AOS-249157	Some APs crashed and rebooted due to memory allocation failure for the trigger frame, which dropped the connection. The fix ensures the APs perform as expected. This issue was observed in APs running AOS-W 8.11.0.0 or later versions.	AOS-W 8.11.0.0
AOS-244334 AOS-247602 AOS-247934	Some access points incorrectly displayed their power supply type as DC despite being connected to a PoE switch port and without a DC supply. As a result, when client devices connected to the AP, power consumption exceeded the 802.3af limit, which in turn caused the AP to reboot. The fix ensures the AP displays its power supply type correctly. This issue was observed in OAW-AP655 access points running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7

Table 6: Resolved Issues in AOS-W 8.11.2.2

New Bug ID	Description	Reported Version
AOS-244576	The datapath route-cache information for L3 GRE tunnels was lost unexpectedly. This was caused as the IPSec tunnel pointed to the wrong IP address whenever it went down and re-established itself, causing uplink issues on the network. The fix ensures uplink works as expected. This issue was observed in switches running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-245777	In the switches Dashboard , under Overview > Clients , applying the grouped by signal quality filter did not correctly organize the client data nor displayed the graph based on signal quality. The fix ensures the correct data is filtered and displayed. This issue was observed in managed devices running AOS-W 8.6.0.0 or later versions.	AOS-W 8.10.0.6
AOS-245788	Some APs crashed and rebooted unexpectedly. The log files listed the reason for the crash as Reboot caused by kernel panic: Take care of the TARGET ASSERT first . The crash-info shows TARGET ASSERT occurred at PC:0x00000000 . The fix ensures APs work as expected. The issue was observed in access points running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-246164 AOS-249753	The profmgr process crashed unexpectedly when configuration changes were applied to an aaa server-group . The fix ensures the process does not crash in this context. This issue was observed in managed devices running AOS-W 8.10.0.9 or later versions.	AOS-W 8.10.0.9
AOS-246184	Some access points crashed and rebooted unexpectedly. The log files listed the reason for the crash as ar_wal_tx_sch_status.c:645 Assertion (PPDU_QUEUE_ID(tx_ctxt) != TX_INVALID_QUEUE PPDU_SCH_ID(tx_ctxt)) . The fix ensures the APs work as expected. This issue was observed in APs running AOS-W 8.10.0.5 or later versions.	AOS-W 8.10.0.5
AOS-246358 AOS-243849	Provisioning failed for the UAC-AP when changing the CPsec mode from enable to disable. The fix ensures the UAC-AP tunnel can be deleted correctly when keepalive times out, and ensures the provision succeeds after disabling the CPsec. This issue was observed in access points running AOS-W 8.10.0.6 or later versions.	AOS-W 8.10.0.6
AOS-246583	OAW-4750XM OmniAccess Mobility Controllers experienced unexpected crashes as a result of a failure in the tnld_node_mgr process. The fix ensures the process works as expected. This issue was observed in OmniAccess Mobility Controllers running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-246839	The usage of ECDSA certificates in a web-server profile caused the unavailability of the WebUI. The fix ensures the WebUI works as expected when using ECDSA certificates. This issue was observed in controllers running AOS-W 8.10.0.7 and 8.10.0.7-FIPS or later versions.	AOS-W 8.10.0.7

Table 6: Resolved Issues in AOS-W 8.11.2.2

New Bug ID	Description	Reported Version
AOS-247070	Some switches crashed and rebooted with the reason Datapath timeout (Intent:cause: 86:56) . The crash was related to sessions deleted due to a QAT response timeout. The fix ensures the switches work as expected. This issue was observed in OAW-4104 switches running AOS-W 8.6.0.20 or later versions.	AOS-W 8.6.0.20
AOS-247147	Virtual OmniAccess Mobility Controllers were consistently generating error logs pertaining to the WMS database on a daily basis. The fix ensures the APs are correctly classified and are not set to unknown in the database. This issue was observed on virtual OmniAccess Mobility Controllers running AOS-W 8.10.0.7.	AOS-W 8.10.0.7
AOS-247387	The Configuration > Access Points > Allowlist section of the WebUI did not appropriately sort the AP allowlist by Name when the entry list exceeded one page. The fix ensures that sorting works appropriately across all pages. This issue was observed in switches running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-247551	The output of the show aaa auth-survivability-cache command displayed station names in uppercase. The fix ensures the output is displayed in lowercase where expected. This issue was observed in managed devices running AOS-W 8.6.0.20 or later versions.	AOS-W 8.6.0.20
AOS-247727	Netdestination allowlist was not working on branch gateways. This issue occurred due to the DNS IP list not being cleared every 24 hours for x86 platforms. This resulted in the DNS IP table getting full and subsequently causing DNS IP allocation failures. The fix ensures that the DNS IP list is cleared at regular intervals. This issue was observed in branch gateways running AOS-W 8.10.0.0 or later versions.	AOS-W 8.10.0.0
AOS-247819	In SNMP walks, IPv6 clients with no IP address caused that the SNMP table was not ended correctly. As a result, the OID was not increasing and the SNMP walk stopped and did not move to the next client. The fix ensures the SNMP walk performs as expected in this scenario. This issue was observed in switches running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-247823	Wired clients connected to some OAW-AP515 access points were unable to authenticate and were not seen on the switch. This issue was observed in Campus APs with multizone profile enabled on the AP. The fix ensures wired clients connect as expected in this scenario. This issue was observed in APs running AOS-W 8.10.0.8 or later versions.	AOS-W 8.10.0.8
AOS-247952	In four-node virtual-machine clusters, the output of the show ap bss-table ap-name and ap monitor ap-list ap-name commands showed incorrect Tx BSSID flag information. Some VAPs showed an incorrect (*+) flag next to their bssid in the CLI output. The fix ensures the table output of the commands is accurate. This issue was observed in OAW-AP635 access points running AOS-W 8.10.0.0 or later versions.	AOS-W 8.10.0.0

Table 6: Resolved Issues in AOS-W 8.11.2.2

New Bug ID	Description	Reported Version
AOS-248092	Some APs displayed their SSID incompletely if there were more than 31 characters when using an XML API query due to the location field being truncated. The fix ensures the SSID displays correctly. This issue was observed in APs running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-248178 AOS-250372	The Diagnostics > Tools > Spectrum Analysis page of the WebUI did not display any data when a sensor from the Connected Sensors list was selected. The graphs displayed the message No data to display . However, this information was available through the CLI. The fix ensures the sensor data is displayed accurately in the WebUI. This issue was observed in switches running AOS-W 8.10.0.9 or later versions.	AOS-W 8.10.0.9
AOS-248267 AOS-251592	The RADIUS/RADSec server could not connect to the FQDN host after rebooting the switch, resulting in IP loopbacks. This issue occurred due to replication problems during validation. The fix ensures the server can successfully establish a connection. This issue was observed in standalone switches running AOS-W 8.10.0.8 or later versions.	AOS-W 8.10.0.8
AOS-248337	Multiple APs failed to upgrade to AOS-W 8.10.0.7, causing reboots and high CPU load. This issue was caused due to a calculation error when a large amount of ESSIDs were configured. The fix ensures the APs work as expected. This issue was observed in APs running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-248371	OAW-4750XM switches failed to copy out crash.tar when the file size was larger than 2 GB. The fix ensures the switches work as expected. This issue was observed in OAW-4750XM switches running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-248537	PMF frames from the client were corrupted by switches while decrypting and forwarding them to AP when the client was connected to WPA3 Enterprise (GCM) (256 bit) Tunnel Mode SSIDs. As a result, devices experienced low throughput. This issue was observed in OAW-41xx Series switches and VMC controllers running AOS-W 8.10.0.0 or later versions.	AOS-W 8.10.0.0
AOS-248680 AOS-248673 AOS-249682 AOS-250174 AOS-250197 AOS-251978 AOS-251054 AOS-251324	Some OAW-AP515 and OAW-AP575 access points crashed, rebooted and reconnected to the network. The log files listed the reason for the event as BUGSoftLockup:CPU#1 stuck for 22s! [kworker/1:3:27856] PC:wlc_bmac_suspend_mac_and_wait+0x21c/0x440 [wl_v6] . This issue occurred on a Mobility Conductors-Managed Devices setup after upgrading to from AOS-W 8.10.0.7 to AOS-W 8.10.0.8. The fix ensures the access points perform as expected. This issue was observed in access points running AOS-W 8.10.0.8 or later versions.	AOS-W 8.10.0.8
AOS-248742	A BSSID mismatch was occurring during WPA3 SAE authentication, resulting in frames being sent to incorrect access points. The fix ensures that the values match. This issue was observed in switches running AOS-W 8.10.0.8 or later versions.	AOS-W 8.10.0.8

Table 6: Resolved Issues in AOS-W 8.11.2.2

New Bug ID	Description	Reported Version
AOS-248891	Some OAW-AP515 access points unexpectedly crashed and rebooted. The log files listed the reason for the event as BadPtr:00000d8 PC:wlc_ampdu_dotxstatus_regmpdu+0x700/0xba0 . The fix ensures the APs work as expected. This issue was observed in OAW-AP515 access points running AOS-W 8.10.0.5 or later versions.	AOS-W 8.10.0.5
AOS-248925	In the System > General > Clock page of the WebUI, the Timezone and Date and Time did not display the correct configuration. The fix ensures the correct information is displayed. This issue was observed in switches running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-248972	Some OAW-AP534, OAW-AP535, OAW-AP555, AP-634, OAW-AP635 and OAW-AP655 access points unexpectedly rebooted. The log files listed the reason for the reboot as Reboot caused by WLAN firmware TARGET ASSERT at twt_ap.c:847 . The fix ensures the access points work as expected. This issue was observed in access points running AOS-W 8.10.0.6 or later versions.	AOS-W 8.10.0.6
AOS-249066	The auth process crashed and reloaded, causing connectivity issues when more than 37 dormant IP addresses were associated with a single MAC address. The fix ensures the process works as expected. This issue was observed in switches running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-249123	Some switches crashed unexpectedly due to the impystart process. The fix ensures the process works as expected. This issue was observed in switches running AOS-W 8.10.0.5 or later versions.	AOS-W 8.10.0.5
AOS-249133	Some switches crashed and rebooted with Reboot Cause: Nanny rebooted machine - fpapps process died (Intent:cause: 86:34) . This issue was caused due to a memory leak problem within the fpapps module. The fix ensures switches work as expected. This issue was observed in switches running AOS-W 8.10.0.4 or later versions.	AOS-W 8.10.0.4
AOS-249197	Some AirGroup servers were not discovered by clients. For example, devices such as Mersive Solstice Pods did not appear in Apple clients' screen mirroring device list. This issue was related to AirGroup's refresh logic when using discovery packets, and it was seen when there were 9 or more MDNS service profiles configured in the AirGroup profile. The fix ensures the managed devices work as expected. This issue was observed in managed devices running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-249253	APs failed to establish standby tunnels upon DHCP failure, which caused datapath user, route, and route-cache information to be removed. The fix ensures the APs work as expected. This issue was observed in access points running AOS-W 8.0.0.0 or later versions.	AOS-W 8.10.0.7

Table 6: Resolved Issues in AOS-W 8.11.2.2

New Bug ID	Description	Reported Version
AOS-249589	In some controllers, the STM process was continuously crashing. As a result, it was not possible to terminate access points on the switches. The fix ensures switches perform as expected. This issue was observed in OAW-4550 OmniAccess Mobility Controllers running AOS-W 8.10.0.8 or later versions.	AOS-W 8.10.0.8
AOS-249749	Neighbor AP information was incomplete in the output of the show ap arm state command. The fix ensures the information displays as expected. This issue was observed in APs running AOS-W 8.10.0.8 or later versions.	AOS-W 8.10.0.9
AOS-249754 AOS-249851	The SNMP walk failed to retrieve data for the fan tray OID. The fix ensures the fan tray OID is displayed correctly. This issue was observed in switches running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-249755	Users were able to connect to Mobility Conductors through SSH despite the subnet being disallowed in the ACL port session. The fix ensures only ACL-allowed clients are able to connect. This issue was observed in Mobility Conductors running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-249765	Some APs crashed and rebooted due to memory issues. The issue occurred when TWT statistics for pending session did not match the TWT statistics for the reported session. The fix ensures the APs work as expected. This issue was observed in access points running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-249815	Tunnel performance with MTU 1500 was low. This issue was caused due to the AP's internal Traffic Allocation Framework (TAF). The fix includes an update to the AP driver, which resolves the tunnel performance problem. This issue was observed in controllers running AOS-W 8.11.2.0 or later versions.	AOS-W 8.11.2.0
AOS-249970	The authentication module crashed repeatedly due to an error with unvalidated MAC addresses. The fix ensures that the authentication module in the gateway works as expected. This issue was observed in 9240 controllers running AOS-W 8.10.0.0 or later versions.	AOS-W 8.10.0.0
AOS-249976	The show ap debug radio-stats , show ap debug bss-stats commands and MIB (wlanAPRxDataBytes64) displayed Rx data byte values lower than the actual received values at 5 GHz. The fix ensures the values are accurate. This issue was observed in switches running AOS-W 8.10.0.9 or later versions.	AOS-W 8.10.0.9
AOS-250070	Some APs were unable to upgrade from AOS-W 8.x to AOS-W 10.x. The issue was related to APs getting stuck at the pre-validation stage. The fix ensures that APs can be upgraded successfully. This issue was observed in OAW-AP615 access points running AOS-W 8.11.0.0 or later versions.	AOS-W 8.10.0.8

Table 6: *Resolved Issues in AOS-W 8.11.2.2*

New Bug ID	Description	Reported Version
AOS-250144	OAW-AP635 access points could not establish IPSec tunnels whenever EST certificates were used. Instead, the devices renewed their certificate repeatedly, causing the deletion of the tunnel by the switch. The issue was due to the APs being unable to read EST-related temporary data from their flash memory. The fix ensures APs can access that data and establish a tunnel connection through EST certificates successfully. This issue was observed in OAW-AP635 access points running AOS-W 8.10.0.9 or later versions.	AOS-W 8.10.0.9

This chapter describes the known issues and limitations observed in this release.

Limitations

Following are the limitations observed in this release.

OAW-AP615, OAW-AP635, and OAW-AP655 Access Points

The OAW-AP615, OAW-AP635, and OAW-AP655 access points have the following limitations:

- All radios for these APs currently do not support spectrum analysis.
- 802.11mc responder and initiator functionality, Hotspot configuration, and Air Slice configuration are not supported on the 6 GHz radio.
- Users can configure only up to 4 VAPs on the 6 GHz radio, instead of 16 VAPs.

Airtime Fairness Mode

Airtime Fairness Mode is not supported in 802.11ax access points.

AP-654 and AP-634 Access Points

For the current release of AOS-W, AP-654 and AP-634 access points do not support 6 GHz band operation. Support for 6 GHz will be enabled in a future software release, and will depend on the local regulatory status reflected in the DRT file.

Known Issues

Following are the known issues observed in this release.

Table 7: *Known Issues in AOS-W 8.11.2.2*

New Bug ID	Description	Reported Version
AOS-232277	Some managed devices running AOS-W 8.7.1.5 or later versions display incorrect timestamp for the NTP server. However, the Mobility Conductor displays the correct timestamp.	AOS-W 8.7.1.5
AOS-237931 AOS-242118 AOS-245405	A datapath crash is observed on Ubuntu 20_04 servers if OS type is set to RHEL 7.2 or above. This issue is observed in virtual machines running on AOS-W 8.7.1.11 or later versions.	AOS-W 8.7.1.11

Table 7: Known Issues in AOS-W 8.11.2.2

New Bug ID	Description	Reported Version
AOS-238160 AOS-246310	Some access points running AOS-W 8.11.0.0 or later versions crash and reboot unexpectedly. The log files list the reason of the event as AP Reboot reason: BadPtr: 00000000 PC: anul_probe_req_find_by_mac+0x88/0x1d4 [anul] Warm-reset.	AOS-W 8.11.0.0
AOS-238648 AOS-250171 AOS-247454	The WebUI displays incorrect Tx station throughput statistics for the client. This issue is observed in APs running AOS-W 8.6.0.17 or later versions.	AOS-W 8.6.0.17
AOS-238803 AOS-246511	switches running AOS-W 8.10.0.7 or later versions log continuous error messages such as web_cc Failed GSM publish web_cc_gsm_publish.	AOS-W 8.10.0.7
AOS-238846	The error message Exceeds the max supported vlans 128 displays when creating layer 2 VLANs at folder level. This issue is observed in Mobility Conductors running AOS-W 8.6.0.15 or later versions.	AOS-W 8.6.0.15
AOS-239165	Some OAW-AP635 access points running AOS-W 8.10.0.2 or later versions crash and reboot unexpectedly. The log files list the reason for the event as Reboot caused by kernel panic with "sched_algo_qos.c:3794 Assertion (rtxop > 0) failed".	AOS-W 8.10.0.2
AOS-239324 AOS-238844 AOS-243905	In some OAW-AP535 access points running AOS-W 8.10.0.2 or later versions, users are unable to associate to neighbor APs with deauthentication message Reason Class 2 frames from non authenticated STA. This issue occurs in 5 GHz SSIDs.	AOS-W 8.10.0.2
AOS-239836 AOS-239952 AOS-241189	The Nbapi-Helper process crashes in some OmniAccess Mobility Controllers running AOS-W 8.10.0.2 or later versions. This prevents users from obtaining the feed from the Analytics and Locations Engine (ALE) servers.	AOS-W 8.10.0.2
AOS-239872	The WebUI does not allow users to live upgrade a cluster. However, the CLI allows users to upgrade a cluster. This issue occurs when the name of the cluster contains spaces. This issue is observed in managed devices running AOS-W 8.5.0.0 or later versions.	AOS-W 8.10.0.4
AOS-240026 AOS-236177 AOS-239232 AOS-240068 AOS-240633	Some customers are unable to access switches through the CLI or WebUI. This issue is related to third-party monitoring tools, such as Armis, causing the CLI sessions to remain open for a long time and accumulating memory leaks, affecting the functioning of the controller. This issue is observed in switches running AOS-W 8.6.0.18 or later versions. Workaround: Reboot the switch and periodically log out of the CLI session.	AOS-W 8.6.0.18
AOS-240149	Some OAW-AP635 access points running AOS-W 8.10.0.5 reboot and crash unexpectedly. The log files list the event as Reboot caused by FW crash. The issue is observed on APs running AOS-W 8.10.0.5 or later versions.	AOS-W 8.10.0.5

Table 7: Known Issues in AOS-W 8.11.2.2

New Bug ID	Description	Reported Version
AOS-240240 AOS-243291 AOS-245463	The output of the show ap radio-database command might not display the correct information in Mobility Conductors and managed devices topologies. This issue is observed in Mobility Conductors and managed devices running AOS-W 8.10.0.4 or later versions.	AOS-W 8.10.0.4
AOS-240279	Mobility Conductors running AOS-W 8.10.0.4 or later versions might push additional IGMP and OSPF configurations to managed devices. This issue occurs when a VLAN configuration is edited.	AOS-W 8.10.0.4
AOS-240601 AOS-241185	In some OAW-AP500 Series access points running AOS-W 8.10.0.2 or later versions, the scheduler algorithm causes a delay. This may introduce latency in the MU schedule for multiple clients.	AOS-W 8.10.0.2
AOS-240953	Some OAW-AP635 access points fail to send data frames when configured in tunnel mode using opmode wpa3-sae-aes encryption. Clients are also unable to obtain IP addresses. This issue is caused by PMF drop when the Prohibit IP Spoofing policy is enabled. This issue is observed in APs running AOS-W 8.10.0.4 or later versions.	AOS-W 8.10.0.4
AOS-240954	Some OAW-AP555 access points running AOS-W 8.10.0.5 or later versions crash and reboot unexpectedly. The log files list the reason for the event as Reboot caused by kernel panic: Fatal exception.	AOS-W 8.10.0.5
AOS-241228	In some standby switches, the disable allowlist-sync command can be issued, causing the switches to enter a CONFIG_FAILURE state. This command is intended for primary switches only. This issue is observed in switches running AOS-W 8.10.0.2 or later versions.	AOS-W 8.10.0.2
AOS-241841	Some OmniAccess Mobility Controllers are unable to ping their default gateway and display neighbor entries when using IPv6. This issue is observed in OmniAccess Mobility Controllers running AOS-W 8.10.0.5 or later versions.	AOS-W 8.10.0.5
AOS-241863	The ACL is incomplete in the SAPD and datapath modules, causing connectivity issues. This issue was observed in APs running AOS-W 8.10.0.5 or later versions.	AOS-W 8.10.0.5
AOS-241898	The Configuration > WLANs > VLANs section of the WebUI does not reflect changes made to VLANs. This issue is observed in switches running AOS-W 8.10.0.5 release or later versions.	AOS-W 8.10.0.5
AOS-241957	The WebUI requires specifying a category when adding a logging server in Configuration > System > Logging . This should not be mandatory for logging server configuration. This issue is observed in Mobility Conductors running AOS-W 8.10.0.5 or later versions.	AOS-W 8.10.0.5
AOS-242003	Moving files from OmniAccess Mobility Controllers to FTP using API POST causes the error: /mm/mynode" COMMAND: -- command execution failed. This issue is observed in Mobility Conductors running AOS-W 8.10.0.5 or later versions.	AOS-W 8.10.0.5

Table 7: Known Issues in AOS-W 8.11.2.2

New Bug ID	Description	Reported Version
AOS-242119	In some switches running AOS-W 8.10.0.4 or later versions, policy names are not displayed in alphabetical order in the switch WebUI.	AOS-W 8.10.0.4
AOS-242429	Some controllers fail after a system upgrade from AOS-W 6.5.x to 8.7.1.4 version. Upon reboot, this error is displayed: Failed to set port as trusted, err=Module Process handling LAG and LACP functionality is busy. Please try later. This issue is observed in APs running AOS-W 8.7.1.4 or later versions.	AOS-W 8.7.1.4
AOS-242477 AOS-247390	The Rx Total Control frames Recvd statistics are incorrectly displayed in the WebUI. This issue is observed in OAW-AP500 Series and 600 Series APs running AOS-W 8.6.0.17 or later versions.	AOS-W 8.6.0.17
AOS-243162	switches restricted to Egypt might not display the country code in the output of the show version command. This issue is observed in switches running AOS-W 8.7.1.4 or later versions.	AOS-W 8.7.1.4
AOS-243440 AOS-246926 AOS-247219 AOS-248180 AOS-248919	Some OAW-AP535 access points might crash and reboot unexpectedly. The log files list the reason of the event as Kernel panic: "Takecare of the TARGET ASSERT first". The crash-info displays TARGET ASSERT occurred at ar_wal_monitor.c:911. The issue is observed in access points running AOS-W 8.10.0.5 or later versions.	AOS-W 8.10.0.5
AOS-243749	Some standalone switches are unable to make changes through the WebUI when using standard admin credentials. This issue is observed in switches running AOS-W 8.10.0.6 or later versions.	AOS-W 8.10.0.6
AOS-244165	OmniAccess Mobility Controllers running AOS-W 8.10.0.6 or later versions might include spurious messages stating TOKEN WAS ABSENT as error logs. These messages are intended to appear as debug logs, not error logs.	AOS-W 8.10.0.6
AOS-245191	Some Mobility Conductors are unable to establish an SSH connection to the managed devices due to login sessions not timing out. This issue is observed in managed devices running AOS-W 8.6.0.18 or later versions.	AOS-W 8.6.0.18
AOS-245266 AOS-244968 AOS-248279	Some access points automatically disable their 6 GHz radio bands. This issue is observed in OAW-AP635 and OAW-AP655 access points running AOS-W 8.10.0.6 or later versions.	AOS-W 8.10.0.6
AOS-245976	In some switches, end users can get locked out of configuration mode if there is only one root user present in the Mobility Conductor or standalone node, that does not have the username as admin . Users are allowed to change the role of this sole root user to read-only, standard, or any other role. After this, users cannot make any configurations since there are no root users available in the node. This issue is observed in switches running AOS-W 8.10.0.9 or later versions.	AOS-W 8.10.0.9

Table 7: Known Issues in AOS-W 8.11.2.2

New Bug ID	Description	Reported Version
AOS-246097	Some OAW-AP535 access points randomly disable the ANI feature. The issue is due to an unintended trigger of the ANI periodic check, which disables the feature. This issue is observed in OAW-AP535 access points running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-246409 AOS-246862 AOS-246945 AOS-247150 AOS-248556	Some access points crash and reboot unexpectedly. The log files list the reason for the crash as FW assert PC:0x4b23a454 : ar_wal_tx_send.c:16021 . The issue is related to the AP image version found in previous versions of AOS-W. This issue is observed in OAW-AP500 Series APs running AOS-W 8.10.0.7 or later versions.	AOS-W 8.10.0.7
AOS-246960	OmniAccess Mobility Controller upgrades trigger license changes which cause the unintended loss of configured user-roles and ACLs in managed devices. This issue is observed in OAW-4010 controllers running AOS-W 8.6.0.21 or later versions. Workaround: Reload the managed device or restart the profmgr process to fix the issue.	AOS-W 8.6.0.21
AOS-247326	The output of the show running configuration command might display VLAN IDs and descriptions on separated lines instead of one. This issue is observed in managed devices running AOS-W 8.10.0.8 or later versions.	AOS-W 8.10.0.8
AOS-247335 AOS-247967 AOS-248500	Some 9240 switches reboot with reason Reboot Cause: Datapath timeout . This issue occurs because dpi packets are sent to CPU with ID 0 in some flow. This issue is observed in switches running AOS-W 8.10.0.6 or later versions.	AOS-W 8.10.0.6
AOS-247457 AOS-248519 AOS-249153	Some OAW-4850 switches unexpectedly crash. The log files list the reason as Reboot Cause: Kernel Panic (Intent:cause:register 12:86:0:20) . This issue is observed in switches running AOS-W 8.10.0.5 or later versions.	AOS-W 8.10.0.5
AOS-249560 AOS-250377	Some APs crash and reboot due to a mismatch in Pending twt sessions count and current twt session issues. This issue is observed in OAW-AP535 access points running AOS-W 8.10.0.6 or later versions.	AOS-W 8.10.0.6
AOS-249565	After an upgrade to 8.10.0.9, Central On-Premises is unable to monitor all managed devices and the error Unknown Trusted Certificate. Please upload the certificate before configuring in the profile is displayed when showing the profile error logs. This issue is observed in switches running AOS-W 8.0.0.0 or later versions.	AOS-W 8.10.0.9

This chapter details software upgrade procedures. It is recommended that you schedule a maintenance window for the upgrade.



Read all the information in this chapter before upgrading your Mobility Conductor, managed device, or stand-alone switch.

Important Points to Remember

To upgrade your managed device or Mobility Conductor:

- Schedule the upgrade during a maintenance window and notify your community of the planned upgrade. This prevents users from being surprised by a brief wireless network outage during the upgrade.
- Avoid making any changes to your network, such as configuration changes, hardware upgrades, or changes to the rest of the network during the upgrade. This simplifies troubleshooting.
- Know your network and verify the state of the network by answering the following questions:
 - How many APs are assigned to each managed device? Verify this information by navigating to the **Dashboard > Access Points** page in the WebUI, or by executing the **show ap active** or **show ap database** commands.
 - How are those APs discovering the managed device (DNS, DHCP Option, Broadcast)?
 - What version of AOS-W runs on your managed device?
 - Are all managed devices running the same version of AOS-W?
 - What services are used on your managed device (employee wireless, guest access, OAW-RAP, wireless voice)?
- Resolve any existing issues (consistent or intermittent) before you upgrade.
- If possible, use FTP to load AOS-W images to the managed device. FTP is faster than TFTP and offers more resilience over slow links. If you must use TFTP, ensure the TFTP server can send over 30 MB of data.
- Always upgrade the non-boot partition first. If you encounter any issue during the upgrade, you can restore the flash, and switch back to the boot partition. Upgrading the non-boot partition gives you a smoother downgrade path, if required.
- Before you upgrade to this version of AOS-W, assess your software license requirements and load any new or expanded licenses that you might require. For a detailed description of these new license modules, refer the *Alcatel-Lucent Mobility Conductor Licensing Guide*.
- With the introduction of the Long Supported Release (LSR) and Short Supported Release (SSR) terminology in AOS-W 8.10.0.0, a Mobility Conductor running an LSR release supports managed devices running the same release and the three preceding releases. This is considered as N-3 support. This allows a customer to run the latest LSR, the previous SSRs and the previous LSR simultaneously. A Mobility Conductor running an SSR release supports managed devices running the same release and the two preceding releases. This would be considered N-2 support and is the same behavior as the pre-AOS-W 8.10.0.0 MultiVersion support.

- Only for the AOS-W 8.10.0.0 LSR release, AOS-W 8.6.0.0 is treated as an LSR despite being beyond N-3. As such a Mobility Conductor running AOS-W 8.10.0.0 supports managed devices running AOS-W 8.10.0.0, AOS-W 8.9.0.0, AOS-W 8.8.0.0, AOS-W 8.7.0.0 and AOS-W 8.6.0.0.

Memory Requirements

All Alcatel-Lucent managed devices store critical configuration data on an onboard compact flash memory module. Ensure that there is always free flash space on the managed device. Loading multiple large files such as JPEG images for RF Plan can consume flash space quickly. Following are best practices for memory management:

- Do not proceed with an upgrade unless 100 MB of free memory is available. Execute the **show memory** command to identify the available free memory. To recover memory, reboot the managed device. After the managed device comes up, upgrade immediately.
- Do not proceed with an upgrade unless the minimum flash space is available. Execute the **show storage** command to identify the available flash space. If the output of the **show storage** command indicates that there is insufficient flash memory, free some used memory. Copy any log files, crash data, or flash backups from your managed device to a desired location. Delete the following files from the managed device to free some memory:
 - **Crash data:** Execute the **tar crash** command to compress crash files to a file named **crash.tar**. Use the procedures described in [Backing up Critical Data on page 29](#) to copy the **crash.tar** file to an external server. Execute the **tar clean crash** command to delete the file from the managed device.
 - **Flash backups:** Use the procedures described in [Backing up Critical Data on page 29](#) to back up the flash directory to a file named **flash.tar.gz**. Execute the **tar clean flash** command to delete the file from the managed device.
 - **Log files:** Execute the **tar logs** command to compress log files to a file named **logs.tar**. Use the procedures described in [Backing up Critical Data on page 29](#) to copy the **logs.tar** file to an external server. Execute the **tar clean logs** command to delete the file from the managed device.



In certain situations, a reboot or a shutdown could cause the managed device to lose the information stored in its flash memory. To avoid such issues, it is recommended that you execute the **halt** command before power cycling.

Deleting a File

You can delete a file using the WebUI or CLI.

In the WebUI

From the Mobility Conductor, navigate to **Diagnostic > Technical Support > Delete Files** and remove any aging log files or redundant backups.

In the CLI

```
(host) #delete filename <filename>
```

Low Free Flash Memory

Sometimes, after extended use, the flash memory might get used up for logs and other files. The AOS-W image has increased in size and this may cause issues while upgrading to newer AOS-W images without cleaning up the flash memory.

Prerequisites

Before you proceed with the freeing up the flash memory:

- Ensure to always backup the configuration and flash memory. Issue the **backup configuration** and **backup flash** commands to backup the configuration and flash.
- Copy the **flashbackup.tar.gz** and **configbackup.tar.gz** files out of the switch. Then delete the **flashbackup.tar.gz** and **configbackup.tar.gz** files from the flash memory of the switch.
- Use only one partition for the upgrade activity and keep the other partition unchanged.

If you use the WebUI to perform an upgrade, a banner on the **Maintenance** page provides the following reminder to have sufficient free flash memory before initiating an upgrade.

For a healthy and stable system it requires free space of 360 MB for AOS v8.3 and 8.5, 570 MB for AOS 8.6 and 8.7 and 450 MB for AOS 8.8 and higher version in the /flash directory. Please make sure minimum required memory is available in /flash before upgrading to newer version.

Freeing up Flash Memory

The following steps describe how to free up the flash memory before upgrading:

1. Check if the available memory in **/flash** is greater than the limits listed in [Table 8](#) for all supported switch models:

Table 8: Flash Memory Requirements

Upgrading from	Upgrading to	Minimum Required Free Flash Memory Before Initiating an Upgrade
8.3.x	8.11.x	360 MB
8.5.x	8.11.x	360 MB
8.6.x	8.11.x	570 MB
8.7.x	8.11.x	570 MB
8.8.x	8.11.x	450 MB
8.9.x	8.11.x	450 MB
8.10.x	8.11.x	450 MB

To check the available free flash memory, issue the **show storage** command. Following is the sample output from a switch with low free flash memory:

```
(host) [mynode] #show storage
Filesystem      Size    Available    Use    %    Mounted on
/dev/usb/flash3 1.4G    1014.2M     386.7M  72%  /flash
```

2. If the available free flash memory is less than the limits listed in [Table 8](#), issue the following commands to free up more memory.
 - **tar crash**
 - **tar clean crash**

- **tar clean logs**
 - **tar clean traces**
3. Issue the **show storage** command again to check if the available space in **/flash** is more than the minimum space required for AOS-W upgrade as listed in [Table 8](#)
 4. **If you are unable to free up sufficient flash memory, contact Technical Support. Do not reboot the switch.**
 5. If sufficient flash memory is available, proceed with the standard AOS-W upgrade. See [Upgrading AOS-W](#).
 6. If a reboot was performed, you may see some of the following errors. Follow the directions below:

- Upgrade using standard procedure. You may see some of the following errors:
 - Error upgrading image: Ancillary unpack failed with tar error (tar: Short header). Please clean up the /flash and try upgrade again.**
 - Error upgrading image: Ancillary unpack failed with tar error (tar: Invalid tar magic). Please clean up the /flash and try upgrade again.**
 - Error upgrading image: Need atleast XXX MB space in /flash for image upgrade, please clean up the /flash and try upgrade again.**
 - Failed updating: [upgradelImageNew.c] extractAncTar (dev: /dev/usb/flash1 imgLoc: /flash/config/ArubaOS_70xx_8.8.0.0-mm-dev_78066**

- If any of the above errors occur, issue the **show image version** command to check for the default boot partition. The partition which was upgraded should become the default partition. Following is the sample output of the **show image version** command:

```
(host) [mynode] #show image version
-----
Partition           : 0:0 (/dev/usb/flash1) **Default boot**
Software Version    : AOS-W 8.9.0.0 (Digitally Signed SHA1/SHA256 - Production
Build)
Build number        : 81046
Label               : 81046
Built on            : Thu Aug 5 22:54:49 PDT 2021
-----
Partition           : 0:1 (/dev/usb/flash2)
Software Version    : AOS-W 8.7.0.0-2.3.1.0 (Digitally Signed SHA1/SHA256 -
Developer/Internal Build)
Build number        : 0000
Label               : arpitg@sdwan-2.3_arpitg-3-ENG.0000
Built on            : Tue Aug 10 15:02:15 IST 2021
-----
```

- If the default boot partition is not the same as the one where you performed the upgrade, change the default boot partition. Issue the **boot system partition <part_number>** command to change the default boot partition. Enter **0** or **1** for **part_number** representing partition 0:0 or partition 0:1, respectively.
- Reload the switch. If any of the errors listed in step 4 were observed, the following errors might occur while booting AOS-W 8.9.0.0.

```
Sample error:
[03:17:17]:Installing ancillary FS [ OK ]
Performing integrity check on ancillary partition 1 [ FAIL : Validating new
ancillary partition 1...Image Integrity check failed for file
/flash/img1/mswitch/sap/arm32.ari. Digest Mismatch]
Extracting Webui files..tar: Short read
chown: /mswitch/webui/*: No such file or directory
```

```
chmod: /mswitch/webui/wms/wms.cgi: No such file or directory
```

- After the switch reboots, the login prompt displays the following banner:

* WARNING: An additional image upgrade is required to complete the *
* installation of the AP and WebUI files. Please upgrade the boot *
* partition again and reload the controller. *

- Repeat steps 1 through 5. If sufficient free flash memory is available, proceed with the standard AOS-W upgrade procedure. See [Upgrading AOS-W](#).
- If sufficient free flash memory is not available, issue the **dir** and **dir flash** commands to identify large files occupying the flash memory.



- Exercise caution while deleting files. Contact Technical Support if you are not sure which large files in the **/flash** directory could be safely deleted to free up the required space.

Issue the **delete filename <filename>** command to delete large files to free more flash memory.

- Check if sufficient flash memory is free as listed in [Table 8](#).
- Proceed with the standard AOS-W upgrade procedure in the same partition. See [Upgrading AOS-W](#).

Backing up Critical Data

It is important to frequently back up all critical configuration data and files on the flash memory to an external server or mass storage device. You should include the following files in these frequent backups:

- Configuration data
- WMS database
- Local user database
- Licensing database
- Custom captive portal pages
- x.509 certificates
- Log files
- Flash backup

Backing up and Restoring Flash Memory

You can backup and restore the flash memory using the WebUI or CLI.

In the WebUI

The following steps describe how to back up and restore the flash memory:

1. In the Mobility Conductor node hierarchy, navigate to the **Maintenance > Configuration Management > Backup** page.
2. Click **Create Backup** to backup the contents of the flash memory to the **flashbackup.tar.gz** file.
3. Click **Copy Backup** to copy the file to an external server.

You can copy the backup file from the external server to the flash memory using the file utility in the **Diagnostics > Technical Support > Copy Files** page.

4. To restore the backup file to the flash memory, navigate to the **Maintenance > Configuration Management > Restore** page and click **Restore**.

In the CLI

The following steps describe how to back up and restore the flash memory:

1. Execute the following command in the **enable** mode:

```
(host) #write memory
```

2. Execute the following command to back up the contents of the flash memory to the **flashbackup.tar.gz** file.

```
(host) #backup flash
Please wait while we take the flash backup.....
File flashbackup.tar.gz created successfully on flash.
Please copy it out of the controller and delete it when done.
```

3. Execute either of the following command to transfer the flash backup file to an external server or storage device.

```
(host) #copy flash: flashbackup.tar.gz ftp: <ftphost> <ftpusername> <ftpuserpassword>
<remote directory>
```

```
(host) #copy flash: flashbackup.tar.gz usb: partition <partition-number>
```

You can transfer the flash backup file from the external server or storage device to the flash memory by executing either of the following command:

```
(host) #copy tftp: <tftphost> <filename> flash: flashbackup.tar.gz
```

```
(host) #copy usb: partition <partition-number> <filename> flash: flashbackup.tar.gz
```

4. Execute the following command to untar and extract the **flashbackup.tar.gz** file to the flash memory.

```
(host) #restore flash
Please wait while we restore the flash backup.....
Flash restored successfully.
Please reload (reboot) the controller for the new files to take effect.
```

Upgrading AOS-W

Upgrade AOS-W using the WebUI or CLI.



CAUTION

Ensure that there is enough free memory and flash space on your Mobility Conductor or managed device. For details, see [Memory Requirements on page 26](#).



NOTE

When you navigate to the **Configuration** tab in the WebUI, the managed device might display the **Error getting information: command is not supported on this platform** message. This message is displayed ccurs when you upgrade using the WebUI and navigate to the **Configuration** tab after the managed device reboots. This message disappears after clearing the Web browser cache.

In the WebUI

The following steps describe how to upgrade AOS-W from a TFTP server, FTP server, or local file.

1. Download the AOS-W image from the customer support site.
2. Upload the AOS-W image to a PC or workstation on your network.
3. Validate the SHA hash for the AOS-W image:
 - a. Download the **Alcatel.sha256** file from the download directory.
 - b. Load the AOS-W image to a Linux system and execute the **sha256sum <filename>** command. Alternatively, use a suitable tool for your operating system that can generate a **SHA256** hash of a file.

- c. Verify that the output produced by this command matches the hash value found on the customer support site.



The AOS-W image file is digitally signed and is verified using RSA2048 certificates preloaded at the factory. The Mobility Conductor or managed device will not load a corrupted AOS-W image.

4. Log in to the AOS-W WebUI from the Mobility Conductor.
5. Navigate to the **Maintenance > Software Management > Upgrade** page.
 - a. Select the **Local File** option from the **Upgrade using** drop-down list.
 - b. Click **Browse** from the **Image file name** to navigate to the saved image file on your PC or workstation.
6. Select the downloaded image file.
7. Choose the partition from the **Partition to Upgrade** option.
8. Enable the **Reboot Controller After Upgrade** toggle switch to automatically reboot after upgrading. If you do not want to reboot immediately, disable this option.



The upgrade does not take effect until reboot. If you chose to reboot after upgrade, the Mobility Conductor or managed device reboots automatically.

9. Select **Save Current Configuration**.
10. Click **Upgrade**.
11. Click **OK**, when the **Changes were written to flash successfully** message is displayed.

In the CLI

The following steps describe how to upgrade AOS-W from a TFTP server, FTP server, or local file.

1. Download the AOS-W image from the customer support site.
2. Open an SSH session to your Mobility Conductor.
3. Execute the **ping** command to verify the network connection between the Mobility Conductor and the SCP server, FTP server, or TFTP server.

```
(host)# ping <ftphost>
```

or

```
(host)# ping <tftphost>
```

or

```
(host)# ping <scphost>
```

4. Execute the **show image version** command to check if the AOS-W image is loaded on the flash partition. The partition number appears in the **Partition** row; **0:0** is partition 0, and **0:1** is partition 1. The active boot partition is marked as **Default boot**.

```
(host) #show image version
```

5. Execute the **copy** command to load the new image to the non-boot partition.

```
(host)# copy ftp: <ftphost> <ftpusername> <image filename> system: partition <0|1>
```

or

```
(host)# copy tftp: <tftphost> <image filename> system: partition <0|1>
```

or

```
(host)# copy scp: <scphost> <scpusername> <image filename> system: partition <0|1>
```

or

```
(host)# copy usb: partition <partition-number> <image filename> system: partition <0|1>
```

6. Execute the **show image version** command to verify that the new image is loaded.

```
(host)# show image version
```

7. Reboot the Mobility Conductor.

```
(host)#reload
```

8. Execute the **show version** command to verify that the upgrade is complete.

```
(host)#show version
```

Verifying the AOS-W Upgrade

Verify the AOS-W upgrade in the WebUI or CLI.

In the WebUI

The following steps describe how to verify that the Mobility Conductor is functioning as expected:

1. Log in to the WebUI and navigate to the **Dashboard > WLANs** page to verify the AOS-W image version.
2. Verify if all the managed devices are up after the reboot.
3. Navigate to the **Dashboard > Access Points** page to determine if your APs are up and ready to accept clients.
4. Verify that the number of APs and clients are as expected.
5. Test a different type of client in different locations, for each access method used.
6. Complete a backup of all critical configuration data and files on the flash memory to an external server or mass storage facility. See [Backing up Critical Data on page 29](#) for information on creating a backup.

In the CLI

The following steps describe how to verify that the Mobility Conductor is functioning as expected:

1. Log in to the CLI to verify that all your managed devices are up after the reboot.
2. Execute the **show version** command to verify the AOS-W image version.
3. Execute the **show ap active** command to determine if your APs are up and ready to accept clients.
4. Execute the **show ap database** command to verify that the number of APs and clients are as expected.
5. Test a different type of client in different locations, for each access method used.
6. Complete a backup of all critical configuration data and files on the flash memory to an external server or mass storage facility. See [Backing up Critical Data on page 29](#) for information on creating a backup.

Downgrading AOS-W

A Mobility Conductor or managed device has two partitions, 0 and 1. If the upgrade fails on one of the partitions, you can reboot the Mobility Conductor or managed device from the other partition.

Pre-requisites

Before you reboot the Mobility Conductor or managed device with the pre-upgrade AOS-W version, perform the following steps:

1. Back up your Mobility Conductor or managed device. For details, see [Backing up Critical Data on page 29](#).
2. Verify that the control plane security is disabled.
3. Set the Mobility Conductor or managed device to boot with the previously saved configuration file.
4. Set the Mobility Conductor or managed device to boot from the partition that contains the pre-upgrade AOS-W version.

When you specify a boot partition or copy an image file to a system partition, Mobility Conductor or managed device checks if the AOS-W version is compatible with the configuration file. An error message is displayed if the boot parameters are incompatible with the AOS-W version and configuration files.

5. After switching the boot partition, perform the following steps:

- Restore the pre-upgrade flash backup from the file stored on the Mobility Conductor or managed device. Do not restore the AOS-W flash backup file.
- Do not import the WMS database.
- If the RF plan is unchanged, do not import it. If the RF plan was changed before switching the boot partition, the changed RF plan does not appear in the downgraded AOS-W version.
- If any new certificates were added in the upgraded AOS-W version, reinstall these certificates in the downgraded AOS-W version.

Downgrade AOS-W version using the WebUI or CLI.

In the WebUI

The following steps describe how to downgrade the AOS-W version:

1. If the saved pre-upgrade configuration file is on an external FTP or TFTP server, copy the file to the Mobility Conductor or managed device by navigating to the **Diagnostics > Technical Support > Copy Files** page.
 - a. From **Select source file** drop-down list, select FTP or TFTP server, and enter the IP address of the FTP or TFTP server and the name of the pre-upgrade configuration file.
 - b. From **Select destination file** drop-down list, select **Flash file system**, and enter a file name (other than default.cfg).
 - c. Click **Copy**.
2. Determine the partition on which your pre-upgrade AOS-W version is stored by navigating to the **Maintenance > Software Management > Upgrade** page. If a pre-upgrade AOS-W version is not stored on your system partition, load it into the backup system partition by performing the following steps:



You cannot load a new image into the active system partition.

- a. Enter the FTP or TFTP server address and image file name.
 - b. Select the backup system partition.
 - c. Enable **Reboot Controller after upgrade**.
 - d. Click **Upgrade**.
3. Navigate to the **Maintenance > Software Management > Reboot** page, select **Save configuration before reboot**, and click **Reboot**.

The Mobility Conductor or managed device reboots after the countdown period.

4. When the boot process is complete, verify that the Mobility Conductor or managed device is using the correct AOS-W version by navigating to the **Maintenance > Software Management > About** page.

In the CLI

The following steps describe how to downgrade the AOS-W version:

1. If the saved pre-upgrade configuration file is on an external FTP or TFTP server, use the following command to copy it to the Mobility Conductor or managed device:

```
(host) # copy ftp: <ftphost> <ftpusername> <image filename> system: partition 1
```

or

```
(host) # copy tftp: <tftphost> <image filename> system: partition 1
```

2. Set the Mobility Conductor or managed device to boot with your pre-upgrade configuration file.

```
(host) # boot config-file <backup configuration filename>
```

3. Execute the **show image version** command to view the partition on which your pre-upgrade AOS-W version is stored.

```
(host) #show image version
```



You cannot load a new image into the active system partition.

4. Set the backup system partition as the new boot partition.

```
(host) # boot system partition 1
```

5. Reboot the Mobility Conductor or managed device.

```
(host) # reload
```

6. When the boot process is complete, verify that the Mobility Conductor or managed device is using the correct AOS-W version.

```
(host) # show image version
```

Before Calling Technical Support

Provide the following information when you call the Technical Support:

- The status of installation (new or existing) and recent changes to network, device, or AP configuration. If there was a configuration change, list the exact configuration steps and commands used.
- A detailed network topology including all the devices in the network with IP addresses and interface numbers.
- The make and model number of the wireless device and NIC, driver date, version, and configuration of the NIC, and the OS version including any service packs or patches.
- The logs and output of the **show tech-support** command.
- The syslog file at the time of the problem.
- The date and time when the problem first occurred. If the problem is reproducible, list the exact steps taken to re-create the problem.
- Any wired or wireless sniffer traces taken during the time of the problem.
- The device site access information.