

# AOS-W Instant 8.11.1.1

## Release Notes

Alcatel·Lucent   
Enterprise

## Copyright Information

The Alcatel-Lucent name and logo are trademarks of Nokia used under license by ALE. To view other trademarks used by affiliated companies of ALE Holding, visit: [www.al-enterprise.com/en/legal/trademarks-copyright](http://www.al-enterprise.com/en/legal/trademarks-copyright). All other trademarks are the property of their respective owners. The information presented is subject to change without notice. Neither ALE Holding nor any of its affiliates assumes any responsibility for inaccuracies contained herein.

© Copyright 2023 ALE International, ALE USA Inc. All rights reserved in all countries.

---

<b>Contents</b>	<b>3</b>
<b>Revision History</b>	<b>4</b>
<b>Release Overview</b>	<b>5</b>
Important Upgrade Information for Clusters that Include OAW-AP320 Series, OAW-AP330 Series, OAW-AP340 Series, and OAW-AP387 Series Access Points	5
<b>Related Documents</b>	<b>5</b>
<b>Supported Browsers</b>	<b>6</b>
<b>Terminology Change</b>	<b>7</b>
Contacting Support	7
<b>What's New</b>	<b>8</b>
<b>Supported Hardware Platforms</b>	<b>9</b>
Deprecated OAW-IAPs	9
<b>Regulatory Updates</b>	<b>11</b>
<b>Resolved Issues</b>	<b>12</b>
<b>Known Issues and Limitations</b>	<b>14</b>
Limitations	14
Known Issues	15
<b>Upgrading an OAW-IAP</b>	<b>16</b>
Upgrading an OAW-IAP Using OmniVista 3600 Air Manager Management Platform	16
Upgrading an OAW-IAP Image Manually Using the WebUI	17
Upgrading an OAW-IAP Image Manually Using CLI	18
Upgrade from AOS-W Instant 6.4.x.x-4.2.x.x to AOS-W Instant 8.11.0.x	19

The following table provides the revision history of this document.

**Table 1:** *Revision History*

Revision	Change Description
Revision 01	Initial release.

This AOS-W Instant release notes includes the following topics:

- [What's New on page 8](#)
- [Supported Hardware Platforms on page 9](#)
- [Regulatory Updates on page 11](#)
- [Resolved Issues on page 12](#)
- [Known Issues and Limitations on page 14](#)
- [Upgrading an OAW-IAP on page 16](#)

For the list of terms, refer to the [Glossary](#).

## Important Upgrade Information for Clusters that Include OAW-AP320 Series, OAW-AP330 Series, OAW-AP340 Series, and OAW-AP387 Series Access Points

Starting from AOS-W Instant 8.11.0.0, OAW-AP320 Series, OAW-AP330 Series, OAW-AP340 Series, and OAW-AP387 Series access points are no longer supported. However, the OAW-AP320 Series, OAW-AP340 Series, and OAW-AP387 Series access points use the Hercules and Draco images, which are also used by AP platforms that have not been deprecated in this release. As such, these images are available for upgrading to AOS-W Instant 8.11.0.0. Attempting to install AOS-W Instant 8.11.x.x firmware on the aforementioned APs may cause these APs to disconnect themselves from the current cluster and form a new cluster running the software version available in their partition.

Therefore, in addition to OAW-AP330 Series access points, please ensure that any OAW-AP320 Series, OAW-AP340 Series, and OAW-AP387 Series access points are removed from the cluster before upgrading it to AOS-W Instant 8.11.x.x.

## Related Documents

The following guides are part of the complete documentation for the Alcatel-Lucent user-centric network:

- *Alcatel-Lucent AP Software Quick Start Guide*
- *AOS-W Instant User Guide*
- *AOS-W Instant CLI Reference Guide*
- *AOS-W Instant REST API Guide*
- *AOS-W Instant Syslog Messages Reference Guide*
- *Alcatel-Lucent OAW-IAP Troubleshooting Guide*

## Supported Browsers

The following browsers are officially supported for use with the AOS-W Instant WebUI:

Web Browser	Operating System
Microsoft Edge (Microsoft Edge 92.0.902.62 and Microsoft EdgeHTML 18.19041) or later	<ul style="list-style-type: none"><li>Windows 10 or later</li><li>macOS</li></ul>
Firefox 107.0.1 or later	<ul style="list-style-type: none"><li>Windows 10 or later</li><li>macOS</li></ul>
Apple Safari 15.4 (17613.1.17.1.13) or later	<ul style="list-style-type: none"><li>macOS</li></ul>
Google Chrome 108.0.5359.71 or later	<ul style="list-style-type: none"><li>Windows 10 or later</li><li>macOS</li></ul>

# Terminology Change

As part of advancing HPE's commitment to racial justice, we are taking a much-needed step in overhauling HPE engineering terminology to reflect our belief system of diversity and inclusion. Some legacy products and publications may continue to include terminology that seemingly evokes bias against specific groups of people. Such content is not representative of our HPE culture and moving forward, Alcatel-Lucent will replace racially insensitive terms and instead use the following new language:

Usage	Old Language	New Language
Campus Access Points + Controllers	Master-Slave	Conductor-Member
Instant Access Points	Master-Slave	Conductor-Member
Switch Stack	Master-Slave	Conductor-Member
Wireless LAN Controller	Mobility Master	Mobility Conductor
Firewall Configuration	Blacklist, Whitelist	Denylist, Allowlist
Types of Hackers	Black Hat, White Hat	Unethical, Ethical

## Contacting Support

**Table 2:** *Contact Information*

Contact Center Online	
Main Site	<a href="https://www.al-enterprise.com">https://www.al-enterprise.com</a>
Support Site	<a href="https://businessportal.al-enterprise.com">https://businessportal.al-enterprise.com</a>
Email	<a href="mailto:ebg_global_supportcenter@al-enterprise.com">ebg_global_supportcenter@al-enterprise.com</a>
Service & Support Contact Center Telephone	
North America	1-800-995-2696
Latin America	1-877-919-9526
EMEA	+800 00200100 (Toll Free) or +1(650)385-2193
Asia Pacific	+65 6240 8484
Worldwide	1-818-878-4507

There are no new features or enhancements introduced in this release.



The following table displays the OAW-IAP platforms supported in AOS-W Instant 8.11.1.x release.

**Table 3:** *Supported OAW-IAP Platforms*

OAW-IAP Platform	Minimum Required AOS-W Instant Software Version
OAW-AP503 Series — OAW-AP503	AOS-W Instant 8.11.1.0 or later
OAW-AP610 Series — OAW-AP615	AOS-W Instant 8.11.0.0 or later
OAW-650 Series — OAW-AP655	AOS-W Instant 8.10.0.0 or later
OAW-630 Series — OAW-AP635	AOS-W Instant 8.9.0.0 or later
OAW-500H Series — OAW-AP503H OAW-560 Series — OAW-AP565 and OAW-AP567	AOS-W Instant 8.7.1.0 or later
OAW-500H Series — OAW-AP505H OAW-518 Series — OAW-AP518 OAW-AP570 Series — OAW-AP574, OAW-AP575, and OAW-AP577 OAW-570EX Series — OAW-AP575EX and OAW-AP577EX	AOS-W Instant 8.7.0.0 or later
OAW-AP500 Series — OAW-AP504 and OAW-AP505	AOS-W Instant 8.6.0.0 or later
OAW-AP530 Series — OAW-AP534 and OAW-AP535 OAW-AP550 Series — OAW-AP535	AOS-W Instant 8.5.0.0 or later
OAW-AP303 Series — OAW-AP303P OAW-AP510 Series — OAW-AP514 and OAW-AP515	AOS-W Instant 8.4.0.0 or later
OAW-AP303 Series — OAW-AP303 OAW-AP318 Series — OAW-AP318 OAW-AP370 Series — OAW-AP374, OAW-AP375, and OAW-AP377	AOS-W Instant 8.3.0.0 or later
OAW-AP360 Series — OAW-AP365 and OAW-AP367	AOS-W Instant 6.5.2.0 or later
OAW-AP300 Series — OAW-IAP304 and OAW-IAP305	AOS-W Instant 6.5.1.0-4.3.1.0 or later
OAW-AP310 Series — OAW-IAP314 and OAW-IAP315	AOS-W Instant 6.5.0.0-4.3.0.0 or later

### Deprecated OAW-IAPs

The following OAW-IAPs are no longer supported from AOS-W Instant 8.11.0.0 onwards:

- OAW-AP203H Series — OAW-AP203H
- OAW-AP203R Series — OAW-AP203R and OAW-AP203RP

- OAW-AP207 Series — OAW-IAP207
- OAW-AP320 Series — OAW-IAP324 and OAW-IAP325
- OAW-AP330 Series — OAW-IAP334 and OAW-IAP335
- OAW-AP340 Series — OAW-AP344 and OAW-AP345

This chapter contains the Downloadable Regulatory Table (DRT) file version introduced in this release. Periodic regulatory changes may require modifications to the list of channels supported by an AP. For a complete list of channels supported by an AP using a specific country domain, access the OAW-IAP Command Line Interface (CLI) and execute the **show ap allowed-channels** command.

For a complete list of countries and the regulatory domains in which the APs are certified for operation, refer to the Downloadable Regulatory Table or the DRT Release Notes at [myportal.al-enterprise.com](http://myportal.al-enterprise.com).

The following DRT file version is part of this release:

- DRT-1.0\_86916

The following issues are resolved in this release.

**Table 4:** Resolved Issues in AOS-W Instant 8.11.1.1

Bug ID	Description	Reported Version
AOS-237750 AOS-239650	An OAW-IAP crashed and rebooted when pre-auth roles was not configured and DPI was enabled. The log file listed the reason for the reboot as <b>BadPtr: 00000000 PC: strncpy+0xc/0x28 Warm-reset</b> . The fix ensures that the AP does not crash when pre-auth roles are not configured. This issue was observed in APs running AOS-W Instant 8.10.0.0 or later versions.	AOS-W Instant 8.10.0.4
AOS-239919	An OAW-IAP connected to a switch port with single stack IPv6 VLAN was unable to obtain DHCPv6 addresses. This caused the AP to revert to IAP mode. The fix ensures that the IPv6 process for obtaining the DHCPv6 addresses is restarted if the AP fails to obtain the addresses. This issue was observed in APs running AOS-W Instant 8.10.0.1 or later versions.	AOS-W Instant 8.10.0.2
AOS-241743 AOS-242212 AOS-244549	Users were unable to connect to the cloud guest SSID, and were being redirected to the Captive Portal page. The log file listed the following reason for the error: <b>Internal Error while getting request ID in radsec server</b> . The fix ensures that users are able to connect to cloud guest SSID without issues. This issue was observed in APs running AOS-W Instant 8.10.0.5 or later versions.	AOS-W Instant 8.10.0.6
AOS-241203	High memory utilization was reported on some OAW-IAPs because the AWC process was consuming high memory. This caused the APs to become unresponsive. The fix ensures that the APs function as expected. This issue was observed in APs running AOS-W Instant 8.10.0.0 or later versions.	AOS-W Instant 8.10.0.0
AOS-241395	Some OAW-IAPs repeatedly formed a connection with PAN firewall despite there being no user connected to the APs. The fix ensures that the APs function as expected. This issue was observed in APs running AOS-W Instant 8.6.0.0 or later versions.	AOS-W Instant 8.6.0.0
AOS-242628	The <b>MIB_WLAN_INDEX</b> entry displayed an incorrect value in <b>MIB_WAP_TABLE</b> . As a result, the correct ESSID of the OAW-IAPs were not displayed in the OmniVista 3600 Air Manager WebUI. The fix ensures that the correct ESSID names are displayed. This issue was observed in OmniVista 3600 Air Manager managed OAW-IAP clusters running AOS-W Instant 8.3.0.0 or later versions.	AOS-W Instant 8.3.0.0
AOS-240398	Wireless users did not receive IP addresses from the DHCP server when the software version of OAW-IAPs was upgraded to AOS-W Instant 8.6.0.19 or later. The fix ensures that users receive IP addresses from the server when the AP boots up. This issue was observed in APs running AOS-W Instant 8.6.0.19 or later versions.	AOS-W Instant 8.6.0.19

**Table 4: Resolved Issues in AOS-W Instant 8.11.1.1**

Bug ID	Description	Reported Version
AOS-240805	Users were unable to upgrade the software version of OAW-AP635 and OAW-AP655 access points using REST API. The fix ensures that the software upgrades using REST API are successful for OAW-AP635 and OAW-AP655 access points. This issue was observed in APs running AOS-W Instant 8.10.0.0 or later versions.	AOS-W Instant 8.11.0.0
AOS-242732	AOS-W Instant 802.11ax access points experienced a noticeable performance drop when the <b>air-time-fairness</b> setting was set to <b>fair-access</b> instead of <b>default-access</b> . The issue was related to the <b>air-time-fairness</b> feature not being compatible with modern APs. The fix ensures this configuration does not impact newer APs negatively. This issue was observed in APs running AOS-W Instant 8.11.0.0 or later versions.	AOS-W Instant 8.11.0.0
AOS-241717 AOS-242136	Some AOS-W Instant APs reported high memory utilization due to which clients were unable to connect to the APs. The fix ensures the APs work as expected. The issue was observed in OAW-AP515 access points running AOS-W Instant 8.0.0.0 or later versions.	AOS-W Instant 8.0.0.0
AOS-242056	A delay in IDS to classify OAW-IAPs as rogue was observed in OAW-AP535 access points running AOS-W Instant 8.10.0.5 or later versions. This issue occurred because the time taken to detect the rogue AP included the scanning duration time. This issue was fixed by changing the rogue classification delay from monitored time to discovered time.	AOS-W Instant 8.10.0.5
AOS-242512	The dynamic TACACS proxy authentication process did not work as expected in APs running AOS-W Instant 8.11.0.1 or later versions. The fix ensures this process works as intended.	AOS-W Instant 8.11.0.1
AOS-239969	The AWC/WSC code was sending continuous ERR and WARN logs causing syslog spam. The fix ensures that the OAW-IAP work as expected. This issue was observed in AP clusters running AOS-W Instant 8.10.0.7 or later versions.	AOS-W Instant 8.10.0.7
AOS-240507	The output of the <b>iftype</b> command displays incorrect SNMP values. The fix ensures that the <b>iftype</b> command displays the correct SNMP values. This issue is observed in APs running AOS-W Instant 8.6.0.0 or later versions.	AOS-W Instant 8.7.1.11
AOS-242813	In some OAW-AP635 access points, the SSID was not hidden on 6 GHz radio after <b>hide-ssid</b> was enabled. The fix ensures the SSID is hidden in this scenario. This issue was observed in APs running AOS-W Instant 8.10.0.0 or later versions.	AOS-W Instant 8.10.0.0

This chapter describes the known issues and limitations observed in this release.

### Limitations

This section describes the limitations in AOS-W Instant 8.11.1.1.

#### OAW-AP615, OAW-AP635, and OAW-AP655 Access Points

The OAW-AP615, OAW-AP635, and OAW-AP655 access points have the following limitations:

- All radios for these APs currently do not support spectrum analysis.
- 802.11mc responder and initiator functionality, Hotspot configuration, and Air Slice configuration are not supported on the 6 GHz radio.
- Users can configure only up to 4 VAPs on the 6 GHz radio, instead of 16 VAPs.

#### Air Slice

Air Slice is partially enabled on OAW-AP500 Series and OAW-AP510 Series access points. However, WMM boost will be functional even if Air Slice high-priority queuing is disabled.

#### Airtime Fairness Mode

Airtime Fairness Mode is not supported in 802.11ax access points.

#### AP Hostname Character Limit Extension

The number of ASCII characters allowed in the OAW-IAP hostname is increased from 32 to 128 characters. The following configuration settings do not support the new limit of 128 ASCII characters in AOS-W Instant 8.11.1.0:

- The AP Name field in Role Derivation or VLAN Derivation.
- The AP Name field in beacon and probe response frames.
- The AP Name field in the **show ap mesh link** and **ap mesh neighbor** commands.

#### Dynamic Multicast Optimization Unsupported with VLAN Derivation

AOS-W Instant does not support Dynamic Multicast Optimization when the SSID is configured with VLAN derivation.

#### Inbound Firewall

The **apip-all** configuration is not supported by the **inbound-firewall** command in OAW-IAP cluster deployments. It is only supported in standalone or single-AP modes of deployment.

#### Unified Communications Manager

UCM does not prioritize NAT traffic.

## Known Issues

Following are the known issues observed in this release.

**Table 5:** *Known Issues in AOS-W Instant 8.11.1.1*

Bug ID	Description	Reported Version
AOS-237965 AOS-237699	View-only users are unable to perform debug operations. This issue occurs when the user is able to log in while the OAW-IAP is in a degraded state. This issue is observed in APs running AOS-W Instant 8.10.0.2 or later versions.	AOS-W Instant 8.10.0.2
AOS-238326	An OAW-IAP crashes and reboots due to high memory utilization. The log file lists the reason for the event as <b>Reboot caused by kernel panic: MemLeak: mem low for 60 seconds, under OMB 10 times, MB free 11 (4%), total 247</b> . This issue is observed in APs with less than 256 MB RAM and OAW-AP203H access points running AOS-W Instant 8.6.0.18 or later versions.	AOS-W Instant 8.6.0.18
AOS-238799 AOS-239104	Clients experience connectivity issues when attempting to connect to an SSID using native VLAN. This issue occurs when LACP is configured with an uplink switch on the OAW-IAP. This issue is observed in APs running AOS-W Instant 8.9.0.2 or later versions.	AOS-W Instant 8.9.0.2
AOS-240266	An OAW-IAP rejects association requests. The log file lists the reason as <b>AP is resource constrained-Max Clients Associated</b> . This issue occurs even though there are no clients associated with the AP. This issue is observed in APs running AOS-W Instant 8.6.0.0 or later versions.	AOS-W Instant 8.10.0.3
AOS-240901	When the hostname of an OAW-IAP is changed, <b>\n</b> is appended to the name in the Discover packet. The DHCP server is unable to create or update the record on the DNS server. This issue is observed in APs running AOS-W Instant 8.10.0.4 or later versions.	AOS-W Instant 8.10.0.5
AOS-241107	Incorrect IPv6 addresses are generated when the software version of the OAW-IAP is upgraded to AOS-W Instant 8.9.0.0 or later. This issue is observed in APs running AOS-W Instant 8.9.0.0 or later versions.	AOS-W Instant 8.11.0.0
AOS-242197	The output of the <b>show ap arm rf-summar</b> and <b>show ap monitor ap-list</b> commands is blank. The output of the <b>show ap debug radio-stats 0</b> command displays the following error message: <b>Command Failed: radio 0 down</b> . This issue occurs when the software version of the OAW-IAP is upgraded to AOS-W Instant 8.10.0.5 or later. This issue is observed in OAW-AP387 access points running AOS-W Instant 8.10.0.5 or later versions.	AOS-W Instant 8.10.0.5

This chapter describes the AOS-W Instant software upgrade procedures and the different methods for upgrading the image on the OAW-IAP.



---

While upgrading an OAW-IAP, you can use the image check feature to allow the OAW-IAP to find new software image versions available on a cloud-based image server hosted and maintained by Alcatel-Lucent. The location of the image server is fixed and cannot be changed by the user. The image server is loaded with the latest versions of the AOS-W Instant software.

---

Topics in this chapter include:

- [Upgrading an OAW-IAP Using OmniVista 3600 Air Manager Management Platform on page 16](#)
- [Upgrading an OAW-IAP Image Manually Using the WebUI on page 17](#)
- [Upgrading an OAW-IAP Image Manually Using CLI on page 18](#)
- [Upgrade from AOS-W Instant 6.4.x.x-4.2.x.x to AOS-W Instant 8.11.0.x on page 19](#)

## Upgrading an OAW-IAP Using OmniVista 3600 Air Manager Management Platform

If the multi-class OAW-IAP network is managed by OmniVista 3600 Air Manager, image upgrades can only be done through the OmniVista 3600 Air Manager WebUI. The OAW-IAP images for different classes must be uploaded on the AMP server. If new OAW-IAPs joining the network need to synchronize their software with the version running on the virtual Switch, and if the new OAW-IAP belongs to a different class, the image file for the new OAW-IAP is provided by OmniVista 3600 Air Manager. If OmniVista 3600 Air Manager does not have the appropriate image file, the new OAW-IAP will not be able to join the network.



---

The virtual Switch communicates with the OmniVista 3600 Air Manager server if OmniVista 3600 Air Manager is configured. If OmniVista 3600 Air Manager is not configured on the OAW-IAP, the image is requested from the Image server.

---

## HTTP Proxy Support through Zero Touch Provisioning

OAW-IAPs experience issues when connecting to OmniVista 3600 Air Manager, or Activate through the HTTP proxy server which requires a user name and password. The ideal way to provide seamless connectivity for these cloud platforms is to supply the proxy information to the OAW-IAP through a DHCP server.

Starting with AOS-W Instant 8.4.0.0, besides being able to authenticate to the HTTP proxy server, the factory default OAW-IAPs can also communicate with the server through a HTTP proxy server DHCP which does not require authentication.

In order for the factory default OAW-IAP to automatically discover the proxy server, you need to configure the HTTP proxy information in the DHCP server option. The OAW-IAP will receive the proxy information and store it in a temporary file.



To retrieve the port and the proxy server information, you need to first configure the DHCP **option 60** to **ArubaInstantAP** as shown below:

```
(Instant AP) (config)# ip dhcp <profile_name>
(Instant AP) ("IP DHCP profile-name")# option 60 ArubaInstantAP
```

Secondly, use the following command to configure the proxy server:

```
(Instant AP) (config)# proxy server <host> <port> [<username> <password>]
```

Use the text string **option 148 text server=host\_ip,port=PORT,username=USERNAME,password=PASSWORD** to retrieve the details of the proxy server.

## Rolling Upgrade on OAW-IAPs with OmniVista 3600 Air Manager

Starting from AOS-W Instant 8.4.0.0, Rolling Upgrade for OAW-IAPs in standalone mode is supported with OmniVista 3600 Air Manager. The upgrade is orchestrated through NMS and allows the OAW-IAPs deployed in standalone mode to be sequentially upgraded such that the APs upgrade and reboot one at a time. With Rolling Upgrade, the impact of upgrading a site is reduced to a single AP at any given point in time. This enhances the overall availability of the wireless network. For more information, see *OmniVista 3600 Air Manager 8.2.8.2 AOS-W Instant Deployment Guide* and *OmniVista 3600 Air Manager 8.2.8.2 Release Notes*.

## Upgrading an OAW-IAP Image Manually Using the WebUI

You can manually obtain an image file from a local file system or from a remote server accessed using a TFTP, FTP or HTTP URL.

The following procedure describes how to manually check for a new firmware image version and obtain an image file using the webUI:

1. Navigate to **Maintenance > Firmware**.
2. Expand **Manual** section.
3. The firmware can be upgraded using a downloaded image file or a URL of an image file.
  - a. To update firmware using a downloaded image file:
    - i. Select the **Image file** option. This method is only available for single-class OAW-IAPs.
    - ii. Click on **Browse** and select the image file from your local system. The following table describes the supported image file format for different OAW-IAP models:

Access Points	Image File Format
OAW-AP514, OAW-AP515, OAW-AP518, OAW-AP574, OAW-AP575, OAW-AP575EX, OAW-AP577, and OAW-AP577EX	AlcatelInstant_Draco_8.11.0.x_xxxx
OAW-AP503H, OAW-AP504, OAW-AP505, OAW-AP505H, OAW-AP565, and OAW-AP567.	AlcatelInstant_Gemini_8.11.0.x_xxxx

Access Points	Image File Format
OAW-IAP314, OAW-IAP315, OAW-AP374, OAW-AP375, OAW-AP377, and OAW-AP318.	AlcatelInstant_Hercules_8.11.0.x_xxxx
OAW-AP534, OAW-AP535, OAW-AP535, OAW-AP584, OAW-AP585, OAW-AP585EX, OAW-AP587, and OAW-AP587EX	AlcatelInstant_Scorpio_8.11.0.x_xxxx
OAW-AP303, OAW-AP303H, OAW-AP303P Series, OAW-IAP304, OAW-IAP305, OAW-AP365, and OAW-AP367	AlcatelInstant_Ursa_8.11.0.x_xxxx

- b. To upgrade firmware using the URL of an image file:
- i. Select the **Image URL** option to obtain an image file from a HTTP, TFTP, or FTP URL.
  - ii. Enter the image URL in the **URL** text field. The syntax to enter the URL is as follows:
    - HTTP - http://<IP-address>/<image-file>. For example, http://<IP-address>/AlcatelInstant\_Hercules\_8.11.0.x\_xxxx
    - TFTP - tftp://<IP-address>/<image-file>. For example, tftp://<IP-address>/AlcatelInstant\_Hercules\_8.11.0.x\_xxxx
    - FTP - ftp://<IP-address>/<image-file>. For example, ftp://<IP-address>/AlcatelInstant\_Hercules\_8.11.0.x\_xxxx
    - FTP - ftp://<user name:password>@<IP-address>/<image-file>. For example, ftp://alcatel:123456@<IP-address>/AlcatelInstant\_Hercules\_8.11.0.x\_xxxx



The FTP server supports both **anonymous** and **username:password** login methods.

Multiclass OAW-IAPs can be upgraded only in the URL format, not in the local image file format.

4. Disable the **Reboot all APs after upgrade** toggle switch if required. This option is enabled by default to allow the OAW-IAPs to reboot automatically after a successful upgrade. To reboot the OAW-IAP at a later time, clear the **Reboot all APs after upgrade** check box.
5. Click **Upgrade Now** to upgrade the OAW-IAP to the newer version.
6. Click **Save**.

## Upgrading an OAW-IAP Image Manually Using CLI

The following procedure describes how to upgrade an image using a HTTP, TFTP, or FTP URL:

```
(Instant AP) # upgrade-image <ftp/tftp/http-URL>
```

The following is an example to upgrade an image by using the FTP URL :

```
(Instant AP) # upgrade-image ftp://192.0.2.7/AlcatelInstant_Hercules_8.11.0.x_xxxx
```

The following procedure describes how to upgrade an image without rebooting the OAW-IAP:

```
(Instant AP)# upgrade-image2-no-reboot <ftp/tftp/http-URL>
```

The following is an example to upgrade an image without rebooting the OAW-IAP:

```
(Instant AP)# upgrade-image2-no-reboot ftp://192.0.2.7/Alcatel_Instant_Hercules_8.11.0.x_xxxx
```

The following command describes how to view the upgrade information:

```
(Instant AP)# show upgrade info
Image Upgrade Progress
-----
Mac IP Address AP Class Status Image Info Error Detail
-----
d8:c7:c8:c4:42:98 10.17.101.1 Hercules image-ok image file none
Auto reboot :enable
Use external URL :disable
```

## Upgrade from AOS-W Instant 6.4.x.x-4.2.x.x to AOS-W Instant 8.11.0.x

Before you upgrade an OAW-IAP running AOS-W Instant 6.5.4.0 or earlier versions to AOS-W Instant 8.11.0.x, follow the procedures mentioned below:

1. Upgrade from AOS-W Instant 6.4.x.x-4.2.x.x or any version prior to AOS-W Instant 6.5.4.0 to AOS-W Instant 6.5.4.0.
2. Refer to the *Field Bulletin AP1804-1* at [myportal.al-enterprise.com](http://myportal.al-enterprise.com).
3. Verify the affected serial numbers of the OAW-IAP units.