

AOS-W Instant 8.7.1.8

Release Notes

Alcatel·Lucent 
Enterprise

Copyright Information

Alcatel-Lucent and the Alcatel-Lucent Enterprise logo are trademarks of Alcatel-Lucent. To view other trademarks used by affiliated companies of ALE Holding, visit:

<https://www.al-enterprise.com/en/legal/trademarks-copyright>

All other trademarks are the property of their respective owners. The information presented is subject to change without notice. Neither ALE Holding nor any of its affiliates assumes any responsibility for inaccuracies contained herein. (2022)

Open Source Code

This product includes code licensed under the GNU General Public License, the GNU Lesser General Public License, and/or certain other open source licenses.

Contents	3
Revision History	4
Release Overview	5
Related Documents	5
Supported Browsers	5
Terminology Change	6
Contacting Support	6
New Features and Enhancements	7
Supported Hardware Platforms	8
Regulatory Updates	9
Resolved Issues	10
Known Issues	11
Limitations	11
Known Issues	11
Upgrading an OAW-IAP	15
Upgrading an OAW-IAP Using OmniVista 3600 Air Manager Management Platform	15
Upgrading an OAW-IAP Image Manually Using WebUI	16
Upgrading an OAW-IAP Image Manually Using CLI	19
Upgrade from AOS-W Instant 6.4.x.x-4.2.x.x to AOS-W Instant 8.7.1.x	19

The following table provides the revision history of this document.

Table 1: *Revision History*

Revision	Change Description
Revision 01	Initial release.

This AOS-W Instant release notes includes the following topics:

- [New Features and Enhancements on page 7](#)
- [Supported Hardware Platforms on page 8](#)
- [Regulatory Updates on page 9](#)
- [Resolved Issues on page 10](#)
- [Known Issues on page 11](#)
- [Upgrading an OAW-IAP on page 15](#)

For the list of terms, refer to the [Glossary](#).

Related Documents

The following guides are part of the complete documentation for the Alcatel-Lucent user-centric network:

- *Alcatel-Lucent AP Software Quick Start Guide*
- *AOS-W Instant User Guide*
- *AOS-W Instant CLI Reference Guide*
- *AOS-W Instant REST API Guide*
- *AOS-W Instant Syslog Messages Reference Guide*
- *Alcatel-Lucent OAW-IAP Troubleshooting Guide*

Supported Browsers

The following browsers are officially supported for use with the AOS-W Instant WebUI:

- Microsoft Internet Explorer 11 on Windows 7 and Windows 8
- Microsoft Edge (Microsoft Edge 38.14393.0.0 and Microsoft EdgeHTML 14.14393) on Windows 10
- Mozilla Firefox 48 or later on Windows 7, Windows 8, Windows 10, and macOS
- Apple Safari 8.0 or later on macOS
- Google Chrome 67 or later on Windows 7, Windows 8, Windows 10, and macOS

Terminology Change

As part of advancing Alcatel-Lucent's commitment to racial justice, we are taking a much-needed step in overhauling Alcatel-Lucent engineering terminology to reflect our belief system of diversity and inclusion. Some legacy products and publications may continue to include terminology that seemingly evokes bias against specific groups of people. Such content is not representative of our Alcatel-Lucent culture and moving forward, Alcatel-Lucent will replace racially insensitive terms and instead use the following new language:

Usage	Old Language	New Language
Campus Access Points + Controllers	Master-Slave	Conductor-Member
Instant Access Points	Master-Slave	Conductor-Member
Switch Stack	Master-Slave	Conductor-Member
Wireless LAN Controller	Mobility Master	Mobility Conductor
Firewall Configuration	Blacklist, Whitelist	Denylist, Allowlist
Types of Hackers	Black Hat, White Hat	Unethical, Ethical

Contacting Support

Table 2: *Contact Information*

Contact Center Online	
Main Site	https://www.al-enterprise.com
Support Site	https://myportal.al-enterprise.com
Email	ebg_global_supportcenter@al-enterprise.com
Service & Support Contact Center Telephone	
North America	1-800-995-2696
Latin America	1-877-919-9526
EMEA	+800 00200100 (Toll Free) or +1(650)385-2193
Asia Pacific	+65 6240 8484
Worldwide	1-818-878-4507

Chapter 2

New Features and Enhancements

There are no new features or enhancements in this release.

The following table displays the OAW-IAP platforms supported in AOS-W Instant 8.7.1.0 release.

Table 3: *Supported OAW-IAP Platforms*

OAW-IAP Platform	Minimum Required AOS-W Instant Software Version
500H Series — AP-503H 560 Series — AP-565 and AP-567	AOS-W Instant 8.7.1.0 or later
500H Series — OAW-AP505H OAW-AP518 — OAW-AP518 OAW-AP570 Series — OAW-AP574, OAW-AP575, and OAW-AP577 570EX Series — AP-575EX and AP-577EX	AOS-W Instant 8.7.0.0 or later
OAW-AP500 Series — OAW-AP504 and OAW-AP505	AOS-W Instant 8.6.0.0 or later
OAW-AP530 Series — OAW-AP534 and OAW-AP535 OAW-AP550 Series — OAW-AP535	AOS-W Instant 8.5.0.0 or later
OAW-AP303 Series — OAW-AP303P OAW-AP387 Series — OAW-AP387 OAW-AP510 Series — OAW-AP514 and OAW-AP515	AOS-W Instant 8.4.0.0 or later
OAW-AP303 Series — OAW-AP303 OAW-AP318 Series — OAW-AP318 OAW-AP340 Series — OAW-AP344 and OAW-AP345 OAW-AP370 Series — OAW-AP374, OAW-AP375, and OAW-AP377 OAW-AP370EX Series — AP-375EX and AP-375EX	AOS-W Instant 8.3.0.0 or later
203H Series — OAW-AP203H	AOS-W Instant 6.5.3.0 or later
203R Series — OAW-AP203R and OAW-AP203RP OAW-AP303H Series — OAW-AP303H and AP-303HR OAW-AP360 Series — OAW-AP365 and OAW-AP367	AOS-W Instant 6.5.2.0 or later
207 Series — OAW-IAP207 OAW-AP300 Series — OAW-IAP304 and OAW-IAP305	AOS-W Instant 6.5.1.0-4.3.1.0 or later
OAW-AP310 Series — OAW-IAP314 and OAW-IAP315 OAW-AP330 Series — OAW-IAP334 and OAW-IAP335	AOS-W Instant 6.5.0.0-4.3.0.0 or later
OAW-AP320 Series — OAW-IAP324 and OAW-IAP325	AOS-W Instant 6.4.4.3-4.2.2.0 or later

This chapter contains the Downloadable Regulatory Table (DRT) file version introduced in this release.

Periodic regulatory changes may require modifications to the list of channels supported by an AP. For a complete list of channels supported by an AP using a specific country domain, access the Switch Command Line Interface (CLI) and execute the **show ap allowed-channels country-code <country-code> ap-type <ap-model>** command.

For a complete list of countries and the regulatory domains in which the APs are certified for operation, refer to the Downloadable Regulatory Table or the DRT Release Notes at myportal.al-enterprise.com.

The following DRT file version is part of this release:

- DRT-1.0_82868

This chapter describes the issues resolved in this release.

Table 4: *Resolved Issues in AOS-W Instant 8.7.1.8*

Bug ID	Description	Reported Version
AOS-229972 AOS-229991 AOS-230192 AOS-230290 AOS-230416 AOS-230554 AOS-230604 AOS-230721 AOS-230725 AOS-230871	Clients were unable to connect to SSIDs that had the 802.11r option enabled. During this period, commands run in the CLI of the affected AP returned the following error message: Module AP STM Low Priority is busy. Please try later. The fix ensures that SSIDs configured with 802.11r option service the client as expected. This issue was observed in APs running AOS-W Instant 8.3.0.0 or later versions.	AOS-W Instant 8.7.1.6

This chapter describes the known issues and limitations observed in this release.

Limitations

This section describes the limitations in AOS-W Instant 8.7.1.8.

AP Hostname Character Limit Extension

The number of ASCII characters allowed in the OAW-IAP hostname is increased from 32 to 128 characters. The following configuration settings do not support the new limit of 128 ASCII characters in AOS-W Instant 8.7.1.8:

- The AP Name field in Role Derivation or VLAN Derivation.
- The AP Name field in beacon and probe response frames.
- The AP Name field in the **show ap mesh link** and **ap mesh neighbor** commands.

Dynamic Multicast Optimization Unsupported with VLAN Derivation

AOS-W Instant does not support Dynamic Multicast Optimization when the SSID is configured with VLAN derivation.

Unified Communications Manager

UCM does not prioritize NAT traffic.

Known Issues

Following are the known issues observed in this release.

Table 5: *Known Issues in AOS-W Instant 8.7.1.8*

Bug ID	Description	Reported Version
AOS-197400	An OAW-IAP fails to switch uplink interfaces during an uplink failover event. This issue occurs when the OAW-IAP is configured with two Ethernet uplinks. This issue is observed in APs running AOS-W Instant 8.6.0.1 or later versions.	AOS-W Instant 8.6.0.1
AOS-204171	<p>Clients intermittently experience high latency when the AP is connected to the backup Switch after a failover event. This issue occurs under the following scenarios:</p> <ul style="list-style-type: none"> ■ The AP attempts to re-connect to the primary Switch. ■ Fast failover is enabled on the AP. <p>This issue is observed in 203R Series access points running AOS-W Instant 8.3.0.0 or later versions.</p>	AOS-W Instant 8.3.0.0

Table 5: Known Issues in AOS-W Instant 8.7.1.8

Bug ID	Description	Reported Version
AOS-208474	An OAW-IAP frequently disconnects itself from the cluster and then rejoins it. The log file lists the reason for the event as: stm PAPI_Send failed, send_papi_message_with_args, 1215: Resource temporarily unavailable . This issue is observed in APs running AOS-W Instant 8.6.0.5 or later versions.	AOS-W Instant 8.6.0.5
AOS-208648	The system log of an OAW-IAP has a lot of Swarm quit factory default status by : ssid_config messages. This issue is observed in APs running AOS-W Instant 8.7.0.0 or later versions.	AOS-W Instant 8.7.0.0
AOS-209051	Clients are unable to send and receive traffic when AOS-W Instant clusters are configured with L3 mobility. This issue occurs under the following scenarios: <ul style="list-style-type: none"> ■ The client is connected to a cluster other than the home cluster. ■ The network experiences high latency due to an overload caused by a broadcast storm. This issue is observed in APs running AOS-W Instant 8.6.0.4 or later versions.	AOS-W Instant 8.6.0.4
AOS-210290	An OAW-IAP fails to update the service ID of AirGroup services when the service ID is configured through the AOS-W Instant WebUI. This issue occurs when the name of the service ID contains a "." character. This issue is observed in APs running AOS-W Instant 8.7.0.0 or later versions.	AOS-W Instant 8.7.0.0
AOS-210440	Administrator authentication fails when accessing the OAW-IAP through the WebUI. This issue occurs when the administrator password includes special characters such as " or '. This issue is observed in APs running AOS-W Instant 8.6.0.5 or later versions. Workaround: Create an administrator password without special characters.	AOS-W Instant 8.6.0.5
AOS-210688	Apple devices are unable to connect to OAW-IAP225 access points operating as Virtual Switches in mesh deployments. This issue occurs when the AP advertises a Channel Switch Announcement and remains in the same channel. This issue is observed in OAW-IAP225 access points running AOS-W Instant 8.6.0.5 or later versions.	AOS-W Instant 8.6.0.5
AOS-210717 AOS-212956	The Client-view heatmap window in Dashboard > Clients page of the AOS-W Instant WebUI does not display any data. This issue occurs when the number of client match history records exceeds 300. This issue is observed in APs running AOS-W Instant 8.7.0.0 or later versions.	AOS-W Instant 8.7.0.0
AOS-216114 AOS-218476	OAW-IAPs in a cluster report the signal value as 0 in the output of show clients command. This issue occurs when disable-arm-wids-functions is turned on in the cluster. This issue is observed in APs running AOS-W Instant 8.7.1.1 or later versions.	AOS-W Instant 8.7.1.1
AOS-217468	The webUI of an OAW-IAP freezes when a new configuration change is applied through the webUI or the CLI. When this issue occurs, the CLI of the conductor AP and the member APs become inaccessible. This issue is observed in APs running AOS-W Instant 8.7.1.1 or later versions.	AOS-W Instant 8.7.1.1

Table 5: Known Issues in AOS-W Instant 8.7.1.8

Bug ID	Description	Reported Version
AOS-217829	The new webUI in OAW-IAPs does not update the status of member APs when they are disconnected from the network. This issue is observed in APs running AOS-W Instant 8.6.0.4 or later versions.	AOS-W Instant 8.6.0.4
AOS-218436 AOS-219302	Zebra scanners are unable to connect to some OAW-AP510 Series access points. This issue is observed in OAW-AP510 Series access points running AOS-W Instant 8.5.0.7 or later versions.	AOS-W Instant 8.5.0.7
AOS-218704 AOS-220857	Some VoIP calls are not sent to the server to be recorded. This issue occurs when: <ul style="list-style-type: none"> ■ The server recording the calls is behind the Switch. ■ Some APs in the cluster are rebooted. This issue is observed in APs running AOS-W Instant 8.6.0.4 or later versions.	AOS-W Instant 8.6.0.4
AOS-218761 AOS-224026	The webUI of the OAW-IAP fails to sort APs according to client count when clicking on the Clients column label in the Dashboard > Access Points page of the AOS-W Instant webUI. This issue is observed in APs running AOS-W Instant 8.7.1.1 or later version.	AOS-W Instant 8.7.1.1
AOS-218919	The AOS-W Instant UI allows a VLAN to be configured as both the VC VLAN and CL2 VLAN. This issue occurs when the CL2 VLAN is configured first and the same VLAN is configured as the VC VLAN. This issue is observed in APs running AOS-W Instant 8.6.0.4 or later versions.	AOS-W Instant 8.6.0.4
AOS-218974	iPhone clients running iOS 14 or later versions are unable to connect to SSIDs when a HotSpot2.0 profile is mapped to it. This issue occurs when a HotSpot 2.0 profile is not configured on the iOS device. This issue is observed in APs running AOS-W Instant 8.6.0.4 or later versions. Workaround: Configure a Hotspot 2.0 profile in the iOS device.	AOS-W Instant 8.6.0.4
AOS-219592	Clients receive router advertisement packets from VLANs other than the assigned VLAN. This issue is observed in SSIDs configured with Dynamic VLAN assignment. This issue is observed in APs running AOS-W Instant 8.6.0.7 or later versions.	AOS-W Instant 8.6.0.7
AOS-219998	The NTP module of an OAW-IAP is stuck in the INIT state. This issue occurs when the NTP server returns an IPv6 address. This issue is observed in APs running AOS-W Instant 8.7.1.2 or later versions.	AOS-W Instant 8.7.1.2
AOS-220385	Clients randomly lose internet connectivity. During this period the affected clients are only able to pass Layer 2 traffic. This issue is observed in APs running AOS-W Instant 8.7.1.3 or later versions. Workaround: Enable the he-mu-mimo-disable parameter in the SSID profile using the CLI.	AOS-W Instant 8.7.0.0
AOS-222909	The show usb-enet command fails to display the list of all USB devices connected to an OAW-IAP cluster. This issue is observed in OAW-IAP clusters running AOS-W Instant 8.6.0.6 or later versions.	AOS-W Instant 8.6.0.6
AOS-222714 AOS-223758	An OAW-AP515 access point crashes and reboots unexpectedly. The log file lists the reason for reboot as: Reboot Time and Cause: AP Reboot reason: BadAddr:403c02bdbbec8 PC:wlc_key_get_info+0x10/0x60 [wl_v6] Warm-reset . This issue is observed in APs running AOS-W Instant 8.7.0.0 or later versions.	AOS-W Instant 8.7.0.0

Table 5: *Known Issues in AOS-W Instant 8.7.1.8*

Bug ID	Description	Reported Version
AOS-225567	Clients connected to a member AP are getting disconnected with the deauthentication reason: Internal only . Clients reconnect to the APs immediately after disconnection. When this occurs the status of clients in the OAW-IAP is shown as disconnected . This issue occurs when a large number of SNMP requests are sent to the Virtual Switch. This issue is observed in APs running AOS-W Instant 8.6.0.8 or later versions.	AOS-W Instant 8.6.0.8
AOS-226071	Clients connected to an AOS-W Instant network randomly encounter a DNS error and lose internet connectivity. The debug log of the OAW-IAP lists the reason for error as: Drop the pkt as we don't know the vlan device on which to send the ARP request . This issue is observed in APs running AOS-W Instant 8.7.1.4 or later versions.	AOS-W Instant 8.7.1.4
AOS-226248	The output of the show datapath user table does not include the information of some clients configured with a static IP address. This issue is observed in APs running AOS-W Instant 8.6.0.7 or later versions.	AOS-W Instant 8.6.0.7

This chapter describes the AOS-W Instant software upgrade procedures and the different methods for upgrading the image on the OAW-IAP.



While upgrading an OAW-IAP, you can use the image check feature to allow the OAW-IAP to find new software image versions available on a cloud-based image server hosted and maintained by Alcatel-Lucent. The location of the image server is fixed and cannot be changed by the user. The image server is loaded with the latest versions of the AOS-W Instant software.

Topics in this chapter include:

- [Upgrading an OAW-IAP Using OmniVista 3600 Air Manager Management Platform on page 15](#)
- [Upgrading an OAW-IAP Image Manually Using WebUI on page 16](#)
- [Upgrading an OAW-IAP Image Manually Using CLI on page 19](#)
- [Upgrade from AOS-W Instant 6.4.x.x-4.2.x.x to AOS-W Instant 8.7.1.x on page 19](#)

Upgrading an OAW-IAP Using OmniVista 3600 Air Manager Management Platform

If the multi-class OAW-IAP network is managed by OmniVista 3600 Air Manager, image upgrades can only be done through the OmniVista 3600 Air Manager WebUI. The OAW-IAP images for different classes must be uploaded on the AMP server. If new OAW-IAPs joining the network need to synchronize their software with the version running on the virtual Switch, and if the new OAW-IAP belongs to a different class, the image file for the new OAW-IAP is provided by OmniVista 3600 Air Manager. If OmniVista 3600 Air Manager does not have the appropriate image file, the new OAW-IAP will not be able to join the network.



The virtual Switch communicates with the OmniVista 3600 Air Manager server if OmniVista 3600 Air Manager is configured. If OmniVista 3600 Air Manager is not configured on the OAW-IAP, the image is requested from the Image server.

HTTP Proxy Support through Zero Touch Provisioning

OAW-IAPs experience issues when connecting to OmniVista 3600 Air Manager, or Activate through the HTTP proxy server which requires a user name and password. The ideal way to provide seamless connectivity for these cloud platforms is to supply the proxy information to the OAW-IAP through a DHCP server.

Starting with AOS-W Instant 8.4.0.0, besides being able to authenticate to the HTTP proxy server, the factory default OAW-IAPs can also communicate with the server through a HTTP proxy server DHCP which does not require authentication.

In order for the factory default OAW-IAP to automatically discover the proxy server, you need to configure the HTTP proxy information in the DHCP server option. The OAW-IAP will receive the proxy information and store it in a temporary file.

To retrieve the port and the proxy server information, you need to first configure the DHCP **option 60** to **ArubaInstantAP** as shown below:

```
(Instant AP) (config)# ip dhcp <profile_name>
(Instant AP) ("IP DHCP profile-name")# option 60 ArubaInstantAP
```

Secondly, use the following command to configure the proxy server:

```
(Instant AP) (config)# proxy server <host> <port> [<username> <password>]
```

Use the text string **option 148 text server=host_ip,port=PORT,username=USERNAME,password=PASSWORD** to retrieve the details of the proxy server.

Rolling Upgrade on OAW-IAPs with OmniVista 3600 Air Manager

Starting from AOS-W Instant 8.4.0.0, Rolling Upgrade for OAW-IAPs in standalone mode is supported with OmniVista 3600 Air Manager. The upgrade is orchestrated through NMS and allows the OAW-IAPs deployed in standalone mode to be sequentially upgraded such that the APs upgrade and reboot one at a time. With Rolling Upgrade, the impact of upgrading a site is reduced to a single AP at any given point in time. This enhances the overall availability of the wireless network. For more information, see *OmniVista 3600 Air Manager 8.2.8.2 AOS-W Instant Deployment Guide* and *OmniVista 3600 Air Manager 8.2.8.2 Release Notes*.

Upgrading an OAW-IAP Image Manually Using WebUI

You can manually obtain an image file from a local file system or from a remote server accessed using a TFTP, FTP or HTTP URL.

In the Old WebUI

To manually check for a new firmware image version and obtain an image file:

1. Navigate to **Maintenance > Firmware**.
2. Under **Manual** section, perform the following steps:
 - a. To update firmware using a downloaded image file:
 - i. Select the **Image file** option. This method is only available for single-class OAW-IAPs.
 - ii. Click on **Browse** and select the image file from your local system. The following table describes the supported image file format for different AP models:

Access Points	Image File Format
OAW-AP344, OAW-AP345, OAW-AP514, OAW-AP515, OAW-AP518, OAW-AP574, OAW-AP575, AP-575EX, OAW-AP577, and AP-577EX	AlcatelInstant_Draco_8.7.1.x_xxxx
AP-503H, OAW-AP504, OAW-AP505, OAW-AP505H, AP-565, and AP-567.	AlcatelInstant_Gemini_8.7.1.x_xxxx

Access Points	Image File Format
OAW-IAP314, OAW-IAP315, OAW-IAP324, OAW-IAP325, OAW-AP374, OAW-AP375, OAW-AP377, OAW-AP318, and OAW-AP387	AlcatelInstant_Hercules_8.7.1.x_xxxx
OAW-IAP334 and OAW-IAP335	AlcatelInstant_Lupus_8.7.1.x_xxxx
OAW-AP534, OAW-AP535, and OAW-AP535	AlcatelInstant_Scorpio_8.7.1.x_xxxx
OAW-AP303, OAW-AP303H, 303P Series, OAW-IAP304, OAW-IAP305, OAW-AP365, and OAW-AP367	AlcatelInstant_Ursa_8.7.1.x_xxxx
OAW-AP203H, OAW-AP203R, OAW-AP203RP, and OAW-IAP207	AlcatelInstant_Vela_8.7.1.x_xxxx

- b. To upgrade firmware using the URL of an image file:
- c. Select the **Image URL** option to obtain an image file from a HTTP, TFTP, or FTP URL.
- d. Enter the image URL in the **URL** text field. The syntax to enter the URL is as follows:
 - HTTP - http://<IP-address>/<image-file>. For example, http://<IP-address>/AlcatelInstant_Hercules_8.7.1.x_xxxx
 - TFTP - tftp://<IP-address>/<image-file>. For example, tftp://<IP-address>/AlcatelInstant_Hercules_8.7.1.x_xxxx
 - FTP - ftp://<IP-address>/<image-file>. For example, ftp://<IP-address>/AlcatelInstant_Hercules_8.7.1.x_xxxx
 - FTP - ftp://<user name:password>@<IP-address>/<image-file>. For example, ftp://alcatel:123456@<IP-address>/AlcatelInstant_Hercules_8.7.1.x_xxxx



The FTP server supports both **anonymous** and **username:password** login methods.

Multiclass OAW-IAPs can be upgraded only in the URL format, not in the local image file format.

3. Clear the **Reboot all APs after upgrade** check box if required. This check box is selected by default to allow the OAW-IAPs to reboot automatically after a successful upgrade. To reboot the OAW-IAP at a later time, clear the **Reboot all APs after upgrade** check box.
4. Click **Upgrade Now** to upgrade the OAW-IAP to the newer version.

In the New WebUI (AOS-W Instant 8.4.0.0 or later versions)

To manually check for a new firmware image version and obtain an image file:

1. Navigate to **Maintenance > Firmware**.
2. Expand **Manual** section.
3. The firmware can be upgraded using a downloaded image file or a URL of an image file.
 - a. To update firmware using a downloaded image file:
 - i. Select the **Image file** option. This method is only available for single-class OAW-IAPs.
 - ii. Click on **Browse** and select the image file from your local system. The following table describes the supported image file format for different OAW-IAP models:

Access Points	Image File Format
OAW-AP344, OAW-AP345, OAW-AP514, OAW-AP515, OAW-AP518, OAW-AP574, OAW-AP575, AP-575EX, OAW-AP577, and AP-577EX	AlcatelInstant_Draco_8.7.1.x_xxxx
AP-503H, OAW-AP504, OAW-AP505, OAW-AP505H, AP-565, and AP-567.	AlcatelInstant_Gemini_8.7.1.x_xxxx
OAW-IAP314, OAW-IAP315, OAW-IAP324, OAW-IAP325, OAW-AP374, OAW-AP375, OAW-AP377, OAW-AP318, and OAW-AP387	AlcatelInstant_Hercules_8.7.1.x_xxxx
OAW-IAP334 and OAW-IAP335	AlcatelInstant_Lupus_8.7.1.x_xxxx
OAW-AP534, OAW-AP535, and OAW-AP535	AlcatelInstant_Scorpio_8.7.1.x_xxxx
OAW-AP303, OAW-AP303H, 303P Series, OAW-IAP304, OAW-IAP305, OAW-AP365, and OAW-AP367	AlcatelInstant_Ursa_8.7.1.x_xxxx
OAW-AP203H, OAW-AP203R, OAW-AP203RP, and OAW-IAP207	AlcatelInstant_Vela_8.7.1.x_xxxx

- b. To upgrade firmware using the URL of an image file:
- i. Select the **Image URL** option to obtain an image file from a HTTP, TFTP, or FTP URL.
 - ii. Enter the image URL in the **URL** text field. The syntax to enter the URL is as follows:
 - HTTP - http://<IP-address>/<image-file>. For example, http://<IP-address>/AlcatelInstant_Hercules_8.7.1.x_xxxx
 - TFTP - tftp://<IP-address>/<image-file>. For example, tftp://<IP-address>/AlcatelInstant_Hercules_8.7.1.x_xxxx
 - FTP - ftp://<IP-address>/<image-file>. For example, ftp://<IP-address>/AlcatelInstant_Hercules_8.7.1.x_xxxx
 - FTP - ftp://<user name:password>@<IP-address>/<image-file>. For example, ftp://<alcatel:123456>@<IP-address>/AlcatelInstant_Hercules_8.7.1.x_xxxx



The FTP server supports both **anonymous** and **username:password** login methods.

Multiclass OAW-IAPs can be upgraded only in the URL format, not in the local image file format.

4. Disable the **Reboot all APs after upgrade** toggle switch if required. This option is enabled by default to allow the OAW-IAPs to reboot automatically after a successful upgrade. To reboot the OAW-IAP at a later time, clear the **Reboot all APs after upgrade** check box.

5. Click **Upgrade Now** to upgrade the OAW-IAP to the newer version.
6. Click **Save**.

Upgrading an OAW-IAP Image Manually Using CLI

To upgrade an image using a HTTP, TFTP, or FTP URL:

```
(Instant AP)# upgrade-image <ftp/tftp/http-URL>
```

The following is an example to upgrade an image by using the FTP URL :

```
(Instant AP)# upgrade-image ftp://192.0.2.7/AlcatelInstant_Hercules_8.7.1.x_xxxx
```

To upgrade an image without rebooting the OAW-IAP:

```
(Instant AP)# upgrade-image2-no-reboot <ftp/tftp/http-URL>
```

The following is an example to upgrade an image without rebooting the OAW-IAP:

```
(Instant AP)# upgrade-image2-no-reboot ftp://192.0.2.7/AlcatelInstant_Hercules_8.7.1.x_xxxx
```

To view the upgrade information:

```
(Instant AP)# show upgrade info
Image Upgrade Progress
-----
Mac IP Address AP Class Status Image Info Error Detail
-----
d8:c7:c8:c4:42:98 10.17.101.1 Hercules image-ok image file none
Auto reboot :enable
Use external URL :disable
```

Upgrade from AOS-W Instant 6.4.x.x-4.2.x.x to AOS-W Instant 8.7.1.x

Before you upgrade an OAW-IAP running AOS-W Instant 6.5.4.0 or earlier versions to AOS-W Instant 8.7.1.x, follow the procedures mentioned below:

1. Upgrade from AOS-W Instant 6.4.x.x-4.2.x.x or any version prior to AOS-W Instant 6.5.4.0 to AOS-W Instant 6.5.4.0.
2. Refer to the *Field Bulletin AP1804-1* at myportal.al-enterprise.com.
3. Verify the affected serial numbers of the OAW-IAP units.