

Release Notes - Maintenance

OmniAccess AP1101

Release 2.1.0.121

The following is a list of issues that have been identified and corrected in this AOS-WNG software release. This document is intended to be used as a pre-upgrade guide and does not replace the GA Release Notes which are created for every GA release of software.

Contents

Contents 2

Fixed Problem Reports Between Builds 111 and 121 3

Fixed Problem Reports Between Builds 102 and 110 3

Fixed Problem Reports In Build 101..... 4

Fixed Problem Reports Between Builds 92 and 100..... 4

Fixed Problem Reports Between Builds 83 and 91 4

Fixed Problem Reports Between Builds 79 and 82 5

Open Problem Reports and Known Issues 6

New Features Introduced - 2.1.0.121 7

New Features Introduced - 2.1.0.110 7

New Features Introduced - 2.1.0.101 8

New Features Introduced - 2.1.0.100 8

New Features Introduced - 2.1.0.91 9

New Features Introduced - 2.1.0.82..... 11

Technical Support 13

Appendix A: Upgrade Instructions 14

Fixed Problem Reports Between Builds 111 and 121

PR	Description
R21ISSUE-76	<p>Summary: AP reboots when trying to set traffic limit parameters.</p> <p>Explanation: The traffic limit module has been updated. AP no longer reboots randomly when setting traffic limit parameters.</p>
R21ISSUE-69	<p>Summary: Roaming performance issue.</p> <p>Explanation: There is no longer speed loss when roaming between APs in the same group.</p>

Fixed Problem Reports Between Builds 102 and 110

PR	Description
R21ISSUE-20	<p>Summary: Captive portal user creation, the "Save" button turns dark blue before the data is entered.</p> <p>Explanation: After entering username and password the "Save" button turns active. It should be grayed out until all mandatory field are filled.</p>
R21ISSUE-28	<p>Summary: Out of window mouse-over "overlay" messages shouldn't happen.</p>
R21ISSUE-31	<p>Summary: Very often we see no clients attached to a rogue/interfering AP. This is very likely due to the short (max) 60ms scan duration.</p> <p>Explanation: Allow increase of scan interval up to 110ms. Default to 110ms.</p>
R21ISSUE-52	<p>Summary: On captive portal SSID, client can ping/access AP WebGUI before authentication.</p> <p>Explanation: The user is not able to PING/SSH the AP before it passes the captive portal authentication.</p>
R21ISSUE-58	<p>Summary: On captive portal page, the checkbox for 'I accept terms of use' is already checked.</p> <p>Explanation: Make the terms of use box unchecked so that when user enters credentials they have to manually check it before logging in.</p>
R21ISSUE-60	<p>Summary: Cannot change the group management IP address.</p> <p>Explanation: The group management IP address is able to be changed and saved without entering 'location' field first.</p>
R21ISSUE-67	<p>Summary: Syslog does not show AP reboot logs.</p> <p>Explanation: Reboot messages are now supported in Syslog.</p>

Fixed Problem Reports In Build 101

There were no issues fixed in AOS-WNG Release 2.1.0.101. This build added French language support for web management.

Fixed Problem Reports Between Builds 92 and 100

The following issues were fixed between AOS-WNG Release 2.1.0.92 and 2.1.0.100.

PR	Description
R21ISSUE-32	<p>Summary: Rogue AP "Black List" does not have SSID information. How do we detect a rogue?</p> <p>Explanation: The SSID field has been added to the "Black List" of Rouge AP.</p>

Fixed Problem Reports Between Builds 83 and 91

The following issues were fixed between AOS-WNG Release 2.1.0.83 and 2.1.0.91.

PR	Description
R21ISSUE-7	<p>Summary: Redefine the priorities of log messages.</p> <p>Explanation: Improvements to syslog capability to provide filtering of messages sent to syslog based on priority levels.</p>
R21ISSUE-12	<p>Summary: "support" user needs ability to change password.</p> <p>Explanation: The AP supports a "support" account for troubleshooting purposes in CLI. If a user logs into the AP with the support account, he now has the ability to change the "support" account password.</p>
R21ISSUE-13	<p>Summary: Country code list for time zone setting needs to be updated. Eg. Malta/Sweden not available.</p> <p>Explanation: Additional country codes added:</p> <p>Belgium - BE; United Kingdom - GB; Guam - GU; Hungary - HU; Ireland - IE;</p> <p>Monaco - MC; Macedonia - MK; Malta - MT; Malaysia - MY; Nigeria - NG; Panama - PA;</p> <p>Russia - RU; Sweden - SE; Thailand - TH; Turkey - TR; Vietnam - VN</p>
R21ISSUE-29	<p>Summary: Captive Portal customization should allow JPG format.</p> <p>Explanation: JPG format is now supported. Additional sizing and dimension</p>

	enhancements added.
R21ISSUE-30	<p>Summary: (Accidentally) Hitting the "backspace" key outside of a text-field will redirect the administrator to the login page of the AP management (login page).</p> <p>Explanation: Pressing the "backspace" key outside of a text field no longer redirects to the login page.</p>
R2ISSUE-54	<p>Summary: Add the option for SVC to take over as PVC.</p> <p>Explanation: Option added to have SVC takeover as PVC.</p>
R21ISSUE-55	<p>Summary: In the "Monitoring" pane, show the AP name instead of the MAC address.</p> <p>Explanation: "Monitoring" pane displays the AP name.</p>

Fixed Problem Reports Between Builds 79 and 82

The following issues were fixed between AOS-WNG Release 2.1.0.79 and 2.1.0.82.

PR	Description
R21ISSUE-15	<p>Summary: Max length of email field in local user creation screen is too short (30 characters).</p> <p>Explanation: It has been increased to 64 characters.</p>
R21ISSUE-16	<p>Summary: Max length of first & last name is too short in local user creation screen (10 characters).</p> <p>Explanation: It has been increased to 35 characters each (according to US Government standards).</p>
R21ISSUE-17	<p>Summary:</p> <p>Captive Portal restrictions:</p> <ol style="list-style-type: none"> 1) Special characters are not allowed in passwords 2) Last name does not allow hyphens or spaces 3) First name does not allow spaces or hyphens 4) Company name does not allow spaces and is limited to 30 characters <p>Explanation:</p> <ol style="list-style-type: none"> 1) Special characters are allowed for captive portal users passwords 2) First names like Jean-Claude and last names e.g. Le-Fleur are allowed.

	<p>3) Spaces are allowed for last names, e.g. "John Doe"</p> <p>4) Company name is allowed 64 characters and spaces. e.g. "Alcatel-Lucent Enterprise Corporation, Argentina".</p>
R21ISSUE-46 R21ISSUE-47	<p>Summary: WLAN changes security mode from Enterprise (WPA) to OPEN on its own.</p> <p>Explanation: Neither encrypt nor decrypt an empty password to keep the same value of password, avoid creating wrong type of WLAN.</p>

Open Problem Reports and Known Issues

There are no known issues in this release.

New Features Introduced - 2.1.0.121

The following new features were introduced.

1. New Language Support


WebGUI now supports Korean, Turkish and Italian languages.

New Features Introduced - 2.1.0.110

The following new features were introduced.

1. Spanish Language Support

Spanish is supported for web management, user can switch to Spanish by selecting 'Español' on the main page.




2. Expand Country code list

The following country codes have been added to the Country Code list:

Albania – AL; Bulgaria – BG; Costa Rica – CR; Croatia – HR; Cyprus – CY; Ecuador – EC; Kenya – KE; Latvia – LV; Macau – MO; Slovenia – SI; El Salvador – SV; Ukraine – UA

3. Title bars that allow enhanced configurations, augmented with settings icon

In addition to highlighting the title bar during mouse over each title bar that allows enhanced configuration has a gear icon for further settings.



4. OXO Connect R2.1 HTTPS Support


Secure ZTP with OXO Connect R2.1. Both the AP configuration and binaries can be auto provisioned over secure HTTPS.

New Features Introduced - 2.1.0.101

The following new features were introduced.

1. French Language Support

French is supported for web management, user can switch to French by selecting 'Francais' on the main page.



New Features Introduced - 2.1.0.100

The following new features were introduced.

1. HTTPS Support

Web pages now support HTTPS. By importing a root certificate, users can login without any untrusted warning and all communication is protected.

First steps to begin using HTTPS:


- 1) Download the root certificate file from the AP;
- 2) Install the certificate for the web browser according to operating system;
- 3) Login with HTTPS to manage the AP group.

Usage Guidelines:

- 1) Google Chrome and Mozilla Firefox are recommended for the HTTPS management. Microsoft Internet Explorer is NOT recommended for use because it does not support HTTPS login through IP address, however HTTPS access via a URL is supported.
- 2) If an AP in the group is reset to the factory default, it is highly recommended to close and reopen the browser for rebuilding the HTTPS connection between the AP and the browser.

2. German Language Support

German is supported for web management, user can switch to German by selecting 'Deutsch' in the main page.



New Features Introduced - 2.1.0.91

The following new features were introduced.

1. Post Mortem Dump - PMD

Post Mortem Dump (PMD) is a troubleshooting method which helps to identify root cause of a core dump and exception pointers after a fatal crash. If PMD is enabled and configured, the AP will send PMD files to a specific TFTP server immediately when there is a key process crashing on the AP.

Web UI Usage:

- 1) Click the Tools link in the main page



Tools link

- 2) Configure PMD



PMD Configuration Window

Table: Key word specification in PMD Window


PMD: <input checked="" type="checkbox"/>	Enable/Disable PMD files sending.
TFTP Server	Specify the TFTP server to which PMD files will be sent.

Usage Guidelines:

- 1) By default, sending PMD files to an external TFTP server is disabled.
- 2) The PMD file name gives the application that crashed. For example a PMD file named “pmd-led_ctrl-2016.11.20-16:57:45”, “led_ctrl” is the application crashed.
- 3) PMD files are coding level information, it is suggested to send them to service & support for analysis.

2. Daylight Saving Time

An option has been added to enable/disable daylight saving time on the System main page.




Daylight-Saving Time

The daylight saving time (DST) varies from different time zones. The DST of supporting time zones is enabled automatically by default, while other time zones are not editable on DST.

3. Disconnect a client from the wireless network

Previously there was no method to force a user or device disconnection without having to put that user or device in the Black List. This resulted in that user or device never being able to connect again until the administrator manually removed it from the Black List. An option to easily disconnect a user or device has been added.

Click the Client bar in the main page to enter the Clients Information Window.



Disconnect a Client

4. Redirect to ADMIN-specified page after successful login

Administrator can specify the web page after successfully logging in.

Go to Access in the main page and click to open the Authentication Configuration Window.

The administrator can enable the URL redirect function and specify the redirect page in the Authentication Configuration Window.

Authentication Configuration

Captive Portal: on

Customized Portal Page

Login by: Account Access Code Terms Of use

Redirect URL: on Save

UserName	Starting Date	Ending Date	Operate
guest1	2016.11.21	2016.11.20	

Add

User Behavior: on

*TFTP Server: Cycle: Save Upload Now

Redirect to ADMIN-specified URL

New Features Introduced - 2.1.0.82

The following new features were introduced.

1. Post Mortem Dump - PMD

Post Mortem Dump (PMD) is a troubleshooting method which helps to identify root cause of a core dump and exception pointers after a fatal crash. If PMD is enabled and configured, the AP will send PMD files to a specific TFTP server immediately when there is a key process crashing on the AP.

Web UI Usage:

- 3) Click the PMD link in the main page



Figure 1 PMD link

- 4) Configure PMD

PMD

Post Mortem Dump(PMD) is mainly for identifying root cause of a core dump and exception pointers after crash. when enabled, PMD will be generated and pushed to a server for analysis.By default, PMD is disabled.

PMD: on

TFTP Server: Save

Figure 2 PMD Configuration Window

Table: Key word specification in PMD Window

PMD:	Enable/Disable PMD files sending.
TFTP Server	Specify the TFTP server to which PMD files will be sent.

Usage Guidelines:

- 4) By default, sending PMD files to an external TFTP server is disabled.
- 5) The PMD file name gives the application that crashed. For example a PMD file named “led_ctrl.11. core”, “led_ctrl” is the application crashed.
- 6) PMD files are coding level information, it is suggested to send them to service & support for analysis.

Note: PMD file naming format is planned to be changed to “pmd-process name-date-time”, such as “pmd-led_ctrl-2016.11.20-16:57:45” in the next release.

2. Guest Operator Account Privileges

Added a new web GUI for the guest operator account that only allows for the creation and deletion of guest users for the AP.

3. Syslog Error Messages

To reduce the many error level syslog messages after configuring or modifying a VLAN ID, the log messages of the WAM module have been downgraded to Debug level.

Technical Support

Alcatel-Lucent technical support is committed to resolving our customer's technical issues in a timely manner. Customers with inquiries should contact us at:

Region	Phone Number
North America	1-800-995-2696
Latin America	+1-877-919-9526
European Union	+800 00200100 (Toll Free) or +1(650)385-2193
Asia Pacific	+65 6240 8484

Email : ebg_global_supportcenter@alcatel-lucent.com

Internet: Customers with service agreements may open cases 24 hours a day via the support web page at: support.esd.alcatel-lucent.com.

Upon opening a case, customers will receive a case number and may review, update, or escalate support cases on-line. Please specify the severity level of the issue per the definitions below. For fastest resolution, please have telnet or dial-in access, hardware configuration—module type and revision by slot, software revision, and configuration file available for each switch.

Severity 1 - Production network is down resulting in critical impact on business—no workaround available.

Severity 2 - Segment or Ring is down or intermittent loss of connectivity across network.

Severity 3 - Network performance is slow or impaired—no loss of connectivity or data.

Severity 4 Information or assistance on product feature, functionality, configuration, or installation.

enterprise.alcatel-lucent.com - Alcatel-Lucent and the Alcatel-Lucent Enterprise logo are trademarks of Alcatel-Lucent. To view other trademarks used by affiliated companies of ALE Holding, visit: enterprise.alcatel-lucent.com/trademarks. All other trademarks are the property of their respective owners. The information presented is subject to change without notice. Neither ALE Holding nor any of its affiliates assumes any responsibility for inaccuracies contained herein.

Appendix A: Upgrade Instructions

Passwords related to the operation of the OAW-AP1101 are not stored securely in software version 2.1.0.67. To resolve this issue the OAW-AP1101 software MUST be upgraded to the latest software version available from customer support. Please Visit <https://support.esd.alcatel-lucent.com/> to get the latest software and follow the upgrade instructions below.

The two cases below describe the Syslog messages that will be seen when an AP running software version 2.1.0.67 is detected in a group with another AP running software version 2.1.0.68 or higher.

- Case1: In a group, AP-00:e0 is acting as the PVC running software version 2.1.0.68 or higher; AP-05:30 running software version 2.1.0.67 is detected in the group:


PVC generates an Error level log message: “AP-05:30 with incompatible software is trying to join the group, please upgrade it!”

- Case2: In a group, AP-05:30 is acting as the PVC running software version 2.1.0.67; AP-00:e0 running software version 2.1.0.68 or higher is detected in the group:

AP-00:e0 generates a Critical level log message: “Some APs in the network are running incompatible software. To avoid network interruptions, an upgrade to the latest software is strongly recommended!”.

Software Upgrade Instructions

1. Login to AP using Administrator account with default password ‘admin’.



2. Click on the AP tab to open up the AP Configuration page.

Alcatel-Lucent Enterprise

AP Group : Demo - 192.168.92.20
Clibasoz_SLAB

Administrator Logout | About Help | English
Tools | Polling Cycle: 30s

WLAN			AP		
WLAN Name	Status	Clients	Primary Name	Status	Clients
HAW-DEMO_1x	On	0	AP_13	Working	0
			AP_12	Working	0
			AP_11	Working	0

Monitoring

System
Wireless
Access

3. On AP Configuration Page, click **Upgrade All Firmware**.

AP Configuration

Primary Name	IP	Firmware	Operate
PVC			
AP_13	192.168.92.59(AP) 192.168.92.20(M)	2.1.0.65	
SVC			
AP_12	192.168.92.53	2.1.0.65	
MEMBER			
AP_11	192.168.92.58	2.1.0.65	
Joining			

Detailed Information

APName: AP_13 [Edit](#)

Location: [Edit](#)

Status: Working

Role in Group: PVC

Serial Number: WKS163500021

Model: OAW-AP1101

Firmware: 2.1.0.65

Upgrade Time: Tue Sep 6 14:49:21 UTC 2016

Upgrade Flag: Success

IP Mode: dhcp [Edit](#)

IP: 192.168.92.59

Netmask: 255.255.255.0

Default Gateway: 192.168.92.254

4. Select the firmware file and click **Upload To All**, this will upgrade the firmware and reboot the AP.

The screenshot shows the 'AP Configuration' window with a table of APs and an 'Update Firmware' dialog box. The dialog box contains a warning: 'Don't turn off the power during the upgrade process!'. It has radio buttons for 'Image File' (selected) and 'Image File URL'. A 'Choose File' button is highlighted with a red arrow. Below it, a file is listed: 'Name: hos-r21-osupgrade-65.bin' and 'Size: 13.56 MB'. There are 'Remove' and 'Upload To All' buttons. A red text box with an arrow points to the 'Choose File' button, containing the text: 'Select the firmware file and click Upload to All.'

Primary Name	IP	Firmware	Operate
PVC			
AP_13	192.168.92.59(AP) 192.168.92.20(M)	2.1.0.65	cfg firmware reboot
SVC			
AP_12	192.168.92.53	2.1.0.65	cfg firmware reboot
MEMBER			
AP_11	192.168.92.58	2.1.0.65	cfg firmware reboot
Joining			

Buttons at the bottom: Clear All Configuration, Backup All Configuration, Restore All Configuration, Upgrade All Firmware

5. Log into the AP group and clear the configuration by clicking **Clear All Configuration** and confirm the reboot. **NOTE:** This step erases the configuration for all the APs in the group. It is only **MANDATORY** when upgrading an AP from software version 2.1.0.67 to a higher version.

The screenshot shows the 'AP Configuration' window with a table of APs and a 'Detailed Information' panel. A red arrow points to the 'Clear All Configuration' button at the bottom. The 'Detailed Information' panel shows details for AP-07:00.

Primary Name	IP	Firmware	Operate
PVC			
AP-07:00	192.168.102.160(AP) 10.0.0.1(M)	2.1.0.77	cfg firmware reboot
SVC			
AP-06:A0	192.168.102.159	2.1.0.77	cfg firmware reboot
MEMBER			
AP-06:B0	192.168.102.161	2.1.0.77	cfg firmware reboot
Joining			

Buttons at the bottom: Clear All Configuration, Backup All Configuration, Restore All Configuration, Upgrade All Firmware

Detailed Information

APName: AP-07:00 [Edit](#)

Location: [Edit](#)

Status: Working

Role in Group: PVC

Serial Number: WKS163510004

Model: OAW-AP1101

Firmware: 2.1.0.77

Upgrade Time: Tue Sep 27 23:25:14 UTC 2016

Upgrade Flag: Success

IP Mode: dhcp [Edit](#)

IP: 192.168.102.160

Netmask: 255.255.255.0

Default Gateway: 192.168.102.254

Additional Upgrade Information for APs with software version 2.1.0.67

When adding an AP(s) with software version 2.1.0.67 to an existing group of APs with a software version higher than 2.1.0.67, the APs with software version 2.1.0.67 must be upgraded and the configuration cleared.

There are two scenarios for adding APs to an existing AP group:

- A) The existing group has a minimal configuration which can be easily cleared and reconfigured. In this case perform the following steps:
 - 1) Add the new APs to the group.
 - 2) Upgrade the APs to the newer software version.
 - 3) Clear the configuration and reboot as described earlier.

- B) The existing group has an extensive configuration that needs to be preserved. In this case, there are 2 options.

Option 1:

- 1) Backup the existing configuration.
- 2) Add the new APs to the group.
- 3) Upgrade the APs to the newer software version.
- 4) Clear the configuration and reboot as described earlier.
- 5) Restore the configuration.

Option 2:

- 1) Use an isolated network, not connected to the existing AP's network.
- 2) Power up the APs and allow them to form their own group.
- 3) Upgrade the APs to the newer software version.
- 4) Clear the configuration and reboot as described earlier.
- 5) Move the APs to the existing network.

NOTE: The backup and restoration of an existing configuration is only supported with a software version higher than 2.1.0.67. All APs with a configuration based on 2.1.0.67 must have their configuration cleared.