

Release Notes - Rev. A

OmniAccess Stellar AP

AWOS Release 4.0.1 - GA Release

These release notes accompany the OmniAccess Stellar Operating System (AWOS) Release 4.0.1 software for the Stellar APs. This document provides important information on individual software and hardware features. Since much of the information in the release notes is not included in the hardware and software user manuals, it is important to read all sections of this document before installing new hardware or loading new software.

Table of Contents

Related Documentation	3
Hardware Supported	4
New Software Features and Enhancements	4
Fixed field problems in build 4.0.1.44.....	4
Open/Known Problems	6
Limitations and/or Dependencies	6
New Software Feature Descriptions	8
Appendix - Upgrade Instructions	13
Technical Support.....	15

Related Documentation

The release notes should be used in conjunction with the associated manuals as listed below. User manuals can be downloaded at: <https://businessportal.al-enterprise.com>.

Stellar AP Quick Start Guide

The Quick Start Guide assists you in quickly connecting to and configuring the Stellar AP.

Stellar AP Installation Guide

Provides technical specifications and installation procedures for the Stellar AP.

Stellar AP Configuration Guide

Includes procedures for managing and configuring all aspects of the Stellar AP using the built-in web interface.

Technical Tips, Field Notices, Upgrade Instructions

Contracted customers can visit our customer service website at: <https://businessportal.al-enterprise.com>.

Hardware Supported

- AP1101, AP1201, AP1220 series, AP1230 series, AP1251, AP1251-RW-B (model addressed for specific country), AP1201H, AP1201L, AP1201HL, AP1320 series, AP1360 series, AP1201BG

New Software Features and Enhancements

The following software features are new with this release, subject to the feature exceptions and problem reports described later in these release notes:

Feature	Platform Support
Out-of-Box MESH (Cluster&OVE&OVC)	All
IPv6 Managed Infrastructure (OVE&OVC)	All
PERWIFI-143: Allow Reflexive Policies on AP (OVE & OVC)	All
mDNS service network with policy control - (OVE & OVC)	Except AP1101
RAP-Support VLAN tag via GRE tunnel	Except AP1101
RAP-Support Local breakout	Except AP1101
AP Management VLAN Support	All
Security vulnerabilities	All
AP wireless scanning enhancement:BG-S	All
Support MU-MIMO enable/disable	All
Support 11ax AP support HE mode enable/disable	11AX
Support Beacon Interval Configuration	All
Support IGMP Snooping Configuration	All

Notes:

- OmniAccess Stellar AP reserves two SSIDs (One on 2.4G band, and one on 5G band). They perform background scanning for WIPs/WIDs services to alert and take preventive actions on any security threat. It is secure and NO clients can connect to these SSIDs.

Fixed field problems in build 4.0.1.44

PR	Description
Case: 00494467 ALEISSUE-796/ ALEISSUE-806/ ALEISSUE-819/ ALEISSUE-831/ ALEISSUE-842/ ALEISSUE-846/ ALEISSUE-856/ ALEISSUE-865/ ALEISSUE-868	Summary: Unknow reason reboot. Explanation: Root cause : With the “memory-access error”, the kes logs might overwrite the data of the area/address for Linux system, that could lead to different abnormal reboots. Solution: Reallocate the memory usage for “kes log” to reserve a special area to avoid the Memory out of bounds by “kes log”. Click for additional information
Case: 00492778 ALEISSUE-810/ ALEISSUE-807	Summary: AP reboot with policy exception. Explanation: Fix a policy process crash issue. Click for additional information
Case: 00502500 ALEISSUE-857	Summary: Heatmap with AP-1321 is not displayed. Explanation: After AP bootup OV will get the AP RF information from AP once, but sometimes the wireless interface is not ready and causes the OV get null information. Optimization of the software to ensure OV can get the correct information. Click for additional information
Case: XXX	Summary: Channel 144 missing in OV for Singapore County code.

ALEISSUE-820	Explanation: Wireless driver add support for channel 144. Click for additional information
Case: XXX ALEISSUE-861	Summary: Stellar AP Data tunnel not able to support packet size more than 1354 Bytes. Explanation: The management frame doesn't support IP fragmentation, so it will be dropped during transmission due to MTU. Management interface MTU set to 1420 by default, also the value can be configured in SUPPORT account.
Case: XXX ALEISSUE-408	Summary: Information disclosure via Rsync default credentials in Express mode. Explanation: Rsync credentials encrypted to enhance security.
Case: XXX ALEISSUE-713	Summary: Configured SSID detected as interference AP by the same AP's scanning function(AP13xx). Explanation: Fixed this scanning issue.
Case: 00486920 ALEISSUE-770	Summary: Multicast traffic flooded on all SSID's with different VLANs. Explanation: In order to roam faster, all the traffic will be forwarded when a client roams to a new AP even if it doesn't finish authentication. But that also causes all packets to be leaked between VLANs since forwarding logic in macvlan layer doesn't distinguish VLAN-ID. In 4.0.1 build packets will be dropped if the VLAN-ID is not the same as the interface VLAN-ID. Click for additional information
Case: 00490818 ALEISSUE-785	Summary: AP eth1,2 and 3 are coming up even before the AP is completely up. Explanation: The downlink port stays disabled if the link between AP and OV is not established completely. Click for additional information
Case: XXX ALEISSUE-818	Summary: AP1231 does not disable 5g High radio even though its unchecked in RF profile. Explanation: Optimize code logic, AP does not upload radio information if this band is disabled.
Case: 00498265 ALEISSUE-826	Summary: Default STP priority for mesh root AP's. Explanation: STP function is disabled in 4.0.1 build. Click for additional information
Case: 00459427 ALEISSUE-666	Summary: Even if the inactive time is disabled, the captive portal users are getting disconnected after 15 minutes. Explanation: The inactivity timeout setting is restricted by wireless driver and the maximum value is 12000 seconds, increase the range from [1-1200s] to [1-12000s]. Click for additional information
Case: 00484996 OVE-7859/ OVE-8174	Summary: Stellar WLAN - reduce DPI manager memory consumption. Explanation: Fixed the bug that memory of DPI process increased when loading preconfig messages. Click for additional information
Case: 00483124 ALEISSUE-766	Summary: Users are getting less bandwidth when we connect to OAW-AP1101 with the mixed cluster-setup Explanation: Optimization done in AWOS 4.0.1 and AWOS 4.0.0 MR-4 to fix this problem Click for additional information
Case: 00467457 OVE-8881	Summary: The data can be forwarded from VPN VA when guest tunnel with vlan. Explanation: Because VLAN-ID field in the packet takes 4-bytes the data interface MTU is set to 1542 by default. Also the value can be configured in SUPPORT account. Click for additional information

Open/Known Problems

The problems listed here include problems known at the time of the product's release. Any problems not discussed in this section should be brought to the attention of the Service and Support organization as soon as possible. Please contact customer support for updates on problem reports (PRs) where no known workaround was available at the time of release.

PR	Description	Workaround
Apple device connection issue on 1320/1360 series.	Summary: When the VLANID in SSID is modified, all clients will be kicked off, but Apple device may not send DHCP request when reconnecting with this SSID, that will cause to keep using old IP address and unable to connect to the network.	Disconnect and re-join this network with the Apple device.
SSID is not created on 11ax device after changed group on OV.	Summary: If AP with RF disabled change to a new OV group with RF enabled, SSID interface cannot be up.	Re-enable RF configuration on OV UI.
DPI function doesn't work if the reflexive is disabled.	Summary: Because DPI depends on first packets of the same contract session, it might not work if the traffic matches NOTRACK policy.	Configure "YES" for reflexive policy.
ALEISSUE-869	Summary: If run as "dedicated scan mode: once" on OV UI, no result seen in RF Scan View.	Utilize the "dedicated scan mode" function instead or perform the "dedicated scan mode: once" in AP UI.
ALEISSUE-836	Summary: If manually set the Tx-power to a static maximum value in 5G band3 (Channels above 100) on 11ax device, the actual value went wrong after upgrading.	Set the Tx-power to auto for 5G static band3 channel.

Limitations and/or Dependencies

Feature	AP Model	Limitations and/or Dependencies
Rogue AP	All	When an AP MAC is configured as "Friendly AP", the network will ensure to not classify it as interfering/rogue AP. Please ensure to not delete the default Stellar MAC OUIs in OV mode (34: e7:0b and dc: 08:56). Note that you can have a maximum of 32 Friendly MAC OUIs/MAC addresses configured. With Rogue AP containment enabled, for any AP classified as rogue, clients attempting to connect to Rogue AP will get disconnected.
Cluster Preemption	All	AP1320 series and AP1360 11AX AP is higher priority than 11AC platform products in the cluster. The 11AX AP will take over the PVM role when it joins an existing 11AC cluster.
Management VLAN	All	Loading management VLAN configuration takes some time when AP boots up, it may cause one cluster to be established between APs with different management VLAN. To prevent this problem, when management VLAN is set to non-0, cluster ID will be increased 20000, which makes AP separate from original cluster. After management VLAN is removed, cluster ID is also restored to original value.


IPv6	All	If AP works in single IPv6 environment (pure IPv6), because wireless client information synchronization does not support IPv6 address, client roaming does not work in this case.
Link Aggregation	AP1360 series, AP1251	Dual ethernet ports do not support forming a link aggregation for AP uplink.
RAP	Except AP1101	<ul style="list-style-type: none"> • Local breakout does not support handing for multiple VLANs • AP1201H downlink port handing for tagged and untagged traffic
DRM	AP1201H/AP1201HL	Band Steering and Smart Load balancing not supported since AWOS401GA because of resource limitation and new feature introducing - mDNS service network with policy control.
DPI	AP1201 AP1220 series, AP1251	When DPI function is enabled, it is recommended to have an initial free memory size of about 30MB after AP booting up for system stable running. If the booting up free memory size is far less than 30MB, suggest removing unnecessary WLAN/VLAN/Policy/DPI rule on AP1201/AP1220/AP1251.

New Software Feature Descriptions


IGMP-snooping Configuration

IGMP-snooping configuration is supported in 4.0.1 release, users can enable or disable this switch as required.

Web UI



OV UI



Static IPv6 address configuration

Static IPv6 address configuration is added on Network Configuration page, when network protocol is specified as “static”, customers can edit interface static IPv4 and IPv6 address.

Web UI

AP Network Configuration

Name	VLAN	Protocol	IP Address	Operate
wan		DHCP	172.16.101.55	

Edit Network

Protocol:

IPv4

IP Address:

Netmask:

DNS:

Default Route: on

Gateway:

IPv6

IP Address:

Subnet prefix length:

static IPv6 address configuration

OV UI

192.168.21.158/#/apRegistration/accessPoint

Access Points

- Access Points
- AP Group
- Certificate
- External Captive Portal Config File
- IoT/Location Server
- Data VPN Servers

Edit IP Mode

IP Mode: DHCP Static

IP Type: IPv4 IPv6

IPv4

*IP Address:

*Netmask:

*Default Gateway:

Preferred DNS:

Alternate DNS:

IPv6

IP Address:

Subnet Prefix Length:

*Default Gateway:

Preferred DNS:

Alternate DNS:

Management VLAN

Since 4.0.1 Release AP supports management VLAN, customers can configure management VLAN-ID in AP UI

AP Network Configuration

Name	VLAN	Protocol	IP Address	Operate
wan		DHCP	172.16.101.15	

Edit Network

Network Name: wan

VLAN:

Protocol:

Default Route:

management VLAN (indicated by a red arrow pointing to the VLAN field)

Scanning channel

Scanning channel configuration is used to specify scanning works on current channel or all channels.

Web UI

Clients

User Name	IP	MAC	WLAN	Auth
	172.16.101.33	cc:20:e8:b7:30:55	yjy1117	OPEN

System

Wireless

RF

2.4GHz Channel Distribution: 11 clients

wIDS/wIPS

Rogue Suppress: off
Dynamic Blacklist: off
Wireless Attack Detection: off

Performance Optimization

Background Scanning: on

Scanning Channel: Working Channel

Scanning Interval: 0 min 20 sec

Scanning Duration: 50ms

Band Steering: on


Load Balance: on

RSSI Threshold: [slider]

Access

IOT


OV UI



Additional RF configuration

We add 3 new RF configurations per band (MU-MIMO, High Efficiency and Beacon Interval), please refer to the screenshot below.

Web UI



OV UI

The screenshot shows the 'Per Band Info' configuration page in the RF Management interface. It features a table with four columns representing different frequency bands: 2.4G, 5G All, 5G Low, and 5G High. Each column contains various settings such as Channel Setting, Client-aware, Channel DRM, Channel List, Channel Width, Power Setting, Minimum TX Power, Maximum TX Power, External Antennas Gain, Beacon Interval, Short Guard Interval, MU-MIMO, and High Efficiency. The 'Beacon Interval' is set to 100 ms for all bands. The 'MU-MIMO' and 'High Efficiency' settings are all set to 'ON'. Three red arrows point to the 'Beacon Interval', 'MU-MIMO', and 'High Efficiency' settings.

MQTT Compatibility


In 4.0.1 Release MQTT tunnel is encrypted to enhance security, for compatibility, MQTT Compatibility must be set to “on” if cluster contains AP running previous version. Otherwise, cluster cannot form correctly.

The screenshot shows the 'General Configuration' page for 'Account Management'. It contains several input fields for configuration: Group Name (AP-Group), Location (0-9a-zA-Z_), Group Management IP (x.x.x.x), Group Management Netmask (x.x.x.x), Group Management IPv6 (::), Group ID (4100), and MQTT Compatibility (off). The MQTT Compatibility setting is a toggle switch currently set to 'off', with a red arrow pointing to it. There are 'Cancel' and 'Save' buttons for the Group ID field.

Appendix - Upgrade Instructions

General Software Upgrade Instructions (WiFi Express)

1. Login to AP using Administrator account with default password 'admin'.



2. Click on the AP tab to open up the AP Configuration page.

Alcatel-Lucent Enterprise AP Group : AP-Group - Administrator | 30s | English

WLAN Enable: 2 Disable: 0

WLAN Name	Status	Clients
weekday	on	0
weekend	on	0

AP Working:3 Down:0 Joining:0

Primary Name	Status	Clients
AP-1A:10	Working	0
AP-DD:50	Working	0
AP-42:20	Working	0

Monitoring Group: AP-Group

System
Wireless
Access

Click here to open AP configuration page

3. On AP Configuration Page, click Upgrade All Firmware.

AP Configuration

Primary Name	IP	Firmware	Operate
PVC			
AP-1A:10	192.168.20.119 (M)	3.0.5.23	
SVC			
AP-42:20	192.168.20.111	3.0.5.27	
MEMBER			
AP-DD:50	192.168.20.128	3.0.5.6	
Joining			
Pending			
Neighboring Group			
AP-32:30	192.168.20.237	3.0.4.2052	

Detailed Information

AP Name: AP-1A:10 [Edit](#)
MAC: 34:E7:0B:00:1A:10
Location: [Edit](#)
Status: Working
Role in Group: PVC
Serial Number: WKS163300071
Model: OAW-AP1251
Firmware: 3.0.5.23
Upgrade Time: Sat Nov 24 08:25:27 2018
Upgrade Flag: successfully

IP Mode: DHCP [Edit](#)
IP: 192.168.20.119
Netmask: 255.255.254.0
Default gateway: 192.168.21.254
DNS: 219.141.136.10

AP Mode: Express [Edit](#)

Reboot All AP | Clear All Configuration | Backup All Configuration | Restore All Configuration | **Upgrade All Firmware** | Connect To Cloud | Convert To Enterprise

Click here to upgrade

4. Select the firmware file and click **Upload To All**, this will upgrade the firmware and reboot the AP.

Multi-model Upgrade

Model	Firmware	AP Quantity	
AP1250	3.0.5.23	1	Expand
AP1101	3.0.5.6	1	Expand
AP1220	3.0.5.27	1	Expand

Upgrade Firmware

Don't turn off the power during the upgrade process.

Image File Image File URL
1. Select corresponding AP model and upload right image

AP1101 No file chosen

AP1220 No file chosen

AP1250 No file chosen

2. Then upload all here

Technical Support

Alcatel-Lucent Enterprise technical support is committed to resolving our customer’s technical issues in a timely manner. Customers with inquiries should contact us at:

Region	Phone Number
North America	1-800-995-2696
Latin America	1-877-919-9526
Europe Union	+800 00200100 (Toll Free) or +1(650)385-2193
Asia Pacific	+65 6240 8484

Email: ebg_global_supportcenter@al-enterprise.com

Internet: Customers with Alcatel-Lucent service agreements may open cases 24 hours a day via Alcatel-Lucent’s support web page at: <https://businessportal.al-enterprise.com/>.

Upon opening a case, customers will receive a case number and may review, update, or escalate support cases on-line. Please specify the severity level of the issue per the definitions below. For fastest resolution, please have telnet or dial-in access, hardware configuration—module type and revision by slot, software revision, and configuration file available for each switch.

Severity 1 - Production network is down resulting in critical impact on business—no workaround available.

Severity 2 - Segment or Ring is down or intermittent loss of connectivity across network.

Severity 3 - Network performance is slow or impaired—no loss of connectivity or data.

Severity 4 - Information or assistance on product feature, functionality, configuration, or installation.