

Release Notes

OmniAccess Stellar AP

AWOS Release 4.0.5 - MR2 Release

These release notes accompany the OmniAccess Stellar Operating System (AWOS) Release 4.0.5 software for the Stellar APs. This document provides important information on individual software and hardware features. Since much of the information in the release notes is not included in the hardware and software user manuals, it is important to read all sections of this document before installing new hardware or loading new software.

Table of Contents

Related Documentation	3
Hardware Supported.....	4
Fixed Problem Reports Between Build 4.0.5.1025 and 4.0.5.2038	4
Fixed Problem Reports Between Build 4.0.5.23 and 4.0.5.1025	6
Open/Known Problems	7
Limitations and/or Dependencies.....	8
New Software Feature Descriptions.....	11
Technical Support	11

Related Documentation

The release notes should be used in conjunction with the associated manuals as listed below.

User manuals can be downloaded at: <https://myportal.al-enterprise.com/>.

Stellar AP Quick Start Guide

The Quick Start Guide assists you in quickly connecting to and configuring the Stellar AP.

Stellar AP Installation Guide

Provides technical specifications and installation procedures for the Stellar AP.

Stellar AP Configuration Guide

Includes procedures for managing and configuring all aspects of the Stellar AP using the built-in web interface.

Technical Tips, Field Notices, Upgrade Instructions

Contracted customers can visit our customer service website at: <https://myportal.al-enterprise.com/>.

Hardware Supported

- AP1101, AP1201, AP1220 series, AP1230 series, AP1251, AP1251-RW-B, AP1261-RW-B, AP1201H, AP1201L, AP1201HL, AP1320 series, AP1360 series, AP1201BG, AP1301, AP1301H, AP1311, AP1331, AP1351, AP1451.

Fixed Problem Reports Between Build 4.0.5.1025 and 4.0.5.2038

PR	Description
Case: 00658064 ALEISSUE-1435	<p>Summary: "AP Name" and "Data Innovations North America" Vendor Specific Information Elements missing from Probe Response.</p> <p>Explanation: Add "AP Name" in the Probe Response frame due to it only included in the Beacon frame in previous build.</p> <p>Click for additional information</p>
Case: N/A ALEISSUE-1432	<p>Summary: DPSK problem.</p> <p>Explanation: It's related to station's MAC auth state before it enters the WPA stage; issue is fixed by improving the condition for requesting station's MAC auth process.</p>
Case: N/A ALEISSUE-1463	<p>Summary: OAW-AP1451 doesn't give correct output for 6 GHz via SNMP.</p>
Case: 00639601 ALEISSUE-1385	<p>Summary: Neighbor report response from stellar AP contains no AP information.</p> <p>Explanation: The neighbor report relies on the AP scan results and aging mechanism, this issue fixes the aging length of the scan results, which increased to 12h, this fix is only included in WiFi5 APs.</p> <p>Click for additional information</p>
Case: 00660891 ALEISSUE-1446	<p>Summary: All WLAN Users not able to associate to Stellar AP after upgrade of OVE to 4.7 R01.</p> <p>Explanation: After the upgrade, OVE issued an illegal Tunnel parameters, the AP cannot be correctly parsed resulting in the restart of the WAM module and block clients to associate, the problem fixes the handling of illegal parameters to increase robustness.</p> <p>Click for additional information</p>
Case: N/A ALEISSUE-1464	<p>Summary: Association of 6 GHz clients will fail if you disable 11b and 11g on 6 GHz SSID.</p>

<p>Case: 000069332 ALEISSUE-1426</p>	<p>Summary: In OV 2500/OV Cirrus Web AP Registration page - APs are seen with IPV6 addresses.</p> <p>Explanation: Optimize the AP IP address displaying logic to show IPv6 address if OV address is IPv6 but not show local IPv6 address, else show the IPv4 address.</p> <p>Click for additional information</p>
<p>Case: 00610440 ALEISSUE-1265</p>	<p>Summary: High rate of tx retry and latency observed at one location with AP 1321.</p> <p>Explanation: The Uplink MU-MIMO 802.11 trigger frame makes the environment channel utilization very high, a new Wi-Fi firmware provided by Qualcomm fixes this issue.</p> <p>Click for additional information</p>
<p>Case: 00658514 ALEISSUE-1445</p>	<p>Summary: Stellar AP running in Express mode - clients IP showing 0.0.0.0 in Web page.</p> <p>Explanation: The client IP address display depends on a module to hook DHCP packets, in case of the high CPU utilization or too many DHCP packets need to handle, the DHCP packets will be dropped by the module. This affects another module that relies on DHCP packets to display user IP addresses. Module is improved gets a valid client IP address.</p> <p>Click for additional information</p>
<p>Case: N/A ALEISSUE-1444</p>	<p>Summary: AP suddenly stops sending LLDP packets.</p> <p>Explanation: Added a workaround for restarting the LLDP process after it stops, and also added a method to record the crash dump log.</p>
<p>Case: 00663120 ALEISSUE-1468</p>	<p>Summary: L2GRE GTTS Failover not working as expected.</p> <p>Explanation: The network detection program failed to calculate the time difference because the character length of the stored time overflowed and failed to calculate the current network condition in time.</p> <p>Click for additional information</p>
<p>Case: 00641061 ALEISSUE-1368</p>	<p>Summary: Need to display error message in the browser using external captive portal.</p>

Fixed Problem Reports Between Build 4.0.5.23 and 4.0.5.1025

PR	Description
Case: 00639594 ALEISSUE-1384	<p>Summary: Broadcast Filter All not working fine, as a consequence lot of broadcast “Who has” requests are generated by AP impacting battery life time and network link</p> <p>Click for additional information</p>
Case: 00647231 ALEISSUE-1383	<p>Summary: Wrong Access Role Profile applied after roaming when captive portal (authentication Open) is used.</p> <p>Explanation: Because the conditions were not reached, the context (ARP / Client MAC Address) was not exchanged between APs during roaming.</p> <p>Click for additional information</p>
Case: N/A ALEISSUE-1375	<p>Summary: APs generating ACI (Adjacent Channel Interference) when selecting wrong channels in the 2.4Ghz frequency.</p> <p>Explanation: As of AWOS 4.0.5 MR-1, the conditions that need to be met when moving from manual adjustment to automatic channel selection is improved.</p>
Case: 00645897 ALEISSUE-1402	<p>Summary: Some Wi-Fi stations are assigned VLAN 0, making them to get IP address from AP management subnet when using VLAN pooling.</p> <p>Explanation: The clients roaming from one band to another in the same AP, the AP will delete the clients roaming context information after it disassociated one band, and this happened before connecting another band. AP can't find the clients original ARP and apply a wrong ARP.</p> <p>Click for additional information</p>
Case: 00647242 ALEISSUE-1410	<p>Summary: Syslog logs lldp message , the AP MAC address omits the zero.</p> <p>Explanation: It is an issue to process display the clients MAC address.</p> <p>Click for additional information</p>
Case: 00642426 ALEISSUE-1413	<p>Summary: Add broadcast and multicast traffic limitation via UI for Stellar AP model AP1251.</p>

Open/Known Problems

The problems listed here include problems known at the time of the product's release. Any problems not discussed in this section should be brought to the attention of the Service and Support organization as soon as possible. Please contact customer support for updates on problem reports (PRs) where no known workaround was available at the time of release.

PR	Description	Workaround
ALEISSUE-990	Deauthentication reason 34(Disassociated because excessive number of frames need to be acknowledged, but are not acknowledged due to AP transmissions and/or poor channel conditions).	No workaround
WCF	WCF Feature is not supported when WLAN Client is running behind an HTTP Proxy	No workaround
WCF	WCF Feature is not supported when WLAN Client is using mobile applications, there is no restrictions (packets are not dropped by AP, no redirection to Restricted Web page)	No workaround
WCF	WCF Feature is not supported when WLAN Client is running IPv6	No workaround
Management VLAN	When the management VLAN is enabled, setting the static IP may fail	The static IP must be set first, and then enable the management VLAN.
DPI	[reflexive] configure link tracking. DPI_DROP does not take effect.	After modifying the reflexive, the client needs to go online and offline again, which can return to normal.
AP stateful ipv6 address	The ipv6 address of the dual-stack AP, AP is a stateful address. After configuring the open type of WLAN, to associate the WLAN, with the wireless network card of win 7 11n set to single-stack V6, check the network on-off condition of the V6 address.	When you manually configure a V6 address of the same network segment on the client as the gateway address, you can communicate with the same network address.
DPI FTP policy	Create one policy list binding and two policies, results that the user cannot access the ftp	There is no known workaround at this time.
ALEISSUE-1327	WCF not working very frequently on Mobile devices using browser.	No workaround.
ALEISSUE-1339	AP1101 can't forward data at 5G when channel utilization is high.	No workaround
ALEISSUE-1308	Interface vlan configuration lost when WLAN access timer is configured.	Will be fixed on AWOS 4.0.6
ALEISSUE-1367	Unable to push network in local breakout if it includes OV2500 IP address.	Will be fixed on AWOS 4.0.5 MR3

DHCP Server	DHCP Server is not available on AP1231 model.	Will be fixed on AWOS 4.0.6
RAP	Clients may not be access to network when switching desired AP from Group of RAP to a regular AP Group on 11AX platform devices.	Will be fixed on AWOS 4.0.6

Limitations and/or Dependencies

Feature	AP Model	Limitations and/or Dependencies
Dynamic VLAN	All	1. In Express mode the support of Dynamic VLAN Attribute returned by the Radius Server is not supported since AWOS 4.0.x
WCF	All	2. WCF does not support http over proxy scenario. 3. WCF does not support blocking mobile applications access. Client's packets are not restricted (packet not dropped by AP, no redirection to Restricted Web Page) 4. WCF does not support RAP scenario. 5. When using Iphone roaming between Aps, reject page can't be redirected when using Safari, but it works ok for other browser such as Chrome
HTTPs CP over proxy	All	For iOS does not support to configure URL to bypass the proxy, this function does not work on iOS devices.
AP 802.1x client	All	Wireless clients can't connect to internet on untag VLAN with AOS switch due to AOS switch treat all untag devices as 802.1x client.
Wired Port	AP1201HL	1. AP1201HL switches to a Group with downlink configuration, wired client cannot access it. 2. AP1201HL enables trust tag and option 82, wired client may not obtain IP address
DRM	All	In some cases, when the channel utilization reaches more than 90%, the channel does not switch automatically, which seriously affects the user experience.
IGMP Snooping	All Stellar Wi-Fi 6 AP Models	For 11AX devices, if there is no multicast querier in the environment, the conversion from multicast to unicast may fail. We recommend that the switch of IGMP Snooping feature be turned on by default.
Mesh	All	Multicast to unicast is not supported in Mesh mode. Because root AP to non-root AP does not implement the function of multicast to unicast in mesh mode, even if the client on non-root AP implements multicast to unicast, the efficiency is still not high.
DPI	AP1201/ AP1220 series/ AP1251	When DPI function is enabled, it is recommended to have an initial free memory size of about 30MB after AP booting up for system stable running. If the booting up free memory size is far less than 30MB, suggest removing unnecessary WLAN/VLAN/Policy/DPI rule on AP1201/AP1220/AP1251.
Bypass VLAN	AP1201H/ AP1201HL	If the bypass VLAN function is enabled, setting VLAN id A, and setting the management VLAN to tag VLAN id is also A, which will cause the AP itself to be inaccessible and

		affect the operation of AP. Therefore, there is a restriction here that the tag for managing VLAN cannot be the same as bypass.
mDNS	AP1201H/ AP1201HL /AP1261- RW-B	AP1201H/1201HL/AP1261-RW-B Downlink Terminal does not support mDNS message forwarding.
Show device name	All	When some clients connect to wlan, there is no option12 field in the dhcp message, so its hostname cannot be displayed.
Management VLAN Static IP LACP	AP1351/A P1451	When configure LACP + Management VLAN + Static IP for AP1351, the network will not be reachable after AP reboot if LACP aggregated link is formed, the workaround of this issue should be disable LACP on switch side.
Link aggregation	All	Link aggregation with management VLANs has a certain probability of failure
Link aggregation	AP1351	There is very low probability on AP1351 that ethernet PHY fail to receive messages in the scenario of link aggregation.
ALEISSUE-1294	All	This improvement might cause some lower version of SSH clients cannot connect to Stellar AP running this new build, upgrade SSH client version will avoid this problem.
ALEISSUE-1343	AP1201H(L)	VLAN 4090-4094 is not allowed configured.
11K	Aps without scan radio	To make sure 11k function work as expected, we should configure the AP background scanning on “Working Channel and Non-working Channel”.
DSCP	AP1451	Will be fixed on AWOS 4.0.6
Enhanced Open WLAN	All	Mobile devices with Apple iOS do not support OWE, Mobile devices with Android 10 or later support OWE, Computers with Windows 10 version 2004 or later and a wireless adapter that supports OWE.
Client Isolation Whitelist	All	Client A connect to WLAN1 with ARP1, and Client B connect to WLAN2 with ARP2, in this case, If Client A and B needs to communicate to each other, both of the two clients need to be added into whitelist, either one of Clients add into whitelist can't ensure communication between these two clients.
WPA Enterprise WLAN	All	Latest version of Windows 11 22h2 can't not connect to WPA Enterprise WLAN due to TLS version upgrade to 1.3, for solving the issue, please refer to link below: https://learn.microsoft.com/en-us/answers/questions/1018468/unable-to-connect-to-network-after-windows-11-22h2.html
Express mode WLAN number	All	Starting with AWOS 4.0.5 in Express mode, we can create 15 user SSIDs on clusters with following models. <ul style="list-style-type: none"> • AP1301H, AP132x, AP1331, AP136x, AP1351 & AP1451 If a cluster has any of the following models, limit remains at 7 user SSIDs. <ul style="list-style-type: none"> • AP1311, AP1301, AP12xx and AP1101

New Software Feature Descriptions

There is no new feature in this release.

Technical Support

Alcatel-Lucent Enterprise technical support is committed to resolving our customer’s technical issues in a timely manner. Customers with inquiries should contact us at:

Region	Phone Number
North America	1-800-995-2696
Latin America	1-877-919-9526
Europe Union	+800 00200100 (Toll Free) or +1(650)385-2193
Asia Pacific	+65 6240 8484

Email: ale.welcomecenter@al-enterprise.com

Internet: Customers with Alcatel-Lucent service agreements may open cases 24 hours a day via Alcatel-Lucent’s support web page at: <https://myportal.al-enterprise.com/>.

Upon opening a case, customers will receive a case number and may review, update, or escalate support cases on-line. Please specify the severity level of the issue per the definitions below. For fastest resolution, please have telnet or dial-in access, hardware configuration—module type and revision by slot, software revision, and configuration file available for each switch.

Severity 1 - Production network is down resulting in critical impact on business—no workaround available.

Severity 2 - Segment or Ring is down or intermittent loss of connectivity across network.

Severity 3 - Network performance is slow or impaired—no loss of connectivity or data.

Severity 4 - Information or assistance on product feature, functionality, configuration, or installation.

www.al-enterprise.com The Alcatel-Lucent name and logo are trademarks of Nokia used under license by ALE. To view other trademarks used by affiliated companies of ALE Holding, visit: www.al-enterprise.com/en/legal/trademarks-copyright. All other trademarks are the property of their respective owners. The information presented is subject to change without notice. Neither ALE Holding nor any of its affiliates assumes any responsibility for inaccuracies contained herein. © Copyright 2022 ALE International, ALE USA Inc. All rights reserved in all countries.