



Intermediate Release Notes

OmniSwitch 6624/6648/7700/7800/8800

Release 5.4.1.601.R01

The following is a list of issues that have been identified and corrected in AOS software release. This document is intended to be used as a pre-upgrade guide and does not replace the Release Notes which are created for every GA release of software.

Important Notice: For a copy of software releases not posted on the Web, or if you have questions or concerns, please contact Alcatel's Technical Support Department.

Intermediate Release Notes	1
OmniSwitch 6624/6648/7700/7800/8800	1
Release 5.4.1.601.R01	1
Problems Fixed Between Builds 236 and 283	3
Problems Fixed Between Builds 284 and 288	8
Problems Fixed Between Builds 289 and 298	9
Problems Fixed Between Builds 299 and 322	10
Problems Fixed Between Builds 323 and 330	12
Problems Fixed Between Builds 331 and 341	13
Problems Fixed Between Builds 342 and 352	14
Problems Fixed Between Builds 353 and 363	15
Problems Fixed Between Builds 364 and 375	17



Problems Fixed Between Builds 376 and 385	18
Problems Fixed Between Builds 386 and 401	18
Problems Fixed Between Builds 402 and 416	20
Problems Fixed Between Builds 417 and 424	21
Problems Fixed Between Builds 425 and 435	22
Problems Fixed Between Builds 436 and 455	23
Problems Fixed Between Builds 456 and 464	25
Problems Fixed Between Builds 465 and 471	26
Problems Fixed Between Builds 472 and 477	26
Problems Fixed Between Builds 478 and 488	27
Problems Fixed Between Builds 489 and 495	27
Problems Fixed Between Builds 496 and 500	28
Problems Fixed Between Builds 501 and 510	28
Problems Fixed Between Builds 511 and 516	29
Problems Fixed Between Builds 517 and 522	30
Problems Fixed Between Builds 523 and 525	31
Problems Fixed Between Builds 526 and 540	31
Problems Fixed Between Builds 541 and 553	32
Problems Fixed Between Builds 554 and 557	33
Problems Fixed Between Builds 558 and 563	34
Problems Fixed Between Builds 564 and 576	34
Problems Fixed Between Builds 577 and 588	36
Problems Fixed Between Builds 589 and 591	36
Problems Fixed Between Builds 592 and 597	37
Problems Fixed Between Builds 598 and 601	37
Under Verification	37
Known Issues	43



Problems Fixed Between Builds 236 and 283

PR	82076	Build:	5.4.1.236.R01
Summary:	Power Down/Up traps not sent to the NMS station if the redundant power supply is not on primary unit		
PR	100171	Build:	5.4.1.236.R01
Summary:	OS6 stalled with QDISPATCHER warnings and Invalid Address used during a memory free with MemMon dump		
Explanation:	IPC Receive logic in 6600 had couple of flaws which resulted in bad memory reference, bad receive and memory double free errors. Resolved these by improving the IPC receive logic and fixing some of the loopholes in transmit functions.		
PR	100358	Build:	5.4.1.236.R01
Summary:	OS6602 doesn't respect IP mobility rule when MAC rule is removed. Impacts Quarantine Manager QM		
Explanation:	VLAN port hardware setting is not flushed properly when MAC rule is getting deleted. So fix is done to flush the VLAN port hardware setting of that specific VLAN configured in that rule.		
PR	100422	Build:	5.4.1.236.R01
Summary:	No Trap are sent to the NMS when a stacking link is disconnected		
PR	100835	Build:	5.4.1.236.R01
Summary:	Clearing the switch log files removes the syslog server configuration		
Explanation:	Preserve swlog socket configuration after swlog clear		
PR	100969	Build:	5.4.1.236.R01
Summary:	CPU spikes caused by TaGmnCtrl when changing VLAN port assignment		
Explanation:	Issue is due to the task stuck up in the for loop for 2-3 seconds. So CPU hikes to 100% utilization. Proper defense checks are added for reducing the for loop. Now 100% CPU usage is avoided.		
PR	100871	Build:	5.4.1.237.R01
Summary:	Apply OpenSSH patch.		



PR	100512	Build:	5.4.1.238.R01
Summary:	ALL SNMP traffic (traps + replies) outgoing the switch should use Loopback0 as IP-SA		
Explanation:	All SNMP traffic should use Loopback0 as IP-SA if configured		
PR	100838	Build:	5.4.1.239.R01
Summary:	"Unable to remove NI %d from multicast socket" is recorded upon NI reboot		
PR	101421	Build:	5.4.1.239.R01
Summary:	OS6: Slow Management Telnet-Ping upon Linkagg Up-Down depending on the Up-Down order		
PR	101753	Build:	5.4.1.242.R01
Summary:	6800 Switch : Auth ip responding to Client DNS query before login		
PR	101522	Build:	5.4.1.243.R01
Summary:	LSA from 64th neighbor not been programmed into the kernel routing table		
PR	101475	Build:	5.4.1.244.R01
Summary:	100% CPU load as soon as port network cable on mobile port is un-plugged and re-plugged		
PR	101991	Build:	5.4.1.245.R01
Summary:	Crashes on AOS switches after turning on IPMS		
PR	101487	Build:	5.4.1.246.R01
Summary:	On OS68, IPMS is blocked when linkagg port disconnects		
PR	101926	Build:	5.4.1.247.R01
Summary:	802.1x fail authentication policy not working in 6602 Switch		
PR	102090	Build:	5.4.1.247.R01
Summary:	OS7 LinkAgg port is not learning/sending any traffic via one port on one VLAN		
PR	101115	Build:	5.4.1.248.R01
Summary:	swlog output socket' completion command refers to rfc-3513		

PR	102212	Build:	5.4.1.248.R01
Summary:	MAC learned on Linkagg are not aging out in CMM		
PR	102718	Build:	5.4.1.250.R01
Summary:	Renew AVLAN java applets		
PR	103096	Build:	5.4.1.250.R01
Summary:	L3SrcUnicast L3DestBroad DHCP packets are not relayed if the L3 src is in the DHCP server network		
PR	101577	Build:	5.4.1.251.R01
Summary:	The mac-address of the client shows up in the Avlan and Default Vlan even after getting de-authen.		
Explanation:	Corrected Mac-address comparison for avlan client mac-address in a specific scenario.		
PR	103198	Build:	5.4.1.253.R01
Summary:	802.1x will not work on the same port that has mac authentication		
PR	102979	Build:	5.4.1.256.R01
Summary:	Unable to display switch log file in WebView		
PR	103093	Build:	5.4.1.257.R01
Summary:	After canceling the scheduled reload it affects the configuration status; Need fix.		
PR	104222	Build:	5.4.1.257.R01
Summary:	Unable to save MD5 ospf configuration		
PR	101544	Build:	5.4.1.258.R01
Summary:	SLB does not work once ip SLB server admin status is disable and enable again		
PR	104878	Build:	5.4.1.258.R01
Summary:	Second Generation Modules are not displayed in the WebView of OS7700		
PR	104067	Build:	5.4.1.259.R01
Summary:	Corrupted multicast entries		



PR	105174	Build:	5.4.1.260.R01
Summary:	DVMRP routes process caused switch to crashed with cs_system.pmd		
Explanation:	DVMRP Route processing logic corrected to terminate the route processing when the length of the packet is less than minimum length.		
<hr/>			
PR	102530	Build:	5.4.1.261.R01
Summary:	Last change value for vlan ip not displayed correctly in OmniVista.		
<hr/>			
PR	104849	Build:	5.4.1.261.R01
Summary:	show 802.1x' on stack of 6600 locks up console		
<hr/>			
PR	104852	Build:	5.4.1.261.R01
Summary:	802.1x non-supp mac-authentication fails but port still passes unicast traffic		
<hr/>			
PR	105047	Build:	5.4.1.261.R01
Summary:	802.1x ports still have 802.1x policies even though 802.1x is disabled		
<hr/>			
PR	105114	Build:	5.4.1.261.R01
Summary:	6600 unit in stack comes back up after crash vlan port never goes to forwarding		
<hr/>			
PR	103547	Build:	5.4.1.262.R01
Summary:	OS7700: Previously configured static route doesn't work after rebooting the switch		
<hr/>			
PR	104966	Build:	5.4.1.262.R01
Summary:	802.1x Request Identity not triggered if there is no EAP-Start		
<hr/>			
PR	105512	Build:	5.4.1.263.R01
Summary:	STP were not detecting and blocking the ports with these Type 1 (IBM) connectors		
<hr/>			
PR	104059	Build:	5.4.1.264.R01
Summary:	QoS classify13 bridged causes the switch not to forward traffic after HSRP routers toggle		
<hr/>			



PR	98493	Build:	5.4.1.266.R01
Summary:	The Switch uses the outer "anonymous" Username in 802.1x Accounting packet in case of EAP-TTLS-PAP		
Explanation:	Radius Client Software on AOS ignores User-Name Attribute returned from Radius Server in Access Accept packets. As per Radius RFC this is not mandatory, but it is important to use this name for accounting requests where the clients authenticate based on t		
PR	105737	Build:	5.4.1.266.R01
Summary:	"memPartAlloc: block too big" memory corruption with large STP configuration file		
PR	104054	Build:	5.4.1.267.R01
Summary:	Internal Error when executing "802.1x initialize slot/port" on non 802.1x ports		
PR	104053	Build:	5.4.1.268.R01
Summary:	Internal Error when creating an IP interface with more than 20 characters		
PR	105880	Build:	5.4.1.269.R01
Summary:	Impossible to stack 6602-48: csHsmNsmT2EndAppliStart() receive EOAS		
PR	99548	Build:	5.4.1.270.R01
Summary:	Interface uptime is wrongly displayed on AOS switches		
PR	104896	Build:	5.4.1.273.R01
Summary:	802.1x mac-auth users go down and never recover after 5 second spanning tree loop		
PR	105359	Build:	5.4.1.273.R01
Summary:	Huge volume of multicast traffic spikes the CPU TO 100 % with TTL value set to 1 in 6602		
Explanation:	Reduce IPMS processing for multicast data packets with IP ttl 1 which are sent to software for statistics purpose.		
PR	105754	Build:	5.4.1.275.R01
Summary:	DHCP Relay forwarding do not comply with RFC2131 when the Offer is not in GiAddr subnet		



PR **99748** Build: 5.4.1.276.R01
 Summary: CLI lock up if the telnet session to the switch is lost when trying to read a pmd file
 Explanation: Mismatch between the MIB file & trap manager file is fixed

PR **103192** Build: 5.4.1.276.R01
 Summary: System hung with crash file

PR **105862** Build: 5.4.1.276.R01
 Summary: Client cannot get an IP address if avlan default-traffic is enabled.

PR **106509** Build: 5.4.1.276.R01
 Summary: AMAP information of Local Slot not displayed properly when using a SNMP Get command on MIB Browser

PR **107150** Build: 5.4.1.279.R01
 Summary: 802.1x performance issue

PR **106173** Build: 5.4.1.281.R01
 Summary: IP interface changes on the switch can not be seen on OmniVista without reload

PR **106193** Build: 5.4.1.282.R01
 Summary: NI extractions

Problems Fixed Between Builds 284 and 288

PR **102999** Build: 5.4.1.285.R01
 Summary: Enhancement code for Data Exception

PR **82076** Build: 5.4.1.287.R01
 Summary: Power Down/Up traps not sent to the NMS station if the redundant power supply isnt on primary unit

PR **105775** Build: 5.4.1.288.R01
 Summary: OmniSwitch running DVMRP reporting "Recvd invalid mask "



PR **107419** Build: 5.4.1.288.R01
 Summary: Port is not moving to mobile when all the rules are of Ethernet II and ethertype alone varies
 Explanation: Code changes done in GMN for handling unknown prototype

PR **107555** Build: 5.4.1.288.R01
 Summary: Permanent Mac is getting Flushed When NI is Made Down

Problems Fixed Between Builds 289 and 298

PR **107618** Build: 5.4.1.289.R01
 Summary: OSPF Route not synchronized with IP routing table

PR **107599** Build: 5.4.1.290.R01
 Summary: Telnet/SS

PR **107864** Build: 5.4.1.291.R01
 Summary: Port shutdown when CPU reach a configured Threshold

PR **103257** Build: 5.4.1.292.R01
 Summary: System timezone configured on any AOS switch is not stored in boot.cfg

PR **93035** Build: 5.4.1.293.R01
 Summary: IP Multicast 'leave group' messages are sent with a wrong Source Address
 Explanation: Leave messages were sent with an invalid Source MAC address, two bytes were added before the MAC address. For example: the following address was sent 00 00 01 00 5e xx instead of 01 00 5e xx xx xx.

PR **108177** Build: 5.4.1.293.R01
 Summary: Unable to create ipms forwarding entry

PR **108236** Build: 5.4.1.293.R01
 Summary: 6648 reporting ipms memory allocation

PR **96221** Build: 5.4.1.295.R01
 Summary: SFM down FABRIC: Awaiting enough UP Fabrics (#up=0)

PR **101853** Build: 5.4.1.295.R01
 Summary: When reading MIB entries a stack is handled as one chassis



PR **107583** Build: 5.4.1.298.R01
 Summary: Switch crashed with MemMon dump and source learning task suspended

PR **108454** Build: 5.4.1.298.R01
 Summary: PC with dynamic IP address fail to classify under non-suppliant GM policy

Problems Fixed Between Builds 299 and 322

PR **94914** Build: 5.4.1.299.R01
 Summary: SNMP response sent twice for the first SNMP get
 Explanation: Drop duplicate SNMP Request packets received in IPNI via the source learning path from hardware in the following particular case - when the destination IP is resolved and when the source IP is not yet resolved/learnt.

PR **108705** Build: 5.4.1.300.R01
 Summary: Though the mobile port is moved to respective vlan , DHCP is flooded on default vlan

PR **101852** Build: 5.4.1.302.R01
 Summary: When reading MIB serial numbers are not shown completely

PR **108528** Build: 5.4.1.303.R01
 Summary: Switch is not rechecking QoS policies when traffic path changes

PR **108625** Build: 5.4.1.303.R01
 Summary: QoS task locked up when OV is disconnected while applying a new rule

PR **107504** Build: 5.4.1.304.R01
 Summary: RMON not updating

PR **108666** Build: 5.4.1.304.R01
 Summary: QoS "maximum bandwidth" limits bandwidth to values not accurate

PR **108907** Build: 5.4.1.306.R01
 Summary: 802.1x port doesn't grab a IP until unless the port belongs to default vlan to which it moves



PR **102303** Build: 5.4.1.307.R01
Summary: 2nd stack switch gets IP address with source MAC address
00:00:00:01:00:00

PR **108701** Build: 5.4.1.308.R01
Summary: Static ARP entries are automatically added to the running configuration after
a takeover on LA
Explanation: Not to store bogus arp entries in configuration file.

PR **108713** Build: 5.4.1.308.R01
Summary: LinkAgg Task crash after NI extraction

PR **108143** Build: 5.4.1.309.R01
Summary: OSPF LSDB entries do not register in the routing table

PR **101176** Build: 5.4.1.312.R01
Summary: AOS switches go to unsaved state when trap replay turned on OV

PR **107510** Build: 5.4.1.314.R01
Summary: 8800 losing communication with NIs running 5.4.1

PR **109280** Build: 5.4.1.314.R01
Summary: 68xx new daylight saving time for March 11, 2007 compliance does not work.
It would select March 4

PR **108850** Build: 5.4.1.315.R01
Summary: Onex task got suspended on 6850 PMD was generated

PR **109307** Build: 5.4.1.315.R01
Summary: Need a command to set the NAS-Port-Type on a switch

PR **109273** Build: 5.4.1.318.R01
Summary: BPDUShutdownPorts is not working for 802.1x port

PR **107557** Build: 5.4.1.319.R01
Summary: OS8800 - Switch crashed after adding new OSPF area into network. PMD
files created.



PR **103274** Build: 5.4.1.320.R01
 Summary: Memory corruption under special telnet exit with "zcBufDelete: Task 0x4016020 freeing bad buffer" (S)

PR **109315** Build: 5.4.1.321.R01
 Summary: OS7800: Dump File Analysis. Switch crashed with pmds.

PR **109228** Build: 5.4.1.322.R01
 Summary: OSPF-RIP NSSA Area redistribution issue

Problems Fixed Between Builds 323 and 330

PR **103890** Build: 5.4.1.325.R01
 Summary: Need to know the reason for message firenzeI2cReceiveAck: Read Error Slot 6 Firenze 2 Gbic 7

PR **108028** Build: 5.4.1.326.R01
 Summary: OS-6648 QDRIVER alert qd efp: enet buffer alloc failure

PR **109686** Build: 5.4.1.327.R01
 Summary: OS7700 will output STR EsmDrv error

PR **109965** Build: 5.4.1.328.R01
 Summary: Wrong vlan assigned after a 802.1x authentication on a radius server connected to an OS6602

PR **111025** Build: 5.4.1.328.R01
 Summary: 802.1x failure result in PC grabbing wrong IP address.

PR **110224** Build: 5.4.1.329.R01
 Summary: After link down - multicast source is not registering with PIMSM RP

PR **110228** Build: 5.4.1.329.R01
 Summary: PIM-SM Crash

PR **109140** Build: 5.4.1.330.R01
 Summary: 7700 uptime reset after 497 days
 Explanation: sysUpTime is not wrapped up after 497 days.

PR **109997** Build: 5.4.1.330.R01
 Summary: OS-7000 showing many PORT-MGR messages

Problems Fixed Between Builds 331 and 341

PR **107496** Build: 5.4.1.331.R01
 Summary: Correct level for systrace messages which are filling up the systrace buffer
 Explanation: Severity level of the systrace buf of the message which fills the system trace buffer reduced.

PR **110080** Build: 5.4.1.333.R01
 Summary: 7700 crash with memory exception

PR **108012** Build: 5.4.1.334.R01
 Summary: OSPF LSDB routes not being processed

PR **101253** Build: 5.4.1.335.R01
 Summary: Webview task is running at 100% when logging using http
 Explanation: When an AVLAN client connects from a PC running Windows Vista, there might be a CPU spike in the switch or in the Windows PC. Also the webview pages might take a long time to download. In such situations the value of the flag 'taskdelaytransmitpend' shoul

PR **110374** Build: 5.4.1.335.R01
 Summary: IGMP Report Messages are duplicated, proxy behavior is not clear

PR **112364** Build: 5.4.1.335.R01
 Summary: RFC 2868 using 802.1x authentication tunnel attributes not working on 7700 using code 5.4.1.322R01

PR **111238** Build: 5.4.1.336.R01
 Summary: OS9700 Cannot rip peer with other vend router. RIP updates received only once after interface is up.

PR **111033** Build: 5.4.1.338.R01
 Summary: Learned Port-Security with mac-range blocks valid and invalid mac-addresses



PR **90581** Build: 5.4.1.339.R01
 Summary: httpServerDoSAttackTrap contains no src IP of the attack

PR **112456** Build: 5.4.1.340.R01
 Summary: When STP is disabled able to see the RP and NBRP
 Explanation: Resetting the Spanning Tree parameters if the Spanning tree is disabled.

PR **92679** Build: 5.4.1.341.R01
 Summary: Task tpimsm suspended after some configuration changes
 Explanation: Using Static-RP Configuration and then changing the max-rps may cause tpimsm to suspend.

PR **111412** Build: 5.4.1.341.R01
 Summary: OS9700 creates dump file and NI 2 hangs up for 5 minutes after upgrading the code.
 Explanation: Process linkAgg Marker PDU's on the ports only where linkagg is enabled. If marker PDU's are received on non-linkAgg ports discard those packets.

Problems Fixed Between Builds 342 and 352

PR **113585** Build: 5.4.1.343.R01
 Summary: 7800 switch does not respond to SNMP query for GNI2-U2 module

PR **115064** Build: 5.4.1.345.R01
 Summary: Port status is Forwarding without a cable attached.

PR **115736** Build: 5.4.1.347.R01
 Summary: Show aaa avlan auth-ip <vlan#> shows unexpected results.

PR **115499** Build: 5.4.1.349.R01
 Summary: SNMP "get" returns wrong values for some AOS mibs

PR **108902** Build: 5.4.1.352.R01
 Summary: New burst of traffic is not being flooded (only 2 out of 10 packets are flooded)

PR **110083** Build: 5.4.1.352.R01
 Summary: It takes around 4 to 5 min for the mac-address to get flushed out when the auth client is disconnect



Problems Fixed Between Builds 353 and 363

PR	114504	Build:	5.4.1.353.R01
Summary:	OSPF Border Routers aging out on 2nd hop router, 1st router not flooding LSA		
PR	116786	Build:	5.4.1.353.R01
Summary:	OSPF issue: In NSSA redistributed RIP routes are not learned with correct destination IP		
PR	116191	Build:	5.4.1.354.R01
Summary:	Show vlan [instance] port and show spantree ports, display different results in 6602 with 5.1.6.353		
PR	116445	Build:	5.4.1.354.R01
Summary:	sysUptime is not reported accurately in WebView		
PR	98291	Build:	5.4.1.355.R01
Summary:	BPDU are not sent out when reverting back to STP Flat Mode and re-enabling VLAN 1		
Explanation:	In FLAT mode, STP kernel is enabled when VLAN admin state is received after the vlan stp state.		
PR	100931	Build:	5.4.1.357.R01
Summary:	802.3ad (Dynamic) and Omnichannel (static) in AOS Vs Etherchannel in IBM P57D (AIX 50) server.		
PR	108600	Build:	5.4.1.357.R01
Summary:	Lpower ->suspended on stack of 6600 and created dump file		
PR	105084	Build:	5.4.1.358.R01
Summary:	Cannot ping, telnet, WebView, vlan1 ip obtained from ip helper bootup enable on 6600 switch		
PR	106638	Build:	5.4.1.358.R01
Summary:	System crash upon creating a new VLAN with CS except handler: exception 768 in task 0x89b4a40		



PR	107673	Build:	5.4.1.358.R01
Summary:	task taQoS was suspended on NI-8 and pmd file created need to analyze the same :		
PR	108563	Build:	5.4.1.358.R01
Summary:	Unexpected takeover of CMM_B on a OS7700 with error exception - Floating-Point Exception IEEE-754		
PR	108708	Build:	5.4.1.358.R01
Summary:	OSPF adjacency cleared and the CMM may reset when the system time is manually changed		
PR	109011	Build:	5.4.1.358.R01
Summary:	When PC moved from one vlan to another the PC still pulls up the same IP as earlier vlan subnet		
PR	109293	Build:	5.4.1.358.R01
Summary:	Ping across static linkagg failed when primary link failed		
PR	111567	Build:	5.4.1.358.R01
Summary:	STP crash while hotswaping 10 gigabit module		
Explanation:	Check added to avoid crash during SNMP get on STP tables.		
PR	113129	Build:	5.4.1.358.R01
Summary:	Certain AVLAN client can't get log off from switch		
Explanation:	The avlan auth ip structure gets corrupted, when a vlan is deleted.		
	The corruption is prevented by using the new vlan instead of previous index while initializing the auth-ip to zero.		
PR	108603	Build:	5.4.1.359.R01
Summary:	Switch Configuration Status Flag modified when executing the reload the command		
PR	107600	Build:	5.4.1.361.R01
Summary:	On OS8800 GNI-U8 and ENI-C24 created PMD: Need analysis.		
PR	108934	Build:	5.4.1.361.R01
Summary:	Telnet session ending issue		



PR **116094** Build: 5.4.1.361.R01
 Summary: PX: info memPartAlloc: block too big - 2048 in partition 0x3cd99c. -- error on console

PR **112742** Build: 5.4.1.362.R01
 Summary: Admin down/up on 10G, random Vlan stops learning/forwarding after reconvergence

PR **111585** Build: 5.4.1.363.R01
 Summary: OmniVista Showing High CPU Traps

PR **117677** Build: 5.4.1.363.R01
 Summary: ip helper' info does not show in write terminal as configured in the CLI

Problems Fixed Between Builds 364 and 375

PR **110032** Build: 5.4.1.364.R01
 Summary: Layer 2 access-list not working as expected in 5.1.6

PR **113556** Build: 5.4.1.364.R01
 Summary: 6600 running 5.1.6.R02 creates extra policy rules while creating a policy using OneTouch voice/data

PR **109555** Build: 5.4.1.366.R01
 Summary: AOS 6800 24L - Webview displays flash-synchro completed while synchronization is still running

PR **113940** Build: 5.4.1.366.R01
 Summary: OS7800: PMD file analysis. slo2sli0ver1.pmd formed due to NI monitoring timeout.

PR **117587** Build: 5.4.1.366.R01
 Summary: "INVALID OUI" error while trying to configure new mac-range on a 7700 running 5.1.5.316.R04.

PR **101593** Build: 5.4.1.367.R01
 Summary: Mirrored port loses connection to VRRP VIP address, Its DGW. Can't go outside its VLAN.



PR **116520** Build: 5.4.1.368.R01
 Summary: Explain the details that could be observed and collected on a spy output

PR **101672** Build: 5.4.1.369.R01
 Summary: No static route added when receiving IP address and gateway from DHCP with IP helper boot-up enabled

PR **116748** Build: 5.4.1.375.R01
 Summary: Debug memory command crashed the switch

Problems Fixed Between Builds 376 and 385

PR **110380** Build: 5.4.1.377.R01
 Summary: Using any 3rd party NMS the Designated Bridge shows wrongly on Non-Designated Bridge

PR **118444** Build: 5.4.1.378.R01
 Summary: OS7700: ip udp relay NBNSNBDD command wrong parsing

PR **112256** Build: 5.4.1.380.R01
 Summary: NI remained down after CMM takeover

Problems Fixed Between Builds 386 and 401

PR **118750** Build: 5.4.1.387.R01
 Summary: Messages to Syslog server do not use Loopback0 as IP-SRC

PR **117322** Build: 5.4.1.389.R01
 Summary: OS7800 Crash producing Rmon task error

PR **119427** Build: 5.4.1.390.R01
 Summary: Static dhcp-snooping binding table entries on 6850 are getting flushed when PC is disconnected and P

PR **106142** Build: 5.4.1.391.R01
 Summary: The mac group policy doesn't work on a authenticated port



PR	102483	Build:	5.4.1.392.R01
Summary:	VRRP ARP entry not updated after removing one NI from a Link agg		
PR	109706	Build:	5.4.1.393.R01
Summary:	Port blocking on a stack of 6602-48 after the power off of the primary unit.		
PR	97958	Build:	5.4.1.395.R01
Summary:	ERROR: esmDrv_findIfIndex<< GlobalPort > when trying to print the port structure of an unknown port		
Explanation:	While getting the lfindx in the ESM driver, there is no check to see whether the module type returned is valid for the slot for which the CLI is executed.		
	Added a check for the verification of the module type and returning without further processing if		
PR	115297	Build:	5.4.1.395.R01
Summary:	NETWORK INSTABILITY WHEN CHANGING THE PORT BLOCKING		
PR	119761	Build:	5.4.1.395.R01
Summary:	Cpu spikes up due to the IPmem process on 8800.		
Explanation:	Changes made to report message should not be transmitted to the neighbor port if the port on which the report has been received and the neighbor connected is same. We dont generate a report message if the client port is same as the querier port.		
PR	119290	Build:	5.4.1.396.R01
Summary:	port does not forward traffic after disabling 802.1x authentication		
PR	118662	Build:	5.4.1.397.R01
Summary:	6602 Idle Unit Crashed During Flash Synchro		
PR	118937	Build:	5.4.1.397.R01
Summary:	OS-6600: Unexpected reboot of a stack of three 6600 running 5.1.6.370.R02		
PR	119860	Build:	5.4.1.397.R01
Summary:	ip dvmrp interface will be lost on rebooting the switch, creating a boot.cfg.err file		
PR	88557	Build:	5.4.1.398.R01
Summary:	Need the ability to disable auto-negotiation on GNI U2 and U12		



PR	119133	Build:	5.4.1.398.R01
Summary:	Stack of 6600 is learning MAC addresses as static instead of dynamic in 5.4.1.234.R01		
PR	119893	Build:	5.4.1.398.R01
Summary:	If RADIUS server returns bogus value in "Alcatel-Lucent-Asa-Access" flag the CPU is going to 100%.		
PR	110057	Build:	5.4.1.399.R01
Summary:	When the auth-ip is manually assigned, after reboot it shows the default auth-ip even after write me		
PR	119696	Build:	5.4.1.401.R01
Summary:	STR NON FATAL: CMM Power set to default value (50 Watts) on OS7000-5.1.6.404R02 seen in every bootup		
Explanation:	entPhysicalPower value is properly updated using the value from BBUS Bridge EEPROM		

Problems Fixed Between Builds 402 and 416

PR	112381	Build:	5.4.1.405.R01
Summary:	UDP relay does not forward broadcast UDP packets		
Explanation:	Supporting subnet broadcast at vlan level.		
PR	115340	Build:	5.4.1.408.R01
Summary:	Reboots with unknown cause in 66xx stack.		
Explanation:	PMD enhancement to include the NI history buffer information		
PR	120614	Build:	5.4.1.410.R01
Summary:	802.1x "supp-timeout" value changes to 2 after switch reload.		
Explanation:	Fix for retaining the supp-timeout value while doing "write memory"		
PR	101093	Build:	5.4.1.411.R01
Summary:	Core2 7800: Unsolicited takeover		
Explanation:	Hello protocol messages to use URGENT pool buffers. Swlog not to wait-forever on message queue, instead timeout on one second		



PR **120335** Build: 5.4.1.414.R01
 Summary: It takes long time for Windows Vista Avlan client to download the java applet after web authenticati
 Explanation: We currently Support Java- SE Runtime Environment 6 update 3.

 Java version 1.6.0_03

 jre-6u3-windows-i586-p-s.exe

Notes: Other Java versions may not have been tested and nor supported.

PR **120915** Build: 5.4.1.416.R01
 Summary: Slow avlan authentication, ip reassigning using window vista client
 Explanation: We currently Support Java- SE Runtime Environment 6 update 3.

 Java version 1.6.0_03
 jre-6u3-windows-i586-p-s.exe

Notes: Other Java versions may not have been tested and nor supported.

Problems Fixed Between Builds 417 and 424

PR **99735** Build: 5.4.1.418.R01
 Summary: SSH crash when commands with long output run on SSH session with slow link to switch
 Explanation: Under certain conditions when long show commands are issued on a ssh session, ssh task crash is observed and the switch reboots with a pmd. Avoided ssh crash by adding suitable defense checks in ssh software which validate a memory address before accessin

PR **120574** Build: 5.4.1.419.R01
 Summary: Network 10 alone not getting redistributed; OS6800

PR **120652** Build: 5.4.1.419.R01
 Summary: Received packet loss on GNI-U12
 Explanation: Fix to dispaly rx lost frms in cli



PR **121290** Build: 5.4.1.421.R01
 Summary: Wake on Lan on 802.1x port does not work properly on OS6800 running 6.3.1R01.
 Explanation: Fixed the issue in opening the egress logic of a 802.1x enabled port

PR **119726** Build: 5.4.1.422.R01
 Summary: Cannot disable ip multicast proxying
 Explanation: Save multicast no proxying command into boot.cfg

PR **120738** Build: 5.4.1.423.R01
 Summary: Non-contiguous mask in a static route getting changed in "Show ip route".
 Explanation: Validation done to check non contiguous mask in a static route.

PR **120581** Build: 5.4.1.424.R01
 Summary: User authentication failed using LDAP server
 Explanation: Use nonblocking LDAP API calls to avoid lockup between the LDAP Main task and the LDAP client task.

Problems Fixed Between Builds 425 and 435

PR **115052** Build: 5.4.1.426.R01
 Summary: "force" the MAC only authentication without checking for a 802.1x supplicant
 Explanation: Support for classifying the client as non-suppliant immediately when the supp-polling retry value is set to zero.

PR **123131** Build: 5.4.1.431.R01
 Summary: DVMRP packets are replicated
 Explanation: Drop IGMP and DVMRP Control packets through unresolved channel in 6602/6624/6648.

PR **119874** Build: 5.4.1.433.R01
 Summary: 1 hr max CPU value not showing correct value on OS7800
 Explanation: Display 1 hour Maximum Value correctly in "show health"

PR **120109** Build: 5.4.1.433.R01
 Summary: CMM crashed due to exception in STP task
 Explanation: Check added to avoid crash during SNMP walk on STP tables.



Problems Fixed Between Builds 436 and 455

PR **123380** Build: 5.4.1.436.R01
 Summary: DHCP does not relay to the 2nd DHCP server
 Explanation: The agent information value i.e, option 82 is checked only once prior to all the DHCP servers configured. Previously it was checked for all the servers separately.

PR **123159** Build: 5.4.1.437.R01
 Summary: 6850 reboots after scanning it using Qualys
 Explanation: To fix Emweb server crash when the QualysScan tool is used to scan the switch.

PR **122781** Build: 5.4.1.438.R01
 Summary: OS8800 - Switch Crash. PMD file analysis required.
 Explanation: UDP packets in NI are rate limited to 256 pkts/ sec and 1024 pkts/ sec on the CMM. This is to ensure a storm of UDP broadcast traffic does not chew up all the system buffers.

PR **121836** Build: 5.4.1.439.R01
 Summary: OS7800 crashed with Hardware Failure type 4 and memory buffer depletion exception

PR **110134** Build: 5.4.1.440.R01
 Summary: PC treated as non-suppligant cannot move back to 802.1x unless down/up switch port
 Explanation: Issue of non-suppligant entries not getting deleted while it is getting deleted in the mac-address table is fixed.

PR **124178** Build: 5.4.1.441.R01
 Summary: Need to disable sending out BPDU's from the Mobile port while STP is disabled
 Explanation: Global variable control in the CMM to block/allow sending out BPDU's from the Mobile port. This would be effective only from AlcatelDebug.cfg during bootup.

PR **123052** Build: 5.4.1.442.R01
 Summary: show spantree cist ports displays wrong primary port for linkagg
 Explanation: Changes done to display the primary port field correctly for linkagg ports in "show spantree cist ports active" cmd

PR	124550	Build:	5.4.1.445.R01
Summary:	INTIP card not able to download image from TFTP server when 6602 is VRRP Primary		
Explanation:	Dropping packet from unresolved channel to CPU to avoid duplicate ICMP reply in case of VRRP VIP and VLAN interface IP are different.		
PR	93822	Build:	5.4.1.448.R01
Summary:	Connectivity Issue in 10G Links between OS8800s		
Explanation:	Problem was discovered to be pre-production release hardware, either the XFP or the 10G NI. Once all hardware that was below proper rev was replaced issues were resolved		
PR	99886	Build:	5.4.1.448.R01
Summary:	NI Task suspended TaskName: talpni followed by NI reboot		
Explanation:	Added invalid memory check at lower boundary of memPools		
PR	123413	Build:	5.4.1.448.R01
Summary:	BBUS resets during the takeover affecting the communication of the Primary and Secondary CMM.		
Explanation:	Enabled auto hello answer and BBUS reset on Primary during secondary's hello inactivity, to stabilize the BBUS and avoid takeover.		
PR	124132	Build:	5.4.1.448.R01
Summary:	Prepend values are not displayed for the Secondary IP of the vlan		
Explanation:	Check for Number of AS Prepended when Queued attribute found for route		
PR	124343	Build:	5.4.1.448.R01
Summary:	6648 .PMD DUMP Analysis		
Explanation:	Validity check introduced for URL lookup in file system		
PR	96520	Build:	5.4.1.449.R01
Summary:	OS6600 "show qos queue" should be removed as it does not return expected information		
Explanation:	show qos queue command removed for OS6 cli		
PR	94213	Build:	5.4.1.450.R01
Summary:	Remove "ip multicast max-ingress-bandwidth" command from CLI guide		
Explanation:	Removed the command "ip multicast max-ingress-bandwidth" as the Omni Switch 6600 does not support it.		



PR	100272	Build:	5.4.1.451.R01
Summary:	Impossible to modify NTP configuration - Internal Error returned by CLI		
Explanation:	In some cases Address Family in received NTP packet was modified to AF_UNSPEC because of which sendto failures were encountered and NTP configuration was failing. Resolved sendto failures by avoiding change of address family for udp packets sent through t		
PR	120398	Build:	5.4.1.451.R01
Summary:	MemDump:Invalid Address used during a memory free (0x312ac) on OS6602 stack-5.1.6.315R02		
Explanation:	Dump the task Name & task ID (in swlog) of the task which did a invalid free, & dump its tt in the memmon dmp file.		
PR	101676	Build:	5.4.1.452.R01
Summary:	OS6 QoS depleting the IPC Pools		
Explanation:	IPC pool depletion issue in QoS Solved.		
PR	124749	Build:	5.4.1.452.R01
Summary:	Traffic not destined for the switch causes ping drop		
Explanation:	Restoring number of packet handled in software.		
Problems Fixed Between Builds 456 and 464			
PR	126097	Build:	5.4.1.456.R01
Summary:	NI HW problem. HW fail type: 4		
Explanation:	Avoid learning 224.0.0.x control multicast range as group updates in the switch.		
PR	125939	Build:	5.4.1.457.R01
Summary:	Unable to associate a name with a static arp		
Explanation:	Slot/Port value not overridden when arp-name configured for a static arp		
PR	126802	Build:	5.4.1.459.R01
Summary:	Ingress CRC error frames on mobile ports trigger MAC authentication with radius server		
Explanation:	Discard the packets with CRC errors coming to CPU on mobile ports.		



PR **127107** Build: 5.4.1.460.R01
 Summary: arp name incorrectly displayed
 Explanation: arp name display corrected

PR **126095** Build: 5.4.1.461.R01
 Summary: OS 6602-48 crashed with csHsmNsmT2EndAppliStart() receive EOAS and dump generated
 Explanation: Validity Check made to avoid Exception in SSH task

Problems Fixed Between Builds 465 and 471

PR **127546** Build: 5.4.1.467.R01
 Summary: Removing mobility rule for a vlan blocks all ports for that vlan
 Explanation: Default vlan association wont be deleted upon deleting a GM rule.

PR **127658** Build: 5.4.1.468.R01
 Summary: Stack OS6600: Disabling Port Flapping feature is taken into account by only PRIMARY unit
 Explanation: Send PortFlap Config to the NIs after they are up

PR **127622** Build: 5.4.1.470.R01
 Summary: "show amap" returns unknown when remote switch is a 6400
 Explanation: Included OS6400 and OS6855 Devices in AMAP

PR **127455** Build: 5.4.1.471.R01
 Summary: OS6600 stack crashed with dump: error "Data storage interrupt Register: 0x0000b032"
 Explanation: The routing,arp and interface informations are added into the PMD.

Problems Fixed Between Builds 472 and 477

PR **120132** Build: 5.4.1.472.R01
 Summary: OS7 need not to route packets arriving with destination mac address = router mac of another vlan
 Explanation: Allow to add router mac in the L2DA Table using a command excuted only during bootstrap



PR **128187** Build: 5.4.1.473.R01
 Summary: OS7800 - error Exception: Mem Address Not Aligned for task VlanMgr
 Explanation: Handled "Mem Address Not Aligned" exception in task 'VlanMgr'.

PR **128686** Build: 5.4.1.475.R01
 Summary: Boot.cfg.1.err is created on secondary CMM for correct configuration of 802.1x
 Explanation: Fix done to stop creating boot.cfg.err for proper 802.1x configuration.

Problems Fixed Between Builds 478 and 488

PR **128104** Build: 5.4.1.480.R01
 Summary: Even there are no changes in the configuration, exit command prompts so - in 6.3.1 R01
 Explanation: Whenever the show tech-support command is executed without any change in the configuration the switch is exited normally.

PR **119386** Build: 5.4.1.481.R01
 Summary: 7700/6800 switch processing the unicast arp reply not destined for it.
 Explanation: Block ARP reply packets which are not destined for switch configured IP interfaces, upon request.

Problems Fixed Between Builds 489 and 495

PR **129515** Build: 5.4.1.489.R01
 Summary: On 6602-48 stack , ports 1-18 or 33-50 missing when we poll the OID 1.3.6.1.2.1.17.1.4 through mib b
 Explanation: Code changes to prevent same bridgePort numbers created for ports in OS6648 (48 port) stack of switches.

PR **109357** Build: 5.4.1.490.R01
 Summary: "prompt date time" is not saved in the user profile from an ssh session
 Explanation: Included user in CLI prompt for SSH sessions.

PR **130718** Build: 5.4.1.494.R01
 Summary: vlan manager - correct the retries so that ipc buffers are not locked up in socket queues
 Explanation: Corrected the retry & delay values to avoid buffers getting stuck in socket queue of vlan msg task



PR **128872** Build: 5.4.1.495.R01
 Summary: cmm b took over and cli task suspended
 Explanation: Save last message processed by mip Gateway task, which will be helpful in debugging CLI lockup issues.

Problems Fixed Between Builds 496 and 500

PR **130155** Build: 5.4.1.498.R01
 Summary: comments shown as leak in "debug memory monitor show log" on 7700 in default config
 Explanation: Fixed the memory leak in dshell

Problems Fixed Between Builds 501 and 510

PR **125881** Build: 5.4.1.502.R01
 Summary: 7700/6850/9800 being attacked by SSH/TELNET/FTP and crashed need memory dump analysis
 Explanation: Rate limiting done on SSH sessions under SSH attack. An SSH attack scenario is defined as when the system gets more than 3 SSH session requests within one single minute. Any new SSH connection will need to be attempted after waiting for one full minute. T

PR **130671** Build: 5.4.1.503.R01
 Summary: MDNS is replicated by 6600 stacks when source mac is not yet learned on the NIs

PR **131814** Build: 5.4.1.506.R01
 Summary: Mobile ports shows blocking even though STP is disabled and bpdu ignore is enabled on the mobile port
 Explanation: Fix timing issue on mobile VPAs during takeover

PR **132369** Build: 5.4.1.506.R01
 Summary: OS7800 NIs crashed:- Urgent pools depletion. "+++ Buffer : Urgent Perc used : 99 Perc allowed: 75"
 Explanation: Added swlog message to indicate freeing of DMA buffers when NI goes down



PR **132573** Build: 5.4.1.506.R01
 Summary: sub-second OSPF route convergence dshell command line needed for OS 7700 as gospfSubSecond = 1 in
 Explanation: Using debug flag achieve sub second OSPF convergence.

PR **132027** Build: 5.4.1.507.R01
 Summary: 7000-516-485-R01 only supports 64 nbrs per Router,
 Explanation: Support larger number of ospf nbrs per area (>= 128) upto max of 255 nbrs per system

PR **132839** Build: 5.4.1.507.R01
 Summary: In enqueue_to_ip_using_ipc, DHCP Snooping vlan-level dropping DHCP packet

Problems Fixed Between Builds 511 and 516

PR **130571** Build: 5.4.1.511.R01
 Summary: High OPSF task tospf due to an unnormal high OSPF LSA activity
 Explanation: Flush the invalid LSA.

PR **132122** Build: 5.4.1.512.R01
 Summary: Topology changes message needs to be logged in swlog with timestamp.
 Explanation: Topology Change Logged Into Swlog for easy reference.

PR **131482** Build: 5.4.1.513.R01
 Summary: 6600: if we apply a deny rule with a destination ip "any" no traffic passes through.
 Explanation: Destination ip any rules are programmed correctly in the Hardware.

PR **133235** Build: 5.4.1.513.R01
 Summary: CMM take over after giving copy flash-synchro
 Explanation: Defence fix added to avoid crash during copy flash synchro.



PR **131336** Build: 5.4.1.514.R01
 Summary: ping and traceroute command not available for read-only users
 Explanation: New CLI command is added to allow ping/traceroute access for read-only users. Here is Sample CLI commands usage

```
user read-only-group allow ping-traceroute
user read-only-group deny ping-traceroute
show user read-only-group ping-traceroute
```

PR **133643** Build: 5.4.1.515.R01
 Summary: Enhance the swlog message when port shutdown due to receive BPDU
 Explanation: Enhanced swlog message during port shutdown due to receive bpdu

Problems Fixed Between Builds 517 and 522

PR **133937** Build: 5.4.1.517.R01
 Summary: SSH Authentication with DSA public keys did not work on OS-6600.
 Explanation: Added public key authentication to ssh session

PR **134338** Build: 5.4.1.517.R01
 Summary: OS 7700 Dhcp-snooping database not updated after the DHCP ip renew
 Explanation: Populate DHCP binding enable if dhcp binding is enabled.

PR **127798** Build: 5.4.1.519.R01
 Summary: FLASH SYNCHRO Aborted. Due to SIMPLEX CMM or 2ndary State
 Explanation: Code changes to correct error messages shown during Flash synchro failures in a duplex setup

PR **134184** Build: 5.4.1.519.R01
 Summary: OS7800 crashed with slot .pmds: "alarm sendPmMsg: sendTo 42 : 0: d: 2 failed!!"
 Explanation: Decrease retries and increase delay while sending messages in VLAN Mgr and HSM

PR **124760** Build: 5.4.1.522.R01
 Summary: Error Open Message Capability Code 65 received from Juniper
 Explanation: Support to ignore Unsupported capabilities for BGP peer and support peers with no optional capabilities.



Problems Fixed Between Builds 523 and 525

PR **134406** Build: 5.4.1.523.R01
 Summary: System reboot with FATAL error when copy flash-synchro
 Explanation: Check for available flash space of the CMM before starting flash synchro.

Note that the new code with the fix has to present in both the CMMs for the fix to work.

PR **134897** Build: 5.4.1.523.R01
 Summary: Debug command "debug set allowed_ssh_session" does not work.
 Explanation: Maximum number of ssh session when set using debug command is retained when there is no attack

PR **136393** Build: 5.4.1.524.R01
 Summary: mac address is not getting aged out if ip relay not able to receive an DHCP address

Problems Fixed Between Builds 526 and 540

PR **134364** Build: 5.4.1.526.R01
 Summary: 6600 and 7700 not sending genral query report when a topology change is detected.
 Explanation: Learn the same client on different ports.

PR **131697** Build: 5.4.1.527.R01
 Summary: PMD enhancement for webView buffer leakage
 Explanation: Dumps will be generated if webView is in problematic condition with webView buffer monitoring information.

PR **137577** Build: 5.4.1.530.R01
 Summary: BBus Debug Improvement
 Explanation: IPC BBUS Debug Counters addition

PR **137884** Build: 5.4.1.531.R01
 Summary: "ip multicast static-neighbor" entry disappears while upgrading 7700 to 541-525-R01 code.
 Explanation: Handle ip multicast static-neighbor configuration properly during bootup



PR **122824** Build: 5.4.1.533.R01
 Summary: Web Authentication failed
 Explanation: Workaround and debug improvement for the Emweb Buffer issue

PR **138175** Build: 5.4.1.534.R01
 Summary: Redundant Multicast group entry when the same client is learnt on other ports: Follow-up PR#134364
 Explanation: Timing out the redundant multicast client entry

PR **127484** Build: 5.4.1.536.R01
 Summary: To merge restricted TCN feature from 6.3.1 to 5.1.6
 Explanation: Feature for restricting the TCN in 5x.

PR **137445** Build: 5.4.1.536.R01
 Summary: spantree ports in forwarding state with DESG role for disabled spanning tree
 Explanation: Operational Status of STP Disabled ports is changed to Disable from Forwarding

PR **138369** Build: 5.4.1.536.R01
 Summary: CPU spike on 6602 when the tcp traffic sent with port number zero.
 Explanation: Handle tcp packets properly with port number zero.

PR **103520** Build: 5.4.1.537.R01
 Summary: Webview is granting access the second time without asking the password

PR **138932** Build: 5.4.1.539.R01
 Summary: static querier configuration disappeared from a running configuration
 Explanation: Avoid timeout of static multicast queriers

Problems Fixed Between Builds 541 and 553

PR **128328** Build: 5.4.1.543.R01
 Summary: Command to change the source of SNMP replies.
 Explanation: New CLI introduced to control the Source IP of the SNMP packets originating from the switch



PR **139534** Build: 5.4.1.544.R01
 Summary: OIDs - dot1dTpFdbPort & dot1qTpFdbPort shows index number instead of port number for OS6602
 Explanation: Display port number instead of index value for Port Mib objects

PR **137663** Build: 5.4.1.545.R01
 Summary: OS7 Dump generation with SNMPagt task suspension (taskId : 0X059CB1B0).
 Explanation: Validation of invalid buffers to IPC call

PR **131963** Build: 5.4.1.548.R01
 Summary: OS6600 stack split with duplicate slot condition/ No PMD files generated
 Explanation: Generate the stackDebug.log file during supervisory msg loss scenarios

PR **140231** Build: 5.4.1.550.R01
 Summary: BBUS resets during the takeover and it is affecting the comm between the CMMs
 Explanation: False suspension alarm for tasks handled, preventing switch crash

PR **141232** Build: 5.4.1.552.R01
 Summary: Change in Default Flood Rate Value
 Explanation: Default flood rate setting for 7700, 7800, 8800 is 47M for 100M and 497M for 1G and in 66xx it is 49M and 496M for 100M and 1G respectively

Problems Fixed Between Builds 554 and 557

PR **141439** Build: 5.4.1.554.R01
 Summary: Client gets diconnected on 802.1x port due to DHCP INFORM packet on 7700

PR **140717** Build: 5.4.1.555.R01
 Summary: Emweb buffer leakage
 Explanation: Fix the Buffer leakage issue and introduce additional dshell commands

PR **94907** Build: 5.4.1.556.R01
 Summary: "Show 802.1x 1/1" command doesn't display anything. Other ports are OK.
 Explanation: Fixed Display Issue with showing 802.1x information on the first port (1/1) using command "show 802.1x 1/1" caused due to a wrong interpretation of index for the port number 1/1.



PR **141539** Build: 5.4.1.557.R01
 Summary: pmd analysis needed
 Explanation: Prevent crash when radius shared secret key is greater than 32

Problems Fixed Between Builds 558 and 563

PR **142168** Build: 5.4.1.558.R01
 Summary: mac-address not learned for non-supplicant clients on OS6600 after authentication when client move
 Explanation: Handled mac move from fixed to mobile port

PR **143743** Build: 5.4.1.560.R01
 Summary: Read-write families differ for same hex value for users in 6850 and 6600.

PR **137979** Build: 5.4.1.561.R01
 Summary: RMON History only available for the first slot.
 Explanation: Fix to display the entries of RMON history table

PR **139238** Build: 5.4.1.563.R01
 Summary: OS8800 Ni crashed "roma: error creating falsock buffer"
 Explanation: IP Directed Broadcast Packets is not processed by the Switch. Controlled using a flag "ipedrSubnetBcastDrop" disabled by default.

"ipedrSubnetBcastDrop" needs to be enabled (set to 1) using AlcatelDebug.cfg

NOTE: Dynamic changes of "ipedrSubnetBcastDrop"

Problems Fixed Between Builds 564 and 576

PR **145192** Build: 5.4.1.564.R01
 Summary: MS Vista (as DHCP client) not getting IP address.
 Explanation: Flags controlling Reply Packet when Snooping / Agent Info not enabled
 >>>>> dhcp_relay_unset_bcast_flag DEFAULT 1

This is to control the setting of BCAST FLAG, by default AOS Does not set the Flag. The field is copied from the Serve



PR	146089	Build:	5.4.1.565.R01
Summary:	6600: Mac-address entries not seen for most devices		
Explanation:	Set correct hardware bits for ipv6 mac address aging.		
PR	131771	Build:	5.4.1.566.R01
Summary:	Switch crashed while putting 32 backward characters or password via open ssh		
Explanation:	Proper validation maximum password length is done. Max password length allowed in 32.		
PR	144501	Build:	5.4.1.567.R01
Summary:	Issues when enable the flag of webMgtBugFix		
Explanation:	Debug cli's have been introduced to cleanup the Emweb buffers		
PR	147129	Build:	5.4.1.569.R01
Summary:	8800 advertising route with higher cost to ospf neighbor		
Explanation:	Install the lowest metric LSA, even if both the LSA forwarding address are same, but originating ASBRs are different in NSSA area		
PR	132031	Build:	5.4.1.571.R01
Summary:	Issue with the Feasible status related to the "show ip bgp path" command		
Explanation:	show ip bgp command display modified to show incomplete origin for redistributed routes.		
PR	109756	Build:	5.4.1.573.R01
Summary:	Unable to route IP traffic after turning on classifyI3 bridge		
Explanation:	ARP for the correct gateway in "classify I3 bridged" scenario.		
PR	149559	Build:	5.4.1.573.R01
Summary:	dot1dTpFdbPort shows incorrect values.		
Explanation:	BasePort values are calculated based on the modified BridgePort values		
PR	143938	Build:	5.4.1.575.R01
Summary:	6602-48 stack of 2 units rebooted with cs_sytem pmd file on Feb 4th		
Explanation:	Release buffer once it is used		
PR	149507	Build:	5.4.1.576.R01
Summary:	6850 does not show up in output of adjacencies in AMAP		
Explanation:	Code changes to display proper switch images in WebView for OS6850 based devices		



Problems Fixed Between Builds 577 and 588

PR **147262** Build: 5.4.1.577.R01
 Summary: OS-7800 100% CPU spike when adding 802.1Q to linkagg in 5.4.1.495.R01
 Explanation: Spiking of cpu when more than 400 vlans tagged to the aggregate is resolved

PR **142329** Build: 5.4.1.579.R01
 Summary: 8800 crash with "alert Buffer : Normal Perc used : 79Perc allowed: 75" logs
 Explanation: CMM Pools moving to DMA Queue , due to NI Pools depletion avoided.

PR **148109** Build: 5.4.1.580.R01
 Summary: SNMP engine not rebooted even after the engine time crossed the limit.
 Explanation: Reset SNMP engine when the time limit exceeds for snmp engine time.

PR **154471** Build: 5.4.1.584.R01
 Summary: Os-7700 switch crashed with "Mem Address Not Aligned" error the task is 0x5bad4c0 "SNMPagt".
 Explanation: Removed access for uninitialised pointer while logging event for invalid buffer deletion.

PR **150479** Build: 5.4.1.585.R01
 Summary: OS6600 memory leak issue
 Explanation: Corrected the Stack trace buffer allocation

PR **154336** Build: 5.4.1.586.R01
 Summary: tCS_PRB & SwLogging tasks are suspended on 6600 standalone switch.
 Explanation: Additional checks have been introduced to validate the fd value when logging output to console

Problems Fixed Between Builds 589 and 591

PR **157270** Build: 5.4.1.590.R01
 Summary: NI1 failed to come up after reboot on OS7800 switches connected with each other



PR **157630** Build: 5.4.1.590.R01
 Summary: LPS restriction does not work for the new slot

Problems Fixed Between Builds 592 and 597

PR **159360** Build: 5.4.1.592.R01
 Summary: Dynamic VPA not restored even after configuring vlan restore disable on 802.1x port.
 Explanation: Check is added for checking the restore enabled/disabled before deleting the vpa on mobile port.

PR **162456** Build: 5.4.1.596.R01
 Summary: The OS-7800 switch crashed due the "tPimsm" task exception.
 Explanation: Defensive check has been introduced in tPimsm task.

Problems Fixed Between Builds 598 and 601

PR **165207** Build: 5.4.1.598.R01
 Summary: Switch crashed with 100% CPU seen on a stack of OS6602-48
 Explanation: Defense Check added to the subnet ID obtained from the routing table

Under Verification

PR **121547** Build: 5.4.1.442.R01
 Summary: Port Shutdown feature CPU Timeout -Seconds does not work properly OS 6600 AOS release 5.1.6.R02.435
 Explanation: Fix to shut the port based on the configured timeout

PR **97572** Build: 5.4.1.448.R01
 Summary: Error Message# Socket failed wdbConfig: error configuring WDB communication interface
 Explanation: The error message "Socket failed wdbConfig: error configuring WDB communication" was displayed during the boot up of the switch. While looking at the code, we understood that the switch is trying to enable WDB during the bootup, which is not possible & u



PR	97572	Build:	5.4.1.448.R01
Summary:	Error Message# Socket failed wdbConfig: error configuring WDB communication interface		
Explanation:	The error message "Socket failed wdbConfig: error configuring WDB communication" was displayed during the boot up of the switch. While looking at the code, we understood that the switch is trying to enable WDB during the bootup, which is not possible & u		
PR	119895	Build:	5.4.1.455.R01
Summary:	OS 9800 running on 6.1.3.838.R01 crashed and generated Dump files.		
Explanation:	Fix to avoid corrupting one byte of next block while configuring vlan tag description		
PR	111559	Build:	5.4.1.458.R01
Summary:	6600 port remains in blocking state after modification of the 802.1Q vlan port description		
Explanation:	Changing the 802.1q description of a vlan port/linkagg have been handled.		
PR	121054	Build:	5.4.1.466.R01
Summary:	After STP changes, Multicast devices do not respond to Multicast query, and hence query timeout		
Explanation:	Avoid flooding of Multicast Packets after IP-PORT Movement. Handle packets coming through unresolved channel in IPMS after IP-PORT Movement.		
PR	99718	Build:	5.4.1.467.R01
Summary:	rls command fails with 'Attempt to lock LS table failed' after an rls timeout		
Explanation:	When the command "rls" is executed from the primary CMM while the secondary CMM is rebooting, the command fails with a timeout. After this the "rls" cmd never gives the o/p (just throws an error), even after the secondary CMM comes up. Code change done to		
PR	128001	Build:	5.4.1.472.R01
Summary:	BBUS Hardware timeout error on the swlog Ni one reset causes all other NIs router MAC flush		
Explanation:	Prevention of special DA Mac deletion after NI 1 reset.		



PR	99205	Build:	5.4.1.476.R01
Summary:	Unexpected takeover on 8800 with "Bbus buffer descriptor pool empty" message in the switch logs.		
Explanation:	Debugs added to get more information for this PR. This will generate pmd file & additional debug information whenever this problem occurs again.		
PR	99205	Build:	5.4.1.476.R01
Summary:	Unexpected takeover on 8800 with "Bbus buffer descriptor pool empty" message in the switch logs.		
Explanation:	Debugs added to get more information for this PR. This will generate pmd file & additional debug information whenever this problem occurs again.		
PR	99205	Build:	5.4.1.476.R01
Summary:	Unexpected takeover on 8800 with "Bbus buffer descriptor pool empty" message in the switch logs.		
Explanation:	Debugs added to get more information for this PR. This will generate pmd file & additional debug information whenever this problem occurs again.		
PR	129719	Build:	5.4.1.485.R01
Summary:	6600 - group member deleted when receiving a group specific member query		
PR	121438	Build:	5.4.1.486.R01
Summary:	Radius agent not to use loopback0 address as its source interface when it's present		
Explanation:	Use Loopback0 Address as source IP for radius agent packets, if Loopback0 Address is configured.		
PR	128556	Build:	5.4.1.488.R01
Summary:	OS7: HandleNIExtraBBD: NI passed bad length Ni Trouble Report Received NI HW problem.HW fail type: 4		
Explanation:	Ratelimiting packets to CPU.		
PR	128556	Build:	5.4.1.488.R01
Summary:	OS7: HandleNIExtraBBD: NI passed bad length Ni Trouble Report Received NI HW problem.HW fail type: 4		
Explanation:	Ratelimiting packets to CPU.		
PR	130160	Build:	5.4.1.492.R01
Summary:	IGMP leave message have no effect with proxying disable		



PR	130720	Build:	5.4.1.494.R01
Summary:	ipedr - correct the retries so that ipc buffers are not locked up in socket queues		
Explanation:	Added retry counters to return back when buf create fails for more that 10 retries, so that ipedr atleast processes the incoming packets.		
PR	130719	Build:	5.4.1.500.R01
Summary:	ipms - correct the retries so that ipc buffers are not locked up in socket queue		
Explanation:	corrected the retry counters to avoid buffers getting stuck in socket queue of ipms task		
PR	122693	Build:	5.4.1.504.R01
Summary:	Functionality issue with "ip ospf redist-filter RIP 0.0.0.0 0.0.0.0 redist-control aggregate" cmd		
Explanation:	Update the external link state database on route changes, when different routes are present for the same network		
PR	125229	Build:	5.4.1.504.R01
Summary:	OSPF Entry not flushed		
Explanation:	Message to Registered Modules is triggered when a Route Del Event happens during Redistribution		
PR	131461	Build:	5.4.1.521.R01
Summary:	analysis of dump file on a 6602-48. Equipment generated pmd files		
Explanation:	Retrieve miniboot version from cached values on OS6		
PR	110473	Build:	5.4.1.523.R01
Summary:	Many "LANPOWER error IpSocketSend: zcBufCreate Failed!" followed by a crash with dumps		
Explanation:	Found 256 byte memory leak in health monitor task		
PR	116738	Build:	5.4.1.523.R01
Summary:	A stack of 4* OS 6850 crashed running code 6.1.3.805.R01		
Explanation:	Validity check made		
PR	131245	Build:	5.4.1.523.R01
Summary:	OS 6850 stack has not rebooted once the queue as maxed out in CSM_REQ state.		
Explanation:	Fix the ipc buffer leak scenario during bootup		

PR	130168	Build:	5.4.1.525.R01
Summary:	8800 Switch crashed took over occur		
PR	129491	Build:	5.4.1.529.R01
Summary:	OS 6850 Flash freespace gives a wrong value when connected in stack and as stand alone no issues.		
Explanation:	Corrected "Free Flash Space" calculation		
PR	138003	Build:	5.4.1.542.R01
Summary:	show amap displays 6850 U 24 as OS6824 Fiber V2 - need to know why and if it can be displayed as U24		
Explanation:	modified product name display in show amap output for cli and webview		
PR	129591	Build:	5.4.1.546.R01
Summary:	FPGA upgrade fails often with latest 5.1.6.498.R02 AOS		
Explanation:	Additional logs to the console after FPGA upgrade completed successfully		
PR	131334	Build:	5.4.1.547.R01
Summary:	Check-in code changes for PR 130961		
Explanation:	SSH is processed only in valid connections.		
PR	131813	Build:	5.4.1.548.R01
Summary:	Need to have Port status as UP/DOWN instead of "+" and "-" in Syslogs		
Explanation:	Changed the log message for Interface status change to be UP/ DOWN instead of +/-		
PR	132514	Build:	5.4.1.549.R01
Summary:	IPC Debug and Logging Improvements		
Explanation:	IPC debug enhancements		
PR	139633	Build:	5.4.1.559.R01
Summary:	OS6850 crashed when command "copy working certified " with "error reading /flash/working/ entr		
Explanation:	Retry mechanism introduced which calculating the checksum of image files		
PR	118093	Build:	5.4.1.561.R01
Summary:	Loopback0 is not part of network group Switch		
Explanation:	Loopback0 ip address was not added to Switch group		

PR	144033	Build:	5.4.1.568.R01
Summary:	OS8800 :: ARP or Gateway being not resolved		
Explanation:	1) Drop entry removed on receiving ARP ADD from another NI. 2) Correct ARP entry checked for flags.		
PR	147610	Build:	5.4.1.569.R01
Summary:	Low path cost routes not preferred in OSPF route selection		
Explanation:	Forwarding address for an area is selected based on the ospf interface cost. The active interface with lowest metric selected as fwd addr for NSSA		
PR	147610	Build:	5.4.1.569.R01
Summary:	Low path cost routes not preferred in OSPF route selection		
Explanation:	Forwarding address for an area is selected based on the ospf interface cost. The interface which is active and with lowest metric is selected as the forwarding address for the NSSA area		
PR	122226	Build:	5.4.1.570.R01
Summary:	OS6850 running 6.3.1.894R01 rebooted and generated pmd files		
Explanation:	A data access exception had occurred and a defense check has been added in the VxWorks api.		
PR	144811	Build:	5.4.1.572.R01
Summary:	Default value for historyControlInterval for rmon is different from its MIB definition		
Explanation:	Implemented new CLI commands to configure history control interval value.		
PR	148569	Build:	5.4.1.578.R01
Summary:	running and saved configuration are different even when no changes made		
Explanation:	Modified Show Configuration Status to sync with CMM Configuration Status		
PR	155074	Build:	5.4.1.587.R01
Summary:	SLB server operational status goes into "retrying" causes clients to jump cluster server.		
Explanation:	Fixing the Server Load Balancing(SLB) timer wrapping issue.		
PR	159245	Build:	5.4.1.594.R01
Summary:	switch is passing traffic on a violated port-security		
Explanation:	New API is introduced to release the LPS violation once moved to shutdown.		



PR **148114** Build: 5.4.1.595.R01
 Summary: Stack of 2x6850 switches reported continuous 100% CPU utilization with sftp_s0 task showing highest
 Explanation: Code changes to eliminate CPU spike by stale SFTP tasks after an abnormal SFTP session termination.

PR **145523** Build: 5.4.1.597.R01
 Summary: Dump analysis following an upgrade to 6.4.2.933

PR **102616** Build: 5.4.1.599.R01
 Summary: BGP How to configure a in-prefix list only to permit the default route
 Explanation: BGP Prefix-list handled properly to accept/deny a particular route if configured

PR **167267** Build: 5.4.1.600.R01
 Summary: Stack of OS6602 rebooted and only 1 device came back up
 Explanation: Enable stackDebug log files to be generated by default

PR **122781** Build: 5.4.1.601.R01
 Summary: UDP Rate Limiting with user specified UDP Port numbers
 Explanation: UDP packets in NI are rate limited to 256 pkts/ sec and 1024 pkts/ sec on the CMM. This is to ensure a storm of UDP broadcast traffic does not chew up all the system buffers.

Known Issues

PR **106871**
 Summary: Switch is not reading owner-attributes from LDAP : so ov3.3 Global QoS does not work

PR **83127**
 Summary: +++ [CLISHELL 46] Error on setting tty options at login(851971) DoS attack: bncex on port 23
 Explanation: A DoS attack on port 23(Telnet) results in "[CLISHELL 32] Error on setting tty options at password(851971)"
 Workaround: The issue is cosmetic and does not affect performance of the switch.



PR **84009**
Summary: igmpInterfaceVersion can set igmp V1 on the interface but CLI and WebView
Explanation: It is not possible to configure an interface as IGMPv1 through the cli or
WebView.
Workaround: Configure an interface as IGMPv1 through SNMP.

PR **84630**
Summary: Show ip udp relay statistics [service] only shows info if there is a vlan
assigned to that service
Explanation: Even webview does not display the entry if there is no vlan associated with
the service.

PR **87960**
Summary: Webview doesn't refresh Source Learning table properly causing submission
failed by MAC deletion
Explanation: Sometimes Webview doesn't refresh Source learning table properly causing
submission failed when trying to delete a MAC
Workaround: Press refresh button before performing mac address deletion.

PR **89316**
Summary: MSTP Edge Port Implementation - We send out rootBridgeID (ffffff) - Anvl
Expect valid Mac Add
Explanation: Every link-up, we send out a BPDU packet with the Root BridgeID of 0xffff...
to elicit a BPDU reply from the adjacent switch in the current Auto-Edge
Detection mechanism.
Workaround: Setting the stpni_useWorstRootBridgeID=0 in NiDbg, then disable/re-enable
the STP instance. (These steps are not expected to be performed by the
customers, but by our Automation testers who need to setup ANVL test
cases.)

PR **90297**
Summary: CST Root convergence in 802.1S takes long or never converges
Explanation: CST Root convergence in 802.1s may be slow due to the circulation of old
'good' spanning tree vectors in the network when a root switch is powered
off
Workaround: 1. Use single MSTP region as much as possible

2. Tune the performance parameters maxAge and hop count to optimal
values for the network.

**PR 91729**

Summary: Remove unsupported ToS and DSCP from Conditions > Layer 3 pages
Explanation: ToS and DSCP options are not removed from Conditions > Layer 3 pages as they are also available through cli.
Workaround: There is no known workaround at this time.

PR 91850

Summary: WV IPX statistics do not display until CLI cmd 'show ipx traffic' is keyed
Explanation: IPX statistics are not correct with Webview or SNMP.
Workaround: A "show ipx traffic" needs to be done on the CLI so that the statistics can be retrieved from the NIs.

PR 98511

Summary: Switch hangs while trying to learn 250 neighbor mac addresses using NDP in IPv6
Explanation: When switch learns any ipv6 neighbor mac address, the entry remains in cache forever with state "Stale", it should get deleted after sometime if no communication between switch and its neighbor is taking place.
Workaround: There is no known workaround at this time.

PR 98522

Summary: igmp proxy version v3 is not functioning on 8800, 78/7700, 6600
Explanation: Received IGMP reports are not proxied as V3 reports when IGMP proxy version is configured as V3 on an OS7000 series switch.
Workaround: There is no known workaround at this time

PR 98526

Summary: WebView Remote System File Mgmt: Delete File, Copy File, and List Files dont work at the bottom pge
Explanation: In WebView Remote System File Management; By deleting the file won't automatically refresh the directory with the current content, it requires clicking the list button in order to see the updated directory contents
Workaround: There is no known workaround at this time

PR 98529

Summary: +++ [CLISHELL 46] Error on setting tty options at login(851971) DoS attack: bncex on port 23
Explanation: A DoS attack on port 23(Telnet) results in "[CLISHELL 32] Error on setting tty options at password(851971)"
Workaround: The issue is cosmetic and does not affect performance of the switch.



PR **98534**
Summary: (FFS corruption tracking PR) 'csCvmUtilRecursiveCopyDir: copy error" when certified and flash-synch
Explanation: Flash File System May become corrupt after Certify, Restore or Flash Synchro process
Workaround: There is no known workaround at this time

PR **98542**
Summary: Problem in sending tagged traffic over mobile ports
Explanation: Currently tagged frames on a mobile port with mobile tag disable will get classified into a vlan if protocol or ip net rules configured on that vlan port.
Workaround: There is no known workaround at this time

PR **98551**
Summary: Webview Ethernet General Modify Does Not Work on OS8800
Explanation: In WebView, Physical > Ethernet > Interface Configuration > General "Modify" window might display a "Set operation finished successfully!" message. However, the changes are not made to the table.
Workaround: Use the "Multiple Modify" window and select the desired slot/port to perform the changes.

PR **98559**
Summary: 9700 WebView Remote System File Management: Copy from/to Primary doesnt work.
Explanation: WebView Remote System File Management: Though the file list is displayed, an error is logged for the primary cmm.
Workaround: There is no known workaround at this time.

PR **98562**
Summary: Cannot add IPv6 default route using WebView
Explanation: On an OS8800 switch, an IPv6 default route to the configuration cannot be added using WebView.
Workaround: Add the IPv6 default route to the configuration using CLI.

PR **98567**
Summary: 10G: "Adding DA entry failed entry = 0x10020,..." msg displayed on some slices upon loading debug
Explanation: After loading debugger on 10G NI, some slice showed "adding DA entry failed entry..." message
Workaround: There is no known workaround at this time.



PR	98580
Summary:	Pmon is not able to capture IPMS flows when the client is sitting on the monitored port.
Explanation:	This is a hardware limitation on 66xx
Workaround:	None

PR	98593
Summary:	WebView Vlan 802.1Q modify and apply a already setup tag on a 10 gig port fails.
Explanation:	WebView allows modification on certain 10 gig ports for 802.1q that it shouldn't cause the modification submission to fail.
Workaround:	There is no known workaround at this time.

PR	98594
Summary:	WebView ethernet general modify: after click apply, set successful message not visible in NS 7.0.
Explanation:	WebView > Physical > Ethernet > Interface Configuration > General modify page might not show the "Set Successful" message in Netscape 7.1.
Workaround:	Ignore; whenever there is an error message, the modify page stays open automatically.

PR	98623
Summary:	802.1X GM STP BPDUs are received while port is not authenticated and direction is both.
Explanation:	802.1X GM STP BPDUs will be received while port is not authenticated and direction is both.STP BPDUs are sent to ensure that no loops are formed on the mobile ports.
Workaround:	There is no known workaround at this time.

PR	98626
Summary:	Duplicate mac add's w/ reset/timeout static & dynamic in same vlan after resetting GNI_U12_C2 board
Explanation:	Duplicate mac addresses in the same vlan with reset static and dynamic mac addresses after resetting GNI_U12_C2.This behavior was happening for specific conditions and it doesn't affect the functionality.
Workaround:	There is no known workaround at this time.



PR **98631**
Summary: No trap is sent out by chassis supervision when sfp module is removed from fiber 6600
Explanation: Logs are available to notify when an sfp is removed or inserted. Currently no traps for this event are defined.
Workaround: There is no known workaround at this time.

PR **98632**
Summary: Generic udp relay for NTP (123) is not working
Explanation: According to UDP relay SFS document (section 2.6) ,

For NTP, the UDP relay will not be able to forward NTP packets, whose destination address is the AOS router port IP address to the NTP server.
Workaround: There is no known workaround at this time

PR **98644**
Summary: Get too many warnings when only info set "v6if-6to4-137 (6To4 tunnel) reachability may be affected"
Explanation: Occasionally many warning messages are logged to console when only info set "v6if-6to4-137 (6To4 tunnel) reachability may be affected"
Workaround: There is no known workaround at this time.

PR **98655**
Summary: No traps are being generated when an 802.1X feature is being disabled on a port
Explanation: Mib change will be required to define traps when an 802.1X feature is being disabled on a port. Currently no traps are defined.
Workaround: There is no known workaround at this time.

PR **82864**
Summary: WebView ethernet general modify: after click apply, set successful message not visible in NS 7.0.
Explanation: WebView > Physical > Ethernet > Interface Configuration > General modify page might not show the "Set Successful" message in Netscape 7.1.
Workaround: Ignore; whenever there is an error message, the modify page stays open automatically.

**PR 84270**

Summary: WebView's UDP relay association page only allows a maximum of three entries
Explanation: If more than 3 services are configured via WebView, only 3 are displayed.
Workaround: All services are displayed via CLI

PR 84856

Summary: IP cam space full, count 16374, slot 1 alert message after stream DoS attack
Explanation: The 6600 learns the source and destination IP address of every forwarded flow, and has a finite space (16K addresses) to store these. These have an aging time of 5 minutes. In certain kind of DoS attacks, the Switch can run out of space to store these add
Workaround: CLI command "clear arp-cache". This will cause the Switch to delete most, if not all the L3 addresses in HW. All forwarded traffic will have to be re-learnt.

PR 86576

Summary: AMAP Adjacencies Remote Host Device field value sometimes shows **ERR("12")** or **ERR("204")**.
Workaround: None

PR 88942

Summary: Cannot add IPv6 default route using WebView
Explanation: Cannot add an IPv6 default route to the configuration using Webview.
Workaround: Add the IPv6 default route to the configuration using the CLI.

PR 90044

Summary: SL entries get flushed by creating GM rule
Explanation: It is possible to see brief interruption in traffic flows once you add rules. This is because all MACs are flushed in the anticipation that rule precedence change may potentially affect the classification status of the learned MACs.
Workaround: There is no known workaround at this time.

PR 92933

Summary: Broadcast-Unicast Traffic forwarded when changing 802.1x parameter to force-unauthorized
Explanation: When port is changed from forced-authorized to forced-unauthorized, MAC address that are learned when the port was force-authorized are not flush and thus traffic can still go through as usual. Please note when switching from auto to forced-unauthorized,
Workaround: Make sure to do a no mac learn to clean the MAC on that port before switching from forced-authorized to forced-unauthorized.



PR	95308
Summary:	Temporary loop on changing bridge priority or port down in RSTP with Link Agg
Explanation:	Temporary traffic loops could happen under the following scenarios: 1. Reloading of a non root bridge. This happens when the bridge is going down and is due to the sequential bringing down of NIs during a reload process .It is purely temporary in nat
Workaround:	For items 1 and 2 above there is no work around presently. For item 3 the following work around could be applied: 1. Tune the max age (and or max hops in the case of MSTP) parameter to a lower value that is optimal for the network.

PR	98550
Summary:	[6600] Oversize pkts transmitted by Mirrored port is being received by Mirroring port (in/out/bi)
Explanation:	This is expected behavior as per the mirroring implementation in hardware. All packets will be mirrored (tx or rx) regardless of the specifics of the packet.
Workaround:	There is no known workaround at this time.

PR	98596
Summary:	After CMM takeover, "show qos port" does not display tagged or trusted 10 Gig ports
Workaround:	Traffic flow on the port is fine and qos rules are also applied. To view the 10gig port in the show qos port command, the port can be administratively disabled and enabled.

PR	100389
Summary:	Takeover on OS8800 with fully loaded Nis did not come up properly
Explanation:	Takeover on OS8800 with fully loaded Nis did not come up properly. This is a hardware issue.
Workaround:	Use different chassis and NIs.

PR	110134
Summary:	PC treated as non-suppliant cannot move back to 802.1x unless down/up switch port
Explanation:	Issue of non-suppliant entries not getting deleted while it is getting deleted in the mac-address table is fixed.



PR **130665**
Summary: OS7 - 5.1.6.498.R02 - "Admin down" is not completely shutting down the port on OS7-ENI-FM12
Explanation: Admin down on OS7-ENI-FM12 port will not bring the remote end link down.
Workaround: There is no known workaround.

PR **142686**
Summary: Improper telnet rejection message
Explanation: TCP flags to be checked correctly

PR **148114**
Summary: Stack of 2x6850 switches reported continuous 100% CPU utilization with sftp_s0 task showing highest
Explanation: Code changes to eliminate CPU spike by stale SFTP tasks after an abnormal SFTP session termination.
