

# Release Notes

## OmniAccess Stellar AP

### AWOS Release 5.0.1 - GA Release

These release notes accompany the OmniAccess Stellar Operating System (AWOS) Release 5.0.1 software for the Stellar APs. This document provides important information on individual software and hardware features. Since much of the information in the release notes is not included in the hardware and software user manuals, it is important to read all sections of this document before installing new hardware or loading new software.

## Table of Contents

|   |    |
|---|----|
| Related Documentation .....                                     | 3  |
| Hardware Supported .....  | 4  |
| Supported Mode .....  | 4  |
| New Software Features and Enhancements .....                    | 4  |
| Fixed Problem Reports Between Build 4.0.7MR6 and 5.0.1.27 ..... | 5  |
| Open/Known Problems .....                                       | 6  |
| Limitations and/or Dependencies.....                            | 8  |
| New Software Feature Descriptions.....                          | 10 |
| Technical Support.....  | 18 |

## Related Documentation

The release notes should be used in conjunction with the associated manuals as listed below. User manuals can be downloaded at: <https://myportal.al-enterprise.com/>.

### **Stellar AP Quick Start Guide**

The Quick Start Guide assists you in quickly connecting to and configuring the Stellar AP.

### **Stellar AP Installation Guide**

Provides technical specifications and installation procedures for the Stellar AP.

### **Stellar AP Configuration Guide**

Includes procedures for managing and configuring all aspects of the Stellar AP using the built-in web interface.

### **Technical Tips, Field Notices, Upgrade Instructions**

Contracted customers can visit our customer service website at: <https://myportal.al-enterprise.com/>.

## Hardware Supported

- AP1101, AP1201, AP1220 series, AP1230 series, AP1251, AP1251-RW-B, AP1261-RW-B, AP1201H, AP1201L, AP1201HL, AP1320 series, AP1360 series, AP1201BG, AP1301, AP1301H, AP1311, AP1331, AP1351, AP1451, AP1431, AP1411, AP1511.

## Supported Mode

- The AWOS 5.0.1.27 is ONLY applicable for Express mode and OmniVista 2500 and OmniVista Cirrus 4, can NOT be used for OmniVista Cirrus 10.

## New Software Features and Enhancements

The following software features are new with this release, subject to the feature exceptions and problem reports described later in these release notes:

| Feature  | Platform Support  |
|--|---|
| MLO Configuration  | AP1511  |
| Enable/Disable PSE POE of AP1301H and AP1360 through UI  | AP1301H, AP1360   |
| Secondary RADIUS Server on Express   | All Wi-Fi7 Wi-Fi 6/6E products: AP1320 series, AP1360 series, AP1301, AP1301H, AP1311, AP1331, AP1351, AP1451, AP1431, AP1411, AP1511 |
| Enhance Stellar Client-Context   | All Wi-Fi7 Wi-Fi 6/6E products: AP1320 series, AP1360 series, AP1301, AP1301H, AP1311, AP1331, AP1351, AP1451, AP1431, AP1411, AP1511 |
| Certificate Renewal in OV2500 and OVC  | ALL   |
| ICMP Policy Condition Support Missing in Unified Policy  | ALL   |
| AWOS support for OVE L3 HA   | All Wi-Fi7 Wi-Fi 6/6E products: AP1320 series, AP1360 series, AP1301, AP1301H, AP1311, AP1331, AP1351, AP1451, AP1431, AP1411, AP1511 |
| AWOS Support for Hotspot2.0 with Ameriband Parameters  | All Wi-Fi7 Wi-Fi 6/6E products: AP1320 series, AP1360 series, AP1301, AP1301H, AP1311, AP1331, AP1351, AP1451, AP1431, AP1411, AP1511 |
| FDB Update with ARP/GARP Enabled by Default in all Modes   | ALL   |
| Load Balancing with Roaming Devices  | ALL   |
| AWOS Must Completely Stop the AP Management Web Server   | ALL   |
| AWOS Support "AP Location" in Suboption2 in DHCP Option 82   | All Wi-Fi7 Wi-Fi 6/6E products: AP1320 series, AP1360 series, AP1301, AP1301H, AP1311, AP1331, AP1351, AP1451, AP1431, AP1411, AP1511 |
| AWOS BLE IoT Support Enable "Discover all devices"   | Except AP1301, AP1221, AP1230, AP1250, AP1101, AP1201L, AP1201HL, AP1201H, AP1261-RW-B, AP1301L                                       |
| AWOS BLE IoT sSupport "iBeacon & RawData"  | Except AP1301, AP1221, AP1230, AP1250, AP1101, AP1201L, AP1201HL, AP1201H, AP1261-RW-B, AP1301L                                       |
| OV4/AWOS Support 6GHz Band at RF Profile for Costa Rica, Guatemala, Argentina, and Dominican Republic. | AP1411, AP1431, AP1451, AP1511  |
| MAC-Authentication-with-IoT-client-profile-check   | ALL   |
| Syslog message always show "Notice" in Severity on Syslog Server                                       | ALL   |

## Fixed Problem Reports Between Build 4.0.7MR6 and 5.0.1.27

| PR  | Description  |
|---|--|
| ALEISSUE-1773<br>Case number:<br>00729492 | <p><b>Summary:</b><br/>The WIPS functionality is not performing as expected with the Stellar AP.</p> <p><b>Explanation:</b><br/>1. Change the WIPS suppression message interval to 1 second<br/>2. Simulate bidirectional sending of disassociation request messages</p> <p><a href="#">Click for additional information</a></p> |
| ALEISSUE-1798<br>Case number:<br>00658943 | <p><b>Summary:</b><br/>AP1101 rebooted due to kernel panic   Kernel panic - not syncing: Fatal exception in interrupt.</p> <p><b>Explanation:</b><br/>Chipset vendor provides two patches for wireless driver to solve this problem.</p> <p><a href="#">Click for additional information</a></p>                                 |
| ALEISSUE-1854<br>Case number:<br>00744752 | <p><b>Summary:</b><br/>Certificate-based authentication (EAP-TLS) fails.</p> <p><b>Explanation:</b><br/>Modify gso-size to ensure that UDP packets can be properly fragmented and forwarded through the GRE tunnel.</p> <p><a href="#">Click for additional information</a></p>  |
| ALEISSUE-1956<br>Case number:<br>00770918 | <p><b>Summary:</b><br/>Stellar AP1361: eth1 and SFP interface not visible on GUI.</p> <p><b>Explanation:</b><br/>Add eth1 and eth2 interface to the default configuration for AP1361.</p> <p><a href="#">Click for additional information</a></p>  |
| ALEISSUE-1954<br>Case number:<br>00770720 | <p><b>Summary:</b><br/>Request for Remediation of Reported Vulnerabilities (Stellar AP) TCP ports 8883 and 1884.</p> <p><b>Explanation:</b><br/>Fix related vulnerabilities.</p> <p><a href="#">Click for additional information</a></p>   |
| ALEISSUE-1964<br>Case number:<br>00773223 | <p><b>Summary:</b><br/>Stellar AP1321-1301: After rebooting, the Ap restart in loop.</p> <p><b>Explanation:</b><br/>Remove redundant and non-valuable power supply from lldp module.</p> <p><a href="#">Click for additional information</a></p>   |

## Open/Known Problems

The problems listed here include problems known at the time of the product's release. Any problems not discussed in this section should be brought to the attention of the Service and Support organization as soon as possible. Please contact customer support for updates on problem reports (PRs) where no known workaround was available at the time of release.

| PR                         | Description   | Workaround  |
|----------------------------|---|---|
| WCF                        | WCF feature is not supported when WLAN Client is running behind an HTTP Proxy.  | No workaround.  |
| WCF                        | WCF feature is not supported when WLAN Client is using mobile applications, there is no restrictions (packets are not dropped by AP, no redirection to Restricted Web page).  | No workaround.  |
| Management VLAN            | When the management VLAN is enabled, setting the static IP may fail.  | The static IP must be set first, and then enable the management VLAN.   |
| DPI                        | [reflexive] configure link tracking. DPI_DROP does not take effect.   | After modifying the reflexive, the client needs to go online and offline again, which can return to normal.   |
| AP stateful IPv6 address   | The IPv6 address of the dual-stack AP is a stateful address. After configuring the open type of WLAN, to associate the WLAN with the wireless network card of win 7 11n set to single-stack V6, check the network on-off condition of the V6 address. | When you manually configure a V6 address of the same network segment on the client as the gateway address, you can communicate with the same network address. |
| DPI FTP policy             | Create one policy list binding and two policies, results that the user cannot access the FTP.   | No workaround.  |
| WCF                        | WCF does not support L3 roaming scenarios.  | No workaround.  |
| Option82                   | After enabling option82 feature, in some scenarios, user roaming and reacquiring IP addresses can cause a brief broadcast storm.  | Will be fixed in future release.  |
| AP1411 Radio Configuration | After switching the radio, the previously unused band is set to a disabled state (Express).   | Manually enable the band in AP RF.  |
| SNMPv3                     | Some special characters can cause SNMP communication issues. The special characters include the following: \$, ", (   | Don't using these special characters.   |
| 6G wIPS                    | 6G radio does not support wIPS feature.   | Will be supported in future release.  |
| mDNS                       | AP1411/AP1431 does not support mDNS feature.  | Will be supported in future release.  |
| DPI                        | DPI memory leak issue.  | Will be fixed in future release.  |
| Mesh                       | 1.If AP working on DFS channel, the client/mesh client can't connect to AP.<br><br>2.Create new WLAN on band different from Mesh, will cause reconnect on mesh network.   | 1.Change the channel to non-DFS channel.<br><br>2.Will be fixed in future release.  |
| Captive Portal             | The client can access the network without CP authentication in roaming scenarios.   | Set a default ARP in Authentication Strategy.   |
| Dynamic VLAN               | 1. When dynamic VLAN is assigned for client, ACL and Client isolation for wired user will not take effect.<br>2. When client roaming with dynamic VLAN, client IP may not be displayed on UI.   | Will be supported in future release.  |

|                  |   |  |
|------------------|---|--|
|                  | 3. Kick off iPhone client, and then connect to WLAN with dynamic VLAN, it can't obtain IP address sometimes, it can be recovered by forgetting the network and connect again. No issue on other type of client.   |  |
| Enhanced Open    | Modify Enhanced Open WLAN to Open, Client can't obtain IP address, this issue happens only on AP1101.   | Disable/Enable WLAN.<br>Will be fixed in future release.           |
| Static WEP       | Wireless client can still connect to WLAN when configured index value different from the WLAN's index.  | Will be fixed in future release.                                   |
| Wired Client     | For devices which supports downlink port, there are issues below:<br>1. Wired Client will go offline and online when modify Wireless WLAN or Downlink port config.<br>2. Plug and unplug Wired Client to OAW-AP1301H and move it to other ports of Switches in the same LAN, then plug it back to OAW-AP1301H, will cause FDB learn error in rare cases. Disable and enable the corresponding port can recover. | Will be fixed in future release.                                   |
| DPI              | The memory of AP1431/AP1411 may suddenly decrease, causing the AP to reboot due to memory issues after enabling DPI function.   | Disable DPI for AP1431/AP1411.<br>Will be fixed in future release. |
| Client Isolation | If the wired client is configured with a static IP, the wired isolation function for this client will not take effect   | Will be fixed in future release.                                   |
| Roaming          | AP will not resend client information to its neighbors after they restart for some reason. This can lead to some roaming failure issues.  | Will be fixed in future release.                                   |
| DRM              | DRM will not trigger active scanning if the current channel is not in the user configured channel list. This will lead to uneven distribution of channels.  | Will be fixed in future release.                                   |
| Syslog           | The multi syslog server function for AP1511 is not effective, which can result in the backup server being unable to receive syslog when the primary server is unavailable.  | Will be fixed in future release.                                   |
| Wi-Fi 7 MLO      | Simultaneously enabling MLO and 11R roaming will cause the client's 11R roaming to fail for AP1511.   | Will be fixed in future release.                                   |
| Wi-Fi 7 MLO      | When the MLO client accesses AP1511, the Rx rate/Tx rate values in the throughput graph of the monitoring module are incorrect.   | Will be fixed in future release.                                   |
| Mesh             | The AP1361 mesh root traffic stuck, the non-root AP can't connect to root.  | Reboot mesh root AP.<br>Will be fixed in future release.           |
| AP freezing      | The AP1221 freezing and getting down.   | Will be fixed in future release.                                   |

## Limitations and/or Dependencies

| Feature                              | AP Model                                 | Limitations and/or Dependencies   |
|--------------------------------------|--|---|
| WCF                                  | All                                      | <ol style="list-style-type: none"> <li>1. WCF does not support http over proxy scenario.</li> <li>2. WCF does not support blocking mobile applications access. Client's packets are not restricted (packet not dropped by AP, no redirection to Restricted Web Page)</li> <li>3. WCF does not support RAP scenario.</li> <li>4. When using Iphone roaming between Aps, reject page can't be redirected when using Safari, but it works ok for other browser such as Chrome</li> <li>5. If the mobile device has already cached the DNS for the corresponding URL, the WCF functionality will not take effect.</li> <li>6. WCF Feature is not supported when WLAN Client enabled secure DNS (DoT or DoH).</li> </ol> |
| HTTPs CP over proxy                  | All                                      | For iOS does not support to configure URL to bypass the proxy, this function does not work on iOS devices.  |
| AP 802.1x client                     | All                                      | Wireless clients can't connect to internet on untag VLAN with AOS switch due to AOS switch treat all untag devices as 802.1x client.  |
| Wired Port                           | AP1201HL                                 | <ol style="list-style-type: none"> <li>1. AP1201HL switches to a Group with downlink configuration, wired client cannot access it.</li> <li>2. AP1201HL enables trust tag and option 82, wired client may not obtain IP address.</li> </ol>   |
| DRM                                  | All                                      | In some cases, when the channel utilization reaches more than 90%, the channel does not switch automatically, which seriously affects the user experience.  |
| IGMP Snooping                        | All Stellar Wi-Fi 6 AP Models            | For 11AX devices, if there is no multicast querier in the environment, the conversion from multicast to unicast may fail. We recommend that the switch of IGMP Snooping feature be turned on by default.  |
| Mesh                                 | All                                      | Multicast to unicast is not supported in Mesh mode.   |
| DPI                                  | AP1201/<br>AP1220<br>series/<br>AP1251   | When DPI function is enabled, it is recommended to have an initial free memory size of about 30MB after AP booting up for system stable running. If the booting up free memory size is far less than 30MB, suggest removing unnecessary WLAN/VLAN/Policy/DPI rule on AP1201/AP1220/AP1251.  |
| Bypass VLAN                          | AP1201H/<br>AP1201HL                     | If the bypass VLAN function is enabled, setting VLAN id A, and setting the management VLAN to tag VLAN id is also A, which will cause the AP itself to be inaccessible and affect the operation of AP. Therefore, there is a restriction here that the tag for managing VLAN cannot be the same as bypass.  |
| mDNS                                 | AP1201H/<br>AP1201HL<br>/AP1261-<br>RW-B | AP1201H/1201HL/AP1261-RW-B Downlink Terminal does not support mDNS message forwarding.  |
| Show device name                     | All                                      | When some clients connect to wlan, there is no option12 field in the dhcp message, so its hostname cannot be displayed.   |
| Management VLAN<br>Static IP<br>LACP | AP1351/A<br>P1451                        | When configure LACP + Management VLAN + Static IP for AP1351, the network will not be reachable after AP reboot if LACP aggregated link is formed, the workaround of this issue should be disable LACP on switch side.  |
| Link aggregation                     | All                                      | Link aggregation with management VLANs has a certain probability of failure.  |
| Link aggregation                     | AP1351                                   | There is very low probability on AP1351 that ethernet PHY fail to receive messages in the scenario of link aggregation.   |
| ALEISSUE-1294                        | All                                      | This improvement might cause some lower version of SSH clients cannot connect to Stellar AP running this new build, upgrade SSH client version will avoid this problem.   |
| ALEISSUE-1343                        | AP1201H(L)                               | VLAN 4090-4094 is not allowed configured.   |
| 11K                                  | Aps without scan radio                   | To make sure 11k function work as expected, we should configure the AP background scanning on "Working Channel and Non-working Channel".  |



|                               |  |  |
|-------------------------------|--|--|
| Enhanced Open WLAN            | All                                      | Mobile devices with Apple iOS do not support OWE, Mobile devices with Android 10 or later support OWE, Computers with Windows 10 version 2004 or later and a wireless adapter that supports OWE.   |
| Client Isolation              | All                                      | 1. Client A connect to WLAN1 with ARP1, and Client B connect to WLAN2 with ARP2, in this case, If Client A and B needs to communicate to each other, both of the two clients need to be added into whitelist, either one of Clients add into whitelist can't ensure communication between these two clients.<br>2. In case of Express mode, configure WLAN using internal portal + external MAC authentication, client isolation will not work, suggest using internal or external portal authentication only. |
| Express mode WLAN number      | All                                      | Starting with AWOS 4.0.5 in Express mode, we can create 15 user SSIDs on clusters with following models.<br>• AP1301H, AP132x, AP1331, AP136x, AP1351 & AP1451<br>If a cluster has any of the following models, limit remains at 7 user SSIDs.<br>• AP1311, AP1301, AP12xx and AP1101  |
| ALEISSUE-1367                 | All                                      | OV IP was not supposed to be included in the local breakout IP range.  |
| RAP wired downlink port       | All Stellar AP with downlink wired port. | 1. Trust tag VLAN ID should not be same as Mac VLAN ID.<br>2. After enabled trust tag, should not use VLAN0.<br>3. Don't support authentication and policy rules.  |
| Certificate management        | All                                      | In express mode, the password of the certificate does not support special characters.  |
| WPA3+11r                      | All                                      | Some clients do not support WPA3+11r.  |
| Enhanced Open Transition Mode | All                                      | Mobile devices with Android OS connects to Enhanced Open Transition Mode WLAN, sometimes it connects to Open WLAN and sometimes it connects to OWE WLAN, When the issue happens AP works as expected broadcasting beacons with related Transition mode info IE. It is suggested to upgrade mobile devices to latest software version.  |
| USB flash drive               | OAW-AP1301                               | Plug in the USB flash drive, and doing factory reset or OS upgrade, AP can't obtain IP address when AP boots up again, power cycle the device will recover.  |
| Mesh                          | All                                      | When AP create a new WLAN on MESH AP, the mesh connection will be interrupted briefly.   |
| 802.1x                        | All                                      | AP doesn't support CoA messages in case of 802.1x authentication.  |
| Wi-Fi 7 MLO                   | AP1511                                   | Clients that support Wi Fi 7 MLO features may not be able to access the MLO 6G radio configured on AP1511 due to compatibility issues.   |
| Wi-Fi 7 MLO                   | AP1511                                   | WPA3 encryption is required for WLAN configured with MLO.  |
| Wi-Fi 7 MLO                   | AP1511                                   | Enhanced Open (Transition Mode) WLAN does not support MLO configuration.   |
| Second Radius Server          | All                                      | The current logic of switching from backup server to primary server has issues with adapting to radsec scenarios.  |
| Wired Port                    | All Stellar AP with downlink wired port. | The scenario where the AP wired downstream port is connected to a switch and the switch is connected to a wired PC is currently not supported, which will cause the 1x authentication of the PC under the switch to fail.  |
| BLE                           | All Stellar AP with BLE chip             | When the Discover all Devices/iBeaconRawData configuration is issued to an old version AP, it may result in no scan data reporting due to the AP's inability to parse the configuration.   |
| DPI                           | AP1511                                   | AP1511 does not support DPI function.  |

# New Software Feature Descriptions

## MLO Configuration

MLO is a key technological innovation in Wi-Fi 7, which allows devices to simultaneously utilize multiple frequency bands (such as 2.4GHz, 5GHz, and 6GHz) for data transmission. This multi-band aggregation method enables Wi-Fi 7 devices to significantly improve the efficiency and speed of data transmission.

Among the devices supporting Wi-Fi 7 in AWOS 5.0.1, MLO is an important feature for users. The configuration of MLO in Express mode is mainly reflected in the following aspects:

### a) MLO WLAN Configuration

On the regular WLAN creation page, added are two parameters MLO & MLO band for Wi-Fi 7 feature. When multiple bands are selected, MLO can be enabled and two or three bands can be selected to aggregate into MLO bands, as follows:

The screenshot shows the 'WLAN Configuration' window. On the left is a table of WLAN configurations. On the right is the 'Edit WLAN Information' form. In the form, the 'MLO' toggle is set to 'on' and the 'MLO Band' dropdown is set to '2.4G, 5G, 6G'. A note below the MLO toggle states: 'Note: MLO function also relies on radio status and its EHT setting. Make sure corresponding radio and its EHT being enabled to activate MLO.'

| WLAN Name | Status | Security Level | Captive Portal | Operate |
|-----------|--------|----------------|----------------|---------|
| MLO_TEST  | Enable | Enhanced Open  | Disable        | <br>WMM |

**Edit WLAN Information**

Hidden:  Yes  No

Multicast:  Yes  No

Broadcast ARP:  Yes  No

Band:  2.4GHz  5GHz  6GHz

MLO:  on

Note: MLO function also relies on radio status and its EHT setting. Make sure corresponding radio and its EHT being enabled to activate MLO.

MLO Band:

Scope Type:

WLAN Access Timer:

MaxClients Per Band:  (1-512)

Create

Note: MLO function also relies on radio status and its EHT setting. Make sure corresponding radio and its EHT are enabled to activate MLO.

### b) MLO MESH Configuration

On the basic of a regular Mesh configuration page, added are two parameters MLO & MLO band for Wi-Fi 7 feature. When Mesh enables MLO, any combination of 2.4G, 5G, and 6G can be used, with 6G only supporting WPA3 personal encryption. As follows:

The screenshot shows the 'Network' configuration page. It has three main sections: 'AP Networks', 'Wired Interface', and 'Mesh Interface'. The 'Mesh Interface' section is highlighted with a red box and contains a table of mesh interfaces.

| Name | Vlan | Protocol | IP Address    |
|------|------|----------|---------------|
| wan  |      | DHCP     | 172.16.101.21 |

| Name  | Mode  | Link Status | Enable |
|-------|-------|-------------|--------|
| ENET0 | Slave | Up          | Yes    |

| Name       | Speed | Type | Essid        | Link Status | Enable |
|------------|-------|------|--------------|-------------|--------|
| Backhaul0  | 0     | Mesh | Stellar-MESH | Down        | No     |
| Connector0 | 0     | Mesh | Stellar-MESH | Down        | No     |

### Mesh Configuration

Enable:  Yes  No

Mode:  Mesh  Bridge

SSID:

Key Management:

Is Root:  Yes  No

MLO:  on

Note: MLO function also relies on radio status and its EHT setting. Make sure corresponding radio and its EHT being enabled to activate MLO.

MLO Band:

Mcast Rate:  Mbit/s

Passphrase:

Confirm:

MLO:  on

Note: MLO function also relies on radio status and its EHT setting. Make sure corresponding radio and its EHT being enabled to activate MLO.

MLO Band:

2.4G, 5G

2.4G, 6G

5G, 6G

2.4G, 5G, 6G

Mcast Rate:  Mbit/s

Passphrase:

Confirm:

Note: MLO function also relies on radio status and its EHT setting. Make sure corresponding radio and its EHT are enabled to activate MLO.

### c) MLO RF Configuration

In the RF configuration, added Extremely High Throughput configuration for Wi-Fi 7 feature. Only when Extremely High Throughput is enabled, MLO related configurations and other Wi-Fi7 feature will take effect.

### RF Configuration

| AP       | 2.4GHz ... | 2.4GHz ... | 5GHz C... | 5GHz Po... | 6GHz C... | 6GHz Po... |
|----------|------------|------------|-----------|------------|-----------|------------|
| AP-20:00 | auto(6)    | auto(40)   | auto(116) | auto(40)   | auto(1)   | auto(40)   |

#### Edit RF Information

Others

Radio:  on

Note: Before disabling radio, make sure the radio is not selected in any WLAN or Mesh with MLO bands.

MU-MIMO:  on

High Efficiency:  on

Extremely High Throughput:  on

Note: Before disabling EHT, make sure the radio is not selected in any WLAN or Mesh with MLO bands.

Beacon Interval:  (60-500)ms

CSA:  on

CSA-Count:  1-10

Short GI:  on

Note: Before disabling Extremely High Throughput, make sure the radio is not selected in any WLAN or Mesh with MLO bands.

#### d) MLO Client

When the MLO client connects to the MLO WLAN, the MLD address of the MLO client is displayed in the client information, and detailed address information on the MLO Band will be displayed below.

Below is the detailed information of the MLO client on the link using MLD address:

The screenshot shows a web interface titled "Clients Information" with a search bar and a close button. Below the header is a table with columns: Name, IP, MAC, WLAN, and Access Point. The table contains one entry: "Xiaomi-13-Pro" with IP "172.16.101.184", MAC "1a:c2:6d:a1:ac:32", WLAN "MLO\_TEST", and Access Point "AP-20:00". To the right of the table is a "Client Detail" panel, outlined in red, which lists the following information:

| Client Detail |                                 |
|---------------|---------------------------------|
| Name:         | Xiaomi-13-Pro                   |
| IPv4:         | 172.16.101.184                  |
| IPv6:         |                                 |
| MAC:          | 1a:c2:6d:a1:ac:32               |
| WLAN:         | MLO_TEST                        |
| Access Point: | AP-20:00<br>(88:3c:93:22:20:00) |
| AP Name:      | AP-20:00                        |
| Auth:         | Enhanced Open                   |
| Online Time:  | 53 s                            |
| Device Type:  | Unknown                         |
| OS type:      | Unknown                         |

Below is the detailed information of MLO client on 5G band:

The screenshot shows the same "Clients Information" interface as above. The table and "Client Detail" panel are identical. The "Client Detail" panel is now expanded to show the "5G" band information, outlined in red:

| Client Detail |                   |
|---------------|-------------------|
| 5G            |                   |
| MAC:          | 44:71:47:c6:52:f9 |
| RSSI:         | -96(dBm)          |
| Working Mode: | 11BEA_EHT80       |
| PHY Rx rate:  | 0.00              |
| PHY Tx rate:  | 6.00              |
| Rx rate:      | 0.00              |
| Tx rate:      | 0.00              |
| Download:     | 0Byte             |
| Upload:       | 0Byte             |
| Rx Error:     | 0                 |
| Tx Retry:     | 0                 |

Below is the detailed information of MLO client on 6G band:

The screenshot shows the 'Clients Information' interface. It features a table with columns: Name, IP, MAC, WLAN, and Access Point. The first row contains the data: 'Xiaomi-13-Pro', '172.16.101.184', '1a:c2:6d:a1:ac:32', 'MLO\_TEST', and 'AP-20:00'. To the right of the table is a 'Client Detail' popup window, which is highlighted with a red border. This window displays various technical specifications for the selected client, including MAC address (44:71:47:c7:52:f9), RSSI (-59(dBm)), Working Mode (11BEA\_EHT80), PHY Rx rate (720.00), PHY Tx rate (6.00), Rx rate (0.00), Tx rate (0.00), Download (156kB), Upload (568Byte), Rx Error (0), and Tx Retry (0). At the bottom of the popup, there is a 'Roaming History' section with a plus sign.

### Enable/Disable PSE POE of AP1301H and AP1360 Through UI

The enhancement is Express UI to support PSE POE enable/disable on the downlink ports of AP1301H and AP1360 Series.

For the AP1301H and AP1360 series, PSE POE can be turned on and off in Express mode. We can configure it through group configuration, Go to Express UI System, Click General and choose Group Info Management, then enable or disable PSE by clicking the button Downlink Port PSE.

The screenshot shows the 'General Configuration' interface. It has four tabs: 'Group Info Management', 'Account Management', 'Certificate Management', and 'Service Management'. The 'Group Info Management' tab is active. The configuration fields include: Group Name (AP-Group), Location (0-9a-zA-Z\_), Group Management IP (x.x.x.x), Group Management Netmask (x.x.x.x), Group Management IPv6 (::), Group ID (1664), MQTT Compatibility (off), and Downlink Port PSE (on). A red arrow points to the 'Downlink Port PSE' toggle switch, which is currently turned on.

Regarding this feature, there are several guidelines as follows:

1. Considering compatibility, the default PSE configuration on the page is enabled to ensure that customers will not perceive any changes when upgrading from an old build to AOWS 5.0.1 release.
2. This function overlaps with the current physical power supply constraints of AT/AF/BT.
  - a. When the physical power supply is at full load, the downstream port PSE configuration should be applied.
  - b. When the physical power supply is limited and PSE is turned off, the downstream PSE configuration can be turned on, but the underlying layer will not take effect.
  - c. When the physical power supply is limited and PSE is enabled, the downstream port PSE configuration should be applied.

### Secondary RADIUS Server on Express

In the previous build, OV mode already supported configuring up to 4 servers, but Express mode only supports configuring a single server.

On AWOS 5.0.1, added a configuration for the Secondary server (Authentication and Accounting) on the Express mode web page.

Go to Express UI WLAN->WLAN Configuration, click Create.

The screenshot shows the 'WLAN Configuration' interface. On the left, there is a table with the following data:

| WLAN Name | Status | Security Level | Captive Portal | Operate |
|-----------|--------|----------------|----------------|---------|
| TEST_01   | Enable | Open           | Disable        | WMM     |
| TEST_02   | Enable | Open           | Disable        | WMM     |

Below the table is a green 'Create' button. On the right, the 'Edit WLAN Information' form is shown. A red box highlights the 'Primary Auth Server' section, which includes the following fields:

- AuthServer:
- AuthPort:
- AuthSecret:
- Nas Identifier:
- Radius Accounting:
- TLS:  Disabling TLS without a Radsec certificate.
- Secondary Auth Server:

Below the highlighted section, there is an 'Inactivity Timeout Status' toggle set to 'off'.

WLAN Configuration
✕

| WLAN Name | Status | Security Level | Captive Portal | Operate    |
|-----------|--------|----------------|----------------|------------|
| TEST_01   | Enable | Open           | Disable        | ✎ ✖<br>WMM |
| TEST_02   | Enable | Open           | Disable        | ✎ ✖<br>WMM |

Create

Edit WLAN Information
✕

Secondary Auth Server:

AuthServer:

AuthPort:

AuthSecret:

Radius Accounting:

Inactivity Timeout Status:  off

Inactivity Timeout Interval:  (60-12000)s

Enable:  Yes  No

Hidden:  Yes  No

Note: There are several guidelines as follows:

1. TLS functionality only supports Primary Server.
2. The logic and time for switching between primary and backup are consistent with OV mode

### FDB Update with ARP/GARP Enabled by Default in All Modes

In previous mechanisms, the FDB Update with ARP feature required administrators to manually enable it. In AWOS 5.0.1, FDB Update with ARP/GARP functionality is enabled by default when creating WLAN.

WLAN Configuration
✕

| WLAN Name | Status | Security Level | Captive Portal | Operate    |
|-----------|--------|----------------|----------------|------------|
| TEST_01   | Enable | Open           | Disable        | ✎ ✖<br>WMM |
| TEST_02   | Enable | Open           | Disable        | ✎ ✖<br>WMM |

Create

Create New WLAN
✕

Downstream Per Client:  (0-65536)kbps

FDB Update on Association:  on

Client Isolate:  off

802.11r:  off

802.11v:  on

802.11k:  on

802.11b:  on

802.11g:  on

Advertise AP Name:  off

A-MSDU:  on

Note: Although the feature is enabled by default, customers can manually disable it when creating WLAN.

## AWOS BLE IoT Support Enable "Discover all devices"

Due to considerations of Bluetooth power consumption and business, the initial Bluetooth scanning mode we set was Discover Generic, which means Bluetooth will scan limited and generic discoverable BLE devices.

The customer has added a batch of Bluetooth tags in the AT project, which do not work in limited and generic discoverable modes, causing our AP to be unable to scan the data of these Bluetooth tags.

In AWOS 5.0.1 build, have added Discover All Device Mode, which will allow our AP to scan all Bluetooth devices.

The screenshot shows the 'BG Configuration' dialog box with the following settings:

- Bluetooth Switch:  on
- Working Mode: Scanning
- Scan Filter Mode:  FilterOUI  No Filter
- Scan Type:  Active  Passive
- Discover All Device:  off (highlighted with a red box)
- Scanning Interval: 100 (4-10240)ms
- Scanning Period: 100 (4-10240)ms
- Scan Allowlist: (empty list with + and x icons)
- Service Config: (dashed line)

Note: When enabling Discover All Device, it may double the number of Bluetooth adv packets scanned by the AP. It is recommended to open it when there is a real demand.

## AWOS BLE IoT Support "iBeacon & RawData"

In some scenarios, customers not only need to filter broadcast messages of type iBeacon, but also need to know the complete raw data of iBeacon messages. Have added configuration support for iBeacon&Raw reporting type in Express mode.



BG Configuration✕

  

Topic:

TopicSecureProfile:

TopicTelemetry:

TopicEmergency:

RssiFormat:

Report Broadcast Type:

Bluetooth Data Report Interval:

- Eddystone-UID
- Eddystone-URL
- S1
- UnKnow
- UnKnownRssiRaw
- iBeaconRawData

## Technical Support

Alcatel-Lucent Enterprise technical support is committed to resolving our customer's technical issues in a timely manner. Customers with inquiries should contact us at:

| Region        | Phone Number                                    |
|---------------|---|
| North America | 1-800-995-2696                                  |
| Latin America | 1-877-919-9526                                  |
| Europe Union  | +800 00200100 (Toll Free) or<br>+1(650)385-2193 |
| Asia Pacific  | +65 6240 8484                                   |

**Email:** [ale.welcomecenter@al-enterprise.com](mailto:ale.welcomecenter@al-enterprise.com)

**Internet:** Customers with Alcatel-Lucent service agreements may open cases 24 hours a day via Alcatel-Lucent's support web page at: <https://myportal.al-enterprise.com/>.

Upon opening a case, customers will receive a case number and may review, update, or escalate support cases on-line. Please specify the severity level of the issue per the definitions below. For fastest resolution, please have telnet or dial-in access, hardware configuration—module type and revision by slot, software revision, and configuration file available for each switch.

**Severity 1** - Production network is down resulting in critical impact on business—no workaround available.

**Severity 2** - Segment or Ring is down or intermittent loss of connectivity across network.

**Severity 3** - Network performance is slow or impaired—no loss of connectivity or data.

**Severity 4** - Information or assistance on product feature, functionality, configuration, or installation.

[www.al-enterprise.com](http://www.al-enterprise.com) The Alcatel-Lucent name and logo are trademarks of Nokia used under license by ALE. To view other trademarks used by affiliated companies of ALE Holding, visit: [www.al-enterprise.com/en/legal/trademarks-copyright](http://www.al-enterprise.com/en/legal/trademarks-copyright). All other trademarks are the property of their respective owners. The information presented is subject to change without notice. Neither ALE Holding nor any of its affiliates assumes any responsibility for inaccuracies contained herein. © Copyright 2024 ALE International, ALE USA Inc. All rights reserved in all countries.