

AOS-W 8.10.0.2 Release Notes



Copyright Information

Alcatel-Lucent and the Alcatel-Lucent Enterprise logo are trademarks of Alcatel-Lucent. To view other trademarks used by affiliated companies of ALE Holding, visit:

<https://www.al-enterprise.com/en/legal/trademarks-copyright>

All other trademarks are the property of their respective owners. The information presented is subject to change without notice. Neither ALE Holding nor any of its affiliates assumes any responsibility for inaccuracies contained herein. (2022)

Open Source Code

This product includes code licensed under the GNU General Public License, the GNU Lesser General Public License, and/or certain other open source licenses.

Contents	3
Revision History	4
Release Overview	5
Important	5
Related Documents	5
Supported Browsers	5
Terminology Change	5
Contacting Support	6
What's New in AOS-W 8.10.0.2	7
Supported Platforms	8
Mobility Conductor Platforms	8
OmniAccess Mobility Controller Platforms	8
AP Platforms	8
End-of-Support	11
Regulatory Updates in AOS-W 8.10.0.2	12
Resolved Issues in AOS-W 8.10.0.2	13
Known Issues in AOS-W 8.10.0.2	19
Limitations	19
Known Issues	20
Upgrade Procedure	25
Important Points to Remember	25
Memory Requirements	26
Low Free Flash Memory	26
Backing up Critical Data	29
Upgrading AOS-W	30
Verifying the AOS-W Upgrade	31
Downgrading AOS-W	32
Before Calling Technical Support	34

The following table lists the revision numbers and the corresponding changes that were made in this release:

Table 1: *Revision History*

Revision	Change Description
Revision 03	AOS-236172 was added as a known issue.
Revision 02	Updated the Limitations section in the Known Issues chapter.
Revision 01	Initial release.

This AOS-W release notes includes the following topics:

- New Features and Enhancements
- Supported Platforms
- Regulatory Updates
- Upgrade Procedure

Important

- As mandated by the Wi-Fi Alliance, AOS-W 8.10.0.x requires Hash-to-Element (H2E) for 6 Ghz WPA3-SAE connections. H2E is supported only on Windows 11, Linux wpa_supplicant version 2.10 and later versions. Hence, users must upgrade their Windows and Linux software for successful 6 Ghz WPA3-SAE connections.
- To align with the Inclusive Terminology Initiative, the factory-default APs running AOS-W 8.9.0.0 or later versions use **aruba-conductor** as the host name instead of **aruba-master** to identify a target managed device or standalone switch during DNS discovery.

Related Documents

The following guides are part of the complete documentation for the Alcatel-Lucent user-centric network:

- *AOS-W Getting Started Guide*
- *AOS-W User Guide*
- *AOS-W CLI Reference Guide*
- *AOS-W API Guide*
- *Alcatel-Lucent Mobility Conductor Licensing Guide*
- *Alcatel-Lucent Virtual Appliance Installation Guide*
- *Alcatel-Lucent AP Software Quick Start Guide*

Supported Browsers

The following browsers are officially supported for use with the AOS-W WebUI:

- Microsoft Internet Explorer 11 on Windows 7 and Windows 8
- Microsoft Edge (Microsoft Edge 38.14393.0.0 and Microsoft EdgeHTML 14.14393) on Windows 10
- Mozilla Firefox 48 or later on Windows 7, Windows 8, Windows 10, and macOS
- Apple Safari 9.0 or later on macOS
- Google Chrome 67 on Windows 7, Windows 8, Windows 10, and macOS

Terminology Change

As part of advancing Alcatel-Lucent Enterprise's commitment to racial justice, we are taking a much-needed step in overhauling ALE engineering terminology to reflect our belief system of diversity and inclusion. Some legacy products and publications may continue to include terminology that seemingly evokes bias against specific groups of people. Such content is not representative of our ALE culture and moving forward, ALE will replace racially insensitive terms and instead use the following new language:

Usage	Old Language	New Language
Campus Access Points + Controllers	Master-Slave	Conductor-Member
Instant Access Points	Master-Slave	Conductor-Member
Switch Stack	Master-Slave	Conductor-Member
Wireless LAN Controller	Mobility Master	Mobility Conductor
Firewall Configuration	Blacklist, Whitelist	Denylist, Allowlist
Types of Hackers	Black Hat, White Hat	Unethical, Ethical

Contacting Support

Table 2: *Contact Information*

Contact Center Online	
Main Site	https://www.al-enterprise.com
Support Site	https://myportal.al-enterprise.com
Email	ebg_global_supportcenter@al-enterprise.com
Service & Support Contact Center Telephone	
North America	1-800-995-2696
Latin America	1-877-919-9526
EMEA	+800 00200100 (Toll Free) or +1(650)385-2193
Asia Pacific	+65 6240 8484
Worldwide	1-818-878-4507

. There are no new features, enhancements or behavioral changes introduced in this release.

This chapter describes the platforms supported in this release.

Mobility Conductor Platforms

The following table displays the Mobility Conductor platforms that are supported in this release:

Table 3: *Supported Mobility Conductor Platforms*

Mobility Conductor Family	Mobility Conductor Model
Hardware Mobility Conductor	MCR-HW-1K, MCR-HW-5K, MCR-HW-10K
Virtual Mobility Conductor	MCR-VA-50, MCR-VA-500, MCR-VA-1K, MCR-VA-5K, MCR-VA-10K

OmniAccess Mobility Controller Platforms

The following table displays the OmniAccess Mobility Controller platforms that are supported in this release:

Table 4: *Supported OmniAccess Mobility Controller Platforms*

OmniAccess Mobility Controller Family	OmniAccess Mobility Controller Model
OAW-40xx Series OmniAccess Mobility Controllers	OAW-4005, OAW-4008, OAW-4010, OAW-4024, OAW-4030
OAW-4x50 Series OmniAccess Mobility Controllers	OAW-4450, OAW-4550, OAW-4650, OAW-4750, OAW-4750XM, OAW-4850
OAW-41xx Series OmniAccess Mobility Controllers	OAW-4104, 9012
9200 Series OmniAccess Mobility Controllers	9240
MC-VA-xxx Virtual OmniAccess Mobility Controllers	MC-VA-10, MC-VA-50, MC-VA-250, MC-VA-1K

AP Platforms

The following table displays the AP platforms that are supported in this release:

Table 5: *Supported AP Platforms*

AP Family	AP Model
OAW-AP200 Series	OAW-AP204, OAW-AP205
OAW-AP203H Series	OAW-AP203H

Table 5: Supported AP Platforms

AP Family	AP Model
OAW-AP203R Series	OAW-AP203R, OAW-AP203RP
OAW-AP205H Series	OAW-AP205H
OAW-AP207 Series	OAW-AP207
OAW-AP210 Series	OAW-AP214, OAW-AP215
OAW-AP 220 Series	OAW-AP224, OAW-AP225
OAW-AP228 Series	OAW-AP228
OAW-AP270 Series	OAW-AP274, OAW-AP275, OAW-AP277
OAW-AP300 Series	OAW-AP304, OAW-AP305
OAW-AP303 Series	OAW-AP303, OAW-AP303P
OAW-AP303H Series	OAW-AP303H, AP-303HR
OAW-AP310 Series	OAW-AP314, OAW-AP315
OAW-AP318 Series	OAW-AP210AP-318
OAW-AP320 Series	OAW-APAP-324, OAW-AP325
OAW-AP330 Series	OAW-AP334, OAW-AP335
OAW-AP340 Series	OAW-AP344, OAW-AP345
OAW-AP360 Series	OAW-AP365, OAW-AP367
OAW-AP370 Series	OAW-AP374, OAW-AP375, OAW-AP377
370EX Series	AP-375EX, AP-377EX, AP-375ATEX
OAW-AP387	OAW-AP387
500 Series	OAW-AP504, OAW-AP505
500H Series	AP-503H, AP-503HR, AP-505H, AP-505HR
510 Series	OAW-AP514, OAW-AP515, AP-518
518 Series	AP-518
530 Series	OAW-AP534, OAW-AP535
550 Series	OAW-AP555

Table 5: *Supported AP Platforms*

AP Family	AP Model
560 Series	AP-565, AP-567
570 Series	AP-574, AP-575, AP-577
580 Series	AP-584, AP-585, AP-585EX, AP-587, AP-587EX
630 Series	AP-635
650 Series	AP-655

This chapter provides information on the Alcatel-Lucent products that are not supported for a particular release. The following AP models will no longer be supported beginning with the next major release, AOS-W 8.11.0.0 and higher:

- 200 Series
- OAW-AP203H Series
- OAW-AP203R Series
- OAW-AP205H Series
- OAW-AP207 Series
- 210 Series
- 220 Series
- OAW-AP228 Series
- 270 Series
- 320 Series
- 330 Series
- OAW-AP340 Series
- OAW-AP387

This chapter contains the Downloadable Regulatory Table (DRT) file version introduced in this release.

Periodic regulatory changes may require modifications to the list of channels supported by an AP. For a complete list of channels supported by an AP using a specific country domain, access the switch Command Line Interface (CLI) and execute the **show ap allowed-channels country-code <country-code> ap-type <ap-model>** command.

For a complete list of countries and the regulatory domains in which the APs are certified for operation, refer to the Downloadable Regulatory Table or the DRT Release Notes at <https://myportal.al-enterprise.com>.

The following DRT file version is part of this release:

- DRT-1.0_84233

This chapter describes the resolved issues in this release.

Table 6: *Resolved Issues in AOS-W 8.10.0.2*

New Bug ID	Description	Reported Version
AOS-228056	Users were unable to delete the configured time range neither through the no time-range command nor through the Configuration > Roles and Policies > <role> > Time Range field of the WebUI. The fix ensures that the users are able to delete the configured time range. This issue was observed in managed devices running AOS-W 8.6.0.9 or later versions.	AOS-W 8.6.0.9
AOS-228771	A dump-server profile with SCP did not work with a Windows SCP server. This issue was observed when a dump-collection profile was configured to use SCP with a Windows SCP server and OpenSSH, but empty test and crash files were sent to the Windows SCP server. The fix ensures that the dump-server profile with SCP works with a Windows SCP server. This issue was observed in managed devices running AOS-W 8.8.0.2 or later versions.	AOS-W 8.8.0.2
AOS-229059	The kernel logs of a switch contained the debug and kernel logs of the APs. The fix ensures that the kernel logs of a switch do not contain the logs of APs. This issue was observed in managed devices running AOS-W 8.0.0.0 or later versions.	AOS-W 8.7.1.5
AOS-229555 AOS-233053	Some AP-635 access points running AOS-W 8.9.0.3 or later versions crashed and rebooted unexpectedly. The log files listed the reason for the event as Reboot caused by kernel panic: Fatal exception in interrupt - PC is at anul_aon_buf_detach_node+0x4/0x90 [anul] . The fix ensures that the APs work as expected.	AOS-W 8.9.0.3
AOS-229559	A wrong policy was enforced when a combination of DPI application-based rules and WebCC-based policies were used. This issue occurred when firewall classified traffic based only on HTTP and HTTPS protocol. The fix ensures that firewall considers other protocols like SSL, HTTP2, QUIC, and SPDY. This issue was observed in managed devices running AOS-W 8.6.0.0 or later versions.	AOS-W 8.7.0.0
AOS-229622 AOS-232085	Some APs running AOS-W 8.6.0.15 or later versions crashed and rebooted unexpectedly. The log files listed the reason for the event as Reboot caused by kernel panic: Rebooting the AP. NSS FW crashed . The fix ensures that the APs work as expected.	AOS-W 8.6.0.15
AOS-229883	The SNMP walk for wlsxWlanRadioTable OID returned incorrect values. The fix ensures that the SNMP walk returns correct values. This issue was observed in managed devices running AOS-W 8.6.0.8 or later versions.	AOS-W 8.6.0.8

Table 6: Resolved Issues in AOS-W 8.10.0.2

New Bug ID	Description	Reported Version
AOS-229897	Users were unable to download logs from the Diagnostics > Technical Support page of the WebUI. The fix ensures that the users are able to download logs using the WebUI. This issue was observed in Mobility Conductors running AOS-W 8.6.0.15 or later versions.	AOS-W 8.6.0.15
AOS-229948	The Configuration > Access Points page of the WebUI did not display the list of available APs. Also, the number of available APs differed between the WebUI and CLI. The fix ensures that the WebUI displays the list of all available APs and there is no discrepancy in the number of available APs between WebUI and CLI. This issue was observed in Mobility Conductors running AOS-W 8.6.0.9 or later versions. Duplicates: AOS-226909, AOS-230436, AOS-231548, AOS-232192	AOS-W 8.6.0.9
AOS-230598	The auth process crashed on managed devices running AOS-W 8.0.0.0 or later versions. The log file listed the reason for the reboot as Segmentation Fault: bridge_ip_user_free . The fix ensures that the managed devices work as expected.	AOS-W 8.7.1.7
AOS-230690	The feature bits of Mobility Controller Virtual Appliance incorrectly changed to enabled after restoring flash backup. The fix ensures that the Mobility Controller Virtual Appliances work as expected. This issue was observed in Mobility Controller Virtual Appliances running AOS-W 8.6.0.5 or later versions.	AOS-W 8.6.0.5
AOS-230732	A few clients did not receive any reply from the DNS server. Also, packets that were dropped were encapsulated in GRE and the outer IP header had a checksum value of 0xFFFF. The fix ensures that the managed devices work as expected. This issue was observed in managed devices running AOS-W 8.6.0.10 or later versions.	AOS-W 8.6.0.10
AOS-230749	The output modifier was not visible as an optional parameter in the show ap active and show ap radio-summary commands. The fix ensures that the output modifier is visible in the show ap active and show ap radio-summary commands. This issue is observed in APs running AOS-W 8.9.0.0 or later versions.	AOS-W 8.9.0.0
AOS-230822	The error message, Error decrementing DS refcountfor cert was displayed when users uploaded a new server certificate. This issue occurred when users tried to change the current switch certificate to an expired certificate. The fix ensures that the referencing for handling switch certificates works as expected. This issue was observed in Mobility Conductors running AOS-W 8.6.0.15 or later versions.	AOS-W 8.6.0.15
AOS-231364 AOS-234152	WPA2 clients were unable to connect to WPA3 SSIDs even if backward compatibility was enabled. This issue occurred when message 3 of 4-way key handshake failed. The fix ensures that the clients are able to connect to WPA3 SSIDs. This issue was observed in stand-alone switches running AOS-W 8.9.0.0 or later versions.	AOS-W 8.9.0.0

Table 6: Resolved Issues in AOS-W 8.10.0.2

New Bug ID	Description	Reported Version
AOS-231399	Users were unable to add MC-VA licenses to any pool and an error message, Can't find GSM license available count was displayed. The fix ensures that users are able to add MC-VA licenses to managed devices. This issue was observed in managed devices running AOS-W 8.9.0.1 or later versions.	AOS-W 8.9.0.1
AOS-231801	The Mobility Conductor incorrectly returned a success message when an invalid custom beacon was configured using the ap ble-configure command. The fix ensures that the Mobility Conductor returns appropriate error messages when invalid custom beacons are configured. This issue was observed in Mobility Conductors running AOS-W 8.10.0.0 or later versions.	AOS-W 8.10.0.0
AOS-231849	Mesh Portal APs did not change channels even after AirMatch changed the channels. This issue was observed in APs that had only mesh VAPs configured. The fix ensures that the APs work as expected. This issue was observed in APs running AOS-W 8.6.0.16 or later versions.	AOS-W 8.6.0.16
AOS-232079	ACLs were not applied correctly. This issue occurred when DPI was enabled. The fix ensures that the ACLs are applied correctly on managed devices. This issue was observed in managed devices running AOS-W 8.6.0.16 or later versions.	AOS-W 8.6.0.16
AOS-232096	S-AAC switches leaked data traffic of wireless clients that were connected in split-tunnel forwarding mode. The fix ensures that the switches do not leak traffic. This issue was observed in managed devices running AOS-W 8.7.1.6 or later versions.	AOS-W 8.7.1.6
AOS-232120	Timestamp value was not updated correctly in the radius accounting packets. The fix ensures that the timestamp value is updated correctly. This issue was observed in OAW-4850 switches running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.0
AOS-232171	The list of clients that were not L2 connected were still displayed in the user table even when CoA disconnect was triggered. The fix ensures that the user table is updated correctly. This issue was observed in managed devices running AOS-W 8.6.0.15 or later versions.	AOS-W 8.6.0.15
AOS-232430	The spanning tree and interface related configuration details were not displayed in the output of the show running-config command. The fix ensures that the command displays the spanning tree and interface related configuration details. This issue was observed in Mobility Conductors running AOS-W 8.6.0.10 or later versions.	AOS-W 8.6.0.10
AOS-232552	A few APs running AOS-W 8.6.0.0 or later versions displayed multiple error log messages. This issue occurred due to a race condition. The fix ensures that the APs work as expected.	AOS-W 8.7.1.8
AOS-232643	Clients that did not support AMPDU aggregation faced periodic downstream traffic disruption. Enhancements to the wireless driver resolved the issue. This issue was observed in APs running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.0

Table 6: Resolved Issues in AOS-W 8.10.0.2

New Bug ID	Description	Reported Version
AOS-232701	Some AP-635 access points running AOS-W 8.9.0.3 or later versions crashed and rebooted unexpectedly. The log files listed the reason for the reboot as Reboot caused by kernel panic: Fatal exception in interrupt - PC is at ieee80211_add_or_retrieve_ie_from_app_opt_ies . The fix ensures that the APs work as expected.	AOS-W 8.9.0.3
AOS-232703	Some OAW-AP534, OAW-AP535, OAW-AP555, and AP-635 access points running AOS-W 8.9.0.3 or later versions crashed and rebooted unexpectedly. The log files listed the reason for the reboot as AP kernel panic: Take care of the TARGET ASSERT first (ar_wal_rx_uplink.c:538 Assertion 0 failed) . The fix ensures that the APs work as expected.	AOS-W 8.9.0.3
AOS-232704	Some AP-635 access points running AOS-W 8.9.0.3 or later versions crashed and rebooted unexpectedly. The log files listed the reason for the reboot as Reboot caused by kernel panic: Take care of the TARGET ASSERT first (:Excep :0 Exception detected Thread name : WLAN BE) . The fix ensures that the APs work as expected.	AOS-W 8.9.0.3
AOS-232712	Some OAW-AP515 access points running AOS-W 8.7.1.5 or later versions crashed and rebooted unexpectedly. The log file listed the reason for the reboot as PC is at wlc_cur_phy+0x140 . Enhancements to the wireless driver resolved the issue.	AOS-W 8.7.1.5
AOS-232757	A BLE southbound API connection was terminated when the characteristic discovery was interrupted. The fix ensures that the BLE southbound API connection is not interrupted. This issue was observed in a managed device running AOS-W 8.10.0.0.	AOS-W 8.10.0.0
AOS-232800	Some managed devices running AOS-W 8.7.1.5 or later versions rebooted unexpectedly. The log files listed the reason for the reboot as Reboot Cause: Nanny rebooted machine - mobileip process died (Intent:cause:register 34:86:50:2) . The fix ensures that the managed devices work as expected.	AOS-W 8.7.1.5
AOS-232874	The WebUI did not work on standby Mobility Conductors running AOS-W 8.7.1.8 or later versions. The fix ensures that the WebUI works on standby Mobility Conductors.	AOS-W 8.7.1.8
AOS-232892	The apb_mac field was not available in the northbound action result messages. The fix ensures that the apb_mac field is available in the northbound action result messages. This issue was observed in Mobility Conductors running AOS-W 8.10.0.0 or later versions.	AOS-W 8.10.0.0
AOS-232896	Some APs running AOS-W 8.9.0.3 or later versions crashed and rebooted unexpectedly. The log files listed the reason for the reboot as Reboot caused by kernel panic: Take care of the TARGET ASSERT first (ar_wal_tx_halphy_send.c:479 Assertion ptx_halphy->ppdu_posted == 0 failed) . The fix ensures that the APs work as expected.	AOS-W 8.9.0.3

Table 6: Resolved Issues in AOS-W 8.10.0.2

New Bug ID	Description	Reported Version
AOS-232967	Some AP-635 access points running AOS-W 8.9.0.3 or later versions crashed unexpectedly. The log files listed the reason for event as Reboot caused by kernel panic: Take care of the TARGET ASSERT first (ar_wal_tx_send.c:16601 Assertion 0 failed) . The fix ensures that the APs work as expected.	AOS-W 8.9.0.3
AOS-233005	Memory leak was observed in the stm process of Mobility Conductor. The fix ensures that the Mobility Conductor works as expected. This issue was observed in Mobility Conductors running AOS-W 8.7.1.7 or later versions.	AOS-W 8.7.1.7
AOS-233115	A few clients dropped Wifi-calling IPsec traffic that came through GRE tunnels. This issue occurred when tunnel keepalive was enabled. The fix ensures that the clients do not drop Wifi-calling IPsec traffic. This issue was observed in managed devices running AOS-W 8.6.0.15 or later versions.	AOS-W 8.6.0.15
AOS-233290	The sapd process crashed on OAW-AP205 access points running AOS-W 8.7.1.6 or later versions. The log files listed the reason for the event as Process /aruba/bin/sapd [pid 12087] died: got signal SIGABRT . The fix ensures that the APs work as expected.	AOS-W 8.7.1.6
AOS-233409 AOS-226801	All the client entries in the user table got deleted. This issue occurred when a license was added to the stand-alone switch. The fix ensures that the user table entries are not deleted whenever the license limit is updated on the stand-alone switch. This issue was observed in stand-alone switches running AOS-W 8.10.0.0 or later versions.	AOS-W 8.10.0.0
AOS-233438	Some OAW-AP515 access points running AOS-W 8.6.0.0 or later versions crashed and rebooted unexpectedly. The log file listed the reason for the reboot as PC is at phy_utils_write_phyreg_nopi+0x70/0x130 [wl_v6] . The fix ensures that the APs work as expected.	AOS-W 8.6.0.0
AOS-233518	Some AP-635 access points running AOS-W 8.9.0.3 or later versions crashed unexpectedly. The log files listed the reason for event as Reboot caused by kernel panic: Take care of the TARGET ASSERT first (:Excep :0 Exception detected Thread name : WLAN_SCHED0) . The fix ensures that the APs work as expected.	AOS-W 8.9.0.3
AOS-233572	Some OAW-AP335 access points running AOS-W 8.7.1.9 or later versions crashed and rebooted unexpectedly. The log files listed the reason for event as Reboot caused by kernel panic: Fatal exception . The fix ensures that the APs work as expected.	AOS-W 8.7.1.9
AOS-233773	The SOLUM USB dongle did not load with AP-635 access points running AOS-W 8.10.0.0 or later versions. Enhancements to the wireless driver resolved the issue.	AOS-W 8.10.0.0
AOS-233857	Some OAW-AP305 access points running AOS-W 8.9.0.3 or later versions crashed and rebooted unexpectedly. The log files listed the reason for the reboot as kernel panic: Out of memory . This issue occurred when BLE feature was enabled. The fix ensures that the APs work as expected.	AOS-W 8.9.0.3

Table 6: *Resolved Issues in AOS-W 8.10.0.2*

New Bug ID	Description	Reported Version
AOS-234577	Some AP-635 access points running AOS-W 8.9.0.3 or later versions crashed unexpectedly. The log files listed the reason for event as Reboot caused by kernel panic: Fatal exception in interrupt (PC is at tun_rcv_esp+0x38/0x2f8) .The fix ensures that the APs work as expected.	AOS-W 8.9.0.3

This chapter describes the known issues and limitations observed in this release.

Limitations

Following are the limitations observed in this release.

IP Default-Gateway Management Address

Alcatel-Lucent recommends to not configure the IP default-gateway management address for 7010, 7024, 7205, and OAW-4850 switches running AOS-W 8.10.0.0.

650 Series and 630 Series Access Points

The 650 Series and 630 Series access points have the following limitations:

- No Wi-Fi uplink on the 6 GHz radio channel
- No spectrum analysis on any radio
- No Zero-Wait DFS
- No Hotspot and Airslice support on the 6 GHz radio
- No 802.11mc responder and initiator functionality on any radio
- Only 4 VAPs on the 6 GHz radio instead of 16
- Maximum of 512 associated clients on any radio, instead of 1024

6 GHz Channel Information in Regulatory Domain Profile

AOS-W does not display the 6 GHz channel information in the existing regulatory domain profile of Wi-Fi 6E APs by default.

To include 6 GHz channel information, ensure that you change the country code to a different country code, apply the change, and then revert it to the original country code. Another option is to create a new regulatory domain profile that includes the 6 GHz channel information by default, or copy the existing regulatory domain profile into a new regulatory domain profile to save the configuration.

The following example configures a regulatory domain profile and specifies a valid 6 GHz band.

```
host) [mynode] (config) #ap regulatory-domain-profile reg-635
host) [mynode] (Regulatory Domain profile "reg-635") #country-code US
host) [mynode] (Regulatory Domain profile "reg-635") #valid-6ghz-channel 165
```

No Support for 6 GHz Radio Band and WPA3-PSK-H2E in Wi-Fi Uplink

The Wi-Fi Uplink feature does not support 6 GHz radio band and WPA3-PSK-H2E encryption type for Wi-Fi 6E APs (630 Series and 650 Series access points).

AirSlice

AirSlice is disabled for 500 Series and 510 Series access points and enabled for 530 Series, 550 Series, and 630 Series access points.

Known Issues

Following are the known issues observed in this release.

Table 7: Known Issues in AOS-W 8.10.0.2

New Bug ID	Old Bug ID	Description	Reported Version
AOS-151022 AOS-188417	185176	The output of the show datapath uplink command displays incorrect session count. This issue is observed in managed devices running AOS-W 8.1.0.0 or later versions.	AOS-W 8.1.0.0
AOS-156537	–	Multicast streaming fails when broadcast and multicast optimization is enabled on the user VLAN. This issue is observed in managed devices running AOS-W 8.7.1.4 or later versions.	AOS-W 8.7.1.4
AOS-190071 AOS-190372	–	A few users are unable to access websites when WebCC is enabled on the user role. This issue occurs in a Per User Tunnel Node (PUTN) setup when the VLAN of user role is in trunk mode. This issue is observed in OAW-4005 switches running AOS-W 8.4.0.0. Workaround: Perform the following steps to resolve the issue: 1. Remove web category from the ACL rules and apply any any any permit policy. 2. Disable WebCC on the user role. 3. Change the VLAN of user role from trunk mode to access mode.	AOS-W 8.4.0.0
AOS-195434	–	An AP crashes and reboots unexpectedly. The log files list the reason for the event as Reboot caused by kernel panic: Fatal exception . This issue is observed in APs running AOS-W 8.5.0.0 or later versions in a Mobility Conductor-Managed Device topology.	AOS-W 8.5.0.2
AOS-205650 AOS-231536	–	DHCP traffic from relay agent is not forwarded through the next-hop list configured in Layer 3 GRE tunnel. This issue is observed in managed devices running AOS-W 8.6.0.15 or later versions.	AOS-W 8.6.0.15
AOS-209580	–	The output of the show ap database command does not display the o or i flags, which indicate whether an AP is an outdoor AP or an indoor AP. This issue occurs when the AP installation type is not set to default. This issue is observed in Mobility Conductors running AOS-W 8.3.0.13 or later versions.	AOS-W 8.3.0.13
AOS-215495	–	Some APs display the error message, ARM Channel 40 Physical_Error_Rate 0 MAC_Error_Rate 84 Frame_Retry_Rate 0 arm_error_rate_threshold 70 arm_error_rate_wait_time 90 . This issue is observed in OAW-AP535 access points running AOS-W 8.5.0.5 or later versions.	AOS-W 8.5.0.5

Table 7: Known Issues in AOS-W 8.10.0.2

New Bug ID	Old Bug ID	Description	Reported Version
AOS-216536 AOS-220630	–	Some managed devices running AOS-W 8.5.0.11 or later versions are unable to come up on the Mobility Conductor. This issue occurs when the managed devices receive the branch IP address as the switch IP address in a VPNC deployment.	AOS-W 8.5.0.11
AOS-216874 AOS-230298	–	The virtual MAC address of a VLAN gets deleted from the bridge table and hence, results in a network outage. This issue is observed in managed devices running AOS-W 8.5.0.11 or later versions.	AOS-W 8.5.0.11
AOS-217628	–	Some managed devices running AOS-W 8.5.0.11 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as, Reboot Cause: Kernel Panic (Intent:cause:register 12:86:f0:2) fib6_clean_node . Duplicates: AOS-226513, AOS-226753, AOS-221178, AOS-226575, and AOS-227666	AOS-W 8.5.0.11
AOS-218219 AOS-224858 AOS-232231	–	A Microsoft Teams call with an external client does not get classified and prioritized by UCC. This issue is observed in managed devices running AOS-W 8.8.0.0 or later versions.	AOS-W 8.8.0.0
AOS-219423	–	Honeywell Handheld 60SL0 devices are unable to connect to 802.1X SSIDs. This issue is observed in managed devices running AOS-W 8.6.0.8 or later versions.	AOS-W 8.6.0.8
AOS-219791	–	The aggressive scanning mode under ARM profile settings is enabled by default. This issue is observed in APs running AOS-W 8.7.1.3 or later versions.	AOS-W 8.7.1.3
AOS-224523 AOS-224762	–	The logging source-interface command does not work as expected. This issue is observed in stand-alone switches running AOS-W 8.7.1.3 or later versions.	AOS-W 8.7.1.3
AOS-226012 AOS-226013	–	Mobility Controller Virtual Appliances running AOS-W 8.7.1.4 or later versions respond with its own MAC address as the management IP address for ARP requests.	AOS-W 8.7.1.4
AOS-226361 AOS-226850 AOS-227154	–	Mobility Conductors running AOS-W 8.7.1.5 or later versions incorrectly route traffic to different ports.	AOS-W 8.7.1.5
AOS-227981	–	A few 7010, 7024, OAW-4450, and OAW-4850 switches running AOS-W 8.0.0.0 or later versions incorrectly route the incoming external subnet traffic on management port to data ports.	AOS-W 8.7.1.6

Table 7: Known Issues in AOS-W 8.10.0.2

New Bug ID	Old Bug ID	Description	Reported Version
AOS-228462	–	The show airmatch debug schedule switch-info command does not display any output. This issue occurs when there are more than 120 switches connected in the network. This issue is observed in Mobility Conductors running AOS-W 8.6.0.10 or later versions.	AOS-W 8.6.0.10
AOS-228581	–	A VPNC crashes and reboots unexpectedly. The log files list the reason for the event as Reboot Cause: Datapath timeout (SOS Assert) (in ipsec_decrypt) . This issue occurs when the buffer memory is queued in the wrong processor. This issue is observed in VPNCs running AOS-W 8.6.0.4 or later versions.	AOS-W 8.6.0.4
AOS-228714	–	APs located in different geographical locations are incorrectly present in the same AirMatch partition. This issue occurs when interferers with same MAC address is present at different geographical locations. This issue is observed in APs running AOS-W 8.6.0.14 or later versions.	AOS-W 8.6.0.14
AOS-229024	–	Some OAW-AP505 access points running AOS-W 8.7.1.5 or later versions crashes and reboots unexpectedly. The log files list the reason for the event as PC is at wlc_mbo_parse_ie+0x15c/0x2b0 [wl_v6] .	AOS-W 8.7.1.5
AOS-229207	–	Users observe a discrepancy between the client count displayed in the WebUI of a Mobility Conductor and the CLI of a managed device. This issue occurs because the WebUI of the Mobility Conductor reports the client count including the client entries that are retained to accommodate temporary client disconnections. This issue is observed in a Mobility Conductor running AOS-W 8.5.0.13 or later versions.	AOS-W 8.5.0.13
AOS-230169	–	The firewall CP deny rule does not work for cluster CoA VRRP addresses. This issue is observed in managed devices running AOS-W 8.8.0.1.	AOS-W 8.8.0.1
AOS-230386	–	A few OAW-AP555 access points running AOS-W 8.9.0.0-FIPS or later versions crash and reboot unexpectedly. The log files list the reason for the event as Reboot caused by kernel panic: Fatal exception .	AOS-W 8.9.0.0-FIPS
AOS-230798 AOS-231576	–	The output of the show global-user-table list command displays duplicate user entries for bridge-mode SSIDs. This issue is observed in Mobility Conductor running AOS-W 8.10.0.1.	AOS-W 8.7.1.8
AOS-231225	–	A few clients are unable to connect to APs running AOS-W 8.7.1.4 or later versions. The log files in the output of the show ap remote debug mgmt-frames ap-name <ap-name> command list the reason for the event as Disassociated due to insufficient resources at AP .	AOS-W 8.7.1.4

Table 7: Known Issues in AOS-W 8.10.0.2

New Bug ID	Old Bug ID	Description	Reported Version
AOS-231283	–	The log files of few Wi-Fi 6E APs (630 Series and 650 Series access points) running AOS-W 8.10.0.0 or later versions incorrectly display the 6G radio 2 disabled due to mfg configuration message during reboot of the APs, even though the 6 GHz radio is not disabled when the APs boot up.	AOS-W 8.10.0.0
AOS-231326	–	Some OAW-4750XM switches running AOS-W 8.7.1.6 or later versions crash and reboot unexpectedly. The log files list the reason for the reboot as Reboot Cause: Kernel Panic (Intent:cause:register 12:86:b0:2) . Duplicates: AOS-231256, AOS-233583, AOS-233673, and AOS-231372	AOS-W 8.7.1.6
AOS-231649	–	Users with read-only access are able to enable configurations and view passwords configured for WLANs. This issue is observed in Mobility Conductors running AOS-W 8.7.1.6 or later versions.	AOS-W 8.7.1.6
AOS-231859	–	OmniVista 3600 Air Manager displays an incorrect number of clients connected to the Mobility Conductor. This issue occurs when AMON stats messages were not sent for OAW-RAP wired users. This issue is observed in Mobility Conductors running AOS-W 8.6.0.0 or later versions.	AOS-W 8.7.1.6
AOS-232014	–	During the EST enrollment process, a dummy private key is generated and stored as a plain text. This issue is observed in APs running AOS-W 8.7.1.6 or later versions.	AOS-W 8.7.1.6
AOS-232130	–	iOS native VPN with EAP authentication does not work on managed devices running AOS-W 8.0.0.0 or later versions.	AOS-W 8.9.0.1
AOS-232311	–	The user table does not list the entries of L3 connected clients and hence, clients are unable to pass traffic. Also, the netdestination configuration is not synchronized between authmgr and sapm processes. This issue is observed when ValidUser ACL is configured for bridge mode clients. This issue is observed in stand-alone switches running AOS-W 8.6.0.10 or later versions.	AOS-W 8.6.0.10
AOS-232443	–	Server derivation rules are not assigned correctly and an error message, Missing server in attribute list is displayed. This issue occurs when there is a delay in response from the RADIUS server. This issue is observed in stand-alone switches running AOS-W 8.7.1.3 or later versions.	AOS-W 8.7.1.3
AOS-232493	–	The entries of denylisted clients are not synchronized between the managed devices. This issue is observed in managed devices running AOS-W 8.6.0.15 or later versions in a cluster setup.	AOS-W 8.6.0.15

Table 7: Known Issues in AOS-W 8.10.0.2

New Bug ID	Old Bug ID	Description	Reported Version
AOS-232620	–	A discrepancy is observed between the total number of APs and the total number of AP BLE devices reported. This issue is observed in stand-alone switches running AOS-W 8.0.0.0 or later versions.	AOS-W 8.8.0.2
AOS-232991	–	Users are unable to issue the lc-cluster exclude-vlan command and an error message, ERROR: Invalid character is displayed. This issue is observed in Mobility Conductors running AOS-W 8.7.1.7 or later versions. Workaround: Issue the no lc-cluster exclude-list command and then add the list of VLANs to be excluded.	AOS-W 8.7.1.7
AOS-233766	–	IPsec flapping is observed between primary and secondary Mobility Conductors in a certificate-based Layer 3 redundancy deployment. This issue is observed in Mobility Conductors running AOS-W 8.6.0.9 or later versions.	AOS-W 8.6.0.9
AOS-234329	–	Some OAW-AP515 access points running AOS-W 8.7.1.6 or later versions crash and reboot unexpectedly. The log file lists the reason for the reboot as PC is at asap_set_wmm+0x5d4 .	AOS-W 8.7.1.6
AOS-236172	–	Wireless clients may not connect to the 5 GHz band. This issue occurs due to the DRT version introduced in the release, which adds support for UNII-4 channel 177. This issue is observed in OAW-AP200 Series, OAW-AP205H Series, OAW-AP210 Series, OAW-AP 220 Series, and OAW-AP228 access points running AOS-W 8.10.0.2. Workaround: Upgrade the DRT to version 1.0_84631.	AOS-W 8.10.0.2

This chapter details software upgrade procedures. It is recommended that you schedule a maintenance window for the upgrade.



Read all the information in this chapter before upgrading your Mobility Conductor, managed device, or stand-alone switch.

Important Points to Remember

To upgrade your managed device or Mobility Conductor:

- Schedule the upgrade during a maintenance window and notify your community of the planned upgrade. This prevents users from being surprised by a brief wireless network outage during the upgrade.
- Avoid making any changes to your network, such as configuration changes, hardware upgrades, or changes to the rest of the network during the upgrade. This simplifies troubleshooting.
- Know your network and verify the state of the network by answering the following questions:
 - How many APs are assigned to each managed device? Verify this information by navigating to the **Dashboard > Access Points** page in the WebUI, or by executing the **show ap active** or **show ap database** commands.
 - How are those APs discovering the managed device (DNS, DHCP Option, Broadcast)?
 - What version of AOS-W runs on your managed device?
 - Are all managed devices running the same version of AOS-W?
 - What services are used on your managed device (employee wireless, guest access, OAW-RAP, wireless voice)?
- Resolve any existing issues (consistent or intermittent) before you upgrade.
- If possible, use FTP to load AOS-W images to the managed device. FTP is faster than TFTP and offers more resilience over slow links. If you must use TFTP, ensure the TFTP server can send over 30 MB of data.
- Always upgrade the non-boot partition first. If you encounter any issue during the upgrade, you can restore the flash, and switch back to the boot partition. Upgrading the non-boot partition gives you a smoother downgrade path, if required.
- Before you upgrade to this version of AOS-W, assess your software license requirements and load any new or expanded licenses that you might require. For a detailed description of these new license modules, refer the *Alcatel-Lucent Mobility Conductor Licensing Guide*.
- With the introduction of the Long Supported Release (LSR) and Short Supported Release (SSR) terminology in AOS-W 8.10.0.0, a Mobility Conductor running an LSR release supports managed devices running the same release and the three preceding releases. This is considered as N-3 support. This allows a customer to run the latest LSR, the previous SSRs and the previous LSR simultaneously. A Mobility Conductor running an SSR release supports managed devices running the same release and the two preceding releases. This would be considered N-2 support and is the same behavior as the pre-AOS-W 8.10.0.0 MultiVersion support.
- Only for the AOS-W 8.10.0.0 LSR release, AOS-W 8.6.0.0 is treated as an LSR despite being beyond N-3. As such a Mobility Conductor running AOS-W 8.10.0.0 supports managed devices running AOS-W 8.10.0.0, AOS-W 8.9.0.0, AOS-W 8.8.0.0, AOS-W 8.7.0.0 and AOS-W 8.6.0.0.

Memory Requirements

All Alcatel-Lucent managed devices store critical configuration data on an onboard compact flash memory module. Ensure that there is always free flash space on the managed device. Loading multiple large files such as JPEG images for RF Plan can consume flash space quickly. Following are best practices for memory management:

- Do not proceed with an upgrade unless 100 MB of free memory is available. Execute the **show memory** command to identify the available free memory. To recover memory, reboot the managed device. After the managed device comes up, upgrade immediately.
- Do not proceed with an upgrade unless the minimum flash space is available. Execute the **show storage** command to identify the available flash space. If the output of the **show storage** command indicates that there is insufficient flash memory, free some used memory. Copy any log files, crash data, or flash backups from your the managed device to a desired location. Delete the following files from the managed device to free some memory:
 - **Crash data:** Execute the **tar crash** command to compress crash files to a file named **crash.tar**. Use the procedures described in [Backing up Critical Data on page 29](#) to copy the **crash.tar** file to an external server. Execute the **tar clean crash** command to delete the file from the managed device.
 - **Flash backups:** Use the procedures described in [Backing up Critical Data on page 29](#) to back up the flash directory to a file named **flash.tar.gz**. Execute the **tar clean flash** command to delete the file from the managed device.
 - **Log files:** Execute the **tar logs** command to compress log files to a file named **logs.tar**. Use the procedures described in [Backing up Critical Data on page 29](#) to copy the **logs.tar** file to an external server. Execute the **tar clean logs** command to delete the file from the managed device.



In certain situations, a reboot or a shutdown could cause the managed device to lose the information stored in its flash memory. To avoid such issues, it is recommended that you execute the **halt** command before power cycling.

Deleting a File

You can delete a file using the WebUI or CLI.

In the WebUI

From the Mobility Conductor, navigate to **Diagnostic > Technical Support > Delete Files** and remove any aging log files or redundant backups.

In the CLI

```
(host) #delete filename <filename>
```

Low Free Flash Memory

Sometimes, after extended use, the flash memory might get used up for logs and other files. The AOS-W image has increased in size and this may cause issues while upgrading to newer AOS-W images without cleaning up the flash memory.

Prerequisites

Before you proceed with the freeing up the flash memory:

- Ensure to always backup the configuration and flash memory. Issue the **backup configuration** and **backup flash** commands to backup the configuration and flash.
- Copy the **flashbackup.tar.gz** and **configbackup.tar.gz** files out of the switch. Then delete the **flashbackup.tar.gz** and **configbackup.tar.gz** files from the flash memory of the switch.
- Use only one partition for the upgrade activity and keep the other partition unchanged.

If you use the WebUI to perform an upgrade, a banner on the **Maintenance** page provides the following reminder to have sufficient free flash memory before initiating an upgrade.

For a healthy and stable system it requires free space of 360 MB for AOS v8.3 and 8.5, 570 MB for AOS 8.6 and 8.7 and 450 MB for AOS 8.8 and higher version in the /flash directory. Please make sure minimum required memory is available in /flash before upgrading to newer version.

Freeing up Flash Memory

The following steps describe how to free up the flash memory before upgrading:

1. Check if the available memory in **/flash** is greater than the limits listed in [Table 8](#) for all supported switch models:

Table 8: Flash Memory Requirements

Upgrading from	Upgrading to	Minimum Required Free Flash Memory Before Initiating an Upgrade
8.3.x	8.11.x	360 MB
8.5.x	8.11.x	360 MB
8.6.x	8.11.x	570 MB
8.7.x	8.11.x	570 MB
8.8.x	8.11.x	450 MB
8.9.x	8.11.x	450 MB
8.10.x	8.11.x	450 MB

To check the available free flash memory, issue the **show storage** command. Following is the sample output from a switch with low free flash memory:

```
(host) [mynode] #show storage
Filesystem          Size    Available      Use    %    Mounted on
/dev/usb/flash3    1.4G    1014.2M        386.7M  72%    /flash
```

2. If the available free flash memory is less than the limits listed in [Table 8](#), issue the following commands to free up more memory.
 - **tar crash**
 - **tar clean crash**
 - **tar clean logs**
 - **tar clean traces**
3. Issue the **show storage** command again to check if the available space in **/flash** is more than the minimum space required for AOS-W upgrade as listed in [Table 8](#)

4. If you are unable to free up sufficient flash memory, contact Technical Support. Do not reboot the switch.
5. If sufficient flash memory is available, proceed with the standard AOS-W upgrade. See [Upgrading AOS-W](#).
6. If a reboot was performed, you may see some of the following errors. Follow the directions below:

- Upgrade using standard procedure. You may see some of the following errors:

Error upgrading image: Ancillary unpack failed with tar error (tar: Short header).

Please clean up the /flash and try upgrade again.

Error upgrading image: Ancillary unpack failed with tar error (tar: Invalid tar magic).

Please clean up the /flash and try upgrade again.

Error upgrading image: Need atleast XXX MB space in /flash for image upgrade, please clean up the /flash and try upgrade again.

Failed updating: [upgradelImageNew.c] extractAncTar (dev: /dev/usb/flash1 imgLoc: /flash/config/ArubaOS_70xx_8.8.0.0-mm-dev_78066

- If any of the above errors occur, issue the **show image version** command to check for the default boot partition. The partition which was upgraded should become the default partition. Following is the sample output of the **show image version** command:

```
(host) [mynode] #show image version
-----
Partition           : 0:0 (/dev/usb/flash1) **Default boot**
Software Version    : ArubaOS 8.9.0.0 (Digitally Signed SHA1/SHA256 - Production
Build)
Build number       : 81046
Label              : 81046
Built on           : Thu Aug 5 22:54:49 PDT 2021
-----
Partition           : 0:1 (/dev/usb/flash2)
Software Version    : ArubaOS 8.7.0.0-2.3.1.0 (Digitally Signed SHA1/SHA256 -
Developer/Internal Build)
Build number       : 0000
Label              : arpitg@sdwan-2.3_arpitg-3-ENG.0000
Built on           : Tue Aug 10 15:02:15 IST 2021
```

- If the default boot partition is not the same as the one where you performed the upgrade, change the default boot partition. Issue the **boot system partition <part_number>** command to change the default boot partition. Enter **0** or **1** for **part_number** representing partition 0:0 or partition 0:1, respectively.
- Reload the switch. If any of the errors listed in step 4 were observed, the following errors might occur while booting AOS-W 8.9.0.0.

Sample error:

```
[03:17:17]:Installing ancillary FS [ OK ]
Performing integrity check on ancillary partition 1 [ FAIL : Validating new
ancillary partition 1...Image Integrity check failed for file
/flash/img1/mswitch/sap/arm32.ari. Digest Mismatch]
Extracting Webui files..tar: Short read
chown: /mswitch/webui/*: No such file or directory
chmod: /mswitch/webui/wms/wms.cgi: No such file or directory
```

- After the switch reboots, the login prompt displays the following banner:

```
*****
* WARNING: An additional image upgrade is required to complete the *
* installation of the AP and WebUI files. Please upgrade the boot *
* partition again and reload the controller. *
*****
```

- Repeat steps 1 through 5. If sufficient free flash memory is available, proceed with the standard AOS-W upgrade procedure. See [Upgrading AOS-W](#).
- If sufficient free flash memory is not available, issue the **dir** and **dir flash** commands to identify large files occupying the flash memory.



Exercise caution while deleting files. Contact Technical Support if you are not sure which large files in the **/flash** directory could be safely deleted to free up the required space.

- Issue the **delete filename <filename>** command to delete large files to free more flash memory.
- Check if sufficient flash memory is free as listed in [Table 8](#).
- Proceed with the standard AOS-W upgrade procedure in the same partition. See [Upgrading AOS-W](#).

Backing up Critical Data

It is important to frequently back up all critical configuration data and files on the flash memory to an external server or mass storage device. You should include the following files in these frequent backups:

- Configuration data
- WMS database
- Local user database
- Licensing database
- Custom captive portal pages
- x.509 certificates
- Log files
- Flash backup

Backing up and Restoring Flash Memory

You can backup and restore the flash memory using the WebUI or CLI.

In the WebUI

The following steps describe how to back up and restore the flash memory:

1. In the Mobility Conductor node hierarchy, navigate to the **Maintenance > Configuration Management > Backup** page.
2. Click **Create Backup** to backup the contents of the flash memory to the **flashbackup.tar.gz** file.
3. Click **Copy Backup** to copy the file to an external server.

You can copy the backup file from the external server to the flash memory using the file utility in the **Diagnostics > Technical Support > Copy Files** page.

4. To restore the backup file to the flash memory, navigate to the **Maintenance > Configuration Management > Restore** page and click **Restore**.

In the CLI

The following steps describe how to back up and restore the flash memory:

1. Execute the following command in the **enable** mode:

```
(host) #write memory
```

2. Execute the following command to back up the contents of the flash memory to the **flashbackup.tar.gz** file.

```
(host) #backup flash
```

```
Please wait while we take the flash backup.....
```

File flashback.tar.gz created successfully on flash.
Please copy it out of the controller and delete it when done.

3. Execute either of the following command to transfer the flash backup file to an external server or storage device.

```
(host) #copy flash: flashback.tar.gz ftp: <ftphost> <ftpusername> <ftpuserpassword>  
<remote directory>
```

```
(host) #copy flash: flashback.tar.gz usb: partition <partition-number>
```

You can transfer the flash backup file from the external server or storage device to the flash memory by executing either of the following command:

```
(host) #copy tftp: <tftphost> <filename> flash: flashback.tar.gz
```

```
(host) #copy usb: partition <partition-number> <filename> flash: flashback.tar.gz
```

4. Execute the following command to untar and extract the **flashbackup.tar.gz** file to the flash memory.

```
(host) #restore flash
```

Please wait while we restore the flash backup.....

Flash restored successfully.

Please reload (reboot) the controller for the new files to take effect.

Upgrading AOS-W

Upgrade AOS-W using the WebUI or CLI.



CAUTION

Ensure that there is enough free memory and flash space on your Mobility Conductor or managed device. For details, see [Memory Requirements on page 26](#).



NOTE

When you navigate to the **Configuration** tab in the WebUI, the managed device might display the **Error getting information: command is not supported on this platform** message. This message is displayed ccurs when you upgrade using the WebUI and navigate to the **Configuration** tab after the managed device reboots. This message disappears after clearing the Web browser cache.

In the WebUI

The following steps describe how to upgrade AOS-W from a TFTP server, FTP server, or local file.

1. Download the AOS-W image from the customer support site.
2. Upload the AOS-W image to a PC or workstation on your network.
3. Validate the SHA hash for the AOS-W image:
 - a. Download the **Alcatel.sha256** file from the download directory.
 - b. Load the AOS-W image to a Linux system and execute the **sha256sum <filename>** command. Alternatively, use a suitable tool for your operating system that can generate a **SHA256** hash of a file.
 - c. Verify that the output produced by this command matches the hash value found on the customer support site.



NOTE

The AOS-W image file is digitally signed and is verified using RSA2048 certificates preloaded at the factory. The Mobility Conductor or managed device will not load a corrupted AOS-W image.

4. Log in to the AOS-W WebUI from the Mobility Conductor.
5. Navigate to the **Maintenance > Software Management > Upgrade** page.
 - a. Select the **Local File** option from the **Upgrade using** drop-down list.
 - b. Click **Browse** from the **Image file name** to navigate to the saved image file on your PC or workstation.

6. Select the downloaded image file.
7. Choose the partition from the **Partition to Upgrade** option.
8. Enable the **Reboot Controller After Upgrade** toggle switch to automatically reboot after upgrading. If you do not want to reboot immediately, disable this option.



The upgrade does not take effect until reboot. If you chose to reboot after upgrade, the Mobility Conductor or managed device reboots automatically.

9. Select **Save Current Configuration**.
10. Click **Upgrade**.
11. Click **OK**, when the **Changes were written to flash successfully** message is displayed.

In the CLI

The following steps describe how to upgrade AOS-W from a TFTP server, FTP server, or local file.

1. Download the AOS-W image from the customer support site.
2. Open an SSH session to your Mobility Conductor.
3. Execute the **ping** command to verify the network connection between the Mobility Conductor and the SCP server, FTP server, or TFTP server.

```
(host)# ping <ftphost>
```

or

```
(host)# ping <tftphost>
```

or

```
(host)# ping <scphost>
```

4. Execute the **show image version** command to check if the AOS-W image is loaded on the flash partition. The partition number appears in the **Partition** row; **0:0** is partition 0, and **0:1** is partition 1. The active boot partition is marked as **Default boot**.

```
(host) #show image version
```

5. Execute the **copy** command to load the new image to the non-boot partition.

```
(host)# copy ftp: <ftphost> <ftpusername> <image filename> system: partition <0|1>
```

or

```
(host)# copy tftp: <tftphost> <image filename> system: partition <0|1>
```

or

```
(host)# copy scp: <scphost> <scpusername> <image filename> system: partition <0|1>
```

or

```
(host)# copy usb: partition <partition-number> <image filename> system: partition <0|1>
```

6. Execute the **show image version** command to verify that the new image is loaded.

```
(host)# show image version
```

7. Reboot the Mobility Conductor.

```
(host)#reload
```

8. Execute the **show version** command to verify that the upgrade is complete.

```
(host)#show version
```

Verifying the AOS-W Upgrade

Verify the AOS-W upgrade in the WebUI or CLI.

In the WebUI

The following steps describe how to verify that the Mobility Conductor is functioning as expected:

1. Log in to the WebUI and navigate to the **Dashboard > WLANs** page to verify the AOS-W image version.
2. Verify if all the managed devices are up after the reboot.
3. Navigate to the **Dashboard > Access Points** page to determine if your APs are up and ready to accept clients.
4. Verify that the number of APs and clients are as expected.
5. Test a different type of client in different locations, for each access method used.
6. Complete a backup of all critical configuration data and files on the flash memory to an external server or mass storage facility. See [Backing up Critical Data on page 29](#) for information on creating a backup.

In the CLI

The following steps describe how to verify that the Mobility Conductor is functioning as expected:

1. Log in to the CLI to verify that all your managed devices are up after the reboot.
2. Execute the **show version** command to verify the AOS-W image version.
3. Execute the **show ap active** command to determine if your APs are up and ready to accept clients.
4. Execute the **show ap database** command to verify that the number of APs and clients are as expected.
5. Test a different type of client in different locations, for each access method used.
6. Complete a backup of all critical configuration data and files on the flash memory to an external server or mass storage facility. See [Backing up Critical Data on page 29](#) for information on creating a backup.

Downgrading AOS-W

A Mobility Conductor or managed device has two partitions, 0 and 1. If the upgrade fails on one of the partitions, you can reboot the Mobility Conductor or managed device from the other partition.

Pre-requisites

Before you reboot the Mobility Conductor or managed device with the pre-upgrade AOS-W version, perform the following steps:

1. Back up your Mobility Conductor or managed device. For details, see [Backing up Critical Data on page 29](#).
2. Verify that the control plane security is disabled.
3. Set the Mobility Conductor or managed device to boot with the previously saved configuration file.
4. Set the Mobility Conductor or managed device to boot from the partition that contains the pre-upgrade AOS-W version.

When you specify a boot partition or copy an image file to a system partition, Mobility Conductor or managed device checks if the AOS-W version is compatible with the configuration file. An error message is displayed if the boot parameters are incompatible with the AOS-W version and configuration files.

5. After switching the boot partition, perform the following steps:

- Restore the pre-upgrade flash backup from the file stored on the Mobility Conductor or managed device. Do not restore the AOS-W flash backup file.
- Do not import the WMS database.
- If the RF plan is unchanged, do not import it. If the RF plan was changed before switching the boot partition, the changed RF plan does not appear in the downgraded AOS-W version.

- If any new certificates were added in the upgraded AOS-W version, reinstall these certificates in the downgraded AOS-W version.

Downgrade AOS-W version using the WebUI or CLI.

In the WebUI

The following steps describe how to downgrade the AOS-W version:

1. If the saved pre-upgrade configuration file is on an external FTP or TFTP server, copy the file to the Mobility Conductor or managed device by navigating to the **Diagnostics > Technical Support > Copy Files** page.
 - a. From **Select source file** drop-down list, select FTP or TFTP server, and enter the IP address of the FTP or TFTP server and the name of the pre-upgrade configuration file.
 - b. From **Select destination file** drop-down list, select **Flash file system**, and enter a file name (other than default.cfg).
 - c. Click **Copy**.
2. Determine the partition on which your pre-upgrade AOS-W version is stored by navigating to the **Maintenance > Software Management > Upgrade** page. If a pre-upgrade AOS-W version is not stored on your system partition, load it into the backup system partition by performing the following steps:



You cannot load a new image into the active system partition.

- a. Enter the FTP or TFTP server address and image file name.
- b. Select the backup system partition.
- c. Enable **Reboot Controller after upgrade**.
- d. Click **Upgrade**.

3. Navigate to the **Maintenance > Software Management > Reboot** page, select **Save configuration before reboot**, and click **Reboot**.

The Mobility Conductor or managed device reboots after the countdown period.

4. When the boot process is complete, verify that the Mobility Conductor or managed device is using the correct AOS-W version by navigating to the **Maintenance > Software Management > About** page.

In the CLI

The following steps describe how to downgrade the AOS-W version:

1. If the saved pre-upgrade configuration file is on an external FTP or TFTP server, use the following command to copy it to the Mobility Conductor or managed device:

```
(host) # copy ftp: <ftphost> <ftpusername> <image filename> system: partition 1
```

or

```
(host) # copy tftp: <tftphost> <image filename> system: partition 1
```

2. Set the Mobility Conductor or managed device to boot with your pre-upgrade configuration file.

```
(host) # boot config-file <backup configuration filename>
```

3. Execute the **show image version** command to view the partition on which your pre-upgrade AOS-W version is stored.

```
(host) #show image version
```



You cannot load a new image into the active system partition.

4. Set the backup system partition as the new boot partition.

```
(host) # boot system partition 1
```

5. Reboot the Mobility Conductor or managed device.

```
(host) # reload
```

6. When the boot process is complete, verify that the Mobility Conductor or managed device is using the correct AOS-W version.

```
(host) # show image version
```

Before Calling Technical Support

Provide the following information when you call the Technical Support:

- The status of installation (new or existing) and recent changes to network, device, or AP configuration. If there was a configuration change, list the exact configuration steps and commands used.
- A detailed network topology including all the devices in the network with IP addresses and interface numbers.
- The make and model number of the wireless device and NIC, driver date, version, and configuration of the NIC, and the OS version including any service packs or patches.
- The logs and output of the **show tech-support** command.
- The syslog file at the time of the problem.
- The date and time when the problem first occurred. If the problem is reproducible, list the exact steps taken to re-create the problem.
- Any wired or wireless sniffer traces taken during the time of the problem.
- The device site access information.