

AOS-W 6.5.4.14



Copyright Information

Alcatel-Lucent and the Alcatel-Lucent Enterprise logo are trademarks of Alcatel-Lucent. To view other trademarks used by affiliated companies of ALE Holding, visit:

<https://www.al-enterprise.com/en/legal/trademarks-copyright>

All other trademarks are the property of their respective owners. The information presented is subject to change without notice. Neither ALE Holding nor any of its affiliates assumes any responsibility for inaccuracies contained herein. (2019)

Open Source Code

This product includes code licensed under the GNU General Public License, the GNU Lesser General Public License, and/or certain other open source licenses.

Contents	3
Revision History	5
Release Overview	6
Supported Browsers	6
Contacting Support	6
New Features	8
Regulatory Updates	9
Resolved Issues	10
Known Issues	13
Upgrade Procedure	22
Upgrade Caveats	22
GRE Tunnel-Type Requirements	24
Important Points to Remember and Best Practices	24
Memory Requirements	25
Backing up Critical Data	25
Upgrading in a Multiswitch Network	27
Installing the FIPS Version of AOS-W 6.5.4.14	27

Upgrading to AOS-W 6.5.4.14	27
Downgrading	31
Before You Call Technical Support	33

Revision History

The following table provides the revision history of this document.

Table 1: *Revision History*

Revision	Change Description
Revision 01	Initial release.

The AOS-W 6.5.4.14 release notes includes the following topics:

- [New Features](#) describes the new features and enhancements introduced in this release.
- [Regulatory Updates](#) lists the regulatory updates in this release.
- [Resolved Issues](#) lists the issues resolved in this release.
- [Known Issues](#) lists the issues identified in this release.
- [Upgrade Procedure](#) describes the procedures for upgrading your WLAN network to the latest AOS-W release version.

Supported Browsers

The following browsers are officially supported for use with AOS-W WebUI:

- Microsoft Internet Explorer 11 on Windows 7 and Windows 8
- Microsoft Edge (Microsoft Edge 38.14393.0.0 and Microsoft EdgeHTML 14.14393) on Windows 10
- Firefox 58 and later on Windows 7, Windows 8, Windows 10, and macOS
- Apple Safari 9.0 or later on macOS
- Google Chrome 67 and later on Windows 7, Windows 8, Windows 10, and macOS

Contacting Support

Table 2: *Contact Information*

Contact Center Online	
Main Site	https://www.al-enterprise.com
Support Site	https://businessportal2.alcatel-lucent.com
Email	ebg_global_supportcenter@al-enterprise.com
Service & Support Contact Center Telephone	

Contact Center Online

North America	1-800-995-2696
Latin America	1-877-919-9526
EMEA	+800 00200100 (Toll Free) or +1(650)385-2193
Asia Pacific	+65 6240 8484
Worldwide	1-818-878-4507

This chapter describes the new features and/or enhancements introduced in AOS-W 6.5.4.14. For more information about these features, refer to the *AOS-W 6.5.4.x User Guide*.

Licensing

Support for Flex ACR License (LIC-ACR)

AOS-W 6.5.4.14 supports Flex ACR License.

This chapter describes the regulatory updates in AOS-W 6.5.4.14.

Periodic regulatory changes may require modifications to the list of channels supported by an AP. For a complete list of channels supported by an AP using a specific country domain, access the switch Command Line Interface (CLI) and execute the **show ap allowed-channels country-code <country-code> ap-type <ap-model>** command.

The following default Downloadable Regulatory Table (DRT) version is part of AOS-W 6.5.4.14:

- DRT-1.0_72277

For a complete list of countries and the regulatory domains in which the APs are certified for operation, refer to the Downloadable Regulatory Table or the DRT Release Notes at support.esd.alcatel-lucent.com.



This software release supports the channel requirements described in *ALE Support Advisory SA-N0033*, available for download from the support.esd.alcatel-lucent.com site.

This chapter describes the issues resolved in AOS-W 6.5.4.14.



We have migrated to a new defect tracking tool. Some bugs are listed with the new bug ID, which is prefixed by AOS.

Table 3: Resolved Issues in AOS-W 6.5.4.14

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-153938	189134	<p>Symptom: Some APs did not handle VLAN tagged packets. The fix ensures that the AP works as expected.</p> <p>Scenario: This issue occurred when the VLAN packets were forwarded to uplink switches without processing and were interpreted as negative packets by the uplink switches. This issue was observed in OAW-AP303H access points running AOS-W 6.5.4.6 or later versions.</p>	AP Datapath	OAW-AP303H access points	AOS-W 6.5.4.6
AOS-155632	191489 193945 193793 195645	<p>Symptom: A switch crashed and rebooted unexpectedly. The log file listed the reason for the event as Control Processor Kernel Panic. Enhancements to the wireless driver resolved this issue.</p> <p>Scenario: This issue occurred when IP options caused the Datapath process to crash. This issue was observed in OAW-4x50 Series switches running AOS-W 6.5.4.8 or later versions.</p> <p>Duplicates: AOS-157337, AOS-157417, AOS-158610, AOS-184786, AOS-186151, AOS-187156, AOS-187576, AOS-187752, AOS-187880, AOS-189198, AOS-189439, AOS-191458, AOS-191603, AOS-192748, AOS-193261, AOS-193272, AOS-193491, AOS-193997</p>	Switch-Platform	OAW-4x50 Series switches	AOS-W 6.5.4.8
AOS-148642 AOS-156454 AOS-158502 AOS-158515 AOS-190258	182031 192618 195518 195534	<p>Symptom: The Postgres process in a switch crashed unexpectedly. The fix ensures that the switch works as expected.</p> <p>Scenario: This issue was observed in OAW-4550 switches running AOS-W 6.4.4.0 or later versions.</p>	Logging	OAW-4550 switches	AOS-W 6.4.4.0

Table 3: Resolved Issues in AOS-W 6.5.4.14

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-185238	—	<p>Symptom: Users were unable to make changes to the ACL position under Security > Access Control > User Roles > Firewall Policies tab. Other ACL positions were also getting disturbed while trying to change an ACL position. The fix ensures that the ACL positions remain unchanged.</p> <p>Scenario: This issue was observed in switches running AOS-W 6.5.4.10 or later versions.</p>	WebUI	All platforms	AOS-W 6.5.4.10
AOS-185745	—	<p>Symptom: The output of the show lldp neighbor command displayed incorrect remote interface information on a switch. Increasing the buffer size resolved this issue.</p> <p>Scenario: This issue occurred when the buffer size to display the remote interface information was insufficient. This issue was observed in switches running AOS-W 6.5.4.10 or later versions.</p>	LLDP	All platforms	AOS-W 6.5.4.10
AOS-186449	—	<p>Symptom: A switch crashed and rebooted unexpectedly. The log file listed the reason for this event as Datapath timeout (SOS Assert) (Intent:cause:register 54:86:50:60).</p> <p>Scenario: This issue was observed in OAW-4030 switches running AOS-W 6.5.4.12 or later versions.</p>	Switch-Datapath	OAW-4030 switches	AOS-W 6.5.4.12
AOS-186653	—	<p>Symptom: Authentication process crashed in a switch. The fix ensures that the switch work as expected.</p> <p>Scenario: This issue occurred when the conflicting authentication types (Campus AP and Remote AP) were passing through the same NAT routing path. This issue was observed in switches running AOS-W 6.5.4.0 or later versions.</p>	Base OS Security	All platforms	AOS-W 6.5.4.0
AOS-188505	—	<p>Symptom: The wlanAPWiredPortRxBytes and wlanAPWiredPortTxBytes displayed incorrect values when an SNMP walk was performed using the IPNetMonitorX tool. The fix ensures that the correct values are displayed.</p> <p>Scenario: This issue occurred when:</p> <ul style="list-style-type: none"> ■ the client generated more traffic. ■ the counters increased beyond 32-bit. <p>This issue was observed in switches running AOS-W 6.5.4.12 or later versions.</p>	Station Management	All platforms	AOS-W 6.5.4.12

Table 3: Resolved Issues in AOS-W 6.5.4.14

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-188777	—	Symptom: The device name does not get updated in a switch whitelist table after removing the AP / Device name in Activate. The fix ensures that the device name gets updated correctly. Scenario: This issue was observed in switches running AOS-W 6.5.4.0 or later versions.	Switch-Platform	All platforms	AOS-W 6.5.4.0
AOS-189551	—	Symptom: Port Based Tunnel (PBT) client traffic from different ports of the same switch was not broadcasted across multiple CPUs and a single CPU was used for client traffic. The fix ensures that the switch is able to broadcast PBT to multiple CPUs. Scenario: This issue was observed in 7280 switches running AOS-W 6.5.4.0 or later versions.	Switch-Datapath	7280 switches	AOS-W 6.5.4.0
AOS-191106	—	Symptom: Alcatel-Lucent switches were sending OSPF LSA logs with error message BAD LSA TYPE in LSA checksum causing the OSPF neighbour to go down. With the fix, Alcatel-Lucent switches do not send bad LSA checksums. Scenario: This issue occurred when the switch established OSPF neighbour relationship with routers other than Alcatel-Lucent routers. This issue was observed in switches running AOS-W 6.5.4.13 or later versions.	OSPF	All platforms	AOS-W 6.5.4.13
AOS-190231 AOS-193796	—	Symptom: The tar crash command failed to generate the crash1.tar file. The fix ensures that the crash file is generated. Scenario: This issue was observed in switches running AOS-W 6.5.4.0 or later versions.	Switch-Platform	All platforms	AOS-W 6.5.4.0
AOS-191752	—	Symptom: Some APs were not being reclassified though the classification rules were modified using the ids ap-classification-rule command. The fix ensures that the APs get reclassified. Scenario: This issue was observed when the AP classifications were changed using ids-rules , but the old classification rules were not changing. This issue was observed in APs running AOS-W 6.5.4.0 or later versions.	Air Management-IDS	All platforms	AOS-W 6.5.4.0
AOS-193660	—	Symptom: Some APs did not respond to the probe request for a hidden BSSID when two SSIDs were configured. The fix ensures that the APs respond to the probe request. Scenario: This issue was observed in APs not limited to any AOS-W release version.	AP-Wireless	All platforms	AOS-W 6.5.4.14

This chapter describes the known and outstanding issues identified in AOS-W 6.5.4.14.



We have migrated to a new defect tracking tool. Some bugs are listed with the new bug ID, which is prefixed by AOS.

Table 4: *Known Issues in AOS-W 6.5.4.14*

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-127789 AOS-128792 AOS-128621 AOS-129208 AOS-130788 AOS-133333 AOS-140532 AOS-141083 AOS-142791 AOS-148054	154625 155709 156383 158536 161789 170955 171717 173885 181227	<p>Symptom: The VRRP state changes although heartbeats are not missed.</p> <p>Scenario: This issue occurs when a standby switch inadvertently transitions to master state because the master switch delays the processing of VRRP advertisements. This issue is observed in switches running AOS-W 6.5.0.3 in a master-local topology.</p> <p>Workaround: Disable debug logs and syslog server. Increase the advertisement interval.</p>	Switch-Platform	All platforms	AOS-W 6.5.0.3
AOS-127982 AOS-145349	177271	<p>Symptom: Some APs display incorrect IPv6 addresses when checked using SNMP.</p> <p>Scenario: This issue is observed in access points running AOS-W 6.5.1.9 or later versions.</p> <p>Workaround: None.</p>	SNMP	All platforms	AOS-W 6.5.1.9
AOS-128831 AOS-147829 AOS-148994	155936 180912 182485	<p>Symptom: A switch does not respond to the PPP LCP echo request messages from a PPPoE server. Hence, the PPPoE link is not usable.</p> <p>Scenario: This issue is observed in switches running AOS-W 6.5.1.2 or later versions.</p> <p>Workaround: None.</p>	PPPoE	All platforms	AOS-W 6.5.1.2

Table 4: *Known Issues in AOS-W 6.5.4.14*

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-130510 AOS-177783	158149 176715	<p>Symptom: The BLE scanning in an AP is slow and fewer BLE devices are reported.</p> <p>Scenario: This issue is observed in OAW-AP207 access points running AOS-W 6.5.2.0 or later versions.</p> <p>Workaround: None.</p>	BLE	OAW-AP207 access points	AOS-W 6.5.2.0
AOS-133222	161655	<p>Symptom: Some high-frequency radio statistics like Tx time, Rx time, and Rx clear are not collected correctly per beacon period in an AP.</p> <p>Scenario: This issue is observed in access points running AOS-W 6.5.2.0.</p> <p>Workaround: None.</p>	AP-Platform	All platforms	AOS-W 6.5.2.0
AOS-133616 AOS-144468 AOS-144501	176047 176088	<p>Symptom: The output of the show ap debug ble-update-status ap-name command displays the number of ineligible beacons.</p> <p>Scenario: This issue is observed in switches running AOS-W 6.5.4.0 or later versions.</p> <p>Workaround: None.</p>	IoT	All platforms	AOS-W 6.5.4.3
AOS-134588	163341	<p>Symptom: Some clients stop sending data traffic after every three hours approximately.</p> <p>Scenario: This issue occurs due to broken L3 connectivity. This issue is observed in access points running AOS-W 6.5.1.5 or later versions.</p> <p>Workaround: None.</p>	AP-Wireless	All platforms	AOS-W 6.5.1.5
AOS-137064 AOS-140141	166426 167050 170409	<p>Symptom: A master switch and a standby switch reboot unexpectedly. The log file lists the reason for this event as Reboot Cause: Datapath timeout (SOS Assert) (Intent:cause:register 54:86:50:60).</p> <p>Scenario: This issue occurs when clients send A-MSDU traffic to switches. This issue is observed in OAW-40xx Series switches running AOS-W 6.5.1.9 or later versions in a master-standby topology.</p> <p>Workaround: None.</p>	Switch-Datapath	OAW-40xx Series switches	AOS-W 6.5.1.9

Table 4: *Known Issues in AOS-W 6.5.4.14*

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-137371 AOS-142604	166800 173645	Symptom: False detections of type-5 radars are triggered in the FCC domain. Scenario: This issue is observed in access points running AOS-W 6.5.1.9 or later versions. Workaround: None.	AP-Wireless	All platforms	AOS-W 6.5.1.9
AOS-138939	168789	Symptom: An AP with 802.1x supplicant configuration fails to boot. Scenario: This issue occurs when an ACL denies a DNS response from DNS server. This issue is observed in access points running AOS-W 6.5.4.0 or later versions. Workaround: None.	AP-Platform	All platforms	AOS-W 6.5.4.0
AOS-139580	169622	Symptom: A syslog server displays the error message, aruba_change_channel 512 channel 6 mode 3 not found for some APs. Scenario: This issue is observed in OAW-AP314 and OAW-AP315 access points running AOS-W 6.5.1.5. Workaround: None.	AP-Wireless	OAW-AP314 and OAW-AP315 access points	AOS-W 6.5.1.5
AOS-139880 AOS-139898	170037 170055	Symptom: An AP does not discover a master switch through ADP. Scenario: This issue occurs when a static IP address is configured in an AP and the ACL denies ADP packets. This issue is observed in access points running AOS-W 6.5.4.2. Workaround: None.	AP-Platform	All platforms	AOS-W 6.5.4.2
AOS-140642	171103	Symptom: A switch crashes and reboots unexpectedly. The log file lists the reason for the event as Reboot Cause: Datapath timeout (SOS Assert) (Intent:cause:register 54:86:50:2) . Scenario: This issue is observed in switches running AOS-W 6.5.1.9. Workaround: None.	Switch-Datapath	All platforms	AOS-W 6.5.1.9
AOS-141091	171726	Symptom: A switch crashes and reboots unexpectedly. The log lists the reason for the event as Datapath timeout (SOS Assert) (Intent: cause:register 54:86:50:2) . Scenario: This issue is observed in OAW-4650 switches running AOS-W 6.5.3.3. Workaround: None.	Switch-Datapath	OAW-4650 switches	AOS-W 6.5.3.3

Table 4: *Known Issues in AOS-W 6.5.4.14*

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-141528	172305	Symptom: A switch sends many SNMP error messages, snmp [21466]: PAPI_Send: To: 7f000001:8419 Type:0x4 Timed out. Scenario: This issue is observed in switches running AOS-W 6.5.1.9 or later versions. Workaround: None.	SNMP	All platforms	AOS-W 6.5.1.9
AOS-142230	173168	Symptom: AppRF does not block Hotspot-Shield traffic in a switch. Scenario: This issue is observed in switches running AOS-W 6.5.1.9 or later versions. Workaround: None.	Switch-Datapath	All platforms	AOS-W 6.5.1.9
AOS-142392	173359	Symptom: A switch crashes and reboots unexpectedly. The log file lists the reason for the event as Datapath timeout (SOS Assert) (Intent:cause:register 54:86:50:2). Scenario: This issue is observed in OAW-4750 switches running AOS-W 6.5.3.3 or later versions. Workaround: None.	Switch-Datapath	OAW-4750 switches	AOS-W 6.5.3.3
AOS-143005	174150	Symptom: A switch crashes and reboots unexpectedly. The log file lists the reason for the event as Datapath crash. Scenario: This issue is observed in 7280 switches running AOS-W 6.5.4.2 or later versions. Workaround: None.	Switch-Datapath	7280 switches	AOS-W 6.5.4.2
AOS-143252	174473	Symptom: A switch crashes and reboots unexpectedly. The log file lists the reason for the event as Datapath crash. Scenario: This issue is observed in 7280 switches running AOS-W 6.5.4.0. Workaround: None.	Switch-Datapath	7280 switches	AOS-W 6.5.4.0
AOS-143457	174743	Symptom: A switch crashes and reboots unexpectedly. The log file lists the reason for the event as Datapath crash. Scenario: This issue is observed in 7280 switches running AOS-W 6.5.4.0 or later versions. Workaround: None.	Switch-Datapath	7280 switches	AOS-W 6.5.4.0

Table 4: Known Issues in AOS-W 6.5.4.14

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-143904	175340	<p>Symptom: The AP logs for a Remote AP displays the error message, connect-debounce failed, port 1 disabled.</p> <p>Scenario: This issue is observed in OAW-RAP3WNP access points running AOS-W 6.5.3.1 or later versions.</p> <p>Workaround: None.</p>	AP-Platform	OAW-RAP3WNP access points	AOS-W 6.5.3.1
AOS-144689	176344	<p>Symptom: A switch does not retain the cached ACR license.</p> <p>Scenario: This issue is observed in switches running AOS-W 6.5.3.3-FIPS version.</p> <p>Workaround: None.</p>	Licensing	All platforms	AOS-W 6.5.3.3-FIPS
AOS-144882	176622	<p>Symptom: The UCC data export function is missing from the AOS-W version running on a switch.</p> <p>Scenario: This issue is observed in switches running AOS-W 6.5.1.9 or later versions.</p> <p>Workaround: None.</p>	UCC	All platforms	AOS-W 6.5.1.9
AOS-145603	177606	<p>Symptom: The error VLAN IP address conflict with another interface is displayed while configuring a named VLAN under Configure Controller > VLANs and IP Interfaces > Named VLANs tab.</p> <p>Scenario: This issue is observed in OAW-4005 switches running AOS-W 6.5.1.4 or later versions.</p> <p>Workaround: None.</p>	WebUI	OAW-4005 switches	AOS-W 6.5.1.4
AOS-145636	177651	<p>Symptom: Some Windows 64 bit clients detected 32 bit version of VIA while trying to download it using Microsoft Edge browser.</p> <p>Scenario: This issue is observed in OAW-AP225 access points running AOS-W 6.5.1.4 or later versions.</p> <p>Workaround: None.</p>	AP-Wireless	OAW-AP225 access points	AOS-W 6.5.1.4
AOS-145876 AOS-156159 AOS-157877	177969 192218 194648	<p>Symptom: On a 2.4 GHz radio, channel utilization is very low for a few APs.</p> <p>Scenario: This issue is observed in OAW-AP203R, OAW-AP207, and OAW-AP315 access points running AOS-W 6.5.4.0 or later versions.</p> <p>Workaround: None.</p>	AP-Wireless	OAW-AP203R, OAW-AP207, and OAW-AP315 access points	AOS-W 6.5.4.9

Table 4: *Known Issues in AOS-W 6.5.4.14*

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-146105 AOS-179536	185354	Symptom: An AP crashes and reboots unexpectedly with reason rebooted caused by external watchdog reset . Scenario: This issue occurs in the driver when Multicast or DMO performance test is done either in bridge mode or tunnel mode. This issue is observed in OAW-AP203H, OAW-AP203R, and OAW-AP207 access points running AOS-W 6.5.4.8 or later versions. Workaround: None.	AP-Wireless	OAW-AP203H, OAW-AP203R, and OAW-AP207 access points	AOS-W 6.5.4.8
AOS-146916	179360	Symptom: A switch displays the Module L2TP is busy. Please try later error message and does not provide the L2TP IP address. Scenario: This issue is observed in switches running AOS-W 6.5.2.0 or later versions. Workaround: None.	IPsec	All platforms	AOS-W 6.5.2.0
AOS-146948	179408	Symptom: A switch log file displays the localdb wl-sync Skipping db_sync messages. Scenario: This issue is observed in OAW-4650 switches running AOS-W 6.5.3.4 or later versions. Workaround: None.	802.1X	OAW-4650 switches	AOS-W 6.5.3.4
AOS-147053	179656	Symptom: An AP crashes and reboots unexpectedly. The log file lists the reason for this event as Kernel panic - not syncing: Fatal exception in interrupt . Scenario: This issue occurs when the mesh role in the AP provisioning profile is set to mesh point. This issue is observed in OAW-AP300 Series access points running AOS-W 6.5.4.0 or later versions. Workaround: None.	AP-Wireless	OAW-AP300 Series access points	AOS-W 6.5.4.6
AOS-147255	179970	Symptom: The flags column in the output of the show ap bss-table displays wrong characters for wired clients. Scenario: This issue is observed in switches running AOS-W 6.5.4.7 or later versions. Workaround: None.	Station Management	All platforms	AOS-W 6.5.4.7

Table 4: *Known Issues in AOS-W 6.5.4.14*

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-147309	180094	Symptom: The console output of an AP shows asap_user_set_acl: no name for id 0 message with the MAC address of the associated clients. Scenario: This issue is observed in access points running AOS-W 6.5.3.6 or later versions. Workaround: None.	Authentication	All platforms	AOS-W 6.5.3.6
AOS-148329	181606	Symptom: The output of the show ap debug log command displays the Bridge entry insertion failure error message. Scenario: This issue is observed in OAW-AP225 and OAW-AP335 access points running AOS-W 6.5.4.5 or later versions. Workaround: None.	AP Datapath	OAW-AP225 and OAW-AP335 access points	AOS-W 6.5.4.5
AOS-149135	182683	Symptom: The redirect page is blank and displays only URL= for WISPR clients. Scenario: This issue occurs when the CPU utilization is high. This issue is observed in switches running AOS-W 6.5.1.6 or later versions. Workaround: None.	WISPR Interoperability	All platforms	AOS-W 6.5.1.6
AOS-151814	186224	Symptom: Clients are unable to connect to a bridge mode virtual AP after a VLAN assignment failure. Scenario: This issue occurs when the VLAN in a switch is removed causing subsequent deauthentication of all the clients associated with the virtual APs. This issue is observed in switches running AOS-W 6.5.4.6. Workaround: None.	Station Management	All platforms	AOS-W 6.5.4.6
AOS-152338	186981	Symptom: The SNMP polling displays incorrect privacy password mismatch error though the credentials are correct. Scenario: This issue is observed in switches running AOS-W 6.5.3.6 or later versions. Workaround: None.	SNMP	All platforms	AOS-W 6.5.3.6

Table 4: Known Issues in AOS-W 6.5.4.14

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-153087	188021	<p>Symptom: A switch generates the following console error snmp An internal system error has occurred at file ../unix/aruba_main.c function snmpRequestProcessing line 704 error Cannot send snmp response.</p> <p>Scenario: This issue is observed in switches running AOS-W 6.5.4.6 or later versions.</p> <p>Workaround: None.</p>	SNMP	All platforms	AOS-W 6.5.4.6
AOS-153844	189017	<p>Symptom: 802.11b clients are unable to pass traffic.</p> <p>Scenario: This issue is observed in OAW-AP305 access points running AOS-W 6.5.4.0 or later versions.</p> <p>Workaround: None.</p>	AP-Wireless	OAW-AP305 access points	AOS-W 6.5.4.6
AOS-154191	189490	<p>Symptom: Some APs send AMON messages such as CL_HT_ MODE with incorrect values displaying 0, 9, and 255.</p> <p>Scenario: This issue is observed in access points running AOS-W 6.5.4.7 or later versions.</p> <p>Workaround: None.</p>	Station Management	All platforms	AOS-W 6.5.4.7
AOS-154324	189646	<p>Symptom: Clients using Fing mobile software are able to discover some wireless devices connected to the same AP.</p> <p>Scenario: This issue is not restricted to any specific switch model or AOS-W release version.</p> <p>Workaround: None.</p>	Multicast	All platforms	AOS-W 6.5.4.8
AOS-154965	190482	<p>Symptom: The global timers under Configuration > Security > Authentication > Advanced tab cannot be configured.</p> <p>Scenario: This issue is observed in switches running AOS-W 6.5.4.9 or later versions.</p> <p>Workaround: None.</p>	WebUI	All platforms	AOS-W 6.5.4.9

Table 4: *Known Issues in AOS-W 6.5.4.14*

New Bug ID	Old Bug ID	Description	Component	Platform	Reported Version
AOS-155267	190912	<p>Symptom: The <code>show datapath bridge ap-name</code> command and <code>show ap mesh debug forwarding-table ap-name</code> command are running in to an infinite loop and displaying Warning: Not enough memory to complete this operation error message.</p> <p>Scenario: This issue occurs when the AP is configured as an RAP with PPPoE enabled. This issue is observed in switches running AOS-W 6.5.4.9 or later versions.</p> <p>Workaround: None.</p>	RAP-NG	All platforms	AOS-W 6.5.4.9
AOS-156223	192294	<p>Symptom: Some BSSIDs are classified as interfering instead of being classified as suspected-rogue.</p> <p>Scenario: This issue occurs when <code>rules_match_mask</code> does not reset while resetting the RAP attributes. This issue is observed in APs running AOS-W 6.5.1.10 or later versions.</p> <p>Workaround: None.</p>	Air Management-IDS	All platforms	AOS-W 6.5.1.10
AOS-157356	193833	<p>Symptom: The cache for firewall <code>dns-name</code> is filling up and causing service interruptions.</p> <p>Scenario: This issue is observed in switches running AOS-W 6.5.4.10 or later versions.</p> <p>Workaround: Reboot the device.</p>	Switch-Datapath	All platforms	AOS-W 6.5.4.10
AOS-157801	194522	<p>Symptom: WebUI certificates are not getting pushed or reflected on the branch switch.</p> <p>Scenario: This issue occurs when the branch switch is mapped to Smart Config under a master switch. This issue is observed in switches running AOS-W 6.5.3.3 or later versions.</p> <p>Workaround: None.</p>	Certificate Manager	All platforms	AOS-W 6.5.3.3
AOS-186649	—	<p>Symptom: The word Fragments is misspelled in the <code>show datapath network ingress</code> command output.</p> <p>Scenario: This issue is not limited to any switch model or AOS-W release versions.</p> <p>Workaround: None.</p>	Switch-Datapath	All platforms	AOS-W 6.5.4.12
AOS-187337	—	<p>Symptom: The WebUI allows access to pages which are inaccessible to administrators.</p> <p>Scenario: This issue is observed in switches running AOS-W 6.5.4.12 or later versions.</p> <p>Workaround: None.</p>	WebUI	All platforms	AOS-W 6.5.4.12

This chapter details the software upgrade procedures. Alcatel-Lucent best practices recommend that you schedule a maintenance window for upgrading your switches.



CAUTION

Read all the information in this chapter before upgrading your switch.

Topics in this chapter include:

- [Upgrade Caveats on page 22](#)
- [GRE Tunnel-Type Requirements on page 24](#)
- [Important Points to Remember and Best Practices on page 24](#)
- [Memory Requirements on page 25](#)
- [Backing up Critical Data on page 25](#)
- [Upgrading in a Multiswitch Network on page 27](#)
- [Installing the FIPS Version of AOS-W 6.5.4.14 on page 27](#)
- [Upgrading to AOS-W 6.5.4.14 on page 27](#)
- [Downgrading on page 31](#)
- [Before You Call Technical Support on page 33](#)

Upgrade Caveats

- OAW-AP120 Series access points, OAW-4306 Series, OAW-4x04 Series, OAW-S3, and OAW-6000 switches are not supported in AOS-W 6.5.x. Do not upgrade to AOS-W 6.5.x if your deployment contains a mix of these switches in a master-local setup.
- If your switch is running AOS-W 6.4.0.0 or later versions, do not use a Windows-based TFTP server to copy the AOS-W image to the nonboot partition of the switch for upgrading or downgrading. Use FTP or SCP to copy the image.
- Starting from AOS-W 6.4.x, you cannot create redundant firewall rules in a single ACL. AOS-W will consider a rule redundant if the primary keys are the same. The primary key is made up of the following variables:
 - source IP or alias
 - destination IP or alias
 - proto-port or service

If you are upgrading from AOS-W 6.1 or earlier and your configuration contains an ACL with redundant firewall rules, upon upgrading, only the last rule will remain.

For example, in the following ACL, both ACE entries could not be configured in AOS-W 6.4.x. When the second ACE is added, it overwrites the first.

```
(host)(config) #ip access-list session allowall-laptop
(host)(config-sess-allowall-laptop) #any any any permit time-range test_range
(host)(config-sess-allowall-laptop) #any any any deny
(host)(config-sess-allowall-laptop) #!
(host)(config) #end
(host) #show ip access-list allowall-laptop
```

```
ip access-list session allowall-laptop
allowall-laptop
-----
Priority      Source  Destination      Service Action  TimeRange
-----
1             any    any              any    deny
```

- When upgrading the software in a multiswitch network (one that uses two or more Alcatel-Lucent switches), special care must be taken to upgrade all the switches in the network and to upgrade them in the proper sequence. (See [Upgrading in a Multiswitch Network on page 27.](#))

Failure to Upgrade to AOS-W 6.5.0.0-FIPS

Customers upgrading from any FIPS version of AOS-W prior to AOS-W 6.5.0.0-FIPS to AOS-W 6.5.0.0-FIPS or later version may experience symptoms that indicate an upgrade failure. Symptoms may include the apparent loss of configuration, being unable to gain administrative access to the switch, and/or the hostname of the switch being set back to the default value.

This condition is caused by a change in the FIPS requirement for the strength of the hashing algorithm that is used to protect the configuration file from outside tampering. Starting from AOS-W 6.5.0.0-FIPS, all versions of AOS-W are changed to use the stronger hashing algorithm to meet FIPS requirements. This change is known to create a challenge when upgrading or downgrading a switch between AOS-W 6.4.0.0-FIPS version and AOS-W 6.5.0.0-FIPS version. In some instances the new stronger hash value may be missing or incorrect. This may cause the switch to not boot normally.

The most common scenario is when a switch has been booted with any version of AOS-W 6.5.0.0-FIPS or later version, is subsequently downgraded to any version of AOS-W 6.4.0.0-FIPS or prior versions, and then at any point in the future is upgraded back to any version AOS-W 6.5.0.0-FIPS or later version.

To restore service, Alcatel-Lucent recommends to roll back the AOS-W to the previous version. This can be accomplished by:

1. Connect an administrative terminal to the console port of the switch.
2. Power cycle the switch to reboot it.
3. On the administrative terminal, interrupt the boot process when prompted to enter the cpboot bootloader.
4. Execute the **osinfo** command to display the versions of AOS-W hosted on partition 0 and partition 1.
5. Execute the **def_part 0** or **def_part 1** command depending on which partition hosts the previous version AOS-W 6.4.0.0-FIPS or later version.

6. Execute the **reset** or **bootf** to reboot the switch.

This restores the switch to the previous version of AOS-W and switch configuration. Contact Alcatel-Lucent support for instructions to proceed with the upgrade.

GRE Tunnel-Type Requirements

This section describes the important points to remember when configuring an L2 GRE tunnel with respect to tunnel type:

- AOS-W 6.5.4.14 continues to support L2 GRE tunnel type zero, but it is recommended to use a non-zero tunnel type.
- If both L2 and L3 tunnels are configured between endpoint devices, you must use a non-zero tunnel type for L2 GRE tunnels.

Important Points to Remember and Best Practices

Ensure a successful upgrade and optimize your upgrade procedure by taking the recommended actions provided in the following list. You should save this list for future use.

- Schedule the upgrade during a maintenance window and notify your community of the planned upgrade. This prevents users from being surprised by a brief wireless network outage during the upgrade.
- Avoid making any other changes to your network, such as configuration changes, hardware upgrades, or changes to the rest of the network during the upgrade. This simplifies troubleshooting.
- Know your network and verify the state of your network by answering the following questions:
 - How many APs are assigned to each switch? Verify this information by navigating to the **Monitoring > NETWORK > All Access Points** section of the WebUI, or by executing the **show ap active** and **show ap database** CLI commands.
 - How are those APs discovering the switch (DNS, DHCP Option, Broadcast)?
 - What version of AOS-W is currently on the switch?
 - Are all switches in a master-local cluster running the same version of software?
 - Which services are used on the switches (employee wireless, guest access, remote AP, wireless voice)?
- Resolve any existing issues (consistent or intermittent) before you upgrade.
- If possible, use FTP to load software images to the switch. FTP is faster than TFTP and offers more resilience over slow links. If you must use TFTP, ensure the TFTP server can send over 30 MB of data.
- Always upgrade the non-boot partition first. If problems occur during the upgrade, you can restore the flash, and switch back to the boot partition. Upgrading the non-boot partition gives you a smoother downgrade path should it be required.
- Before you upgrade to this version of AOS-W, assess your software license requirements and load any new or expanded licenses you may require. For a detailed description of these new license modules, refer to the “Software Licenses” chapter in the *AOS-W 6.5.x User Guide*.

Memory Requirements

All Alcatel-Lucent switches store critical configuration data on an onboard compact flash memory module. Ensure that there is always free flash space on the switch. Loading multiple large files such as JPEG images for RF Plan can consume flash space quickly. To maintain the reliability of your WLAN network, the following compact memory best practices are recommended:

- Confirm that there is at least 60 MB of free memory available for an upgrade using the WebUI, or execute the **show memory** command to confirm that there is at least 40 MB of free memory available for an upgrade using the CLI. Do not proceed unless this much free memory is available. To recover memory, reboot the switch. After the switch comes up, upgrade immediately.
- Confirm that there is at least 75 MB of flash space available for an upgrade using the WebUI, or execute the **show storage** command to confirm that there is at least 60 MB of flash space available for an upgrade using the CLI.



In certain situations, a reboot or a shutdown could cause the switch to lose the information stored in its compact flash card. To avoid such issues, it is recommended that you execute the **halt** command before power cycling.

If the output of the **show storage** command indicates that there is insufficient flash memory space, you must free up some used memory. Any switch logs, crash data, or flash backups should be copied to a location off the switch, then deleted from the switch to free up flash space. You can delete the following files from the switch to free up some memory before upgrading:

- **Crash Data:** Execute the **tar crash** command to compress crash files to a file named **crash.tar**. Use the procedures described in [Backing up Critical Data on page 25](#) to copy the **crash.tar** file to an external server, and then execute the **tar clean crash** command to delete the file from the switch.
- **Flash Backups:** Use the procedures described in [Backing up Critical Data on page 25](#) to back up the flash directory to a file named **flash.tar.gz**, and then execute the **tar clean flash** command to delete the file from the switch.
- **Log files:** Execute the **tar logs** command to compress log files to a file named **logs.tar**. Use the procedures described in [Backing up Critical Data on page 25](#) to copy the **logs.tar** file to an external server, and then execute the **tar clean logs** command to delete the file from the switch.

Backing up Critical Data

It is important to frequently back up all critical configuration data and files on the compact flash file system to an external server or mass storage device. At the very least, you should include the following files in these frequent backups:

- Configuration data
- WMS database
- Local user database
- Licensing database
- Floor plan JPEGs
- Custom captive portal pages

- X.509 certificates
- Switch Logs

Backing up and Restoring Compact Flash in the WebUI

The WebUI provides the easiest way to back up and restore the entire compact flash file system. The following steps describe how to back up and restore the compact flash file system using the WebUI on the switch:

1. Click the **Configuration** tab.
2. Click **Save Configuration** at the top of the page.
3. Navigate to the **Maintenance > File > Backup Flash** page.
4. Click **Create Backup** to back up the contents of the compact flash file system to the **flashbackup.tar.gz** file.
5. Click **Copy Backup** to copy the file to an external server.

You can later copy the backup file from the external server to the compact flash file system using the file utility in the **Maintenance > File > Copy Files** page.

6. To restore the backup file to the Compact Flash file system, navigate to the **Maintenance > File > Restore Flash** page and click **Restore**.

Backing up and Restoring Compact Flash in the CLI

The following steps describe the backup and restore procedure for the entire compact flash file system using the switch's command line:

1. Make sure you are in the **enable** mode in the switch CLI, and execute the following command:

```
(host) # write memory
```

2. Execute the **backup** command to back up the contents of the compact flash file system to the **flashbackup.tar.gz** file.

```
(host) # backup flash
Please wait while we tar relevant files from flash...
Please wait while we compress the tar file...
Checking for free space on flash...
Copying file to flash...
File flashbackup.tar.gz created successfully on flash.
```

3. Execute the **copy** command to transfer the backup flash file to an external server or storage device.

```
(host) copy flash: flashbackup.tar.gz ftp: <ftphost> <ftpusername> <ftpuserpassword> <remote directory>
(host) copy flash: flashbackup.tar.gz usb: partition <partition-number>
```

You can later transfer the backup flash file from the external server or storage device to the compact flash file system by executing the **copy** command.

```
(host) # copy tftp: <tftphost> <filename> flash: flashbackup.tar.gz
(host) # copy usb: partition <partition-number> <filename> flash: flashbackup.tar.gz
```

4. Execute the **restore** command to untar and extract the **flashbackup.tar.gz** file to the compact flash file system.

```
(host) # restore flash
```

Upgrading in a Multiswitch Network

In a multiswitch network (a network with two or more Alcatel-Lucent switches), special care must be taken to upgrade all switches based on the switch type (master or local). Be sure to back up all switches being upgraded, as described in [Backing up Critical Data on page 25](#).



For proper operation, all switches in the network must be upgraded with the same version of AOS-W software. For redundant environments such as VRRP, the switches should be of the same model.

To upgrade an existing multiswitch system to this version of AOS-W:

1. Load the software image onto all switches (including redundant master switches).
2. If all the switches cannot be upgraded with the same software image and rebooted simultaneously, use the following guidelines:
 - a. Upgrade the software image on all the switches. Reboot the master switch. After the master switch completes rebooting, you can reboot the local switches simultaneously.
 - b. Verify that the master and all local switches are upgraded properly.

Installing the FIPS Version of AOS-W 6.5.4.14

Download the FIPS version of the software from <https://support.esd.alcatel-lucent.com>.

Instructions on Installing FIPS Software



Before you install a FIPS version of the software on a switch that is currently running a non-FIPS version of the software, follow the procedure below. If you are currently running a FIPS version of the software on the switch, you do not have to perform a **write erase** to reset the configuration as mentioned in step 2.

Follow the steps below to install the FIPS software on a switch that is currently running a non-FIPS version of the software:

1. Install the FIPS version of the software on the switch.
2. Execute the **write erase** command to reset the configuration to the factory default; otherwise, you cannot log in to the switch using the CLI or WebUI.
3. Reboot the switch by executing the **reload** command.

This is the only supported method of moving from non-FIPS software to FIPS software.

Upgrading to AOS-W 6.5.4.14

The following sections provide the procedures for upgrading the switch to AOS-W 6.5.4.14 by using the WebUI and the CLI.

Install Using the WebUI



Confirm that there is at least 60 MB of free memory and at least 75 MB of flash space available for an upgrade using the WebUI. For details, see [Memory Requirements on page 25](#).



When you navigate to the **Configuration** tab of the switch's WebUI, the switch may display the **Error getting information: command is not supported on this platform** message. This error occurs when you upgrade the switch from the WebUI and navigate to the **Configuration** tab as soon as the switch completes rebooting. This error is expected and disappears after clearing the Web browser cache.

Upgrading From a Recent Version of AOS-W

The following steps describe the procedure to upgrade from one of these recent AOS-W versions:

- AOS-W 3.4.4.1 or later
- AOS-W 5.0.3.1 or the latest version of AOS-W 5.0.x
- AOS-W 6.0.1.0 or later version of AOS-W 6.x



When upgrading from an existing AOS-W 6.4.x release, it is required to set AMON packet size manually to a desired value. However, the packet size is increased to 32K by default for fresh installations of AOS-W 6.4.3.9.

Install the AOS-W software image from a PC or workstation using the WebUI on the switch. You can also install the software image from a TFTP or FTP server using the same WebUI page.

1. Download AOS-W 6.5.4.14 from the customer support site.
2. Upload the new software image(s) to a PC or workstation on your network.
3. Validate the SHA hash for a software image:
 - a. Download the **Alcatel.sha256** file from the download directory.
 - b. To verify the image, load the image onto a Linux system and execute the **sha256sum <filename>** command or use a suitable tool for your operating system that can generate a **SHA256** hash of a file.
 - c. Verify that the output produced by this command matches the hash value found on the support site.



The AOS-W image file is digitally signed, and is verified using RSA2048 certificates preloaded on the switch at the factory. Therefore, even if you do not manually verify the SHA hash of a software image, the switch will not load a corrupted image.

4. Log in to the AOS-W WebUI from the PC or workstation.
5. Navigate to the **Maintenance > Controller > Image Management** page.
 - a. Select the **Local File** option.
 - b. Click **Browse** to navigate to the saved image file on your PC or workstation.

6. Select the downloaded image file.
7. Choose the nonboot partition from the **Partition to Upgrade** radio button.
8. Choose **Yes** in the **Reboot Controller After Upgrade** radio button to automatically reboot after upgrading. Choose **No**, if you do not want the switch to reboot immediately.



Upgrade will not take effect until you reboot the switch.

9. Choose **Yes** in the **Save Current Configuration Before Reboot** radio button.
10. Click **Upgrade**.
When the software image is uploaded to the switch, a popup window displays the **Changes were written to flash successfully** message.
11. Click **OK**.
If you chose to automatically reboot the switch in step 8, the reboot process starts automatically within a few seconds (unless you cancel it).
12. When the reboot process is complete, log in to the WebUI and navigate to the **Monitoring > NETWORK > All WLAN Controllers** page to verify the upgrade.

When your upgrade is complete, perform the following steps to verify that the switch is functioning as expected.

1. Log in to the WebUI to verify all your switches are up after the reboot.
2. Navigate to the **Monitoring > NETWORK > Network Summary** page to determine if your APs are up and ready to accept clients. In addition, verify that the number of access points and clients are what you would expect.
3. Verify that the number of access points and clients are what you would expect.
4. Test a different type of client for each access method that you use and in different locations when possible.
5. Complete a backup of all critical configuration data and files on the compact flash file system to an external server or mass storage facility. See [Backing up Critical Data on page 25](#) for information on creating a backup. If the flash (Provisioning/Backup) image version string shows the letters *rn*, for example, 3.3.2.11-rn-3.0, note those AP names and IP addresses.

Install Using the CLI



Confirm that there is at least 40 MB of free memory and at least 60 MB of flash space available for an upgrade using the CLI. For details, see [Memory Requirements on page 25](#).

Upgrading From a Recent Version of AOS-W

The following steps describe the procedure to upgrade from one of these recent AOS-W versions:

- AOS-W 3.4.4.1 or later

- AOS-W 5.0.3.1 or the latest version of AOS-W 5.0.x
- AOS-W 6.0.1.0 or later version of AOS-W 6.x

To install the AOS-W software image from a PC or workstation using the CLI on the switch:

1. Download AOS-W 6.5.4.14 from the customer support site.
2. Open an SSH session on your master (and local) switches.
3. Execute the **ping** command to verify the network connection from the target switch to the SCP/FTP/TFTP server.

```
(host)# ping <ftphost>
```

or

```
(host)# ping <tftphost>
```

or

```
(host)# ping <scphost>
```

4. Execute the **show image version** command to check if the AOS-W images are loaded on the switch's flash partitions. The partition number appears in the **Partition** row; **0:0** is partition 0, and **0:1** is partition 1. The active boot partition is marked as **Default boot**.
5. Execute the **copy** command to load the new image onto the nonboot partition.

```
(host)# copy ftp: <ftphost> <ftpusername> <image filename> system: partition <0|1>
```

or

```
(host)# copy tftp: <tftphost> <image filename> system: partition <0|1>
```

or

```
(host)# copy scp: <scphost> <scpusername> <image filename> system: partition <0|1>
```

or

```
(host)# copy usb: partition <partition-number> <image filename> system: partition <0|1>
```



The USB option is available on the OAW-40xx Series and OAW-4x50 Series switches.

6. Execute the **show image version** command to verify that the new image is loaded.
7. Reboot the switch.
8. Execute the **show version** command to verify that the upgrade is complete.

```
(host)# reload
```

```
(host)# show version
```

When your upgrade is complete, perform the following steps to verify that the switch is functioning as expected.

1. Log in to the CLI to verify that all your switches are up after the reboot.
2. Execute the **show ap active** command to determine if your APs are up and ready to accept clients.
3. Execute the **show ap database** command to verify that the number of access points and clients are what you expected.

4. Test a different type of client for each access method that you use and in different locations when possible.
5. Complete a backup of all critical configuration data and files on the compact flash file system to an external server or mass storage facility. See [Backing up Critical Data on page 25](#) for information on creating a backup.

Downgrading

If necessary, you can return to your previous version of AOS-W.



Database versions are not compatible between different AOS-W releases.



If you do not downgrade to a previously saved pre-6.1 configuration, some parts of your deployment may not work as they previously did. For example, when downgrading from AOS-W 6.5.4.14 to 5.0.3.2, changes made to WIPS in AOS-W 6.x prevent the new predefined IDS profile assigned to an AP group from being recognized by the older version of AOS-W. This unrecognized profile can prevent associated APs from coming up, and can trigger a profile error.

These new IDS profiles begin with *ids-transitional* while older IDS profiles do not include *transitional*. If you have encountered this issue, execute the **show profile-errors** and **show ap-group** commands to view the IDS profile associated with the AP group.



When reverting the switch software, whenever possible, use the previous version of software known to be used on the system. Loading a release not previously confirmed to operate in your environment could result in an improper configuration.

Before You Begin

Before you reboot the switch with the preupgrade software version, you must perform the following steps:

1. Back up your switch. For details, see [Backing up Critical Data on page 25](#).
2. Verify that the control plane security is disabled.
3. Set the switch to boot with the previously saved pre-AOS-W 6.5.4.14 configuration file.
4. Set the switch to boot from the system partition that contains the previously running AOS-W image.

When you specify a boot partition (or copy an image file to a system partition), the software checks to ensure that the image is compatible with the configuration file used on the next switch reload. An error message is displayed if system boot parameters are set for incompatible image and configuration files.

5. After downgrading the software on the switch, perform the following steps:
 - Restore pre-AOS-W 6.5.4.14 flash backup from the file stored on the switch. Do not restore the AOS-W 6.5.4.14 flash backup file.
 - You do not need to reimport the WMS database or RF Plan data. However, if you have added changes to RF Plan in AOS-W 6.5.4.14, the changes do not appear in RF Plan in the downgraded AOS-W version.
 - If you installed any certificates while running AOS-W 6.5.4.14, you need to reinstall the certificates in the downgraded AOS-W version.

Downgrading Using the WebUI

The following section describes how to use the WebUI to downgrade the software on the switch.

1. If the saved preupgrade configuration file is on an external FTP/TFTP server, copy the file to the switch by navigating to the **Maintenance > File > Copy Files** page.
 - a. For **Source Selection**, select FTP/TFTP server, and enter the IP address of the FTP/TFTP server and the name of the preupgrade configuration file.
 - b. For **Destination Selection**, enter a file name (other than default.cfg) for Flash File System.
2. Set the switch to boot with your preupgrade configuration file by navigating to the **Maintenance > Controller > Boot Parameters** page.
 - a. Select the saved preupgrade configuration file from the **Configuration File** drop-down list.
 - b. Click **Apply**.
3. Determine the partition on which your previous software image is stored by navigating to the **Maintenance > Controller > Image Management** page. If there is no previous software image stored on your system partition, load it into the backup system partition (you cannot load a new image into the active system partition) by performing the following steps:
 - a. Enter the FTP/TFTP server address and image file name.
 - b. Select the backup system partition.
 - c. Click **Upgrade**.
4. Navigate to the **Maintenance > Controller > Boot Parameters** page.
 - a. Select the system partition that contains the preupgrade image file as the boot partition.
 - b. Click **Apply**.
5. Navigate to the **Maintenance > Controller > Reboot Controller** page. Click **Continue**. The switch reboots after the countdown period.
6. When the boot process is complete, verify that the switch is using the correct software by navigating to the **Maintenance > Controller > Image Management** page.

Downgrading Using the CLI

The following section describes how to use the CLI to downgrade the software on the switch.

1. If the saved preupgrade configuration file is on an external FTP/TFTP server, use the following command to copy it to the switch:

```
(host) # copy ftp: <ftphost> <ftpusername> <image filename> system: partition 1
```

or

```
(host) # copy tftp: <tftphost> <image filename> system: partition 1
```
2. Set the switch to boot with your preupgrade configuration file.

```
(host) # boot config-file <backup configuration filename>
```
3. Execute the **show image version** command to view the partition on which your previous software image is stored. You cannot load a new image into the active system partition (the default boot).

In the following example, partition 1, the backup system partition, contains the backup release AOS-W 6.1.3.2. Partition 0, the default boot partition, contains the AOS-W 6.5.4.14 image.

4. Set the backup system partition as the new boot partition.

```
(host) # boot system partition 1
```

5. Reboot the switch.

```
(host) # reload
```

6. When the boot process is complete, verify that the switch is using the correct software.

```
(host) # show image version
```

Before You Call Technical Support

Before you place a call to Technical Support, follow these steps:

1. Provide a detailed network topology (including all the devices in the network between the user and the Alcatel-Lucent switch with IP addresses and Interface numbers if possible).
2. Provide the wireless device's make and model number, OS version (including any service packs or patches), wireless Network Interface Card (NIC) make and model number, wireless NIC's driver date and version, and the wireless NIC's configuration.
3. Provide the switch logs and output of the **show tech-support** command via the WebUI Maintenance tab or via the CLI (**tar logs tech-support**).
4. Provide the syslog file of the switch at the time of the problem. Alcatel-Lucent strongly recommends that you consider adding a syslog server if you do not already have one to capture logs from the switch.
5. Let the support person know if this is a new or existing installation. This helps the support team to determine the troubleshooting approach, depending on whether you have an outage in a network that worked in the past, a network configuration that has never worked, or a brand new installation.
6. Let the support person know if there are any recent changes in your network (external to the Alcatel-Lucent switch) or any recent changes to your switch and/or AP configuration. If there was a configuration change, list the exact configuration steps and commands used.
7. Provide the date and time (if possible) of when the problem first occurred. If the problem is reproducible, list the exact steps taken to re-create the problem.
8. Provide any wired or wireless sniffer traces taken during the time of the problem.
9. Provide the switch site access information, if possible.