

# AOS-W 8.6.0.8



## **Copyright Information**

Alcatel-Lucent and the Alcatel-Lucent Enterprise logo are trademarks of Alcatel-Lucent. To view other trademarks used by affiliated companies of ALE Holding, visit:

<https://www.al-enterprise.com/en/legal/trademarks-copyright>

All other trademarks are the property of their respective owners. The information presented is subject to change without notice. Neither ALE Holding nor any of its affiliates assumes any responsibility for inaccuracies contained herein. (2021)

## **Open Source Code**

This product includes code licensed under the GNU General Public License, the GNU Lesser General Public License, and/or certain other open source licenses.

---

<b>Contents</b> .....	<b>3</b>
Revision History .....	5
<b>Release Overview</b> .....	<b>6</b>
Important Point Before Upgrading to AOS-W 8.6.0.0 .....	6
Supported Browsers .....	6
Contacting Support .....	7
<b>New Features and Enhancements</b> .....	<b>8</b>
<b>Supported Platforms</b> .....	<b>9</b>
Mobility Master Platforms .....	9
OmniAccess Mobility Controller Platforms .....	9
AP Platforms .....	10
<b>Regulatory Updates</b> .....	<b>12</b>
<b>Resolved Issues</b> .....	<b>13</b>
<b>Known Issues and Limitations</b> .....	<b>14</b>
<b>Upgrade Procedure</b> .....	<b>28</b>
Important Points to Remember .....	28
Memory Requirements .....	29

---

Backing up Critical Data .....	30
Upgrading AOS-W .....	31
Downgrading AOS-W .....	34
Before Calling Technical Support .....	36

## Revision History

The following table provides the revision history of this document.

**Table 1:** *Revision History*

Revision	Change Description
Revision 01	Initial release.

This AOS-W release notes includes the following topics:



---

Throughout this document, branch switch and local switch are termed as managed device.

---

- [New Features and Enhancements on page 8](#)
- [Supported Platforms on page 9](#)
- [Regulatory Updates on page 12](#)
- [Resolved Issues on page 13](#)
- [Known Issues and Limitations on page 14](#)
- [Upgrade Procedure on page 28](#)

For a list of terms, refer to the [Glossary](#).

## Important Point Before Upgrading to AOS-W 8.6.0.0

**Your CPU should support version SSE4.2.** For deployments on versions prior to AOS-W 8.5.0.0, SSE3 is the minimum supported version. Additionally the CPU should also support Intel VT.

## Supported Browsers

The following browsers are officially supported for use with the AOS-W WebUI:

- Microsoft Internet Explorer 11 on Windows 7 and Windows 8
- Microsoft Edge (Microsoft Edge 38.14393.0.0 and Microsoft EdgeHTML 14.14393) on Windows 10
- Mozilla Firefox 48 or later on Windows 7, Windows 8, Windows 10, and macOS
- Apple Safari 9.0 or later on macOS
- Google Chrome 67 on Windows 7, Windows 8, Windows 10, and macOS

## Contacting Support

**Table 2:** *Contact Information*

Contact Center Online	
Main Site	<a href="https://www.al-enterprise.com">https://www.al-enterprise.com</a>
Support Site	<a href="https://businessportal2.alcatel-lucent.com">https://businessportal2.alcatel-lucent.com</a>
Email	<a href="mailto:ebg_global_supportcenter@al-enterprise.com">ebg_global_supportcenter@al-enterprise.com</a>
Service & Support Contact Center Telephone	
North America	1-800-995-2696
Latin America	1-877-919-9526
EMEA	+800 00200100 (Toll Free) or +1(650)385-2193
Asia Pacific	+65 6240 8484
Worldwide	1-818-878-4507

#### New Features and Enhancements in AOS-W 8.6.0.8

There are no new features or enhancements introduced in this release.



### Supported Platforms in AOS-W 8.6.0.8

This chapter describes the platforms supported in this release.

### Mobility Master Platforms

The following table displays the Mobility Master platforms that are supported in this release:

**Table 3:** Supported Mobility Master Platforms in AOS-W 8.6.0.8

Mobility Master Family	Mobility Master Model
Hardware Mobility Master	MM-HW-1K, MM-HW-5K, MM-HW-10K
Virtual Mobility Master	MM-VA-50, MM-VA-500, MM-VA-1K, MM-VA-5K, MM-VA-10K

### OmniAccess Mobility Controller Platforms

The following table displays the OmniAccess Mobility Controller platforms that are supported in this release:

**Table 4:** Supported OmniAccess Mobility Controller Platforms in AOS-W 8.6.0.8

OmniAccess Mobility Controller Family	OmniAccess Mobility Controller Model
OAW-40xx Series Hardware OmniAccess Mobility Controllers	OAW-4005, OAW-4008, OAW-4010, OAW-4024, OAW-4030
OAW-4x50 Series Hardware OmniAccess Mobility Controllers	OAW-4450, OAW-4550, OAW-4650, OAW-4750, OAW-4750XM, OAW-4850
OAW-41xx Series Hardware OmniAccess Mobility Controllers	OAW-4104
MC-VA-xxx Virtual OmniAccess Mobility Controllers	MC-VA-10, MC-VA-50, MC-VA-250, MC-VA-1K, MC-VA 4K, MC-VA 6K



MC-VA-4K and MC-VA-6K are not orderable SKUs. However, you can scale up by installing multiple instances of MC-VA-1K. For example to deploy 4K APs on a single Mobility Controller Virtual Appliance, you need to add four MC-VA-1K licenses.

## AP Platforms

The following table displays the AP platforms that are supported in this release:

**Table 5:** *Supported AP Platforms in AOS-W 8.6.0.8*

AP Family	AP Model
OAW-AP100 Series	OAW-AP104, OAW-AP105
OAW-AP103 Series	OAW-AP103
OAW-AP110 Series	OAW-AP114, OAW-AP115
OAW-AP130 Series	OAW-AP134, OAW-AP135
OAW-AP 170 Series	OAW-AP175AC, OAW-AP175AC-F1, OAW-AP175DC, OAW-AP175DC-F1, OAW-AP175P, OAW-AP175P-F1
OAW-AP200 Series	OAW-AP204, OAW-AP205
OAW-AP203H Series	OAW-AP203H
OAW-AP205H Series	OAW-AP205H
OAW-AP207 Series	OAW-AP207
OAW-AP203R Series	OAW-AP203R, OAW-AP203RP
OAW-AP210 Series	OAW-AP214, OAW-AP215
OAW-AP 220 Series	OAW-AP224, OAW-AP225
228 Series	OAW-AP228
OAW-AP270 Series	OAW-AP274, OAW-AP275, OAW-AP277

**Table 5: Supported AP Platforms in AOS-W 8.6.0.8**

AP Family	AP Model
OAW-AP300 Series	OAW-AP304, OAW-AP305
OAW-AP303 Series	OAW-AP303, OAW-AP303P
OAW-AP303H Series	OAW-AP303H
OAW-AP310 Series	OAW-AP314, OAW-AP315
OAW-AP318 Series	OAW-AP210AP-318
OAW-AP320 Series	OAW-APAP-324, OAW-AP325
OAW-AP330 Series	OAW-AP334, OAW-AP335
OAW-AP340 Series	OAW-AP344, OAW-AP345
OAW-AP360 Series	OAW-AP365, OAW-AP367
OAW-AP370 Series	OAW-AP374, OAW-AP375, OAW-AP377
OAW-AP387	OAW-AP387
500 Series	OAW-AP504, OAW-AP505
510 Series	OAW-AP514, OAW-AP515
530 Series	OAW-AP534, OAW-AP535
550 Series	OAW-AP555
OAW-RAP3 Series	OAW-RAP3WN, OAW-RAP3WNP
OAW-RAP100 Series	OAW-RAP108, OAW-RAP109
OAW-RAP155 Series	OAW-RAP155, OAW-RAP155P

This chapter contains the Downloadable Regulatory Table (DRT) file version introduced in this release.

Periodic regulatory changes may require modifications to the list of channels supported by an AP. For a complete list of channels supported by an AP using a specific country domain, access the switch Command Line Interface (CLI) and execute the **show ap allowed-channels country-code <country-code> ap-type <ap-model>** command.

For a complete list of countries and the regulatory domains in which the APs are certified for operation, refer to the Downloadable Regulatory Table or the DRT Release Notes at [businessportal2.alcatel-lucent.com](http://businessportal2.alcatel-lucent.com).

### Regulatory Updates in AOS-W 8.6.0.8

The following DRT file version is part of this release:

- DRT-1.0\_79055

### Resolved Issues in AOS-W 8.6.0.8

This release includes an update to address [CVE-2020-25705](#).

Also, the following issue has been resolved in this release.

**Table 6:** *Resolved Issues in AOS-W 8.6.0.8*

Bug ID	Description	Reported Version
AOS-215576	Some managed devices running AOS-W 8.6.0.7 crashed and rebooted unexpectedly. The log files listed the reason for the event as <b>Reboot Cause: Nanny rebooted machine - gsmmgr process died (Intent:cause:register 34:86:0:2c)</b> . This issue occurred due to memory leak. The fix ensures that the managed devices work as expected. <b>Duplicates:</b> AOS-215484, AOS-215550, AOS-215560, AOS-216996, AOS-217224, AOS-217248, AOS-217305, AOS-217431, AOS-217697, AOS-217756, AOS-217901, AOS-217984, AOS-218046, AOS-218072, and AOS-218079	AOS-W 8.6.0.7

### Known Issues and Limitations in AOS-W 8.6.0.8

This chapter describes the known issues and limitations observed in this release.

#### Limitation

Following are the limitations observed in this release:

#### Port-Channel Limitation in OAW-4850 switches

On OAW-4850 switches with all the member ports of each port-channel configured from the same NAE (Network Acceleration Engine), if one of the member ports experiences link flap either due to a network event or a user driven action, the rest of the port-channels also observe the link flap for less than a second.

#### No Support for Unique Local Address over IPv6 Network

The IPv6 addresses for interface tunnels do not accept unique local addresses.

#### Known Issues

Following are the known issues observed in this release.

**Table 7:** *Known Issues in AOS-W 8.6.0.8*

New Bug ID	Old Bug ID	Description	Reported Version
AOS-151022 AOS-188417	185176	The output of the <b>show datapath uplink</b> command displays incorrect session count. This issue is observed in managed devices running AOS-W 8.1.0.0 or later versions.	AOS-W 8.1.0.0
AOS-151355	185602	A few managed devices are unable to pass traffic to the nexthop VPN concentrator (VPNC) using policy-based routing. This issue is observed in managed devices running AOS-W 8.0.1.0 or later versions.	AOS-W 8.0.1.0
AOS-153742 AOS-194948	188871	A stand-alone switch crashes and reboots unexpectedly. The log files list the reason for the event as <b>Hardware Watchdog Reset (Intent:cause:register 51:86:0:8)</b> . This issue is observed in OAW-4010 switches running AOS-W 8.5.0.1 or later versions in a Mobility Master-Managed Device topology.	AOS-W 8.5.0.1

**Table 7: Known Issues in AOS-W 8.6.0.8**

New Bug ID	Old Bug ID	Description	Reported Version
AOS-155404 AOS-207878	191106	An AP is unable to establish IKE/IPsec tunnel with the managed device. This issue occurs when the AP is enrolled with EST certificates. This issue is observed in OAW-AP515 access points running AOS-W 8.5.0.0 or later versions in a Mobility Master-Managed Device topology.	AOS-W 8.6.0.4
AOS-156068	192100	The <b>DDS</b> process in a managed device running AOS-W 8.2.1.1 or later versions crashes unexpectedly.	AOS-W 8.2.1.1
AOS-182847	—	A few users are unable to copy the <b>WPA Passphrase</b> field and <b>High-throughput</b> profile to a new SSID profile in the <b>Configuration &gt; System &gt; Profiles &gt; Wireless LAN &gt; SSID &gt; &lt;SSID_Profile&gt;</b> option of the WebUI. This issue occurs when a new SSID profile is created from an existing SSID profile using WebUI. This issue is observed in managed devices running AOS-W 8.4.0.0 or later versions in a Mobility Master-Managed Device topology.	AOS-W 8.4.0.0
AOS-183706	—	The TX radio power of a few APs are lesser than the TX radio power of other APs in the same network. This issue is observed in APs running AOS-W 8.3.0.6 or later versions.	AOS-W 8.3.0.6
AOS-184947 AOS-192737	—	The jitter and health score data are missing from the <b>Dashboard &gt; Infrastructure &gt; Uplink &gt; Health</b> page in the WebUI. This issue is observed in Mobility Masters running AOS-W 8.4.0.4 or later versions.	AOS-W 8.4.0.4
AOS-185538 AOS-195334	—	High number of EAP-TLS timeouts are observed in a managed device. This issue occurs when multiple IP addresses are assigned to each client. This issue is observed in managed devices running AOS-W 8.3.0.8 or later versions.	AOS-W 8.3.0.8
AOS-187395 AOS-188564	—	The AAA test to the external server fails when executed from the <b>Diagnostics &gt; Tools &gt; AAA Server Test</b> page of the WebUI. This issue occurs when the user enters the ", %, and # special characters in the <b>Password</b> field and clicks the <b>Test</b> option. As a result, the WebUI displays the <b>Authentication</b> field as <b>failed</b> and <b>Processing time (ms)</b> field as <b>N/A</b> . This issue is observed in managed devices running AOS-W 8.3.0.0 or later versions.	AOS-W 8.3.0.0
AOS-188972 AOS-194746 AOS-208631 AOS-213627	—	Mobility Master displays the blacklisted clients although the clients were removed from the managed device. This issue is observed in Mobility Masters running AOS-W 8.4.0.4 or later versions in a cluster setup.	AOS-W 8.4.0.4

**Table 7: Known Issues in AOS-W 8.6.0.8**

New Bug ID	Old Bug ID	Description	Reported Version
AOS-190071 AOS-190372	—	A few users are unable to access websites when WebCC is enabled on the user role. This issue occurs in a Per User Tunnel Node (PUTN) setup when the VLAN of user role is in trunk mode. This issue is observed in OAW-4005 switches running AOS-W 8.4.0.0. <b>Workaround:</b> Perform the following steps to resolve the issue: 1. Remove web category from the ACL rules and apply <b>any any any permit</b> policy. 2. Disable WebCC on the user role. 3. Change the VLAN of user role from trunk mode to access mode.	AOS-W 8.4.0.0
AOS-192725	—	The <b>Dashboard &gt; Overview</b> page of the WebUI displays incorrect number of users intermittently. This issue is observed in Mobility Masters running AOS-W 8.3.0.8 or later versions. <b>Duplicates:</b> AOS-188255, AOS-190476, AOS-190946, AOS-193586, AOS-194784, AOS-196004, and AOS-200375	AOS-W 8.3.0.8
AOS-193184	—	All L2 connected managed devices move to L3 connected state after an upgrade. This issue is observed in managed devices running AOS-W 8.5.0.2 or later versions.	AOS-W 8.5.0.2
AOS-193560 AOS-198565 AOS-200262 AOS-204794 AOS-212249 AOS-208110 AOS-209989	—	The number of APs that are DOWN are incorrectly displayed in the <b>Dashboard &gt; Overview</b> page of the WebUI. However, the CLI displays the correct status of APs. This issue is observed in Mobility Masters running AOS-W 8.4.0.4 or later versions.	AOS-W 8.4.0.4
AOS-193775 AOS-194581 AOS-197372	—	A mismatch of AP count and client count is observed between the Mobility Master and the managed device. This issue is observed in Mobility Masters running AOS-W 8.3.0.0 or later versions.	AOS-W 8.5.0.2
AOS-193883 AOS-197756	—	A few APs are unable to use DHCP IPv6 addresses and option 52 for master discovery. This issue occurs when APs did not clear the previous LMS entries after an upgrade. This issue is observed in access points running AOS-W 8.3.0.8 or later versions. <b>Workaround:</b> Delete the IPv4 addresses from ap system profile using the command, <b>ap system-profile</b> and from high availability profiles using the command, <b>ha</b> .	AOS-W 8.3.0.8
AOS-194381	—	Some managed devices lose the route-cache entries and drop the VRRP IP addresses sporadically. This issue is observed in managed devices running AOS-W 8.3.0.7 or later versions.	AOS-W 8.3.0.7
AOS-194911	—	Incorrect flag output is displayed for APs configured with 802.1X authentication when the <b>show ap database</b> command is executed. This issue is observed in APs running AOS-W 8.5.0.2 or later versions.	AOS-W 8.5.0.2



**Table 7: Known Issues in AOS-W 8.6.0.8**

New Bug ID	Old Bug ID	Description	Reported Version
AOS-194964	—	A few users are unable to clone configuration from an existing group to a new group in a Mobility Master. This issue is observed in Mobility Masters running AOS-W 8.4.0.1 or later versions. <b>Workaround:</b> Execute the <b>rf dot11a-radio-profile &lt;profile name&gt;</b> command to change the operating mode of the AP from am-mode to ap-mode.	AOS-W 8.5.0.2
AOS-195089	—	The DNS traffic is incorrectly getting classified as <b>Thunder</b> and is getting blocked. This issue occurs when the DNS traffic is blocked and peer-peer ACL is denied for users. This issue is observed in managed devices running AOS-W 8.3.0.7 or later versions.	AOS-W 8.3.0.7
AOS-195100 AOS-198302 AOS-204455 AOS-206735	—	The health status of a managed device is incorrectly displayed as <b>Poor</b> in the <b>Dashboard &gt; Infrastructure</b> page of the Mobility Master's WebUI. This issue is observed in Mobility Masters running AOS-W 8.3.0.7 or later versions.	AOS-W 8.3.0.7
AOS-195177	—	Some managed devices frequently generate internal system error logs. This issue occurs when the <b>sapd</b> process reads a non-existent interface. This issue is observed in OAW-4650 switches running AOS-W 8.3.0.7 or later versions.	AOS-W 8.3.0.7
AOS-195434	—	An AP crashes and reboots unexpectedly. The log files list the reason for the event as <b>Reboot caused by kernel panic: Fatal exception</b> . This issue is observed in APs running AOS-W 8.5.0.0 or later versions in a Mobility Master-Managed Device topology.	AOS-W 8.5.0.2
AOS-195526	—	Some clients are unable to get DHCP addresses. This issue occurs when the ACE entries of the logon role ACL changes to <b>Deny all</b> when the PEFNG feature is disabled. This issue is observed in managed devices running AOS-W 8.3.0.8 or later versions.	AOS-W 8.3.0.8
AOS-196399	—	DDS traffic causes IP reassembly failures in datapath. This issue is observed in Mobility Masters running AOS-W 8.3.0.6 or later versions.	AOS-W 8.3.0.6
AOS-196457	—	High radio noise floor is observed on APs. This issue is observed in OAW-AP515 access points running AOS-W 8.5.0.2 or later versions.	AOS-W 8.5.0.2
AOS-196864	—	Although a new VLAN ID is successfully connected, the managed device displays that the VLAN ID fails with a different ID. This issue is observed when new VLANs are added and the total number of VLANs are 100/101, 200/201, 300/301 and so on. This issue is observed in managed devices running AOS-W 8.5.0.3 or later versions.	AOS-W 8.5.0.3

**Table 7: Known Issues in AOS-W 8.6.0.8**

New Bug ID	Old Bug ID	Description	Reported Version
AOS-196878 AOS-197216	—	The <b>Datapath</b> process crashes on a managed device. The log file lists the reason for the event as <b>wlan-n09-nc1.gw.illinois.edu</b> . This issue is observed in managed devices running AOS-W 8.5.0.2 or later versions.	AOS-W 8.5.0.2
AOS-197023	—	Mobility Master sends incorrect AP regulatory-domain-profile channel changes to the managed device during the initial configuration propagation. This issue is observed in Mobility Masters running AOS-W 8.0.0.0 or later versions. <b>Workaround:</b> The following are recommended: <ul style="list-style-type: none"> <li>■ In the CLI, execute the <b>ap regulatory-domain-profile</b> command to create an AP regulatory-domain-profile without any channel configuration, save the changes, and later add or delete channels as desired.</li> <li>■ In the WebUI, create an AP regulatory-domain-profile with default channel selected, save the changes, and later add or delete channels as desired in the <b>Configuration &gt; AP Groups</b> page.</li> </ul>	AOS-W 8.5.0.4
AOS-197497	—	AirMatch selects the same channel for two neighboring APs even after radar detection. This issue is observed in managed devices running AOS-W 8.5.0.3 or later versions.	AOS-W 8.5.0.3
AOS-197812	—	A mismatch of user roles is observed in the WebUI and CLI of the Mobility Master and managed device. This issue occurs when UDR is configured to assign user roles to clients. This issue is observed in Mobility Masters and managed devices running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.0
AOS-198024	—	Users are unable to access any page after the fifth page using the <b>Maintenance &gt; Access Point</b> page in the WebUI. This issue is observed in stand-alone switches running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.0
AOS-198281	—	The details of the <b>Up</b> time in <b>Managed network &gt; Dashboard &gt; Access Points &gt; Access Points</b> table does not get updated correctly. This issue is observed in Mobility Masters running AOS-W 8.2.2.6 or later versions.	AOS-W 8.2.2.6
AOS-198483	—	WebUI does not have an option to map the <b>rf dot11-60GHz-radio-profile</b> to an AP group. This issue is observed in Mobility Masters running AOS-W 8.5.0.4 or later versions.	AOS-W 8.5.0.4
AOS-198849 AOS-198850	—	Users are unable to configure 2.4 GHz radio profile in the <b>Configuration &gt; System &gt; Profiles &gt; 2.4 GHz radio profile</b> page and the WebUI displays an error message, <b>Feature is not enabled in the license</b> . This issue is observed in stand-alone switches running AOS-W 8.5.0.3 or later versions.	AOS-W 8.5.0.3
AOS-198991	—	Users are unable to add a VLAN to an existing trunk port using the <b>Configuration &gt; Interfaces &gt; VLANs</b> page of the WebUI. This issue is observed in Mobility Masters running AOS-W 8.6.0.1 or later versions.	AOS-W 8.6.0.2
AOS-199492	—	Some APs do not get displayed in the <b>show airgroup aps</b> command output and the auto-associate policy stops working as expected. This issue occurs when the AirGroup domain is in distributed mode and is not validated in a cluster deployment. This issue is observed in managed devices running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.0

**Table 7: Known Issues in AOS-W 8.6.0.8**

New Bug ID	Old Bug ID	Description	Reported Version
AOS-200733	—	Some APs running AOS-W 8.5.0.3 or later versions crash and reboot unexpectedly. The log file list the reason for the event as <b>kernel page fault at virtual address 00005654, epc == c0bd7dd4, ra == c0bf95f8.</b>	AOS-W 8.5.0.3
AOS-200765	—	Some managed devices running AOS-W 8.3.0.7 or later versions in a cluster setup log the error message, <b>&lt;199804&gt; &lt;4844&gt;  authmgr   cluster  gsm_auth.c, auth_gsm_publish_ip_user_local_section:1011: auth_gsm_publish_ip_user_local_section: ip_user_local_flags.</b>	AOS-W 8.3.0.7
AOS-200781 AOS-210273	—	Some managed devices log the error message, <b>INFO&gt;  dot1x-proc:1  Sending request for Switch IP6</b> although there are no IPv6 configurations in the network. This issue is observed in managed devices running AOS-W 8.6.0.5 or later versions.	AOS-W 8.6.0.5
AOS-201003 AOS-212135	—	Some OAW-RAPs are unable to come up in a cluster. This issue is observed in managed devices running AOS-W 8.0.2.0 or later versions.	AOS-W 8.0.2.0
AOS-201042	—	A large number of packet drops are observed in a few APs running AOS-W 8.3.0.6 or later versions. This issue occurs when the AP SAP MTU datapath tunnel is set to 1514.	AOS-W 8.3.0.6
AOS-201150 AOS-201997 AOS-204328	—	Some 510 Series access points running AOS-W 8.6.0.2 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as <b>AP Reboot reason: External-WDT-reset.</b>	AOS-W 8.6.0.2
AOS-201376	—	The measured power, <b>Meas. Pow</b> column in the <b>show ap debug ble-table</b> command does not get updated when the TX power of an AP is changed. This issue is observed in APs running AOS-W 8.5.0.6 or later versions.	AOS-W 8.5.0.6
AOS-201439 AOS-201448	—	Some OAW-AP303H access points running AOS-W 8.5.0.5 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as <b>PC is at skb_panic+0x5c/0x68.</b>	AOS-W 8.5.0.5
AOS-202129 AOS-204127	—	The <b>Configuration &gt; AP groups</b> page does not have the <b>Split radio</b> toggle button to enable the tri-radio feature. This issue is observed in stand-alone switches running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.0
AOS-202426 AOS-203652	—	Some 510 Series access points running AOS-W 8.6.0.4 crash and reboot unexpectedly. The log files lists the reason for the event as <b>PC is at: wlc_phy_enable_hwaci_28nm+0x938 - undefined instruction: 0 [#1].</b>	AOS-W 8.6.0.4
AOS-202497 AOS-212608	—	Some APs running AOS-W 8.6.0.5 or later versions crash and reboot unexpectedly. The log file displays the reason for the event as, <b>Kernel panic: PC is at wlc_apps_psp_resp_complete+0x24.</b>	AOS-W 8.6.0.5

**Table 7: Known Issues in AOS-W 8.6.0.8**

New Bug ID	Old Bug ID	Description	Reported Version
AOS-203077 AOS-203232	—	Configurations committed using the <b>firewall cp</b> command are not synchronized on the standby Mobility Master. This issue occurs when static firewall entries are deleted. This issue is observed in Mobility Masters running AOS-W 8.6.0.3 or later versions.	AOS-W 8.6.0.3
AOS-203201	—	A managed device is unable to download configurations from the Mobility Master using VPN. This issue is observed in managed devices running AOS-W 8.2.2.6 or later versions.	AOS-W 8.2.2.6
AOS-203336	—	The <b>Dashboard &gt; Infrastructure &gt; Access Points</b> page of the WebUI and the <b>show log</b> command display different values for the last AP reboot time. This issue is observed in stand-alone switches running AOS-W 8.5.0.5 or later versions.	AOS-W 8.5.0.5
AOS-203438	—	The configuration for EIRP made using the WebUI is not visible in stand-alone switches running AOS-W 8.6.0.3 or later versions.	AOS-W 8.6.0.3
AOS-203517 AOS-204709	—	The <b>Datapath</b> process crashes on managed devices unexpectedly. The log file lists the reason for the event as <b>Reboot Cause: Datapath timeout (SOS Assert) (Intent:cause:register 54:86:50:2)</b> . This issue occurs when data packets undergo multiple GRE encapsulation. This issue is observed in managed devices running AOS-W 8.3.0.7 or later versions.	AOS-W 8.3.0.7
AOS-203614 AOS-209261	—	The Mobility Master dashboard does not display the number of APs and clients present in the network. This issue is observed in Mobility Masters running AOS-W 8.6.0.2 or later versions.	AOS-W 8.6.0.2
AOS-203910 AOS-209692	—	The stand-alone switches running AOS-W 8.6.0.3 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as, <b>Datapath timeout (Heartbeat Initiated) (Intent:cause:register 53:86:0:2c)</b> .	AOS-W 8.6.0.3
AOS-204187	—	The command <b>vpn-peer peer-mac</b> does not support Suite-B cryptography for custom certificates. This issue is observed in Mobility Masters running AOS-W 8.2.2.8 or later versions.	AOS-W 8.2.2.8
AOS-204241	—	Managed devices log spurious DHCP DEBUG messages. This issue is observed in managed devices running AOS-W 8.5.0.8 or later versions.	AOS-W 8.5.0.8
AOS-204414	—	The VLAN range configured using the <b>ntp-standalone vlan-range</b> command is not correctly sent to the managed devices. This issue occurs when the user repeatedly modifies the VLAN range. This issue occurs in Mobility Masters running AOS-W 8.0.1.0 or later versions. <b>Workaround:</b> Delete the VLAN range configured on the Mobility Master and re-configure the <b>ntp-standalone vlan-range</b> .	AOS-W 8.3.0.8
AOS-204892	—	The upgrade of AOS-W switches is delayed due to slow uplink speed. This issue is observed in stand-alone switches running AOS-W 8.2.0.0 or later versions.	AOS-W 8.2.0.0

**Table 7: Known Issues in AOS-W 8.6.0.8**

New Bug ID	Old Bug ID	Description	Reported Version
AOS-206178	—	System logs do not display the reason why an AP has shut down. This issue is observed in Mobility Masters running AOS-W 8.6.0.4 or later versions.	AOS-W 8.6.0.4
AOS-206537	—	The <b>H</b> flag indicating standby tunnel is not displayed in the output of the <b>show datapath tunnel-table</b> command and this results in a network loop. This issue is observed in Mobility Masters running AOS-W 8.6.0.4 or later versions.	AOS-W 8.6.0.4
AOS-206541	—	The <b>Maintenance &gt; Software Management</b> page does not display the list of all managed devices that are a part of a cluster. This issue is observed in Mobility Masters running AOS-W 8.5.0.8 or later versions.	AOS-W 8.5.0.8
AOS-206725	—	High CPU utilization is observed on a Mobility Master when the user inserts a USB modem. This issue is observed in Mobility Masters running AOS-W 8.6.0.3 or later versions.	AOS-W 8.6.0.3
AOS-206752	—	The console log of OAW-4450 switches running AOS-W 8.5.0.9 or later versions displays the <b>ofald    sdn  ERRS ofconn_rx:476 &lt;10.50.1.26:6633&gt; socket read failed, err:Resource temporarily unavailable(11)</b> message.	AOS-W 8.5.0.9
AOS-206795	—	A user is unable to rename a node from the Mobility Master node hierarchy. This issue is observed in Mobility Masters running AOS-W 8.3.0.7 or later versions. <b>Workaround:</b> Restart <b>profmgr</b> process to rename the node.	AOS-W 8.3.0.7
AOS-206801	—	A managed device running AOS-W 8.2.2.3 or later versions contacts the Activate server more than once during ZTP. This issue is observed in managed devices running AOS-W 8.2.2.3 or later versions.	AOS-W 8.2.2.3
AOS-206890	—	The <b>body</b> field in the <b>Configuration &gt; Services &gt; Guest Provisioning</b> page of the WebUI does not allow users to add multiple paragraphs for email messages. This issue is observed in Mobility Masters running AOS-W 8.6.0.4 or later versions.	AOS-W 8.6.0.4
AOS-206902 AOS-208241	—	AirGroup users are unable to connect to Sonos speakers. This issue is observed in managed devices running AOS-W 8.5.0.9 or later versions.	AOS-W 8.5.0.9
AOS-206907	—	Some OAW-AP303H access points running AOS-W 8.5.0.5 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as <b>Kernel panic - not syncing: assert.</b>	AOS-W 8.5.0.5
AOS-207245	—	Some managed devices running AOS-W 8.5.0.8 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as <b>Hardware Watchdog Reset (Intent:cause:register 53:86:0:802c).</b>	AOS-W 8.5.0.8

**Table 7: Known Issues in AOS-W 8.6.0.8**

New Bug ID	Old Bug ID	Description	Reported Version
AOS-207337	—	After upgrading from AOS-W 8.2.x.x to AOS-W 8.5.0.0- FIPS or later versions, a few managed devices are stuck in the <b>LAST SNAPSHOT</b> state. This issue is observed in managed devices running AOS-W 8.5.0.0 or later versions.	AOS-W 8.5.0.9
AOS-207366	—	The <b>show advanced options</b> menu is not available in the <b>Configuration &gt; Access Points &gt; Campus APs</b> page of the WebUI. This issue occurs when more than one AP is selected. This issue is observed in Mobility Masters running AOS-W 8.3.0.13.	AOS-W 8.3.0.13
AOS-207691	—	CLI displays incorrect IP address for a TACACS server. This issue occurred when the <b>configuration purge-pending-config</b> command was executed on group nodes. This issue is observed in managed devices running AOS-W 8.3.0.8 or later versions. <b>Workaround:</b> Restart the <b>profmgr</b> process by issuing the <b>process restart profmgr</b> command for CLI to display the correct IP address.	AOS-W 8.3.0.8
AOS-207692	—	Some managed devices running AOS-W 8.6.0.4 or later versions log multiple authentication error messages.	AOS-W 8.6.0.4
AOS-207795	—	Users are unable to access the WebUI of the Mobility Master. This issue is observed in Mobility Masters running AOS-W 8.2.2.6 or later versions.	AOS-W 8.2.2.6
AOS-208337 AOS-209348 AOS-212655 AOS-213442	—	The <b>airmatch_recv</b> process crashes on Mobility Controller Virtual Appliances running AOS-W 8.5.0.7 or later versions.	AOS-W 8.5.0.7
AOS-208420	—	Users are unable to log in to CLI of a switch. This issue occurs when the password has special characters, < and/or >. This issue is observed in switches running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.5
AOS-208696	—	The <b>profmgr</b> process crashes after configuring LACP and the error message, <b>Module profmgr is busy</b> is displayed. This issue is observed in Mobility Masters running AOS-W 8.6.0.4 or later versions.	AOS-W 8.6.0.4
AOS-209069	—	The control plane security configuration, <b>auto-cert-allowed-addrs</b> pushed from a Mobility Master to the managed devices is not visible in the <b>Configuration &gt; System &gt; CPsec</b> page of the WebUI. This issue is observed in managed devices running AOS-W 8.5.0.9 or later versions.	AOS-W 8.5.0.9
AOS-209545	—	MAC authentication is not initialized when IPv6 is globally disabled. This issue is observed in managed devices running AOS-W 8.3.0.13.	AOS-W 8.3.0.13
AOS-209977	—	SNMP query with an incorrect string fails to record the offending IP address. This issue is observed in managed devices running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10

**Table 7: Known Issues in AOS-W 8.6.0.8**

New Bug ID	Old Bug ID	Description	Reported Version
AOS-210342	—	The VRRP authentication password is not encrypted in the output of the <b>show running config</b> command. This issue is observed in managed devices running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10
AOS-210404	—	The <b>Pending Changes</b> option does not appear in the WebUI. This issue occurs when there are too many unsaved nodes and the <b>show configuration unsaved-nodes</b> command has an output of more than 1024 characters. This issue is observed in Mobility Masters running AOS-W 8.3.0.7 or later versions.	AOS-W 8.3.0.7
AOS-210482	—	Some managed devices running AOS-W 8.3.0.6 or later versions display the error message, <b>Invalid set request</b> while configuring ESSID for a Beacon Report Request profile.	AOS-W 8.3.0.6
AOS-210484	—	Some managed devices running AOS-W 8.0.0.0 or later versions do not display the 802.11k measurements from clients.	AOS-W 8.3.0.6
AOS-210638	—	The <b>ARM</b> process crashes on managed devices running AOS-W 8.6.0.5 or later versions.	AOS-W 8.6.0.5
AOS-210896	—	Hotspot 2.0 IEs are not present in beacons frames. This issue is observed in APs running AOS-W 8.6.0.0 or later versions.	AOS-W 8.6.0.0
AOS-210922	—	The <b>auth</b> process crashes on stand-alone switches and APs reboot unexpectedly. The log file lists the reason for the reboot as <b>Unable to set up IPsec tunnel, Error:RC_ERROR_IKEV2_TIMEOUT</b> . This issue is observed in stand-alone switches running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10
AOS-210992	—	The Mobility Master displays an error message, <b>Flow Group delete: id not found</b> after an upgrade. This issue occurs when logging levels are not configured correctly. This issue is observed in Mobility Masters running AOS-W 8.6.0.5 or later versions.	AOS-W 8.6.0.5
AOS-211256	—	The SFP J8177D, JD089B, and Cisco GLC-TE transceivers do not work with OAW-4450 switches running AOS-W 8.6.0.3.	AOS-W 8.6.0.3
AOS-211324	—	iPads are unable to connect to SSIDs. The log file lists the reason for the event as <b>STA Requesting Association without authentication</b> . This issue is observed in OAW-AP535 access points running AOS-W 8.5.0.8 or later versions.	AOS-W 8.5.0.8
AOS-211389	—	Users are unable to install evaluation licenses. This issue occurs when the Mobility Master displays an expired installation date. This issue is observed in Mobility Masters running AOS-W 8.5.0.4 or later versions.	AOS-W 8.5.0.4

**Table 7: Known Issues in AOS-W 8.6.0.8**

New Bug ID	Old Bug ID	Description	Reported Version
AOS-211658	—	A few clients are unable to connect to OAW-AP535 access points running AOS-W 8.6.0.5 or later versions in a cluster setup. This issue occurs when WMM and HT configurations are enabled.	AOS-W 8.6.0.5
AOS-211730	—	Users are unable to a map server certificate as switch certificate on a secondary Mobility Master running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10
AOS-211841	—	The <b>Dashboard &gt; Infrastructure</b> page of the WebUI displays the client status as <b>Unknown</b> . This issue is observed in managed devices running AOS-W 8.6.0.4 or later versions.	AOS-W 8.6.0.4
AOS-211863	—	Some APs do not come up on managed devices. This issue occurs when <ul style="list-style-type: none"> <li>■ the forwarding mode is changed to bridge mode.</li> <li>■ the name of the ACL is 64 bytes.</li> </ul> This issue is observed in managed devices running AOS-W 8.6.0.5 or later versions.	AOS-W 8.6.0.5
AOS-211878 AOS-214377	—	Some APs fail to come up as OAW-RAPs. This issue occurs when the MTU size is not adjusted automatically. This issue is observed in APs running AOS-W 8.3.0.0 or later versions.	AOS-W 8.3.0.0
AOS-212039	—	User debug logging information is not available in <b>Configuration &gt; System &gt; Logging &gt; Logging Levels</b> page of the WebUI. This issue is observed in Mobility Masters running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10
AOS-212063	—	Licenses get installed with incorrect dates in Mobility Masters running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10
AOS-212123	—	The SNMP trap <b>wlsxNUserAuthenticationFailed</b> is not generated upon failed authentication in a termination-enabled dot1X configuration. This issue occurs in stand-alone switches running AOS-W 8.0.0.0 or later versions.	AOS-W 8.3.0.0
AOS-212198	—	Some OAW-RAP3WN OAW-RAPs running AOS-W 8.5.0.8 or later versions reboot unexpectedly. This issue occurs when time between the controller and the Remote AP is not in synchronization. <b>Workaround:</b> Reboot the OAW-RAP to resolve the issue.	AOS-W 8.5.0.8
AOS-212203 AOS-213878 AOS-213879 AOS-212560	—	Some users experience poor network performance. This issue occurs due to 2.4G beacon power fluctuations in OAW-AP505 access pints running AOS-W 8.6.0.5 or later versions.	AOS-W 8.6.0.5
AOS-212255	—	Some APs are stuck in <b>Not in Progress</b> state during cluster live upgrade. This issue is observed in managed devices running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10



**Table 7: Known Issues in AOS-W 8.6.0.8**

New Bug ID	Old Bug ID	Description	Reported Version
AOS-212486	—	L2TP IP address leak is observed and VLAN pool gets exhausted. This issue is observed in managed devices running AOS-W 8.5.0.11.	AOS-W 8.5.0.11
AOS-212530	—	Some OAW-AP515 access points running AOS-W 8.5.0.10 crash and reboot unexpectedly. The log files list the reason for the event as, <b>reboot Intermittently-suspecting scb rrm cubby corruption.</b>	AOS-W 8.5.0.10
AOS-212568	—	The <b>aaa / certmgr / cpsec</b> security categories in the <b>Configuration &gt; System &gt; Logging &gt; Logging Levels</b> page of the WebUI displays <b>None</b> even if values are configured. This issue is observed in Mobility Masters running all AOS-W 8.0.0.0 or later versions.	AOS-W 8.3.0.13
AOS-212576	—	Some APs running AOS-W 8.6.0.5 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as <b>Kernel panic - not syncing: rcu_sched detected stalls (pc is at __schedule+0x78/0x360).</b>	AOS-W 8.6.0.5
AOS-212599 AOS-211699 AOS-212564 AOS-212567	—	Some APs running AOS-W 8.6.0.5 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as <b>Kernel panic - not syncing: jiffies stall (pc is at __schedule+0x78/0x360).</b>	AOS-W 8.6.0.5
AOS-212696 AOS-212656	—	The custom captive portal page does not load completely. This issue occurs when the <b>use http authentication option</b> is enabled. This issue is observed in managed devices running AOS-W 8.5.0.11 or later versions.	AOS-W 8.5.0.11
AOS-212707	—	Some Mobility Masters running AOS-W 8.5.0.10 log the error message, <b>Fri Oct 16 23:58:53 2020, 0, 0, 0, 0, 0, 0, 0.</b>	AOS-W 8.5.0.10
AOS-212843	—	Some users are randomly assigned the default role. This issue occurs when 802.11r feature is enabled. This issue is observed in managed devices running AOS-W 8.6.0.4 or later versions.	AOS-W 8.6.0.4
AOS-212861 AOS-215350 AOS-215522 AOS-216305	—	Some OAW-AP535 and OAW-AP555 access points running AOS-W 8.6.0.6 or later versions crash and reboot unexpectedly. The log file lists the reason for the reboot as <b>kernel panic: Take care of the TARGET ASSERT first.</b>	AOS-W 8.6.0.6
AOS-212935	—	Temporary ACL is still applied to user roles even if the disaster-recovery mode is disabled. This issue occurs when configuration changes in disaster recovery mode are not submitted using the <b>write memory</b> command. This issue is observed in managed devices running AOS-W 8.3.0.6 or later versions. <b>Workaround:</b> Ensure to submit the configuration changes made in the disaster-recovery mode.	AOS-W 8.3.0.6

**Table 7: Known Issues in AOS-W 8.6.0.8**

New Bug ID	Old Bug ID	Description	Reported Version
AOS-212991	—	The <b>use-ip-for-calling-station</b> parameter of the <b>aaa authentication-server radius</b> command does not work as expected for VIA clients. This issue is observed in stand-alone switches running AOS-W 8.6.0.6.	AOS-W 8.6.0.6
AOS-213089	—	Some managed devices running AOS-W 8.3.0.0 or later versions crash and reboot unexpectedly. The log file lists the reason for the event as <b>Reboot Cause: Kernel Panic (Intent:cause:register 12:86:f0:2)</b> . <b>Duplicates:</b> AOS-213044, AOS-213295, AOS-214238, AOS-214431, AOS-214678, AOS-215123, and AOS-215572	AOS-W 8.3.0.0
AOS-213099 AOS-214123	—	The <b>dpagent</b> process crashes on managed devices running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10
AOS-213115	—	Some managed devices running AOS-W 8.5.0.10 crash and reboot unexpectedly. The log file lists the reason for the event as <b>Reboot caused by kernel panic: Take care of the HOST ASSERT first.</b>	AOS-W 8.5.0.10
AOS-213132	—	Users are unable to upload server certificates in PEM or DER format. This issue is observed in Mobility Masters running AOS-W 8.6.0.6-FIPS. <b>Workaround:</b> Temporarily upload root CA and intermediate CAs as trusted CA in /mm node. This accepts the server certificates in PEM/DER format in /md node. When server certificate configuration in /md path node is successful, CA certificates from /mm node can be removed.	AOS-W 8.6.0.6
AOS-213558	—	Users are unable to add a new node to an existing cluster of eight nodes. This issue is observed in managed devices running AOS-W 8.5.0.6 or later versions.	AOS-W 8.5.0.6
AOS-213865	—	The WebUI displays the message, <b>one or more settings have been overridden at bottling</b> and displays the older folder name after an override. This issue is observed in Mobility Masters running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10
AOS-214255	—	Older 802.11b clients are unable connect to a few APs. This issue occurs when VAPs on 2.4 GHz radio are configured with different basic rates and when some of which do not include 802.11b CCK rates. This issue is observed in OAW-AP203R, OAW-AP203RP, OAW-AP203H, and OAW-AP207 access points running AOS-W 8.3.0.0 or later versions. <b>Workaround:</b> Configure all VAPs on 2.4 GHz radio with the same 802.11b/CCK basic rates.	AOS-W 8.3.0.0
AOS-214714	—	Some stand-alone switches running AOS-W 8.5.0.11 or later versions reboot unexpectedly. The log file lists the reason for the event as, <b>Datapath timeout (SOS Assert) (Intent:cause:register 54:86:50:60)</b> . <b>Workaround:</b> Disable DPI by navigating to <b>Configuration &gt; Services &gt; Firewall &gt; Global Settings</b> and disable the <b>Enable deep packet inspection</b> check-box.	AOS-W 8.5.0.11
AOS-215022	—	Clients authenticated using wpa3-sae-aes with MAC authentication are disconnected from the network. This issue occurs when a 4-way handshake is not initiated. This issue is observed in managed devices running AOS-W 8.5.0.9 or later versions.	AOS-W 8.5.0.9

**Table 7: Known Issues in AOS-W 8.6.0.8**

New Bug ID	Old Bug ID	Description	Reported Version
AOS-215073	—	Some OAW-AP515 access points running AOS-W 8.5.0.8 or later versions go down and keeps rebooting.	AOS-W 8.5.0.8
AOS-215172	—	The <b>profmgr</b> process crashes and an error message, <b>Reference retrieval error</b> is displayed when users try to make changes to a AAA server group profile. This issue is observed in Mobility Masters running AOS-W 8.5.0.10 or later versions.	AOS-W 8.5.0.10
AOS-216204	—	Some OAW-AP535 access points running AOS-W 8.5.0.10 or later versions crash unexpectedly. The log file lists the reason for the event as, <b>Reboot caused by kernel panic: subsys-restart: Resetting the SoC - q6v5-wcss crashed.</b>	AOS-W 8.5.0.10
AOS-203926	—	Voice traffic using NOE protocol is not getting tunneled in split-tunnel forwarding mode. This issue occurs when openflow is enabled. This issue is observed in managed devices running AOS-W 8.6.0.3 or later versions.	AOS-W 8.6.0.3
AOS-210481	—	The <b>Dashboard &gt; Infrastructure &gt; Clusters</b> page does not list all the clusters. This issue is observed in managed devices running AOS-W 8.6.0.5 or later versions.	AOS-W 8.6.0.5
AOS-211430	—	The WebUI does not display the list of APs and clients. This issue occurs when VRRP IPv4 / IPv6 dual stack is used to form IPsec tunnel between the Mobility Master and managed device. This issue is observed in Mobility Masters running AOS-W 8.6.0.5 or later versions.	AOS-W 8.6.0.5
AOS-212686	—	Some APs send higher SAP MTU frames than the configured value. This issue occurs when fragmented GRE packets are exchanged. This issue is observed in APs running AOS-W 8.6.0.6 or later versions.	AOS-W 8.6.0.6
AOS-215021	—	<b>Channel Width Capability</b> configured on OmniVista 3600 Air Manager is not available in the <b>Dashboard &gt; Overview &gt; Wireless Clients</b> page of the WebUI. This issue is observed in managed devices running AOS-W 8.6.0.6 or later versions.	AOS-W 8.6.0.6
AOS-215546	—	The CLI does not trigger session timeout if paging is enabled. This issue is observed in Mobility Masters and managed devices running AOS-W 8.0.0.0 or later versions.	AOS-W 8.6.0.5
AOS-215641 AOS-215642	—	The <b>ISAKMPD</b> process crashes on managed devices running AOS-W 8.6.0.0 or later versions in a PSK-RAP setup.	AOS-W 8.7.1.1

This chapter details software upgrade procedures. It is recommended that you schedule a maintenance window for the upgrade.



---

Read all the information in this chapter before upgrading your Mobility Master, managed device, master switch, or stand-alone switch.

---

Topics in this chapter include:

- [Important Points to Remember on page 28](#)
- [Memory Requirements on page 29](#)
- [Backing up Critical Data on page 30](#)
- [Upgrading AOS-W on page 31](#)
- [Downgrading AOS-W on page 34](#)
- [Before Calling Technical Support on page 36](#)

## Important Points to Remember

To upgrade your managed device or Mobility Master:

- Schedule the upgrade during a maintenance window and notify your community of the planned upgrade. This prevents users from being surprised by a brief wireless network outage during the upgrade.
- Avoid making any changes to your network, such as configuration changes, hardware upgrades, or changes to the rest of the network during the upgrade. This simplifies troubleshooting.
- Know your network and verify the state of the network by answering the following questions:
  - How many APs are assigned to each managed device? Verify this information by navigating to the **Dashboard > Access Points** page in the WebUI, or by executing the **show ap active** or **show ap database** commands.
  - How are those APs discovering the managed device (DNS, DHCP Option, Broadcast)?
  - What version of AOS-W runs on your managed device?
  - Are all managed devices running the same version of AOS-W?
  - What services are used on your managed device (employee wireless, guest access, OAW-RAP, wireless voice)?
- Resolve any existing issues (consistent or intermittent) before you upgrade.

- If possible, use FTP to load AOS-W images to the managed device. FTP is faster than TFTP and offers more resilience over slow links. If you must use TFTP, ensure the TFTP server can send over 30 MB of data.
- Always upgrade the non-boot partition first. If you encounter any issue during the upgrade, you can restore the flash, and switch back to the boot partition. Upgrading the non-boot partition gives you a smoother downgrade path, if required.
- Before you upgrade to this version of AOS-W, assess your software license requirements and load any new or expanded licenses that you might require. For a detailed description of these new license modules, refer the *Alcatel-Lucent Mobility Master Licensing Guide*.
- Multiversion is supported in a topology where the managed devices are running the same version as the Mobility Master, or two versions lower. For example multiversion is supported if a Mobility Master is running AOS-W 8.5.0.0 and the managed devices are running AOS-W 8.5.0.0, AOS-W 8.4.0.0, or AOS-W 8.3.0.0.

## Memory Requirements

All Alcatel-Lucent managed devices store critical configuration data on an onboard compact flash memory module. Ensure that there is always free flash space on the managed device. Loading multiple large files such as JPEG images for RF Plan can consume flash space quickly. Following are best practices for memory management:

- Do not proceed with an upgrade unless 100 MB of free memory is available. Execute the **show memory** command to identify the available free memory. To recover memory, reboot the managed device. After the managed device comes up, upgrade immediately.
- Do not proceed with an upgrade unless 150 MB of flash space is available. Execute the **show storage** command to identify the available flash space. If the output of the **show storage** command indicates that there is insufficient flash memory, free some used memory. Copy any log files, crash data, or flash backups from your the managed device to a desired location. Delete the following files from the managed device to free some memory:
  - **Crash data:** Execute the **tar crash** command to compress crash files to a file named **crash.tar**. Use the procedures described in [Backing up Critical Data on page 30](#) to copy the **crash.tar** file to an external server. Execute the **tar clean crash** command to delete the file from the managed device.
  - **Flash backups:** Use the procedures described in [Backing up Critical Data on page 30](#) to back up the flash directory to a file named **flash.tar.gz**. Execute the **tar clean flash** command to delete the file from the managed device.
  - **Log files:** Execute the **tar logs** command to compress log files to a file named **logs.tar**. Use the procedures described in [Backing up Critical Data on page 30](#) to copy the **logs.tar** file to an external server. Execute the **tar clean logs** command to delete the file from the managed device.



---

In certain situations, a reboot or a shutdown could cause the managed device to lose the information stored in its flash memory. To avoid such issues, it is recommended that you execute the **halt** command before power cycling.

---

## Deleting a File

You can delete a file using the WebUI or CLI.

## In the WebUI

From the Mobility Master, navigate to **Diagnostic > Technical Support > Delete Files** and remove any aging log files or redundant backups.

## In the CLI

```
(host) #delete filename <filename>
```

## Backing up Critical Data

It is important to frequently back up all critical configuration data and files on the flash memory to an external server or mass storage device. You should include the following files in these frequent backups:

- Configuration data
- WMS database
- Local user database
- Licensing database
- Custom captive portal pages
- x.509 certificates
- Log files
- Flash backup

## Backing up and Restoring Flash Memory

You can backup and restore the flash memory using the WebUI or CLI.

### In the WebUI

The following steps describe how to back up and restore the flash memory:

1. In the Mobility Master node hierarchy, navigate to the **Maintenance > Configuration Management > Backup** page.
2. Click **Create Backup** to backup the contents of the flash memory to the **flashbackup.tar.gz** file.
3. Click **Copy Backup** to copy the file to an external server.

You can copy the backup file from the external server to the flash memory using the file utility in the **Diagnostics > Technical Support > Copy Files** page.

4. To restore the backup file to the flash memory, navigate to the **Maintenance > Configuration Management > Restore** page and click **Restore**.

### In the CLI

The following steps describe how to back up and restore the flash memory:

1. Execute the following command in the **enable** mode:

```
(host) #write memory
```

2. Execute the following command to back up the contents of the flash memory to the **flashbackup.tar.gz** file.

```
(host) #backup flash
Please wait while we take the flash backup.....
File flashbackup.tar.gz created successfully on flash.
Please copy it out of the controller and delete it when done.
```

3. Execute either of the following command to transfer the flash backup file to an external server or storage device.

```
(host) #copy flash: flashbackup.tar.gz ftp: <ftphost> <ftpusername> <ftpuserpassword> <remote directory>
```

```
(host) #copy flash: flashbackup.tar.gz usb: partition <partition-number>
```

You can transfer the flash backup file from the external server or storage device to the flash memory by executing either of the following command:

```
(host) #copy tftp: <tftphost> <filename> flash: flashbackup.tar.gz
```

```
(host) #copy usb: partition <partition-number> <filename> flash: flashbackup.tar.gz
```

4. Execute the following command to untar and extract the **flashbackup.tar.gz** file to the flash memory.

```
(host) #restore flash
Please wait while we restore the flash backup.....
Flash restored successfully.
Please reload (reboot) the controller for the new files to take effect.
```

## Upgrading AOS-W

Upgrade AOS-W using the WebUI or CLI.



CAUTION

---

Ensure that there is enough free memory and flash space on your Mobility Master or managed device. For details, see [Memory Requirements on page 29](#).

---



NOTE

---

When you navigate to the **Configuration** tab in the WebUI, the managed device might display the **Error getting information: command is not supported on this platform** message. This message is displayed ccurs when you upgrade using the WebUI and navigate to the **Configuration** tab after the managed device reboots. This message disappears after clearing the Web browser cache.

---

### In the WebUI

The following steps describe how to upgrade AOS-W from a TFTP server, FTP server, or local file.

1. Download the AOS-W image from the customer support site.
2. Upload the AOS-W image to a PC or workstation on your network.

3. Validate the SHA hash for the AOS-W image:
  - a. Download the **Alcatel.sha256** file from the download directory.
  - b. Load the AOS-W image to a Linux system and execute the **sha256sum <filename>** command. Alternatively, use a suitable tool for your operating system that can generate a **SHA256** hash of a file.
  - c. Verify that the output produced by this command matches the hash value found on the customer support site.



---

The AOS-W image file is digitally signed and is verified using RSA2048 certificates preloaded at the factory. The Mobility Master or managed device will not load a corrupted AOS-W image.

---

4. Log in to the AOS-W WebUI from the Mobility Master.
5. Navigate to the **Maintenance > Software Management > Upgrade** page.
  - a. Select the **Local File** option from the **Upgrade using** drop-down list.
  - b. Click **Browse** from the **Image file name** to navigate to the saved image file on your PC or workstation.
6. Select the downloaded image file.
7. Choose the partition from the **Partition to Upgrade** option.
8. Enable the **Reboot Controller After Upgrade** toggle switch to automatically reboot after upgrading. If you do not want to reboot immediately, disable this option.



---

The upgrade does not take effect until reboot. If you chose to reboot after upgrade, the Mobility Master or managed device reboots automatically.

---

9. Select **Save Current Configuration**.
10. Click **Upgrade**.
11. Click **OK**, when the **Changes were written to flash successfully** message is displayed.

## In the CLI

The following steps describe how to upgrade AOS-W from a TFTP server, FTP server, or local file.

1. Download the AOS-W image from the customer support site.
2. Open an SSH session to your Mobility Master.
3. Execute the **ping** command to verify the network connection between the Mobility Master and the SCP server, FTP server, or TFTP server.

```
(host)# ping <ftphost>
```

or

```
(host)# ping <tftphost>
```

or

```
(host)# ping <scphost>
```



- Execute the **show image version** command to check if the AOS-W image is loaded on the flash partition. The partition number appears in the **Partition** row; **0:0** is partition 0, and **0:1** is partition 1. The active boot partition is marked as **Default boot**.

```
(host) #show image version
```

- Execute the **copy** command to load the new image to the non-boot partition.

```
(host)# copy ftp: <ftphost> <ftpusername> <image filename> system: partition <0|1>
```

or

```
(host)# copy tftp: <tftphost> <image filename> system: partition <0|1>
```

or

```
(host)# copy scp: <scphost> <scpusername> <image filename> system: partition <0|1>
```

or

```
(host)# copy usb: partition <partition-number> <image filename> system: partition <0|1>
```

- Execute the **show image version** command to verify that the new image is loaded.

```
(host)# show image version
```

- Reboot the Mobility Master.

```
(host)#reload
```

- Execute the **show version** command to verify that the upgrade is complete.

```
(host)#show version
```

## Verifying the AOS-W Upgrade

Verify the AOS-W upgrade in the WebUI or CLI.

### In the WebUI

The following steps describe how to verify that the Mobility Master is functioning as expected:

- Log in to the WebUI and navigate to the **Dashboard > WLANs** page to verify the AOS-W image version.
- Verify if all the managed devices are up after the reboot.
- Navigate to the **Dashboard > Access Points** page to determine if your APs are up and ready to accept clients.
- Verify that the number of APs and clients are as expected.
- Test a different type of client in different locations, for each access method used.
- Complete a backup of all critical configuration data and files on the flash memory to an external server or mass storage facility. See [Backing up Critical Data on page 30](#) for information on creating a backup.

### In the CLI

The following steps describe how to verify that the Mobility Master is functioning as expected:

- Log in to the CLI to verify that all your managed devices are up after the reboot.

2. Execute the **show version** command to verify the AOS-W image version.
3. Execute the **show ap active** command to determine if your APs are up and ready to accept clients.
4. Execute the **show ap database** command to verify that the number of APs and clients are as expected.
5. Test a different type of client in different locations, for each access method used.
6. Complete a backup of all critical configuration data and files on the flash memory to an external server or mass storage facility. See [Backing up Critical Data on page 30](#) for information on creating a backup.

## Downgrading AOS-W

A Mobility Master or managed device has two partitions, 0 and 1. If the upgrade fails on one of the partitions, you can reboot the Mobility Master or managed device from the other partition.

### Pre-requisites

Before you reboot the Mobility Master or managed device with the pre-upgrade AOS-W version, perform the following steps:

1. Back up your Mobility Master or managed device. For details, see [Backing up Critical Data on page 30](#).
2. Verify that the control plane security is disabled.
3. Set the Mobility Master or managed device to boot with the previously saved configuration file.
4. Set the Mobility Master or managed device to boot from the partition that contains the pre-upgrade AOS-W version.

When you specify a boot partition or copy an image file to a system partition, Mobility Master or managed device checks if the AOS-W version is compatible with the configuration file. An error message is displayed if the boot parameters are incompatible with the AOS-W version and configuration files.

5. After switching the boot partition, perform the following steps:
  - Restore the pre-upgrade flash backup from the file stored on the Mobility Master or managed device. Do not restore the AOS-W flash backup file.
  - Do not import the WMS database.
  - If the RF plan is unchanged, do not import it. If the RF plan was changed before switching the boot partition, the changed RF plan does not appear in the downgraded AOS-W version.
  - If any new certificates were added in the upgraded AOS-W version, reinstall these certificates in the downgraded AOS-W version.

Downgrade AOS-W version using the WebUI or CLI.

### In the WebUI

The following steps describe how to downgrade the AOS-W version:

1. If the saved pre-upgrade configuration file is on an external FTP or TFTP server, copy the file to the Mobility Master or managed device by navigating to the **Diagnostics > Technical Support > Copy Files** page.
  - a. From **Select source file** drop-down list, select FTP or TFTP server, and enter the IP address of the FTP or TFTP server and the name of the pre-upgrade configuration file.
  - b. From **Select destination file** drop-down list, select **Flash file system**, and enter a file name (other than default.cfg).
  - c. Click **Copy**.
2. Determine the partition on which your pre-upgrade AOS-W version is stored by navigating to the **Maintenance > Software Management > Upgrade** page. If a pre-upgrade AOS-W version is not stored on your system partition, load it into the backup system partition by performing the following steps:



---

You cannot load a new image into the active system partition.

---

- a. Enter the FTP or TFTP server address and image file name.
  - b. Select the backup system partition.
  - c. Enable **Reboot Controller after upgrade**.
  - d. Click **Upgrade**.
3. Navigate to the **Maintenance > Software Management > Reboot** page, select **Save configuration before reboot**, and click **Reboot**.  
The Mobility Master or managed device reboots after the countdown period.
  4. When the boot process is complete, verify that the Mobility Master or managed device is using the correct AOS-W version by navigating to the **Maintenance > Software Management > About** page.

## In the CLI

The following steps describe how to downgrade the AOS-W version:

1. If the saved pre-upgrade configuration file is on an external FTP or TFTP server, use the following command to copy it to the Mobility Master or managed device:  

```
(host) # copy ftp: <ftphost> <ftpusername> <image filename> system: partition 1
```

or

```
(host) # copy tftp: <tftphost> <image filename> system: partition 1
```
2. Set the Mobility Master or managed device to boot with your pre-upgrade configuration file.  

```
(host) # boot config-file <backup configuration filename>
```
3. Execute the **show image version** command to view the partition on which your pre-upgrade AOS-W version is stored.  

```
(host) #show image version
```



---

You cannot load a new image into the active system partition.

---

4. Set the backup system partition as the new boot partition.

```
(host) # boot system partition 1
```

5. Reboot the Mobility Master or managed device.

```
(host) # reload
```

6. When the boot process is complete, verify that the Mobility Master or managed device is using the correct AOS-W version.

```
(host) # show image version
```

## Before Calling Technical Support

Provide the following information when you call the Technical Support:

- The status of installation (new or existing) and recent changes to network, device, or AP configuration. If there was a configuration change, list the exact configuration steps and commands used.
- A detailed network topology including all the devices in the network with IP addresses and interface numbers.
- The make and model number of the wireless device and NIC, driver date, version, and configuration of the NIC, and the OS version including any service packs or patches.
- The logs and output of the **show tech-support** command.
- The syslog file at the time of the problem.
- The date and time when the problem first occurred. If the problem is reproducible, list the exact steps taken to re-create the problem.
- Any wired or wireless sniffer traces taken during the time of the problem.
- The device site access information.