

Omni Switch 6250/ 6450

Release 6.6.3.531.R01

The following is a list of issues that have been identified and corrected in AOS software release. This document is intended to be used as a pre-upgrade guide and does not replace the Release Notes which are created for every GA release of software.

Important Notice: For a copy of software release not posted on the Web or if you have any question or concern please contact Alcatel's Technical Support Department.

Problems Fixed Between Builds 375 and 413	2
Problems Fixed Between Builds 414 and 438	2
Problems Fixed Between Builds 439 and 451	4
Problems Fixed Between Builds 452 and 470	6
Problems Fixed Between Builds 471 and 478	7
Problems Fixed Between Builds 479 and 495	9
Problems Fixed Between Builds 496 and 510	11
Problems Fixed Between Builds 511 and 520	13
Problems Fixed Between Builds 521 and 531	14
Under Verification:	14
Known Issues:	27
New Software Features:	28

Problems Fixed Between Builds 375 and 413

PR **169945** Build: 6.6.3.386.R01
 Summary: When IP phones connected to the OS6250 they crashed

PR **170802** Build: 6.6.3.404.R01
 Summary: Special characters % and ! are refused in RADIUS/TACACS keys. Same were accepted in AOS 6.6.1
 Explanation: Allow special characters % and ! in CLI input

PR **170503** Build: 6.6.3.404.R01
 Summary: dshell is currently in use, try again later; CHASSIS warning unable to post semaphore, 6250 over memo
 Explanation: Recover dshell for debug purpose

PR **171146** Build: 6.6.3.405.R01
 Summary: snmpenginetime give wrong value for OID
 Explanation: SNMP offset and snmpEngineTime corrections

Problems Fixed Between Builds 414 and 438

PR **172367** Build: 6.6.3.415.R01
 Summary: Unable to set the maximum egress rate on OS6250
 Explanation: Correcting the show port output to reflect in the configured bandwidth

PR **171812** Build: 6.6.3.415.R01
 Summary: Per-Queue bandwidth issue when configured value is in the range 48 52 Mbps
 Explanation: Fixing the Per-Queue bandwidth issue when configured value is in the range 48 52 Mbps

PR **173206** Build: 6.6.3.416.R01
 Summary: 6250-M :: SAA error log seen every "interval" timer (10 min by default)
 Explanation: Initialize Ethoam/SAA control entry before initiating the reply timestamp info stats

PR **170080** Build: 6.6.3.417.R01
 Summary: Issue with "show aaa-device all-users" output.
 Explanation: show aaa-device all-users will display all the clients in the switch.

PR	172353	Build:	6.6.3.421.R01
Summary:	QoS queue WRR weights are reset if port is admin down/up		
Explanation:	Show qos queue command will properly display the configured queue weight after the interface is down/up.		
PR	173963	Build:	6.6.3.422.R01
Summary:	IPv6 next header condition is not accepted in CLI		
Explanation:	nh keyword removed from policy condition command		
PR	173410	Build:	6.6.3.423.R01
Summary:	10Gb license not getting applied on OS6450.		
Explanation:	Updated the applicability of the error message for the appropriate license		
PR	173517	Build:	6.6.3.424.R01
Summary:	Following error message in OS6450, "LANPOWER (108) warning message: +++ IpGetBackupPowerOnLine: 48v		
Explanation:	Validating the 48V in 6450 is skipped due to hardware not supported		
PR	174324	Build:	6.6.3.424.R01
Summary:	First multicast packets are not flooded sometimes on OS6450 when disabled at VLAN level		
Explanation:	Configure correct vlan id in hardware while disabling/enabling multicast status on a vlan.		
PR	171051	Build:	6.6.3.425.R01
Summary:	Issue with SOURCEPHOTONICS SFP (SFP-100-BX20LT) which are 100MB SFP are displayed as 1000 by default		
Explanation:	Support for 100-FX SOURCE PHOTONICS SFP		
PR	174577	Build:	6.6.3.428.R01
Summary:	"user password-policy cannot-contain-username" shown incorrectly under show configuration snapshot		
Explanation:	Changes done to update running configuration correctly		
PR	172573	Build:	6.6.3.428.R01
Summary:	When qos IS applied user ports are not able to ping each other.		
Explanation:	Accept arps on qos UserPorts for Ips which belongs to networks on UserPorts		

PR **172729** Build: 6.6.3.429.R01
 Summary: OS6450 stack issue causing loop-detection on OS10K
 Explanation: Deferring adding of stacking ports to vlan table post the aggregation of the stacking ports.

PR **174436** Build: 6.6.3.430.R01
 Summary: The "ip-source-filter" feature doesn't block ARP Spoofing attacks
 Explanation: Block forwarding of ALL ARP requests on ISF enabled ports

Problems Fixed Between Builds 439 and 451

PR **175703** Build: 6.6.3.440.R01
 Summary: Remote host device shows as unknown for OS6450 on OS6850
 Explanation: Code changes done to display correct name in Remote host device in "show amap" output for missed OS6450 products

PR **175736** Build: 6.6.3.440.R01
 Summary: "Show ni" command gives the output as "6450 24 PORT COPPER GE POE" where 6450-p24 is expected.

PR **175247** Build: 6.6.3.441.R01
 Summary: DHCP Option-60 Vendor Class Identifier to carry OS model specific details
 Explanation: Option 60 for 66X based product in-line with the module name

PR **175171** Build: 6.6.3.441.R01
 Summary: OS6450 sends "Omniswitch-OS6250" as the DHCP Option 60 Vendor Class Identifier
 Explanation: Option 60 for OS6450 should be "Omniswitch-OS6450"

PR **174513** Build: 6.6.3.441.R01
 Summary: OS6450 Switch (DHCP client) sends "DHCP Decline" (clients which are getting IP from the dhcp server)
 Explanation: Changed the transaction ID for Dhcp-Inform packets

PR **173962** Build: 6.6.3.442.R01
 Summary: An error is send to console when configuring policy list "type ingress"
 Explanation: Corrected the Validation for Ingress Policy List Configuration

PR **174428** Build: 6.6.3.442.R01
 Summary: The "ipv6" keyword is not taken into account in "policy condition"
 Explanation: Corrected IPV6 Keyword Usage in ICMP policy condition

PR	175606	Build:	6.6.3.443.R01
Summary:	6250-P24 stack units reboot (except Primary unit) and PMD file generated		
Explanation:	Prevent the condition of spurious interrupts when insertion and extraction of power supplies happen at the same time.		
PR	174967	Build:	6.6.3.443.R01
Summary:	hal_fdb_delete_shadow_entry error on console		
Explanation:	Ignore the ip multicast packets in qdispatcher when LPS & UNI are implemented in the port.		
PR	175516	Build:	6.6.3.445.R01
Summary:	OS6250 - LLDP not working with MITEL phones after the firmware upgrade of the phones.		
Explanation:	Instead of the dropping the frame, handle the packet and generate error		
PR	176559	Build:	6.6.3.445.R01
Summary:	switch displayed as 6648 on AMAP output		
Explanation:	Have done changes to display correct name in Remote host device in "show amap" output for all the devices.		
PR	160755	Build:	6.6.3.447.R01
Summary:	A SAP doesn't process any frames if the number of CVLANs exceeds 256		
Explanation:	Error message seen on console when number of vstk SAp VPA crosses the limit of 256 and SAP not able to process any packet for existing VPAs after that		
PR	175236	Build:	6.6.3.447.R01
Summary:	mdi & mdix is not working properly in the OS6250.		
Explanation:	Added a error message for the interfaces crossover command when executed in cli.		
PR	175781	Build:	6.6.3.448.R01
Summary:	6450 igmp Proxy Service not functioning properly.		
Explanation:	During handling of IGMP Packets in software, multiple VLAN tags are handled properly.		
PR	176953	Build:	6.6.3.450.R01
Summary:	Rule mapped to ingress\egress policy list is not applied after reload.		
Explanation:	policy list egress type egress rules r1" saved as "policy list egress rules r1" in boot.cfg", so it will not parsed during the bootup. fix done to make the right qos command to save on the boot.cfg so that it would be parsed without any error while rebooting.		

PR	177138	Build:	6.6.3.451.R01
Summary:	"debug system kf0" and upgrade to AOS 6.6.3.438.R01 corrupts flash (meta blocks)		
Explanation:	Fix to prevent flash issues when upgrading to latest 6.6.3.R01 builds and executing "debug system kf0" command.		

Problems Fixed Between Builds 452 and 470

PR	166699	Build:	6.6.3.452.R01
Summary:	show microcode working, ls, show log swlog and fsck /flash commands are not giving any output on CLI		

PR	162618	Build:	6.6.3.452.R01
Summary:	Implementation of the new swlog when CPU over/below the threshold		
Explanation:	Implementaion of new swlog when Cpu crosses the above/below threshold value		

PR	176573	Build:	6.6.3.452.R01
Summary:	Remote command-log does not include IP address of session at the syslog		
Explanation:	Code changes done to send value 0 as argument for showDebug while sending command info to the session mgr for logging		

PR	176617	Build:	6.6.3.452.R01
Summary:	Qos user port configuration gets changed after a reload.		
Explanation:	qos userport filter and shutdown uses the single list for parsing the configurations, Need to reset the list once the parsing was done for the particular category.		
	Ensure the configuration applied for one category should not reflect in other.		

PR	177208	Build:	6.6.3.452.R01
Summary:	"Show ni" command gives the output as "OS6450-C10" where "OS6450-10" is expected.		
Explanation:	Work around to display proper model name and description as per the requirement		

PR	177139	Build:	6.6.3.453.R01
Summary:	IPv6 reachability issue while IPv4 works.		
Explanation:	Done mirroring of neighbor solicitation packets to CPU		

PR **177110** Build: 6.6.3.453.R01
 Summary: Radius Return Attributes for SSH in OS6450
 Explanation: Have done changes to display correct hexa value for SSH in "show aaa priv hexa" output.

PR **142907** Build: 6.6.3.457.R01
 Summary: mac stuck at filtering on a mobile-tag group after a power failure or reload the ni
 Explanation: Mobile Tag option retained even after NI reset

PR **177338** Build: 6.6.3.461.R01
 Summary: OS6250 RIP interface stopping sending of route updates under particular conditions
 Explanation: The customer specific workaround is controlled by debug variable:
 You can set this is in dshell or in AlcatelDebug.cfg

 debug set ripRedistMaxAllowedRoutes 5

 5 denotes the number of routes you want to redistribute to RIP from local r

PR **177781** Build: 6.6.3.462.R01
 Summary: Issue with source learning on port 1/1 and more than 20/25 ports are mobile

PR **177189** Build: 6.6.3.466.R01
 Summary: Not possible to configure IPMVLAN address for the multicast network address
 Explanation: Mask option for group address included in ipmvlan cli command

PR **179195** Build: 6.6.3.468.R01
 Summary: idle unit crash with talpx suspend
 Explanation: IPX packets will not be handled in software as Omni Switches does not support IPX

Problems Fixed Between Builds 471 and 478

PR **178020** Build: 6.6.3.471.R01
 Summary: qos user-port shutdown dhcp-server is not working
 Explanation: Previously In 663R01, a UserPort with Spoofing enabled should have at least one IP interface. If no interfaces are configured in the switch, we would drop the traffic, but not shut the port down. A similar issue was fixed in 644 and we have merged the change (to delete the check and accept if at least one interface is configured) done using PR #132621 to 663R01 to make it work. Now this part of the code is same in 644 and 663 and it works fine.

7 / 47

PR	178004	Build:	6.6.3.471.R01
Summary:	OS6450: Unable to get authentication using AAA.		
Explanation:	Fix done to calculate and display the correct bitmap value in webview.		

PR	178575	Build:	6.6.3.471.R01
Summary:	Rule mapped to qos policy list missing after reboot		
Explanation:	Validate qos rule with default action "accept"		

PR	178087	Build:	6.6.3.471.R01
Summary:	OS6450 tftp incorrect behavior		
Explanation:	Clearing the buffer to prevent taking previous file name from the buffer		

PR	178945	Build:	6.6.3.471.R01
Summary:	6450/6250 standalone switch always not shown as monoswitch while doing a mib walk		
Explanation:	Check has been added to set the synchronization status as CS_SYNCHROSTATUS_MONOCMM if it is a standalone unit		

PR	178021	Build:	6.6.3.471.R01
Summary:	Poor traffic shaping performance on OS6450		
Explanation:	Modified the code to allow user to configure depth based on their requirement, and default depth is configured to 12KB.		

PR	178702	Build:	6.6.3.474.R01
Summary:	DHCP release packets seen twice on NNI port.		
Explanation:	By disabling snooping in that vlan, two release packets are not seen and also client interface in that switch can get ip		

PR	179935	Build:	6.6.3.474.R01
Summary:	"Show NI" and "Show Hardware info" shows two different FPGA versions on OS6450-P48.		

PR	180320	Build:	6.6.3.477.R01
Summary:	Stack not accessible through Management IP address with Excep in task: taNiEsmDrv PC : 0xd76e440 mes		

Problems Fixed Between Builds 479 and 495

PR	180028	Build:	6.6.3.480.R01
Summary:	IPMS not working after qos reapply		
Explanation:	IPMS policies configured using QOS does not work after changing the disposition.		
PR	180837	Build:	6.6.3.480.R01
Summary:	Switch doesn't recognize IGMP packet with IP Header Total Length Field 46 bytes and discards the pkt		
Explanation:	Switch doesn't recognize IGMP packet with IP Header with total length field of 46 bytes. As long as the IGMP message type is recognized, we must ignore anything past the first 8 octets while processing the packet.		
PR	180961	Build:	6.6.3.481.R01
Summary:	6850E - QOS policy list disappear after switch reboot generating a boot.cfg.1.err file		
Explanation:	Generated CLI to parse from and type keywords properly.		
PR	180834	Build:	6.6.3.482.R01
Summary:	OS6450 - Mobility issue		
PR	180803	Build:	6.6.3.482.R01
Summary:	DHCP discover packets getting dropped		
Explanation:	DHCP discover packets are not considered as spoof		
PR	181243	Build:	6.6.3.482.R01
Summary:	Usertable not in sync after flash synchro was performed.		
Explanation:	Enabling the change in password on Primary to reflect on secondary CMM also.		
PR	181112	Build:	6.6.3.483.R01
Summary:	In SAA statistics RTT Avg values are smaller than RTT Min in case of ICMP Packet loss		
PR	181004	Build:	6.6.3.483.R01
Summary:	Switch crash while enabling mobile tag.		
Explanation:	Fix for preventing crash while enabling mobile tag		

PR	181045	Build:	6.6.3.484.R01
Summary:	MIB walk for DhcpSnoopingPortIpSourceFiltering does not shows all the ports.		
Explanation:	Mibwalk shows the status of all mobile ports if snooping is enabled globally		
PR	180605	Build:	6.6.3.486.R01
Summary:	Ping delay to and from OS6250 or OS6450 experiences very high variation		
Explanation:	Ping delay to 6450		
PR	181685	Build:	6.6.3.487.R01
Summary:	Stack split with taStp task suspended		
PR	180754	Build:	6.6.3.487.R01
Summary:	Third-party AP 1200 not powering up		
Explanation:	Code changes done to allow AT power for class 1,2 and 3 devices.		
PR	181581	Build:	6.6.3.487.R01
Summary:	"show stack status" showing incorrect values.		
Explanation:	Corrected "show stack status" tokens display issue.		
PR	181003	Build:	6.6.3.489.R01
Summary:	Delay on port activating with LLDP-MED configuration on OS6450.		
Explanation:	when IP phone is connected to switch1 on port 1/4 and port 1/24 of switch1 is connected to the switch2 1/10. when the IP phone gets up, the mac address of the IP phone is getting learned properly on the port 1/4 of the switch1 and uplink port 1/10 of switch2.then when we connect IP phone to to the port 1/4 of switch2. the mac address of the IP Phone is not getting on the Port till the mac on the uplink port gets aged out. Once the mac is getting aged out ,it is get learned on the connected port.ie the Mac movement is not happening properly when we have connect to IP phone . So Changes have been done for proper mac movement handling .		
PR	181695	Build:	6.6.3.490.R01
Summary:	OS6450 Stack issue: Primary CMM MAC is not getting synchronized correctly to IDLE Unit.		
Explanation:	IDLE unit Interface MAC is correctly synced with the Primary CMM MAC in the hardware table.		
PR	180489	Build:	6.6.3.490.R01
Summary:	Unable to enable mobility after deleting 802.1q tagging on the port		
Explanation:	Ports can be configured as Mobile after removal of 802.1q tagging .		

PR **181650** Build: 6.6.3.490.R01
 Summary: VLANs to see each other traffic when in "bridge" is in "mode flat" on OS6250 & OS6450
 Explanation: Code correction done for VLAN 1 traffic to be received only by port configured for VLAN 1.

PR **181456** Build: 6.6.3.490.R01
 Summary: OS 6250 hanged with exception in task taEthOAM_NI, tSLNAdrLrn, lpedr
 Explanation: Added a defensive check to check for the pointer value of encoded TLV.

PR **179754** Build: 6.6.3.490.R01
 Summary: Fan temperature co-relation queries and to modify the level at which fan starts cooling.
 Explanation: Added a global variable "RunFanAtFullSpeed" through which fan speed can be adjusted irrespective of temperature for 6450-U24 model either by cli/AlcatelDebug.cfg.

Problems Fixed Between Builds 496 and 510

PR **182027** Build: 6.6.3.496.R01
 Summary: QoS value is showing negative value
 Explanation: alaQoSQueuePacketsSent count always be positive.

PR **182150** Build: 6.6.3.496.R01
 Summary: Inconsistent QoS Manager when programming egress policy rules
 Explanation: Error will not be thrown when the order of configuring the egress policy rules are changed.

PR **182564** Build: 6.6.3.497.R01
 Summary: OS6450 - IP connectivity issue after upgrading stack to 6.6.3.495.R01

PR **182292** Build: 6.6.3.498.R01
 Summary: The switch configured with tacacs+ server gets crashed when tried to telnet to switch.
 Explanation: Packet with size exceeding the buffer size caused the crash , fix done to increase the buffer size to accommodate such packet(s).

PR **182502** Build: 6.6.3.498.R01
 Summary: Issue of mac address display in OS6250
 Explanation: changing the severity level to warning and correcting the mac address display issue

PR	181850	Build:	6.6.3.499.R01
Summary:	when DHCP snooping enabled on the switch then the PXE clients are unable to get the response		
Explanation:	DHCP packets are trapped using source UDP Port (instead of destination UDP Port which does not match for PXE Packets)		
PR	182219	Build:	6.6.3.499.R01
Summary:	DHCP server showing the lease time as 0 while configured as infinity.		
Explanation:	Changes done to display the lease time correctly when infinite lease time is set in server		
PR	182667	Build:	6.6.3.499.R01
Summary:	Remote address 0.0.0.0 is reported in accounting command packets sent from switch to server		
PR	182718	Build:	6.6.3.500.R01
Summary:	Max command lengths are 250 for accounting and 259 for authorization		
Explanation:	The argument max length as per Tacacs+ packet format can support max of 255, thus if the argument length is more than 255, it is truncated to 255, so that accounting is succeeded.		
PR	183031	Build:	6.6.3.500.R01
Summary:	aaa accounting command local not printing any commands in swlogs		
Explanation:	aaa accounting command works fine after reload and accounting messages are logged in switch log .		
PR	182637	Build:	6.6.3.500.R01
Summary:	Accounting packets sent to all the servers configured with tacacs		
Explanation:	Tacacs accounting packet will be sent only to first active Server		
PR	182391	Build:	6.6.3.500.R01
Summary:	In OS6850 aaa accounting command server1, server2 local		
Explanation:	Local parameter is not working. As per CLI guide code change have been done to accept aaa accounting command server as LOCAL		
PR	183170	Build:	6.6.3.501.R01
Summary:	Password command on secondary management module should not be allowed		
Explanation:	Password command is not allowed in secondary CMM		

PR **183151** Build: 6.6.3.502.R01
 Summary: simple ping from the WLAN controller console to the OS6250/6450 is only 20% successful however from
 Explanation: Checksum is calculated properly for an ICMP packet received from different vendors.

PR **183277** Build: 6.6.3.502.R01
 Summary: Issue with Command::ethernet-service nni 1/10 tpid 0x88a8.
 Explanation: Fix done to change the tpid on nni port based on the configuration made for the tpid either 8100 or 88a8.

PR **183168** Build: 6.6.3.502.R01
 Summary: Crash issue with Omni switch.

PR **183032** Build: 6.6.3.502.R01
 Summary: Unexpected crash noticed with Omni Switch.

PR **183839** Build: 6.6.3.510.R01
 Summary: swlogs filled with below error message
 DHLAA error Csnmp(2332)
 DHLAA error Cpm(193)
 Explanation: Below switch logs are changed from errors to debug
 DHLAA error Csnmp(2332)
 DHLAA error Cpm(193)

PR **182251** Build: 6.6.3.510.R01
 Summary: OS6450 - MAC movement not happening properly between stack members
 Explanation: MAC movement on mobile ports across Ni's is handled properly .

PR **183686** Build: 6.6.3.510.R01
 Summary: OS6250 configuration changes has not save flash memory.
 Explanation: Fix done for Mip overflow in ethernet services

Problems Fixed Between Builds 511 and 520

PR **185665** Build: 6.6.3.512.R01
 Summary: "show ethernet-service uni-profile ieee-drop-all l2pt-statistics" triggers an error
 Explanation: Fix done to stop the error for expected behavior while accessing l2pt-statistics for uni profile IEEE_FWD_ALL and IEEE_DROP_ALL.

PR	183666	Build:	6.6.3.514.R01
Summary:	DHCP discover from extended module port like 1/51 is not forwarded to linkagg port		
Explanation:	After initialization uplink ports will not lose their vlan membership .		
PR	186071	Build:	6.6.3.515.R01
Summary:	OS6250 configuration changes has not save flash memory.(old PR#183686)		
Explanation:	Fix done for Mip overflow in ethernet services.		
PR	186423	Build:	6.6.3.515.R01
Summary:	OS6450: swlog showing wrong port number.		
Explanation:	The fix contains correction of port number in swlog for SFP plug out on fixed SFP plus port and Stacking ports.		

Problems Fixed Between Builds 521 and 531

PR	186067	Build:	6.6.3.521.R01
Summary:	Qos Policy is getting matched and getting altered by the qos policy, but the policy counter does not		
PR	188671	Build:	6.6.3.523.R01
Summary:	static routes become inactive after reload the switch.		
PR	188806	Build:	6.6.3.524.R01
Summary:	No IP connectivity after removing a VLAN from protected VLAN list in an ERP ring		
Explanation:	Deletion of protected vlan in flat mode doesn't change STP status of the erp ports in other protected to blocking		
PR	188451	Build:	6.6.3.524.R01
Summary:	Switch got crash again with Mozilla Firefox(25.0.1) when we FTP the switch.		
Explanation:	Provided defensive mechanism to avoid crash		
PR	188774	Build:	6.6.3.525.R01
Summary:	DHCP Discover and Offer are not forwarded between trusted ports		

Under Verification:

PR	155739	Build:	6.6.3.26.R01
Summary:	SNMP Violating MAC Trap		

PR	154905	Build:	6.6.3.164.R01
Summary:	When using tunnel-group-private-id for 802.1x, hex tag fails but string value succeeds		
Explanation:	Corrected logic to copy TUNNEL_PRIVATE_GP_ID information from radius packet irrespective of length		
PR	164144	Build:	6.6.3.180.R01
Summary:	OS6250 ipmvlan bootcast problem with set-top-boxes		
PR	163485	Build:	6.6.3.183.R01
Summary:	OS6250 - IPMS tasks hogging 100% CPU after reboot whereas IP multicast status is disabled		
PR	157631	Build:	6.6.3.184.R01
Summary:	How to disable the gratuitous ARP.		
Explanation:	Introduced control over sending of gratuitous arps for ips configured for interfaces in the switch. This is done by help of existing variable "ipedrArpPoisonLrn", when set to 0 will stop the sending of gratuitous arps over the network.		
PR	154917	Build:	6.6.3.188.R01
Summary:	DHCP discover packet is dropped when "dhcp-snooping" is enabled when connected to telco.		
PR	158283	Build:	6.6.3.197.R01
Summary:	Switches susceptible to Denial of Service attack on UDP port 123 (ntp)		
Explanation:	A node receiving an error response should not be responded automatically to it with it's own error response.		
PR	156542	Build:	6.6.3.199.R01
Summary:	PCs are not able to get IP address until we disable the DHCP-snooping		
PR	155507	Build:	6.6.3.199.R01
Summary:	DHCP discover packets drooped when discover has different client and source MAC addresses		
Explanation:	When the mac-address verification is disabled And if the source mac address and Hardware mac-address are different, Source mac is replaced with Hardware mac address in the software mac-address list available in udp-relay module.		

PR	155961	Build:	6.6.3.206.R01
Summary:	issue were static routes added on fly are going inactive and after a reboot few will come up.		
Explanation:	Allow host specific static route, if the gateway is on different subnet		
PR	155894	Build:	6.6.3.223.R01
Summary:	No multicast neighbor seen with "show ip multicast neighbor" although querier properly seen		
Explanation:	PIM/DVMRP packets trapped to CPU, for CPU to learn neighbor router to forward multicast data to it.		
PR	163332	Build:	6.6.3.225.R01
Summary:	If 802.1x and LPS are enabled then a MAC address of a supplicant is not learned		
Explanation:	Search and delete LPS table as per vlan specified		
PR	163281	Build:	6.6.3.225.R01
Summary:	Authenticated-T after receiving an Access-Reject from the RADIUS server		
PR	160039	Build:	6.6.3.246.R01
Summary:	After upgrade to 6.4.3.779.R01, vlan 1 traffic is not passing through tagged port		
Explanation:	Clear untagged port bitmap alone for all vlans while initializing stp task		
PR	129352	Build:	6.6.3.251.R01
Summary:	After resetting NI 16 switch crashed on tNetTask		
Explanation:	Code changes done to add the task trace of tnet task into swlog.		
PR	157953	Build:	6.6.3.260.R01
Summary:	Need to redefine the MAC range in alaPhones mac group		
Explanation:	Addition of mac range to the existing alaPhones mac group		
PR	163868	Build:	6.6.3.282.R01
Summary:	"qos user-port shutdown bpdu" does not work on mobile ports		
PR	167148	Build:	6.6.3.366.R01
Summary:	AOS Switch does not respond to MS Windows 7 ARP with APIPA source IP.		
Explanation:	Policy Switch Network group can be used from LDAP for QOS configuration		

PR	162946	Build:	6.6.3.403.R01
Summary:	Sending any packets with destination tunnel MAC (01:00:0c:cd:cd:d0) dropped at the UNI port.		
Explanation:	To disable layer 2 tunneling protocol using debug variable from AlcatelDebug.cfg[If noMacTunnelFeature =1, the layer 2 protocol tunneling is disabled, "debug set MacTunnelFeature 1"]		
PR	158888	Build:	6.6.3.408.R01
Summary:	The default (blt) network group Switch cannot be used via OmniVista.		
Explanation:	Policy Switch Network group can be used from LDAP for QOS configuration		
PR	169442	Build:	6.6.3.419.R01
Summary:	OS6250 - ipms_flood_unknown feature does not exist in 6.6.x		
Explanation:	Added Support for the CLI command "ip multicast flood unknown enable/disable"		
PR	144097	Build:	6.6.3.427.R01
Summary:	vlan mac-range mobile port in filtering		
Explanation:	Allow packets with vlan id 0 to be classified based on vlan-mac rule		
PR	172887	Build:	6.6.3.430.R01
Summary:	OS6250 Sends AMAP from a STP disabled port		
Explanation:	Amap status can be enabled / disabled per port		
PR	175596	Build:	6.6.3.440.R01
Summary:	Command "show ip helper dhcp-snooping ip-source-filter {vlan port}" not working in 6250		
Explanation:	Command Implemented to show port level ip source filtering info , configured in DHCP Snooping		
PR	174567	Build:	6.6.3.457.R01
Summary:	VU-091113-1: Vulnerability in the SSL/TLS protocol.		
Explanation:	Disabling Renegotiation in open SSL		
PR	174371	Build:	6.6.3.457.R01
Summary:	VU-101208-2: Vulnerabilities in OpenSSL		
Explanation:	Work around for using older Netscape browser and servers is not available now		
PR	178076	Build:	6.6.3.475.R01
Summary:	6450: pmd analysis needed		
Explanation:	Length of the incoming bootp/ dhcp packets are validated.		

PR	181862	Build:	6.6.3.489.R01
Summary:	DHCP Snooping issue with port mobility for IP Phones.		
Explanation:	DHCP Snooping issue with port mobility for IP Phones. Assuming a client connected to a port in 6450 which has mobility and LPS enabled, the switch seems to drop the DISCOVER packet from the client when snooping is enabled. And the other issue is that the MAC of the client was not getting learned with DISCOVER packet. Seems that on a mobile port, if DISCOVER packet comes in with unknown SA, first, Group Mobility determines the vlan the packet should classify in. For this reason, packet was not sent to Source Learning. And, when snooping is enabled, DISCOVER packet received on a LPS port when being checked for DHCP rules was failing even when there were no DHCP rules.		
PR	182918	Build:	6.6.3.500.R01
Summary:	Messages from TACACS+ server are not reported to end user in the console output		
Explanation:	Changes have been done to intimate the end user with server responds message.		
PR	183430	Build:	6.6.3.511.R01
Summary:	UNP with policy list is not getting matched.		
Explanation:	Now ARP replies forwarded through the switch.		
PR	186887	Build:	6.6.3.517.R01
Summary:	Spanning tree issue with Omni Switch with MSTP protocol when we disable cist on ports.		
Explanation:	Fix done to display the correct status of the STP operational status, after disabling the cist on port.		
PR	187275	Build:	6.6.3.521.R01
Summary:	I2C read error is overwhelming the switch, need to tone down the retries		
PR	185859	Build:	6.6.3.526.R01
Summary:	Stack splits when enable qos rules to protect user port.		
PR	189941	Build:	6.6.3.528.R01
Summary:	"qos user-port shutdown bpdu" - shutdown is not triggered by PVST+ BPDUs until 1x1 PVST+ compatibility		
PR	190178	Build:	6.6.3.529.R01
Summary:	OS6450 switches in stack crashed with suspended tasks: tCsCSMtask2 & Vrrp .		

PR	174943	Build:	6.6.3.450.R01
Summary:	Unable to create ipmvlan on a OS6450 running 663 GA in Enterprise mode.		
Explanation:	Changes made to ensure the ipmvlan in enterprise mode will work for non metro units.(Non metro units should support ipmvlan enterprise mode irrespective of metro license, License required only for ipmvlan in vlan stacking mode)		
PR	189171	Build:	6.6.3.530.R01
Summary:	OS 6250 stack reboot issue		
PR	185296	Build:	6.6.3.510.R01
Summary:	TACACS Authorization not working properly when server becomes unreachable and then becomes reachable		
Explanation:	Tacacs authorisation will be handled properly during the change in server status from unreachable to reachable.		
PR	183211	Build:	6.6.3.501.R01
Summary:	with aaa accounting command local having more than 255 character crashes the switch		
Explanation:	As per our analysis the root cause of the issue is whenever aaa send command message to server for processing the accounting request, the aaa command accounting will use the maximum size of command length which is 512.but when aaa command accounting is configured as local, it is using the buffer of size 255 because of this local accounting server is not able to hold the entire values of accounting command which also makes the switch to crash. So changes have been made to increase the buffer size as same as accounting command.		
PR	182768	Build:	6.6.3.500.R01
Summary:	Not all commands are sent to TACACS+ server to be authorized from the OmniSwitch.		
Explanation:	We have done changes for whoami and history size. We have added these commands to session management families.		
PR	114746	Build:	6.6.3.411.R01
Summary:	6200 :: %BRG_AMAP-N-AMAP_STATUS: AMAP status: Port g1 data changed.		
Explanation:	Initialize the buffer used for filling system name so that AMAP status change messages are not displayed wrongly.		

PR	156049	Build:	6.6.3.188.R01
Summary:	OS9 - Subnet broadcast in Bootp Packets are not relayed to the relay address configured.		
Explanation:	Bootp buffer handling size increased from 1024 to 1400 to handle pxe discover packets		
	NOTE: BOOTP Packets of Max Size 1400 Bytes only will be handled by AOS 64x Devices		
PR	160791	Build:	6.6.3.490.R01
Summary:	OS6850:Problem in QoS no trusted port.		
Explanation:	Changed mechanism to copy webhostname from http request header		
PR	174370	Build:	6.6.3.457.R01
Summary:	VU-110617-3: Vulnerability in OpenSSL		
Explanation:	Add protection against ECDSA timing attacks		
PR	173664	Build:	6.6.3.428.R01
Summary:	Syslog message output seen with a different format		
Explanation:	Syslog message to follow RFC 3164 format		
PR	174571	Build:	6.6.3.472.R01
Summary:	VU-080718-1: Vulnerability in various IPv6 protocol implementations.		
Explanation:	Vulnerability Fix based on the openbsd patch		
PR	177150	Build:	6.6.3.486.R01
Summary:	Issue with DHCP snooping, dropping the DHCP ACK frame		
Explanation:	DHCP Request packet will be relayed to only the server-ip ,if it carries in his contents. This implementation is controlled by debug variable "dhcp_isc_enable". This is disabled by default, to enable this feature set this variable in AlcatelDebug.cfg		
PR	156360	Build:	6.6.3.205.R01
Summary:	OS6400 doesn't forward option-82 information to another switch (Telco) when DHCP snooping is enabled		
Explanation:	The DHCP packet will be forwarded without stripping opt82 format from the packet if POLICY_KEEP is enabled.		
PR	158136	Build:	6.6.3.278.R01
Summary:	OS 6250 flash corruption happened in 6.6.1.791		
Explanation:	6250 Enhanced upgrade procedure for flash corruption & corrected few flash related errors		

PR	160597	Build:	6.6.3.188.R01
Summary:	OS6850: Problem in flushing of RIP route from routing table.		
Explanation:	RIP Drc Retry queue is scheduled as needed		
PR	159544	Build:	6.6.3.415.R01
Summary:	OS6250 QoS port maximum egress bandwidth maximum ingress bandwidth		
Explanation:	Correct the policing CBS and EBS values. Also provide options to configure the maxBucketSize field in the shaper. (qos port max default depth)		
PR	161347	Build:	6.6.3.212.R01
Summary:	crash on radius server nt reachable message "Excep in task: RADIUS Cli PC : 0x2607b78 "		
Explanation:	Fix to restrict the typecasting only for authentication requests. So accounting requests will not have any chance to go and access the wrong location.		
PR	166712	Build:	6.6.3.442.R01
Summary:	STR NON FATAL messages on log after the switch was upgraded		
Explanation:	case for mip_chassisSupervisionRfsDfSlot has been included in order to avoid error messages(No such instance: rcvd nominatot 1invalid) in the log.		
PR	166512	Build:	6.6.3.428.R01
Summary:	OS6850 - LPS MAC learning issue		
Explanation:	Correcting flush logic on LPS port for permanent mac		
PR	173649	Build:	6.6.3.447.R01
Summary:	Swlog logging messages on high CPU status for CMM / NI. Reference PR# 162618		
Explanation:	Additional Changes added to the current swlog to display if CMM/NI side task is affected while during an CPU spike		
PR	173651	Build:	6.6.3.450.R01
Summary:	SAA statistics are not consistent		
Explanation:	Corrected the SAA Statistics with Proper timestamp in Packets		
PR	170650	Build:	6.6.3.455.R01
Summary:	UNP-Allocation fails in case of bulk 802.1x-client-requests.		
Explanation:	DataPackets from Client before authentication is properly handled.		
PR	156504	Build:	6.6.3.188.R01
Summary:	CMM crashed with tCs_Probe task suspended: Analysis required		
Explanation:	Defense check added to prevent the Crash on an access of Invalid node in the IPV6 router List		

PR	169586	Build:	6.6.3.386.R01
Summary:	OS6450-POE Switches: Disabled POE ports comes up for few seconds after a switch reboot.		
Explanation:	PoE disabled till configuration from CMM is applied		
PR	180448	Build:	6.6.3.478.R01
Summary:	multicast packet drops in IP-DECT environment		
Explanation:	Instead of tagging a flood bitmap index to multicast disabled software learned flows, we will flush the same from hardware if the vlan multicast status is disabled		
PR	176235	Build:	6.6.3.473.R01
Summary:	OS6250 LED problem: Some LEDs are not flashing though the link is up		
Explanation:	When the unit's stacking LED is on, recover the switch to normal state where the port LEDs would be ON after 30 seconds. Also the issue with stack push button is resolved with FPGA version 14.		
PR	177090	Build:	6.6.3.477.R01
Summary:	IP CAM not getting power when connected to 6250 device		
Explanation:	Changes done on the PoE controller firmware to change the threshold of the foldback protection for voltage drop.		
PR	187195	Build:	6.6.3.516.R01
Summary:	6450P10: using SFP-GIG-T on port 1/11 or 1/12 prevents the link to come up post a reload		
Explanation:	Changes done to ensure the 1G link using triple speed SFP remains up post a reload on OS6450 P10 boards.		
PR	155814	Build:	6.6.3.171.R01
Summary:	OS-9000 getting crashed whenever we enable/disable the stp status via WEB GUI on port basis.		
Explanation:	Reset stp pointer to initial value after changing admin status for all mstp instances		
PR	156356	Build:	6.6.3.186.R01
Summary:	OS6850 gives internal error when trying to add same ip for snmp station as the loopback0		
Explanation:	SNMP Station address configuration restricted only to Pure Loopback0 address (not same as physical ip interface address)		

PR	155084	Build:	6.6.3.225.R01
Summary:	Issue with Dchp snooping PXE with AltBootService (UDP 4011)		
Explanation:	Not to drop non-dhcp packets(with Dest Port 68 or 67) when snooping is enabled		
PR	160221	Build:	6.6.3.195.R01
Summary:	Is it possible to have NTP server DNS name in boot.cfg instead of ip address of NTP server		
Explanation:	DNS name will be displayed in configuration snapshot if NTP server is configured with DNS name.		
PR	171329	Build:	6.6.3.408.R01
Summary:	Interface flood rate command remains on the CLI for 6450.		
PR	171349	Build:	6.6.3.410.R01
Summary:	OS6250M - Need explanation for ETHOAM log "error 2018:handle_dmr_info:Timer expired at CMM."		
Explanation:	Changed severity of the ethoam log message "handle_dmr_info:Timer expired at CMM"		
PR	171193	Build:	6.6.3.404.R01
Summary:	OS6250 crashed with taEthOAM_NI task suspended when tried to pull statistics from SAM.		
Explanation:	Optimize memory management on receiving CFMs over SAA configured		
PR	180822	Build:	6.6.3.498.R01
Summary:	Query upgrading SSH Version to 5.2		
PR	181549	Build:	6.6.3.498.R01
Summary:	SSH vulnerabilities in OS9800: SSL Version 2 (v2) Protocol Detection which reportedly suffers from s		
Explanation:	Disabled the ssl-v2 support due to vulnerabilities		
PR	181521	Build:	6.6.3.484.R01
Summary:	Locally configured routes are displayed with EMP interface when we configured with 6.4.5.447 R01 build		
Explanation:	When a route with gateway 127.0.0.1 is configured, the interface was getting displayed as a EMP because of the ifindex value of the route is 0 . A condition is introduced to display the interface of routes with gateway 127.0.0.1 as "Loopback' in routing database.		

PR	175252	Build:	6.6.3.431.R01
Summary:	L2pt-statistics not working on OS6250-8m running AOS 6.6.3.416		
Explanation:	Fix the QOS PCL entries to get the accurate L2TP profile behavior		
PR	176959	Build:	6.6.3.473.R01
Summary:	ARP entry of printbox aging out in combination with NAC setup on particular stack		
Explanation:	Proper handling of CCODE in case of ARP packets received on a .1x port		
PR	189500	Build:	6.6.3.527.R01
Summary:	DHCP packets getting dropped on the trusted ports.		
PR	186818	Build:	6.6.3.515.R01
Summary:	OS6450-P10 crashes when a new vlan is created when running on a official 663.514.R01.		
PR	186600	Build:	6.6.3.522.R01
Summary:	psNotOperational Power supply is inoperable, Object: powerSuply 2, Index: 65		
Explanation:	Changes done to send trap only when power supply is present and non-operational.		
PR	159993	Build:	6.6.3.225.R01
Summary:	802.1x issue after upgrade to 6.4.3		
Explanation:	Pass message to all Nis when mobile entry is deleted		
PR	159333	Build:	6.6.3.246.R01
Summary:	IP interface status remains up even when link agg goes down.		
Explanation:	Deactivate the IP interface, when the corresponding vlan(STP disabled vlan) is operationally down.		
PR	163005	Build:	6.6.3.225.R01
Summary:	MAC address is learned but no connectivity		
Explanation:	Correcting dot1x message and callback handling		
PR	166306	Build:	6.6.3.260.R01
Summary:	snmpenginetime give wrong value for OID		
Explanation:	Reset SNMP engine when the time limit exceeds for snmp engine time.		

PR **180835** Build: 6.6.3.481.R01
 Summary: SSL related Vulnerabilities in OS6850E Switches.
 Explanation: For web view Authentication ssl certificate is integrated in code under path
 /sw/management/switch_management/emweb/html/avlan/custom
 . These certificates were incorporated in secu.img and get extracted to the switch

PR **174986** Build: 6.6.3.438.R01
 Summary: OS6450-P48 crash issue.
 Explanation: Code changes to prevent File System Error issue.
 For more details about OS6450 file system error issue, refer the tech tip
 (Knowledge base) document# 12505 in Customer Support website.
 For more details about OS6250 file system error issue, refer the tech tip
 (Knowledge base) document# 12506 in Customer Support website.

PR **188377** Build: 6.6.3.522.R01
 Summary: NTP issue with Omni switch.
 Explanation: Controlling the snapshot of NTP configuration to store the IP address

PR **187933** Build: 6.6.3.521.R01
 Summary: Multiple simultaneous crashes (stacked and standalone)

PR **184016** Build: 6.6.3.512.R01
 Summary: Unable to retrieve entire Mac-address table per port through SNMP
 Explanation: Fix done to retrieve all the static mac entries on LPS port through the snmp.

PR **154325** Build: 6.6.3.197.R01
 Summary: Relay-agent(switch) forwards only the first offer pkt with snooping enable
 Explanation: Accept all DHCP-OFFERS when multiple offers are received, when dhcp-snooping is enabled

PR **160479** Build: 6.6.3.415.R01
 Summary: Changes to qos port max default depth alone are not applied , AOS 6.6.x
 Explanation: qos port depth command will work similar to 64x

PR **160497** Build: 6.6.3.260.R01
 Summary: 802.1X not connecting all users after reboot of 6850 (ref PR#156204)
 Explanation: Ignore packet received on dot1x port for ip task to be ready after reload

PR **162320** Build: 6.6.3.197.R01
 Summary: DHCP snooping is not working in slot 7 on a stack of 8 units of 6850.
 Explanation: Reset Udprelay-CMM to NI socket completely on NI down events

PR **165716** Build: 6.6.3.445.R01
 Summary: Incorrect NAS Port value in Radius accounting request
 Explanation: Introduced NASPortValueEnable flag to control NAS port value. Default value 0, NAS prt value will be 77. WHEN set to 1, NAS Port will be the co-responding port number

PR **180623** Build: 6.6.3.482.R01
 Summary: In OmniSwitch OS6400/OS6850RE, "Running configuration and saved configuration are different" is shown
 Explanation: Modified the behaviour of Show Configuration Status to sync with CMM Configuration Status

PR **179716** Build: 6.6.3.504.R01
 Summary: Third-party GBPTControl frames (DA mac 01:00:0c:cd:cd:d0) tunneled by software in 6.6.3.R01
 Explanation: Implemented CLI command to enable and disable MAC tunneling as below:

ethernet-service mac-tunneling enable/disable (usage: To enable or disable the mac-tunneling feature).

show ethernet-service mac-tunneling (usage:To know the status of the mac-tunnel feature like whether the feature is enabled or disabled and applied or not).

In 6.6.X releases the uni profile treatment should be tunnel for following protocols in order to tunnel along with the above command in order to tunnel the DA MAC 01:00:0c:cd:cd:d0

PAGP
 UDLD
 CDP
 VTP
 DTP
 PVST
 VLAN
 UPLINK

PR	188601	Build:	6.6.3.529.R01
Summary:	Unable to see snmp traps when enabling dying gasp on switch.		
Explanation:	adding dying gasp trap support for snmp version 1 (v1)		
PR	187362	Build:	6.6.3.517.R01
Summary:	6450-P10: Detect MAC movement when moving same PC among DHCP-SNOOPING ports.		
PR	188855	Build:	6.6.3.524.R01
Summary:	lacp agg actor port priority command accepting value beyond 0-255		
PR	185970	Build:	6.6.3.513.R01
Summary:	DHCP snooping trusted port and binding table		
Explanation:	Implemented the cli "show ip helper dhcp-snooping ip-source-filter binding". This command is used to display the binding entries for the clients connected in ip-source-filtering enabled ports.		
PR	186300	Build:	6.6.3.523.R01
Summary:	show fan output not giving the exact status of the fan.		
Explanation:	Fix done to show proper running FAN status for OS6450		
PR	182765	Build:	6.6.3.500.R01
Summary:	EXIT command issue with Omni Switch.		
Explanation:	Changes have been done to intimate accounting command information for exit command to tacacs server even there is no configuration		

Known Issues:

PR	183629		
Summary:	unable to create QOS Rule with Register profile		
Explanation:	QoS Port nested command with register keyword is handled properly		
PR	180957		
Summary:	Duplicate primary and secondary switch were noticed after we reload the entire stack		
Explanation:	Fix done to unblock AOS tasks when unable to write output on to the tty driver's write buffer.		

New Software Features:

1. Control Frame Tunnel Statistics

Introduction:

This feature Enhancement provides the facility to view the statistics of the processing of Layer 2 control frames received per port per protocol on UNI and NNI ports as set according to the UNI-Profile

Platforms Supported:

Omni Switch 6450, 6250M

Commands usage:

show ethernet-service uni [[linkagg<num>] / <port>] l2pt-statistics

This command displays per UNI port statistics of all protocols. When no port(s) specified, statistics of all UNI ports are displayed.

Syntax Definitions

Num *Linkagg whose statistics are requested*

Port *Port whose statistics are requested.*

Usage Guidelines:

The port should be an UNI port

```

172.25.50.200 - PuTTY
PS1: 172.25.50.70-> show ethernet-service uni l2pt-statistics
Rx,Tunnel and Drop are counted only in software

```

Port Peer	L2 Protocol MAC Tunnel	MAC De-tunnel	Source Rx MAC	Tunnel	Drop
0/1	802.3ad	0	0	0	0
0/1	LACP	0	0	0	0
0/1	OAM	0	0	0	0
0/1	802.1x	0	0	0	0
0/1	802.1ab	0	0	0	0
0/1	AMAP	0	0	0	0
0/1	PAGP	0	0	0	0
0/1	UDLD	0	0	0	0
0/1	CDP	0	0	0	0
0/1	VTP	0	0	0	0
0/1	DTP	0	0	0	0
0/1	PVST	0	0	0	0
0/1	VLAN	0	0	0	0
0/1	UPLINK	0	0	0	0
0/1	STP	0	73	73	0
0/1	GVRP	0	0	0	0
0/1	MVRP	0	0	0	0

show ethernet-service nni [[linkagg<num>] / <port>]] l2pt-statistics

This command displays per NNI port statistics of all protocols. When no port(s) specified, statistics of all NNI ports are displayed.

Syntax Definitions:

Num Linkagg whose statistics are requested
Port Port whose statistics are requested.

Usage Guidelines:

The port should be an NNI port

Example :

```
PS2: 172.25.50.73-> show ethernet-service nni l2pt-statistics
```

Port	Rx Mac-Tunnel	Mac-tunnel discard
1/3	169	0

```
PS2: 172.25.50.73->
```

show ethernet-service uni-profile [<profile_name>] l2pt-statistics

This command displays per uni-profile statistics of all protocols. When no profile specified, statistics of all UNI profiles are displayed.

Syntax Definitions:

Uni profile name Name of the uni-profile whose statistics to be displayed.

Usage Guidelines:

When the name is given, the uni-profile entry should be already configured

```
>
->
-> show ethernet-service uni-profile u4 l2pt-statistics
UNI Profile: u4
  Total RX: 97,
  L2 Protocol:
    802.3ad, OAM, LACPMARKER
      Rx: 0,
      Hardware processing: CPU,
    802_1x
      Rx: 0,
      Hardware processing: DROP,
    802.1ab
      Rx: 4,
      Hardware processing: DROP,
    AMAP
      Rx: 3,
      Hardware processing: DROP,
    PAPG, UDLD, CDP, DTP, VTP, PVST, VLAN, UPLINK
      Rx: 0,
      Hardware processing: CPU,
    STP
      Rx: 90,
      Hardware processing: CPU,
    GVRP, MVRP
      Rx: 0,
      Hardware processing: FWD,
```

clear ethernet-service uni [[linkagg<num>] / <port>]] l2pt-statistics

30 / 47

This command clears UNI port statistics of all protocols.

Syntax Definitions:

Num *Linkagg whose statistics to be cleared*
Port *Port whose statistics to be cleared*

Usage Guidelines:

The port should be an UNI port

clear ethernet-service nni [[linkagg<num>] / <port>] l2pt-statistics

This command clears NNI port statistics of all protocols.

Syntax Definitions:

Num *Linkagg whose statistics to be cleared*
Port *Port whose statistics to be cleared*

Usage Guidelines:

The port should be an NNI port

clear ethernet-service uni-profile [<uni profile_name>] l2pt-statistics

This command clears uni profile statistics of all protocols.

Syntax Definitions:

Uni profile name *Name of the uni-profile whose statistics to be displayed.*

Usage Guidelines:

When the name is given, the uni-profile should be already configured

Limitations:

None

2. Acct-Input-Gigawords & Acct-Output-Gigawords

Introduction:

This enhancement feature provides the facility to identify how many times the Acct-Input-Octets(type-42), Acct-Output-Octets(Type-43) counter has wrapped around 2^{32} it will calculate the value in multiples of 4GB and send using the attributes Acct-Input-Gigawords (type 52) & Acct-Output-Gigawords (type 53). Earlier, size of Acct-Input-Octets & Acct-Output-Octets with which we can only represent maximum 4GB(2^{32}) of Octets. In this enhancement Acct-Input-Gigawords, Acct-Output-Gigawords will be sent in Interim-Update, Periodic-Interim-Update & Stop Messages. Acct-Input-Gigawords, Acct-Output-Gigawords that are sent in accounting packets for both supplicant and non-supplicant users.

Platforms Supported:

Omni Switch 6250
Omni Switch 6450

Commands usage:

No New commands introduced

Limitations:

None

3. Case Sensitive Mac-Address Authentication

Introduction:

This enhancement feature enables the AOS switches to send MAC address of the non-supplicant client in lower case as username and password for authentication to the authentication server. During non-supplicant authentication the client MAC address is sent as username and password. Earlier, for non-supplicant authentication the client MAC address is sent as username and password. This MAC address is sent in Uppercase for username and password. This enhancement enables to the send the MAC address of client as username and password in lower case.

Platforms Supported:

Omni Switch 6250
Omni Switch 6450

Commands usage:

No New commands introduced

Limitations:

None

4. UNP Bandwidth Rate Limiting

Introduction:

This feature Enhancement provides the facility to apply ingress and egress bandwidth limitations on a port on basis of UNP classification locally or remotely through radius-server return attribute. A UNP profile will be associated with maximum ingress and egress bandwidth, whenever authenticates under UNP policy either through radius returned UNP attribute or through local policy, associated bandwidth limitations are applied on port. When Qos port with ingress or egress bandwidth specified will override bandwidth associated due to UNP. If ingress/egress bandwidth is set through qos port command then any change in qos port parameter will over ride bandwidth set due to UNP.

When multiple users authenticate under same port latest bandwidth limitation will overwrite the previous limitation existing on the port. Earlier there was no option to associate bandwidth parameters with UNP. Hence No bandwidth limitation can be applied to the port on basis of UNP classification.

Platforms Supported:

Omni Switch 6450
Omni Switch 6250/ OS6250M

Commands usage:

aaa user-network-profile name <profile-name> vlan <vlan> [maximum-ingress-bandwidth <num> maximum-egress-bandwidth <num> maximum-default-depth <num>]

Syntax Definitions

Maximum-ingress-bandwidth	Ingress bandwidth to be applied on the port
Maximum-egress-bandwidth	egress bandwidth to be applied on the port
Maximum-default-depth	depth to be applied on the port

Defaults

Maximum-ingress-bandwidth	-1 (no rate-limit)
Maximum-egress-bandwidth	-1 (no rate-limit)
Maximum-default-depth	-1 (1 Mbps)

Show 802.1X rate-limit

```
-> show 802.1x rate-limit
```

Slot	Max	Ingress BW		Max	Egress BW	
Port	Ingress-BW	Type	UNP-ProfileName	Egress-BW	Type	UNP-ProfileName
3/7	64K	UNP	geetha8	64K	UNP	geetha8

Limitations:

None

5. LPS Sticky mode

Introduction:

This feature Enhancement provides the facility to configure the learning window to learn all Mac as static.

Earlier, The LPS feature limits the number of MACs that can be learned, up to a pre-determined number, plus supports a learning time window, and provides logging and notification if a rule violation occurs. This feature is enhanced to learn the MAC as static from the initial stage

Platforms Supported:

Omni Switch 6450

Omni Switch 6250/ 6250M

Commands usage:

port-security shutdown <num> [no-aging {enable|disable}] [convert-to-static {enable|disable}] [boot-up {enable|disable}] [learn-as-static {enable|disable}]

Syntax Definitions

Learn-as-static : this option is used for learning a MAC as static during learning window.

Enable : Enables LAS functionality on this port.

Disable : Disables LAS feature on this port without removing LPS configuration.

Usage Guidelines

By default, LAS admin-status is N/A.

When disabled, all filtered MAC addresses on the port are removed and all bridged and static MAC addresses stay “forwarding”. The LPS static Mac configuration is preserved. The source learning mode is set the hardware mode for the port and all new MAC addresses are learnt and not visible in the LPS context. The port-security configuration is still allowed but not applied, but configuration of LPS static Mac is refused. Reducing the “maximum” to a lower value than the number of static Mac is also refused.

port-security shutdown <0> [{ no-aging <enable|disable>} |{convert-to-static <enable | disable>} | {boot-up <enable|disable>} | {learn-as-static <enable|disable>}]

Configuration will enable user to use all the options for learning window when the shut down time is zero.

Syntax Definitions:

Num : Learning window time in minutes (Max value ->65535)

No-aging : When enabled, MAC learnt during learning window will not

be flushed.

Convert-to-static: When enabled, MAC are learnt during learning window are converted into static MAC.

Boot-up : When enabled, Learning window should occur at boot-up time when box restarts.

Learn-as-static : this option is used for learning a MAC as static during learning window.

Usage Guidelines:

User can use all, any or none of flags with “port-security shutdown 0 command now. Show commands are same as in previous feature.

```

172.25.50.200 - PuTTY
DUT1--> show port-security

Legend: Mac Address: * = Duplicate Static
        Mac Address: # = Pseudo Static

Port: 1/3
Operation Mode      :          ENABLED,
Max MAC bridged    :              1,
Trap Threshold     :          DISABLED,
Max MAC filtered   :              5,
Low MAC Range      :      00:00:00:00:00:00,
High MAC Range     :      ff:ff:ff:ff:ff:ff,
Violation          :          RESTRICT,
Violating MAC      :          NULL

MAC Address      VLAN  TYPE
-----+-----+-----
00:00:00:00:00:05    1  STATIC

Port: 2/13
Operation Mode      :          ENABLED,
Max MAC bridged    :              1,
Trap Threshold     :          DISABLED,
Max MAC filtered   :              5,
Low MAC Range      :      00:00:00:00:00:00,
High MAC Range     :      ff:ff:ff:ff:ff:ff,
Violation          :          RESTRICT,
Violating MAC      :          NULL

MAC Address      VLAN  TYPE
-----+-----+-----
00:00:00:00:00:05    1  STATIC (*)

```

Limitations:

None

6. DHCP SERVER

Introduction:

A DHCP server provides dynamic IP addresses on lease for client interfaces on a network. It manages a pool of IP addresses and information about client configuration parameters. The DHCP server obtains an IP address request from the client interfaces. After obtaining the requests, the DHCP server assigns an IP address, a lease period, and other IP configuration parameters, such as the subnet mask and the default gateway

For enabling the DHCP-server in DUT we have to keep the below files in flash/switch directory and it is having the information about ip address details assigned to client when DHCP-client sends DHCP-request.

dhcpd.pcy
dhcpd.conf

Platforms Supported:

Omni Switch 6450

Commands usage:

dhcp-server {enable | disable | restart}

Enables, disables, or restarts the DHCP server operation.

Syntax Definitions:

Enable Enables operation status of the DHCP server.

Disable Disables operation status of the DHCP server.

Restart Restarts the DHCP Server.

clear dhcp-server statistics

Clears the packet counters of dhcp-server statistics.

show dhcp-server statistics [packets | hosts | subnets | all]

Displays the statistics of the DHCP server.

Syntax Definitions:

packets Displays general statistical information along with specific information about data packets received, dropped and transmitted.

hosts	Displays general statistical information along with specific information about hosts related to all the subnets.
subnets	Displays general statistical information along with specific information about all the subnets.
all	Displays all statistical information related to the DHCP server.

show dhcp-server leases [ip_address | mac_address | count] [type {static | dynamic}]

Displays the leases offered by the DHCP server.

Syntax Definitions:

ip_address	Specifies IP address of the interface configured with DHCP server.
mac_address	Specifies MAC address of the interface configured with DHCP server.
static	Displays only static leases.
dynamic	Displays only dynamic leases.

Limitations:

None

7. LLDP Power via MDI Enhancement

Introduction

This feature enhancement facilitates to support the link layer classification in order to interoperate with newer class 4 PD's(Powered Device) , because these devices require a response to the LLDPDU power via MDI TLV before they will draw additional power from PSE(Power). Earlier the maximum power is set to the maximum allowed power for the detected Power Class of the Power Device connected on the port. The Power Class detection is done via hardware by the POE controller. POE Devices in general can draw any amount of power up to the maximum power that is set for the port. In any condition, the maximum power that the PD can request from the PSE cannot exceed the maximum allowed power for the Power Class in which the PD(Powered Device) is detected, But these newer class 4PD's(Powered devices) requires to draw additional power than the maximum power set for the port Hence this feature is introduced.

Platforms Supported

Omni Switch 6250, 6450

Commands usage

```
lldp {slot/port | slot | chassis} tlv dot3 power-via-mdi {enable | disable}
```

Syntax Definitions

slot/port	Slot number for the module and physical port number on that module
slot	The slot number for a specific module.
enable	Enables 802.3 TLV LLDPDU transmission.
disable	Disables 802.3 TLV LLDPDU transmission.

Usage Guidelines

- The LLDPDU must be enabled and set to transmit before using this command.
- If this command is applied to a slot or chassis, then the existing configuration related to this command is lost.

Limitations:

None

8. Increased number of Telnet/ Syslog & NTP**Introduction**

This enhancement has increased the number of telnet sessions from 4 to 6, no of syslog servers increased from 3 to 12 and no of NTP servers increased from 3 to 12

Platforms Supported

Omni Switch 6250, 6450

Commands usage

No new CLI introduced for this

Limitations:

None

9. Enable / Disable the console session**Introduction**

This feature Enhancement provides the facility to enable/disable the console cli session so that access to the switch configuration shell through the console port can be in a controlled manner as required. By default this facility (console access) will be enabled. This can also be stored in configuration file so that console access control can be applied even after reboot.

Recovery Procedure

If both the console cli session is disabled in the configuration file on both working and certified directory and if the telnet/ssh/web view session is not available to the switch, to get access to the switch console cli session user have to stop the switch in miniboot by setting the boot flags to 0x1000 and once the switch stops in miniboot user shall delete the configuration file and reboot the switch to get console access to the switch.

Earlier, there was no provision to control the access for console cli session.

Platforms Supported

Omni Switch 6250, 6450

Commands usage

Session console {enable disable}

Usage Guidelines

- By default, the cli console shell is enabled.
- The command shall be accepted only via Telnet/SSH session, and not through console sessions to the switch.
- When it is disabled, even the switch log output to the console shall be disabled.
- Command shall be stored to the configuration file using write memory.
- Command shall be used only on standalone unit, even if used in stack only primary unit console CLI session shall stay disabled.

Limitations:

None

10. 802.1q capability over NNI ports**Introduction:**

This feature Enhancement provides the 'Standard VLAN support on NNI ports' will allow any standard (non-service) VLAN to be associated to NNI ports. This allowed association can be of type untagged or 8021q tagged. However, there is an exception for VLAN 1, which shall not be associated as untagged member to a NNI port. This will allow the customers to configure 802.1q services, QinQ service and untagged services using the same uplink NNI port. This will also allow the customer to use an untagged management VLAN to manage the switch via NNI ports.

With the implementation of this feature, the following will be the changes on the behavior of the switch:

The standard VLAN configuration (both untagged and 802.1q tagged association) will now be allowed on an NNI interface binded with a service VLAN.

- The binding of service VLAN to NNI interface will now be allowed when the interface (physical or linkagg) is already tagged with standard VLAN.
- 802.1q VLAN tagging to an NNI interface will not be allowed if the interface is set with TPID other than 0x8100.
- Any modification with respect to TPID will not be allowed if the NNI interface is 802.1q tagged.

There would also be significant changes with respect to the default VLAN of the NNI interface (both physical and LAG):

- If an interface is already an untagged member of a standard VLAN other than VLAN 1, then on making it an NNI interface, there should not be any change with respect to the default VLAN of the interface. (Currently, the default VLAN changes to 4095).
- If the default VLAN is removed from the NNI interface, then the default VLAN should be changed to 4095
- It implies, from the above two points, that it shall not be possible to configure VLAN 1 as default VLAN of an NNI interface.

Platforms Supported:

Omni Switch 6450
Omni Switch 6250

Commands usage:

Show the standard VLAN of an NNI interface:

```
> ethernet-service svlan 1000
> ethernet-service service-name customerA svlan 1000
> ethernet-service svlan 1000 nni 1/38
> vlan 10
> vlan 10 port default 1/38
> show vlan port 1/38
vlan      type      status
-----+-----
    10     default   forwarding
   1000     vstkQtag  forwarding
```

Show 802.1q on NNI port:

```
-> ethernet-service svlan 1000
-> ethernet-service svlan 1000 nni 1/38
-> vlan 10
-> vlan 10 802.1q 1/38
-> show 802.1q 1/38

Acceptable Frame Type      :      Any Frame Type
Force Tag Internal         :                      NA
Tagged VLANs      Internal Description
-----+-----
    10     TAG PORT 1/38 VLAN 10
   1000     SVLAN
```


Show the default VLAN of an NNI interface:

```
-> dshell
Working: [Kernel]->vstkShowPort

***** VLAN Stacking Port *****

Port      Type      TPID    BPDU*    Accepted  Lookup  Dflt  Cust-BPDU
-----+-----+-----+-----+-----+-----+-----+-----+
1/14      user-cus  8100    flooded  all       drop    4095  disable
1/38      network  8100    flooded  all       drop    4095  disable
-----+-----+-----+-----+-----+-----+-----+-----+-----+
```

Limitations:

None

11. TRI SPEED (10/100/1000)SFP SUPPORT ON OS6450 U24

Introduction:

This feature Enhancement provides the 'Tri speed SFP support on OS6450 U24'. The Copper Small Form Pluggable(SFP)s Finisar FCLF 8521-3 and Finisar FCLF 8521 P2BTL are compatible with Gigabit Ethernet(1000 Mbps), Fast Ethernet (100 Mbps) and Ethernet(10 Mbps).

Platforms Supported:

Omni Switch 6450

Commands usage:

Show interface : show configuration snapshot interface

Syntax Definitions

Configuration snapshot interface verify the configuration of the interface

Limitations:

None

12. POLICY PORT GROUP ENHANCEMENT

Introduction

This feature enhancement facilitates to configure policy rule that specifies rate limiting as action for a group of ports or individual ports as per our requirement. For this enhancement new attribute “split & non-split” has been added for a policy port group to specify whether the group needs to be treated as a list of individual port or not respectively. This feature provides the following two modes to be applied as a part of the policy source port group:

1. Non-split: When used with this mode, the rule for rate limiting is applied for the group of ports. This is the default behavior for the source port group.
2. Split: When used with this mode, the rule for rate limiting is actually applied for each of the individual ports. However, the action is not restricted to rate limit the incoming traffic, action could be anything other than the keyword “share”. Moreover, other actions can also be applied in addition to rate limiting, such as changing the dscp value, etc. Any incoming traffic in excess of the applied bandwidth to an individual port will be dropped.

Before this enhancement, on configuring a policy rule that specifies a rate limiter as action and a source port group as condition, the rate limiter is actually applied for the group of ports, not each individual port.

Platforms Supported

Omni Switch OS6250M(Metro), OS6450

Commands usage

```
policy port group <name> [mode {non-split | split}] <slot/port> <slot/port1-port2>
```

Syntax Definitions

split When used with this mode, the rule for rate limiting is actually applied for each of the individual ports.

non-split When used with this mode, the rule for rate limiting is applied for the group of ports. This is the default behavior for the source port group.

Usage Guidelines

- When the port group is configured in the split mode, the rule needs to be split into multiple sub-rules.

- Depending on the policy condition for the rule, each sub-rule may consist of multiple entries
- The rate limiter is to be shared between the entries for the same sub-rule.

```
DUT1:172.25.50.70-> policy port group pg1 mode split 1/1 2/3
DUT1:172.25.50.70-> policy port group pg1 mode non-split 2/1 2/2
```

show active policy rule r1 extended:

```
DUT1:172.25.50.70-> show active policy rule extended
Policy          Port          Matches
r1              1/1           6336985
                2/3           2808383
```

show active policy rule r1 meter-statistics extended:

```
DUT1:172.25.50.70-> show active policy rule meter-statistics extended
Policy:r1, Port:1/1
Green   :          2198284
Yellow  :             1
Red     :          8379624
Matches :    10577909
Policy:r1, Port:2/3
Green   :          2124936
Yellow  :           48294
Red     :          3428873
Matches :     5602103
```

show policy port group:

```
DUT1:172.25.50.70-> show policy port group
Group Name      From  Entries  Mode
Slot01         blt   1/1-10  non-split
Slot02         blt   2/1-10  non-split
pg1            cli   1/1     split
                2/3
```

Limitations:

The scope of this feature is limited to source port group can be attached to only default policy list. Any rule with the source port group in the split mode attached to policy list will throw an error.

13. SSH Access to Read-Only Users

Introduction:

This feature Enhancement provides the facility to Establish a SSH Session for a Read-Only Users through Switch as Local Server,Radius Server,LDAP,TACACS.This SSH Read-Only Session allows to view the SSH Specific show commands .

Earlier it is not possible to SSH to a switch and access for a user unless he has read-write permissions. This is the current default behavior. But telnet to switch does not validate the permissions of the user and therefore switch becomes accessible.

Platforms Supported:

Omni Switch 6450, 6250

Commands usage:

```
user {username} read-only ssh password {maximum 8 }
```

Syntax Definitions:

Read-only :Specify the User Privilege

Ssh:The type of Service and Family the Belong to.

Defaults

Parameter	Default
Read only for families	None

Usage Guidelines

- Read-Only user configuration must specify the SSH family
- Creating a user with Family as "none " will not permit access to SSH

Show users:

Displays information about the all the user configuration

Examples:

User name = goog,
Password expiration = None,
Password allow to be modified date = None,
Account lockout = None,
Password bad attempts = 0,
Read Only for domains = ,
Read only for families = ssh ,
Read/Write for domains = None,
Snmp allowed = YES,
Snmp authentication = NONE,
Snmp encryption = NONE

LIMITATIONS:

None

14.TACACS Command Based Authorization

Introduction:

Prior to this enhancement command authorization in TACACS is done based on partition-management family that the command belongs to.

According to the new feature, after authentication, once command based authorization is enabled then every cli command that the user executes on the switch is sent to the TACACS+ server. So TACACS+ server will do the authorization for the whole command and send the RESPONSE message to the TACACS+ client. If command based authorization is disabled then PM family for the command is sent for the authorization.

Platforms Supported:

Omni Switch 6250, 6450

Commands usage:

```
aaa tacacs command-authorization {enable/disable}  
By default command authorization is disabled
```

Configuration snapshot:

1. Snapshot of : aaa tacacs command-authorization disable

```
172.25.50.21 show configuration snapshot aaa
! AAA :
aaa radius-server "radius" host 172.25.50.220 key e47ac0f11e9fa869 retransmit 3
timeout 2 auth-port 1812 acct-port 1813
aaa tacacs+-server "SysServTACACS" host 172.65.200.20 key "563abdlae5376e70" port
49 timeout 2
aaa authentication console "local"
aaa authentication telnet "SysServTACACS"
aaa authentication ftp "local"
aaa authentication http "local"
aaa authentication ssh "SysServTACACS"
aaa authentication 802.1x "radius"
aaa authentication mac "radius"
! PARTM :
! AVLAN :
! 802.1x :
```

2. Snapshot of : aaa tacacs command-authorization enable

```
172.25.50.21 aaa tacacs command-authorization enable
172.25.50.21 show configuration snapshot aaa
! AAA :
aaa tacacs command-authorization enable
aaa radius-server "radius" host 172.25.50.220 key e47ac0f11e9fa869 retransmit 3
timeout 2 auth-port 1812 acct-port 1813
aaa tacacs+-server "SysServTACACS" host 172.65.200.20 key "563abdlae5376e70" port
49 timeout 2
aaa authentication console "local"
aaa authentication telnet "SysServTACACS"
aaa authentication ftp "local"
aaa authentication http "local"
aaa authentication ssh "SysServTACACS"
aaa authentication 802.1x "radius"
aaa authentication mac "radius"
! PARTM :
! AVLAN :
! 802.1x :
172.25.50.21
```

Limitations:

Snmp and http are not supported in Command based authorization.

15. Tacacs Server-Wait-Time

Introduction

This feature is introduced to configure wait time, which depicts the time that CLI task can wait for aaa response to be received from Tacacs+ server, before processing the next consecutive command passed by the user.

Earlier, there was no provision to control the time gap between the response received from the Tacacs+ server for a previous authorization request and current authorization request that is sent from AOS switch to Tacacs+ server, when there are continuous authorization requests. Hence unauthorized users were able to perform write operations on switch.

Platforms Supported

Omni Switch 6250, 6450

Commands usage

```
aaa tacacs server-wait-time <seconds>
```

Usage Guidelines

- By default, the wait time value is 5 seconds.
- The Maximum wait time value that can be configured is 200 Seconds
- The Minimum wait time value that can be configured is 0 Seconds

Limitations:

None