



## Intermediate Release Notes for the OmniSwitch 6800: Release 5.3.1.R01

The following is a list of issues that have been identified and corrected in AOS software release 5.3.1.R01 since GA (Generally Available). This document is intended to be used as a pre-upgrade guide and does not replace the Release Notes which are created for every GA release of software.

### **Important Notice:**

For a copy of a software release not posted on the Web, or if you have questions or concerns, please contact Alcatel's Technical Support Department.

### **The below list includes software problems found and resolved from GA up to release 5.3.1.380.R01**

- Kite QoS: policy condition exhausting the masks can't be modified and generates internal error message
- Command "no ip service secure-http" caused boot.cfg.err
- Multiple ip-helper not working in AVLAN environment
- IPX local route disappeared with "show ipx route"
- Telnet from Kite to adjacent switch corrupts Kite system time cause routing protocol instability
- Source Learning table gets flushed upon takeover by Group Mobility
- Keep pimsm/ipmrm in sync when adding native flows along with registered flows
- Errors generated from boot configuration file (boot.cfg) during bootup for Dynamic Routing Config
- Traceroute output of one telnet session is received on ping output of another telnet session
- Can't disable "debug command-info"
- Info vm tx error (-6) to: 255 0 8 36 -- continuously scrolling in swlog
- Fix for wrong DHCP IP Helper address after login/logout from AVLAN
- ARP is not updated properly when there is a topology change
- icmp type 0 -- echo reply is partially broken, ping reply even when it is denied
- ARP table not flushed on linkagg when a port is disconnected
- Stp disabled setting not retained over a reboot
- Show Chassis command does not display the correct reload or reboot timer

- Add debug code to catch the source ip address of an unknown SA packet
- Unauthentication (logoff) from AVLAN doesn't work.

**Known Issues:**

- Quotes must be used for special character in a password and exclamation mark not allowed in password (PR 88606)
- "drvIoctl is NULL! driver 14" messages printed continuously on console upon write memory (PR 89951)
- Telnet session allows a reboot when stack is syncing code to other stacks (PR 90291)
- STP reconfiguration across a stack of 6800: hardware L2 MAC table is not flushed (PR 90582)

**6800 Features / Functions Tested:**

Install and Activate Software  
Stack Topology Status  
Module Status  
NI Status  
NISUP NI Task Status  
Memory Stack Status  
Interface Port Status  
Spanning Tree Status  
Vlan Port Default Status  
Source Learning  
802.1Q Bridging  
Group Mobility (MAC + IP-Net Rule)  
L3 Switching / Routing  
QoS  
IPMS  
RIP  
OSPF  
UDP Relay  
L2 Multicast  
SNMP  
Copy Working Certified  
Reload DUT