

# FastIron 08.0.80e for Ruckus ICX Switches Release Notes Version 1

Supporting FastIron 08.0.80e

# Copyright, Trademark and Proprietary Rights Information

© 2019 ARRIS Enterprises LLC. All rights reserved.

No part of this content may be reproduced in any form or by any means or used to make any derivative work (such as translation, transformation, or adaptation) without written permission from ARRIS International plc and/or its affiliates ("ARRIS"). ARRIS reserves the right to revise or change this content from time to time without obligation on the part of ARRIS to provide notification of such revision or change.

## Export Restrictions

These products and associated technical data (in print or electronic form) may be subject to export control laws of the United States of America. It is your responsibility to determine the applicable regulations and to comply with them. The following notice is applicable for all products or technology subject to export control:

*These items are controlled by the U.S. Government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations.*

## Disclaimer

THIS CONTENT AND ASSOCIATED PRODUCTS OR SERVICES ("MATERIALS"), ARE PROVIDED "AS IS" AND WITHOUT WARRANTIES OF ANY KIND, WHETHER EXPRESS OR IMPLIED. TO THE FULLEST EXTENT PERMISSIBLE PURSUANT TO APPLICABLE LAW, ARRIS DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, FREEDOM FROM COMPUTER VIRUS, AND WARRANTIES ARISING FROM COURSE OF DEALING OR COURSE OF PERFORMANCE. ARRIS does not represent or warrant that the functions described or contained in the Materials will be uninterrupted or error-free, that defects will be corrected, or are free of viruses or other harmful components. ARRIS does not make any warranties or representations regarding the use of the Materials in terms of their completeness, correctness, accuracy, adequacy, usefulness, timeliness, reliability or otherwise. As a condition of your use of the Materials, you warrant to ARRIS that you will not make use thereof for any purpose that is unlawful or prohibited by their associated terms of use.

## Limitation of Liability

IN NO EVENT SHALL ARRIS, ARRIS AFFILIATES, OR THEIR OFFICERS, DIRECTORS, EMPLOYEES, AGENTS, SUPPLIERS, LICENSORS AND THIRD PARTY PARTNERS, BE LIABLE FOR ANY DIRECT, INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, EXEMPLARY OR CONSEQUENTIAL DAMAGES, OR ANY DAMAGES WHATSOEVER, EVEN IF ARRIS HAS BEEN PREVIOUSLY ADVISED OF THE POSSIBILITY OF SUCH DAMAGES, WHETHER IN AN ACTION UNDER CONTRACT, TORT, OR ANY OTHER THEORY ARISING FROM YOUR ACCESS TO, OR USE OF, THE MATERIALS. Because some jurisdictions do not allow limitations on how long an implied warranty lasts, or the exclusion or limitation of liability for consequential or incidental damages, some of the above limitations may not apply to you.

## Trademarks

ARRIS, the ARRIS logo, Ruckus, Ruckus Wireless, Ruckus Networks, Ruckus logo, the Big Dog design, BeamFlex, ChannelFly, Edgellon, FastIron, HyperEdge, ICX, IronPoint, OPENG, SmartCell, Unleashed, Xclaim, ZoneFlex are trademarks of ARRIS International plc and/or its affiliates. Wi-Fi Alliance, Wi-Fi, the Wi-Fi logo, the Wi-Fi CERTIFIED logo, Wi-Fi Protected Access (WPA), the Wi-Fi Protected Setup logo, and WMM are registered trademarks of Wi-Fi Alliance. Wi-Fi Protected Setup™, Wi-Fi Multimedia™, and WPA2™ are trademarks of Wi-Fi Alliance. All other trademarks are the property of their respective owners.

# Contents

---

<b>Document History.....</b>	<b>5</b>
<b>Introduction.....</b>	<b>7</b>
About FastIron Release 08.0.80.....	7
Document Feedback.....	7
Ruckus Product Documentation Resources.....	7
Online Training Resources.....	8
Contacting Ruckus Customer Services and Support.....	8
What Support Do I Need?.....	8
Open a Case.....	8
Self-Service Resources.....	8
<b>New in This Release.....</b>	<b>11</b>
Hardware.....	11
Software Features.....	11
New Software Features in 08.0.80e.....	11
New Software Features in 08.0.80cd.....	11
New Software Features in 08.0.80ca.....	11
New Software Features in 08.0.80c.....	11
New Software Features in 08.0.80b.....	11
New Software Features in 08.0.80a.....	12
New Software Features in 08.0.80.....	12
CLI Commands.....	15
New Commands in 08.0.80e.....	15
New Commands in 08.0.80d.....	15
New Commands in 08.0.80ca.....	15
New Commands in 08.0.80c.....	15
New Commands in 08.0.80b.....	15
New Commands in 08.0.80a.....	15
New Commands in 08.0.80.....	15
Modified Commands in 08.0.80c.....	16
Modified Commands in 08.0.80.....	16
Deprecated Commands in 08.0.80.....	17
RFCs and Standards.....	18
New Standards and RFCs in Release 08.0.80e.....	18
New Standards and RFCs in Release 08.0.80d.....	18
New Standards and RFCs in Release 08.0.80ca.....	18
New Standards and RFCs in Release 08.0.80c.....	18
New Standards and RFCs in Release 08.0.80b.....	18
New Standards and RFCs in Release 08.0.80a.....	18
New Standards and RFCs in Release 08.0.80.....	18
MIBs.....	18
New MIBs in Release 08.0.80e.....	18
New MIBs in Release 08.0.80d.....	18
New MIBs in Release 08.0.80ca.....	19
New MIBs in Release 08.0.80c.....	19
New MIBs in Release 08.0.80b.....	19

New MIBs in Release 08.0.80a.....	19
New MIBs in Release 08.0.80.....	19
<b>Hardware Support.....</b>	<b>21</b>
Supported Devices.....	21
Supported Power Supplies.....	21
Supported Optics.....	21
<b>Software Upgrade and Downgrade.....</b>	<b>23</b>
Image File Names.....	23
PoE Firmware Files.....	23
Open Source and Third Party Code.....	24
<b>Issues.....</b>	<b>27</b>
Closed in Release 08.0.80e.....	27
Closed with Code Change in Release 08.0.80d.....	34
Known Issues in Release 08.0.80ca.....	36
Closed with Code Changes in Release 08.0.80b.....	36
Known Issues in Release 08.0.80b.....	37
Closed with Code Changes in Release 08.0.80.....	38
Known Issues in Release 08.0.80.....	58

# Document History

---

Version	Summary of changes	Publication date
FastIron 08.0.80e for ICX Switches Version 1	Resolved issues.	April 19, 2019
FastIron 08.0.80d for ICX Switches Version 1	Resolved issues.	November 26, 2018
FastIron 08.0.80ca for ICX Switches Version 1	Resolved issue.	October 12, 2018
FastIron 08.0.80c for ICX Switches Version 1	New feature.	October 4, 2018
FastIron 08.0.80b for ICX Switches Version 1	Resolved issues.	September 5, 2018
FastIron 08.0.80a for ICX Switches Version 1	New features and resolved issues for the 08.0.80a release.	August 20, 2018
FastIron 08.0.80 for ICX Switches Version 1	New enhancements and features for the 08.0.80 release.	July 9, 2018



# Introduction

---

- [About FastIron Release 08.0.80.....](#) 7
- [Document Feedback.....](#) 7
- [Ruckus Product Documentation Resources.....](#) 7
- [Online Training Resources.....](#) 8
- [Contacting Ruckus Customer Services and Support.....](#) 8

## About FastIron Release 08.0.80

FastIron Release 8.0.80 introduces a number of key software features and enhancements to improve ICX switch management, usability, and scalability. This release introduces support for Ruckus SmartZone management of ICX switches, which enables SmartZone to provide monitoring, status, usage visibility, and some basic management, including configuration backups and firmware management, of ICX switches. Also introduced is a new image format called Unified FastIron Image (UFI), which combines both the FastIron application image and boot code. New Layer 2 features include Remote Switched Port Analyzer (RSPAN) for remote mirroring. FastIron Release 08.0.80 introduces usability features such as simplified dual-mode for VLANs and increases default VLAN support and range to 1024 VLANs. This release also brings scalability enhancements in the areas of DHCP snooping, IP Source Guard, and Dynamic ARP Inspection (DAI). Another key enhancement in FastIron release 08.0.80 is the introduction of support for ICX 7650 as a cost-effective Campus Fabric (SPX) control bridge.

## Document Feedback

Ruckus is interested in improving its documentation and welcomes your comments and suggestions.

You can email your comments to Ruckus at [ruckus-docs@arris.com](mailto:ruckus-docs@arris.com).

When contacting us, include the following information:

- Document title and release number
- Document part number (on the cover page)
- Page number (if appropriate)

For example:

- Ruckus SmartZone Upgrade Guide, Release 5.0
- Part number: 800-71850-001 Rev A
- Page 7

## Ruckus Product Documentation Resources

Visit the Ruckus website to locate related documentation for your product and additional Ruckus resources.

Release Notes and other user documentation are available at <https://support.ruckuswireless.com/documents>. You can locate the documentation by product or perform a text search. Access to Release Notes requires an active support contract and a Ruckus Support Portal user account. Other technical documentation content is available without logging in to the Ruckus Support Portal.

White papers, data sheets, and other product documentation are available at <https://www.ruckuswireless.com>.

## Online Training Resources

To access a variety of online Ruckus training modules, including free introductory courses to wireless networking essentials, site surveys, and Ruckus products, visit the Ruckus Training Portal at <https://training.ruckuswireless.com>.

## Contacting Ruckus Customer Services and Support

The Customer Services and Support (CSS) organization is available to provide assistance to customers with active warranties on their Ruckus products, and customers and partners with active support contracts.

For product support information and details on contacting the Support Team, go directly to the Ruckus Support Portal using <https://support.ruckuswireless.com>, or go to <https://www.ruckuswireless.com> and select **Support**.

### What Support Do I Need?

Technical issues are usually described in terms of priority (or severity). To determine if you need to call and open a case or access the self-service resources, use the following criteria:

- Priority 1 (P1)—Critical. Network or service is down and business is impacted. No known workaround. Go to the **Open a Case** section.
- Priority 2 (P2)—High. Network or service is impacted, but not down. Business impact may be high. Workaround may be available. Go to the **Open a Case** section.
- Priority 3 (P3)—Medium. Network or service is moderately impacted, but most business remains functional. Go to the **Self-Service Resources** section.
- Priority 4 (P4)—Low. Requests for information, product documentation, or product enhancements. Go to the **Self-Service Resources** section.

### Open a Case

When your entire network is down (P1), or severely impacted (P2), call the appropriate telephone number listed below to get help:

- Continental United States: 1-855-782-5871
- Canada: 1-855-782-5871
- Europe, Middle East, Africa, Central and South America, and Asia Pacific, toll-free numbers are available at <https://support.ruckuswireless.com/contact-us> and Live Chat is also available.
- Worldwide toll number for our support organization. Phone charges will apply: +1-650-265-0903

We suggest that you keep a physical note of the appropriate support number in case you have an entire network outage.

### Self-Service Resources

The Ruckus Support Portal at <https://support.ruckuswireless.com> offers a number of tools to help you to research and resolve problems with your Ruckus products, including:

- Technical Documentation—<https://support.ruckuswireless.com/documents>



- Community Forums—<https://forums.ruckuswireless.com/ruckuswireless/categories>
- Knowledge Base Articles—<https://support.ruckuswireless.com/answers>
- Software Downloads and Release Notes—[https://support.ruckuswireless.com/#products\\_grid](https://support.ruckuswireless.com/#products_grid)
- Security Bulletins—<https://support.ruckuswireless.com/security>

Using these resources will help you to resolve some issues, and will provide TAC with additional data from your troubleshooting analysis if you still require assistance through a support case or RMA. If you still require help, open and manage your case at [https://support.ruckuswireless.com/case\\_management](https://support.ruckuswireless.com/case_management).



# New in This Release

---

- Hardware..... 11
- Software Features..... 11
- CLI Commands..... 15
- RFCs and Standards..... 18
- MIBs..... 18

## Hardware

There is no new hardware in FastIron Release 08.0.80.

## Software Features

The following section lists new, modified, and deprecated software features for this release. For information about which platforms support these features, refer to the FastIron Features and Standards Support Matrix, available at [www.ruckuswireless.com](http://www.ruckuswireless.com).

### New Software Features in 08.0.80e

There are no new features in this release.

### New Software Features in 08.0.80cd

There are no new features in this release.

### New Software Features in 08.0.80ca

There are no new features in this release.

### New Software Features in 08.0.80c

The following software features and enhancements are introduced in this release.

Feature	Description
SmartZone IP Address Configuration Using ICX Switch Registrar Discovery	This feature allows an ICX switch to use a DB registrar discovery mechanism to discover the list of SmartZone IP addresses.

### New Software Features in 08.0.80b

There are no new features in this release.

## New Software Features in 08.0.80a

The following software features and enhancements are introduced in this release.

Feature	Description
Remote Ping MIB	Remote Ping MIB was implemented as defined in RFC 4560.
Remote Traceroute MIB	Remote Traceroute MIB was implemented as defined in RFC 4560.

## New Software Features in 08.0.80

The following software features and enhancements are introduced in this release.

Feature	Description
Reset CLI to factory default settings	The command triggers the factory reset action upon user accepting the reset warning message. Autocomplete is disabled for this CLI command to prevent accidental execution.
Show version for bootcode	The modified command output includes a message which warns you about any mismatch with the recommended u-boot version.
Unified FastIron Image (UFI) support	<p>A unified FastIron image (UFI), consisting of the application image, the boot code image, and the FI signature, can be downloaded in one file. From 08.0.80, it is possible to update all the necessary software components in a setup using one command.</p> <p>The UFI is recommended for all image upgrades.</p> <p>A stack can be upgraded using a UFI bundle, and all stack members are also upgraded.</p> <p>The manifest Image will use the UFI to upgrade images in future releases. The manifest image will continue to use application and boot image download to downgrade to images for releases earlier than 08.0.80. The CLI for UFI image downloads will be the same as the CLI for application image downloads, except the filenames will be different.</p>
Self-Authenticated Upgrade (SAU) licensing was implemented on all ICX7xxx platforms that run FastIron 08.0.80 or later releases.	SAU licensing, which allows a licensed feature set to be installed with a single command, was implemented for ICX 7250, ICX 7450, and ICX 7750 devices.
Ruckus SmartZone management of ICX switches	The enhancement introduces SmartZone management and monitoring of ICX switches. This initial release is the first step toward a full-featured wired/wireless integration plan and focuses on monitoring, status, usage visibility, and some basic management, including configuration backups and firmware management.
Remote Switched Port Analyzer (RSPAN)	RSPAN supports remote monitoring of multiple switches across a network. When RSPAN is enabled, a copy of each incoming or outgoing packet from one port on a network switch is forwarded to another port on the same switch where the packet can be analyzed. RSPAN can be used as a diagnostic tool for preventing network attacks. RSPAN is implemented only at the port level.
Change in default syslog buffer size	ICX devices support a local syslog buffer of up to 4,000 messages. The default value of dynamic syslog messages being logged is increased from 50 to 4,000.
HTTPS image download and configuration download/upload	HTTPS support is added for the following: <ul style="list-style-type: none"><li>• Image download to the flash over HTTPS.</li><li>• Downloading a configuration file from the HTTPS server to the startup configuration file.</li></ul>

	<ul style="list-style-type: none"> <li>Uploading a copy of the running configuration file or the startup configuration file from a FastIron device to an HTTPS server.</li> </ul>
Change to IPv4 ACL command	The <b>access-list</b> command has been deprecated. All instances of the <b>access-list</b> command have been replaced with the <b>ip access-list</b> command.
<b>no-login</b> keyword addition to the RADIUS server definition.	The keyword specifies that the RADIUS server cannot be used for login features such as TELNET, SSH, CONSOLE, EXEC, or Web-management AAA. The command allows you to designate one server for login and a different RADIUS server for NAC (including 802.1x, MAC, and Web authentication).
Flexible authentication enhancements	These Flexible authentication enhancements have been added: <ul style="list-style-type: none"> <li>Single host authentication</li> <li>Multiple host authentication</li> <li>Tagged VM client authentication</li> <li>Information on Ruckus Vendor-Specific Attributes for RADIUS</li> <li>MAC authentication support for the RADIUS user-name attribute</li> <li>New configuration commands, including <b>auth allow-tagged enable</b>, <b>auth auth-mode</b>, <b>auth-mode</b>, <b>dot1x macauth-override</b>, and <b>mac-authentication dot1x-disable</b>.</li> <li>New <b>show authentication</b> commands that integrate output for 802.1X and MAC authentication. and new commands for clearing authentication information: <b>clear authentication sessions</b> and <b>clear authentication statistics</b>.</li> </ul>
ICX 7650 devices as Control Bridge (CB) units	ICX 7650 devices can be configured as a CB stack or standalone in a Campus Fabric (SPX) system. A cost-effective alternative as CB units, ICX 7650 devices have functionality equivalent to ICX 7750 CB units.
Port Extender (PE) console authentication	The console on a PE unit in a Campus Fabric network, similar to stack member behavior, redirects to the active controller console and is authenticated using the active controller CB unit user name and password.
Reconfiguring a live Campus Fabric (SPX) LAG	The <b>no</b> versions of the <b>multi-spx-port</b> and <b>mutli-spx-lag</b> command are introduced to allow SPX links to be broken on a live system. This introduces the ability to break a PE ring other than by physically disconnecting it.
Increased VLANs per PE port	By default, four VLANs are reserved per PE port, and the number of allowable VLANs per PE port is 32. The <b>max-vlans-per-pe-port</b> command is used to change the allowed number of VLANs per PE port from the default. The <b>max-vlans-per-pe-port</b> command replaces the <b>max-vlan</b> (SPX) command from this release. The <b>show spx-pe-port-vlan-resources</b> command is introduced to check related settings and resources, and the current non-default setting is displayed in <b>show running-config</b> command output.
1-Gbps Campus Fabric (SPX) links	1-Gbps SPX links are supported between ICX 7650 or ICX 7750 devices serving as CB units and connected PE units in a Campus Fabric network.
ARP inspection scale enhancements	The maximum number of static ARP inspection entries that can be configured for the entire stack has increased to 42,000.
Manifest upgrade CLI	Router and switch image can be specified for download.
Manifest upgrade (DHCP)	DHCP auto-provisioning enhancements allow overriding default behavior where the DHCP client is forced to download the application image type based on the current version of the device. The application

New in This Release  
Software Features

	image type and the flash image location can be configured as part of option 67, along with the file name.
DHCP Snooping: enable/disable DHCP option 82 at a global level	DHCP Option 82 (also known as DHCP snooping relay information) can be enabled or disabled on a VLAN or globally for all VLANs.
DHCP snooping scale enhancements	The maximum number of DHCP snooping entries that can be configured for the entire stack has increased to 32,000.
Discovery of SZ based on DHCP Option 43	DHCP option 43 can be parsed so that the SmartZone (SZ) IP address from the vendor class identifier (VCI) is received from the DHCP server and by the DHCP client as part of its request packets.
IP Source Guard scale improvements/enhancements	The maximum number of IPSG clients per port has increased to 8,000.
VLAN range command changes	The following features can be enabled on multiple VLANs with a single command: <ul style="list-style-type: none"> <li>• DHCPv4 and DHCPv6 snooping</li> <li>• Dynamic ARP inspection</li> <li>• IP Source Guard</li> <li>• Neighbor Discovery inspection.</li> </ul>
"Dual-mode" CLI deprecation	An interface can be added as tagged in multiple VLANs and untagged in one VLAN. No additional CLI commands are added. The interface retains its untagged VLAN membership when added as a tagged interface in another VLAN. The user can add an interface to or remove an interface from the default VLAN as an untagged member.
Increase in default system max VLANs	The default system max VLANs is increased from 64 to 1024.
VLAN and VE pre-provisioning	The enhancement allows creation of VLANs and VEs without ports so that applications can configure any feature, even before ports are added to a VLAN or VE.
VLAN range Increase	The maximum number of VLANs you can create or configure with a range command is 1024.
VLAN Mapping	VLAN Mapping provides a mechanism for Service Providers to translate CVLANs to SVLANs when a packet enters or leaves the network.
IPv6 Neighbor Discovery (ND) options	The following ND options are added: <ul style="list-style-type: none"> <li>• Domain Name System Search List (DNSSL) is an IPv6 router advertisement option that allows IPv6 devices to advertise domain names of DNS suffixes to IPv6 hosts in a local area network.</li> <li>• Recursive DNS server addresses (RDNSS) is an IPv6 router advertisement feature that allows IPv6 devices to advertise recursive DNS server addresses and lifetime multiplier values to IPv6 hosts in a local area network.</li> <li>• IPv6 address advertisement suppression is an IPv6 router advertisement option that suppresses the advertisement of specified IPv6 addresses or all IPv6 addresses for router advertisement messages on an interface.</li> </ul>
Multiple Service VLAN (SVLAN) support	A maximum of 50 SVLANs can be configured on an interface for the Q-in-Q feature.
Bridge Protocol Data Unit (BPDU) scaling	Scaling is improved for BPDU tunneling for the Q-in-Q feature.
Link Aggregation Control Protocol (LACP) timeout change without LAG flap	LACP timeout and mode changes are achieved without LAG flap.
Validation of NAC features by Cloudpath 5.2	Cloudpath release 5.2 support validation of FastIron NAC features such as 802.1X authentication, MAC authentication, Web authentication, and CoA options.
Increased number of monitor ports	The enhancement increases to 20 the number of ports that can be monitored using port mirroring or RSPAN.

Enhancement of tab-based autocomplete

When entering characters for a command or keyword that match more than one entry, you can press the Tab key to fill in the entry up to the last matching character and then enter the next unique character of the desired command or keyword to complete the entry automatically.

## CLI Commands

The commands listed in this section were introduced, modified, or deprecated in FastIron 08.0.80.

### New Commands in 08.0.80e

No commands were introduced or modified in this release.

### New Commands in 08.0.80d

No commands were introduced or modified in this release.

### New Commands in 08.0.80ca

No commands were introduced or modified in this release.

### New Commands in 08.0.80c

The following commands were introduced in this release:

- **sz registrar**
- **sz registrar-list**
- **sz registrar-query-restart**

### New Commands in 08.0.80b

No commands were introduced or modified in this release.

### New Commands in 08.0.80a

No commands were introduced or modified in this release.

### New Commands in 08.0.80

The following commands were introduced in this release:

- **auth allow-tagged enable**
- **auth auth-mode**
- **auth-mode**
- **clear authentication sessions**

- **clear authentication statistics**
- **copy https flash**
- **copy https startup-config**
- **copy running-config https**
- **copy startup-config https**
- **dot1x macauth-override**
- **ip dhcp snooping relay information disable**
- **ipv6 nd ra-domain-name**
- **ipv6 nd ra-dns-server**
- **ipv6 nd suppress-ra address**
- **license delete perpetual**
- **license set serial-number**
- **mac-authentication dot1x-disable**
- **max-vlans-per-pe-port (SPX)**
- **rspan destination**
- **rspan source**
- **rspan-vlan**
- **show authentication acls**
- **show authentication configuration**
- **show authentication sessions**
- **show authentication statistics**
- **show boot-monitor**
- **show rspan-vlan**
- **show spx pe-port-vlan-resources**
- **show sz status**
- **sz active-list**
- **sz disconnect**
- **sz disable**
- **sz query**

## Modified Commands in 08.0.80c

The following command was modified in this release:

- **show sz status**

## Modified Commands in 08.0.80

The following commands were modified in this release:

- **authentication max-sessions**
- **copy scp flash**



- **copy tftp flash**
- **copy tftp system-manifest**
- **crypto key client generate**
- **crypto key generate**
- **ip arp inspection vlan**
- **ip dhcp snooping vlan**
- **ipv6 dhcp6 snooping vlan**
- **ipv6 neighbor inspection vlan**
- **license delete unit**
- **license install perpetual**
- **logging buffered**
- **radius-server host**
- **show chassis**
- **show ip dhcp-client options**
- **show ip dhcp-server address-pool**
- **show license**
- **show license installed**
- **show license node-locked**
- **show license non-node-locked**
- **show license unit**
- **show logging**
- **show running-config vlan**
- **show version**
- **source-guard enable**
- **system-max max-dhcp-snoop-entries**
- **system-max max-static-inspect-arp-entries**
- **tagged ethernet**

## Deprecated Commands in 08.0.80

The following commands were deprecated in this release:

- **access-list (standard numbered)**
- **access-list enable accounting**
- **access-list remark**
- **dual-mode [ VLAN-ID ]**
- **lldp-pass-through** (Flexible authentication)
- **max-vlan** (SPX)

## RFCs and Standards

The following sections list newly supported standards and RFCs.

### New Standards and RFCs in Release 08.0.80e

No new standards or RFCs are supported in FastIron Release 08.0.80e.

### New Standards and RFCs in Release 08.0.80d

No new standards or RFCs are supported in FastIron Release 08.0.80d.

### New Standards and RFCs in Release 08.0.80ca

No new standards or RFCs are supported in FastIron Release 08.0.80ca.

### New Standards and RFCs in Release 08.0.80c

No new standards or RFCs are supported in FastIron Release 08.0.80c.

### New Standards and RFCs in Release 08.0.80b

No new standards or RFCs are supported in FastIron Release 08.0.80b.

### New Standards and RFCs in Release 08.0.80a

- RFC 4560

### New Standards and RFCs in Release 08.0.80

No new standards or RFCs are supported in FastIron Release 08.0.80.

## MIBs

The following sections list newly supported MIBs.

### New MIBs in Release 08.0.80e

No new MIBs are supported in this release.

### New MIBs in Release 08.0.80d

No new MIBs are supported in this release.

## **New MIBs in Release 08.0.80ca**

No new MIBs are supported in this release.

## **New MIBs in Release 08.0.80c**

No new MIBs are supported in this release.

## **New MIBs in Release 08.0.80b**

No new MIBs are supported in this release.

## **New MIBs in Release 08.0.80a**

- Remote Ping MIB
- Remote Traceroute MIB

## **New MIBs in Release 08.0.80**

No new MIBs are supported in this release.



# Hardware Support

---

- Supported Devices..... 21
- Supported Power Supplies..... 21
- Supported Optics..... 21

## Supported Devices

The following devices are supported in FastIron 08.0.80:

- ICX 7150 Series (ICX 7150-C12P, ICX 7150-24, ICX 7150-24P, ICX 7150-48, ICX 7150 48P, ICX 7150-48PF, ICX 7150-48ZP)
- ICX 7250 Series (ICX 7250-24, ICX 7250-24G, ICX 7250-24P, ICX 7250-48, ICX 7250-48P)
- ICX 7450 Series (ICX 7450-24, ICX 7450-24P, ICX 7450-32ZP, ICX 7450-48, ICX 7450-48F, ICX 7450-48P)
- ICX 7650 Series (ICX 7650-48P, ICX 7650-48ZP, ICX 7650-48F)
- ICX 7750 Series (ICX 7750-26Q, ICX 7750-48C, ICX 7750-48F)

## Supported Power Supplies

For a list of supported power supplies, refer to the Data Sheet for your device. Data Sheets are available online at [www.ruckuswireless.com](http://www.ruckuswireless.com).

## Supported Optics

For a list of supported fiber-optic transceivers that are available from Ruckus, refer to the latest version of the Ruckus Ethernet Optics Family Data Sheet available online at [www.ruckuswireless.com/optics](http://www.ruckuswireless.com/optics).



# Software Upgrade and Downgrade

- Image File Names..... 23
- PoE Firmware Files..... 23
- Open Source and Third Party Code.....24

## Image File Names

Download the following images from [www.ruckuswireless.com](http://www.ruckuswireless.com).

Device	Boot image file name	Flash image file name
ICX 7150	mnz10114.bin	SPR08080e.bin/SPS08080e.bin
ICX 7250	spz101114.bin	SPR08080e.bin/SPS08080e.bin
ICX 7450	spz10114.bin	SPR08080e.bin/SPS08080e.bin
ICX 7650	tnu10114.bin	TNR08080e.bin/TNS08080e.bin
ICX 7750	swz10114.bin	SWR08080e.bin/SWS08080e.bin

## PoE Firmware Files

The following tables lists the PoE firmware file types supported in this release.

Device	Firmware version	File name
ICX 7150	2.1.0 fw	icx7xxx_poe_02.1.0.b002.fw
ICX 7250	2.1.0 fw	icx7xxx_poe_02.1.0.b002.fw
ICX 7450	2.1.0 fw	icx7xxx_poe_02.1.0.b002.fw
ICX 7650	2.1.0 fw	icx7xxx_poe_02.1.0.b002.fw

The firmware files are specific to their devices and are not interchangeable. For example, you cannot load ICX 7250 firmware on an ICX 7450 device.

**NOTE**

Please note the following recommendations and notices:

- Inline power is enabled by default as of FastIron release 08.0.70.
- As of FastIron release 08.0.70 **legacy-inline-power** configuration is disabled by default.
- Data link operation is decoupled from inline power by default as of FastIron release 08.0.70.
- The commands **no inline power** and **inline power** can be used to power cycle the PD.
- Data link operation is coupled with inline power using the command **inline power ethernet x/x/x couple-datalink** in Privileged EXEC mode or in interface configuration mode using the command **inline power couple-datalink**. The PoE behavior remains the same as in releases prior to 08.0.70 (08.0.30, 08.0.40, 08.0.50, 08.0.61).
- Do not downgrade PoE firmware from the factory installed version. When changing the PoE firmware, always check the current firmware version with the **show inline power detail** command, and make sure the firmware version you are installing is higher than the version currently running.
- The PoE circuitry includes a microcontroller pre-programmed at the factory. The software can be loaded as an external file. The initial release of the microcontroller code is still current and does not need to be upgraded. The PoE firmware version string will be kept updated to match the corresponding FastIron software version; however, this is only a cosmetic change, and the firmware itself remains unchanged. If a new version of the code is released, Ruckus Technical Support will notify its customers of the needed code upgrade. Finally, in the remote case that a failure occurs during an upgrade process, the switch would still be functional but without PoE circuitry. If you encounter such an issue, please contact Ruckus Technical Support.
- PoE firmware will auto upgrade to version 2.1.0 fw during the loading of FastIron Release 08.0.80. This auto upgrade of the PoE firmware will add approximately 10 minutes to the loading of FastIron Release 08.0.80 on ICX 7150, ICX 7250, ICX 7450, and ICX 7650 devices.

## Open Source and Third Party Code

Ruckus FastIron software contains or references the following third-party or open source software.

Manufacturer	Third Party Software
InMon	Sflow
Broadcom Inc	SDK 6.5.6
open source S/W	u-boot 2011.09
open source S/W	u-boot 2015.01
open source S/W	u-boot 2016.01
open source S/W	Linux 3.6.5
open source S/W	Linux 3.14
open source S/W	Linux 4.4
Aquantia Inc	Aquantia phy driver AQR API 2.1.0
Aquantia	Aquantia phy drivers: <ul style="list-style-type: none"> <li>• ICX7150: AQR 3.5.E</li> <li>• ICX7450: AQR 2.C.5</li> <li>• ICX7650: AQR 3.5.E</li> <li>• ICX7750: AQR 1.38.11</li> </ul>
open source S/W	Parted utility
Broadcom Inc	Miura Phy driver 1.5



Manufacturer	Third Party Software
Broadcom Inc	EPDM driver 1.5.1
Spansion	Flash driver
<a href="http://www.bzip.org/">http://www.bzip.org/</a>	Bzip
<a href="http://www.hackersdelight.org/">http://www.hackersdelight.org/</a>	Integer square root computation
GNU ( <a href="http://www.gnu.org/">http://www.gnu.org/</a> )	LZMA SDK (compression method)
Freescale (NXP)	Software for PowerPC chip
Open Source SW	openssl_tpm_engine-0.4.2
Open Source SW	tpm-tools-1.3.8
Open Source SW	trousers-0.3.11.2
Infineon Technologies AG	ELTT_v1.3
Allegro Software	HTTP/HTTP-S, SSHv2
WindRiver	SNMPv1,v2c,v3; IPSecure
Interlink	Radius
SafeNet Sentinel RMS	Software Licensing Code - SafeNet Sentinel RMS
open source S/W	NSS 3.12.4 with NSPR 4.8
open source S/W	OpenSSL FIPS Object Module v2.0.5
open source S/W	OpenSSL crypto Ver 1.0.1e
GubuSoft	Javascript based tree display
GubuSoft	Javascript based tree display
GNU (The Regents of the University of California)	Syslog
BSD(The Regents of the University of California)	DNS Query/Resolution
BSD(The Regents of the University of California)	TimeZone Code (SNTP)
BSD(The Regents of the University of California)	Router Renumbering
BSD(The Regents of the University of California)	IPv6 defines
RouterWare Inc	TCP/IP stack, IPX, OSPFv2, TELNET, STP, LSL, TFTP client, BOOTP client and relay
IP Infusion	RIPng, OSPFv3, BGP4
Github	AVL Tree



# Issues

- Closed in Release 08.0.80e..... 27
- Closed with Code Change in Release 08.0.80d..... 34
- Known Issues in Release 08.0.80ca..... 36
- Closed with Code Changes in Release 08.0.80b..... 36
- Known Issues in Release 08.0.80b..... 37
- Closed with Code Changes in Release 08.0.80..... 38
- Known Issues in Release 08.0.80..... 58

## Closed in Release 08.0.80e

<b>Issue</b>	FI-190996
<b>Symptom</b>	On a ICX 7650-48f stack, the standby/member deleted itself from the stack and then reloaded. After reboot the module gets struck in continuous boot loop.
<b>Condition</b>	On a ICX7650-48f stack, when configure "speed-duplex 1000-full" in interface range mode for standby/member, the module struck for some time and then reloaded.
<b>Workaround</b>	Configure the "speed-duplex 1000-full" in a smaller range of interfaces.
<b>Recovery</b>	Remove "speed-duplex 1000-full" configuration in standby/member and Configure the "speed-duplex 1000-full" in a smaller range of interfaces.
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	System - System

<b>Issue</b>	FI-187743
<b>Symptom</b>	When one of the power supplies is removed from a running system, the switch may reboot unexpectedly.
<b>Condition</b>	The system reboots when one of power supplies is removed.
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	System - System

<b>Issue</b>	FI-191375
<b>Symptom</b>	Openflow controller does not communicate to ICX on management VRF
<b>Condition</b>	On ICX devices, enabling VRF on management interface does not communicate with openflow controller.
<b>Workaround</b>	No
<b>Recovery</b>	NA
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70 FI 08.0.80
<b>Technology / Technology Group</b>	SDN - OpenFlow 1.3

Issues

Closed in Release 08.0.80e

<b>Issue</b>	FI-196670
<b>Symptom</b>	Unexpected device reload while forming SPX chains using ZTP.
<b>Condition</b>	SPX chain formation using ZTP with ICX7650 as CB and ICX7450,ICX7150 as PE's
<b>Workaround</b>	NA
<b>Recovery</b>	NA
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.90 FI 08.0.91
<b>Technology / Technology Group</b>	Stacking - Mixed Stacking

<b>Issue</b>	FI-186638
<b>Symptom</b>	When SNMP walk is done for lldpRemPortId in the Extreme switch, the output is HEX string for the interface name instead of text string.
<b>Condition</b>	When lldpRemPortId sub-type is configured as the value 5 (interfaceName) in ICX device and connected to the Extreme switch, the SNMP walk run in the Extreme side gives HEX string value for the interface.
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Management - SNMP - Simple Network Management Protocol

<b>Issue</b>	FI-188972
<b>Symptom</b>	One ARP-HIPR Filter might miss in the PCL table
<b>Condition</b>	1. Configure BUM limit in all the interfaces to exhaust the L2 filters. 2. After reload the ARP-HIPR rule will miss in the standby PCL Table.
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	Security - ACLs - Access Control Lists

<b>Issue</b>	FI-191475
<b>Symptom</b>	"show inline power" shows wrong ports as powered. Some PDs might not even power.
<b>Condition</b>	PoE power would be impacted on some of the ports
<b>Workaround</b>	None
<b>Recovery</b>	Upgrade to latest patch
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-189830
<b>Symptom</b>	Increased UFI image of size > 62MB failed tftp copy. Support for larger image has been added

<b>Issue</b>	FI-189830
<b>Condition</b>	copy tftp flash <tftp-server-ip> <image-path> primary/secondary
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.90
<b>Technology / Technology Group</b>	Management - CLI - Command Line Interface

<b>Issue</b>	FI-191297
<b>Symptom</b>	Increased UFI image of size > 62MB failed tftp copy to stack units. Support for larger image has been added
<b>Condition</b>	copy tftp flash <tftp-server-ip> <image-path> primary/secondary
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.90
<b>Technology / Technology Group</b>	Management - CLI - Command Line Interface

<b>Issue</b>	FI-191471
<b>Symptom</b>	Device status is not descriptive in "show inline power detail debug-info"
<b>Condition</b>	Better debug-ability. Added descriptive device status information in "show inline power detail debug-info" output. With this information, if the device status says "Failed" or "Lost", the unit can be RMAed.
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-195159
<b>Symptom</b>	Sometimes ICX device is not allowing to connect incoming SSH sessions.
<b>Condition</b>	When large number of SSH connections happening to ICX device, sometimes SSH to ICX device fails.
<b>Workaround</b>	Clear the ssh sessions using kill command.
<b>Recovery</b>	
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	Management - SSH2 and SCP - Secure Shell and Copy

<b>Issue</b>	FI-190396
<b>Symptom</b>	Failure in firmware upgrade via https
<b>Condition</b>	Image upgrade will fail when copy is performed via https. using the command copy https flash <ip> <filename>
<b>Workaround</b>	None

Issues

Closed in Release 08.0.80e

<b>Issue</b>	FI-190396
<b>Recovery</b>	None
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.90
<b>Technology / Technology Group</b>	Cloud Management - Cloud Agent

<b>Issue</b>	FI-194684
<b>Symptom</b>	During scp copy of image, parallel copies corrupted the boot image.
<b>Condition</b>	copy scp flash <ip> <image-path> primary / secondary along with copy through multiple interfaces: console, mgmt, ssh
<b>Workaround</b>	Single copy at a time
<b>Recovery</b>	re-copy
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.90
<b>Technology / Technology Group</b>	Management - SSH2 and SCP - Secure Shell and Copy

<b>Issue</b>	FI-184698
<b>Symptom</b>	Running configuration file is getting truncated while copying using scp.
<b>Condition</b>	Perform copy running-config scp <ip-addr> running.txt
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.30
<b>Technology / Technology Group</b>	Management - SSH2 and SCP - Secure Shell and Copy

<b>Issue</b>	FI-195770
<b>Symptom</b>	Ipsec tunnel configuration is not allowed with L3-base License.
<b>Condition</b>	Should have I3-base license and trying to configure IPsec.
<b>Workaround</b>	N/A
<b>Recovery</b>	N/A
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	Security - IPsec - IP Security

<b>Issue</b>	FI-185696
<b>Symptom</b>	In untagged VLAN open flow hybrid port for unprotected VLAN, a flow with out VLAN id gets added though its not supported.
<b>Condition</b>	When VLAN is configured as protected , the flow without VLAN id is accepted and installed . When the port is turned to unprotected, previously installed flow still persists.
<b>Workaround</b>	VLAN should not be changed from protected to unprotected mode when flow without VLAN id is configured .
<b>Recovery</b>	NA
<b>Probability</b>	

<b>Issue</b>	FI-185696
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	SDN - OpenFlow 1.3

<b>Issue</b>	FI-191763
<b>Symptom</b>	Increased UFI image of size > 62MB failed tftp copy. Support for larger image has been added
<b>Condition</b>	copy tftp flash <tftp-server-ip> <image-path> primary/secondary will fail if the image size is greater than 62MB
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.80 FI 08.0.90
<b>Technology / Technology Group</b>	Management - CLI - Command Line Interface

<b>Issue</b>	FI-193916
<b>Symptom</b>	On ICX device, ssh session hangs sometimes without displaying prompt.
<b>Condition</b>	Sometimes ssh login might hang after the initial password entry.
<b>Workaround</b>	Retry the ssh login, and it'll succeed.
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	Management - SSH2 and SCP - Secure Shell and Copy

<b>Issue</b>	FI-191344
<b>Symptom</b>	"ip ospf md5-authentication" deprecated command configuration is not getting replaced by "ip ospf authentication md5 " for tunnel interface after upgrade to 8070.
<b>Condition</b>	"ip ospf md5-authentication" command configured on tunnel interface with ICX code version below 8070. Upgrade to 8070 and the configuration will not be displayed in the running-config and lost.
<b>Workaround</b>	NA
<b>Recovery</b>	NA
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	Layer 3 Routing/Network Layer - OSPF - IPv4 Open Shortest Path First

<b>Issue</b>	FI-186384
<b>Symptom</b>	High CPU utilization or CPU spike.
<b>Condition</b>	FDP enabled on a scaled 802.1BR setup with over 2200 ports.
<b>Workaround</b>	None
<b>Recovery</b>	Disabling CDP will reduce the CPU spike
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	Management - FDP - Foundry Discovery Protocol

Issues

Closed in Release 08.0.80e

<b>Issue</b>	FI-193199
<b>Symptom</b>	Removing a sequence from a ACL and reapplying doesn't work as expected.
<b>Condition</b>	Issue is seen only when ACL has multiple sequences. The sequence which is removed and re-added should be before a deny rule for the issue to occur.
<b>Workaround</b>	Remove and re-add entire ACL resolve's the issue.
<b>Recovery</b>	Remove and re-add entire ACL recover's the issue.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	Security - ACLs - Access Control Lists

<b>Issue</b>	FI-187465
<b>Symptom</b>	When PBR used in network, trace-route from a host report the packet taking default route rather than PBR route.
<b>Condition</b>	PBR is configured on the network.
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.30
<b>Technology / Technology Group</b>	Security - PBR - Policy-Based Routing

<b>Issue</b>	FI-102190
<b>Symptom</b>	High CPU utilization due to UDP traffic destined for port 520 forwarded to CPU.
<b>Condition</b>	UDP traffic with destination port as 520.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	Medium
<b>Found In</b>	
<b>Technology / Technology Group</b>	Layer 3 Routing/Network Layer - RIP - IPv4 Routing Information Protocol

<b>Issue</b>	FI-197232
<b>Symptom</b>	Latest PoE FW file is not available for manual upgrade.
<b>Condition</b>	Latest PoE FW file is not packaged.
<b>Workaround</b>	Get the file from TAC
<b>Recovery</b>	No recovery is required, FW auto upgrade is already updating the FW to latest.
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-193742
<b>Symptom</b>	Text "Failed to create task object for task TELNET_INCSES_1" will be displayed on session terminal. There is no functionality impact.
<b>Condition</b>	When NMAP port scanner script run to scan the TCP ports in ICX device. (Example: "nmap -A -v X.X.X.X" )
<b>Workaround</b>	Stop the NMAP Port scanner.



<b>Issue</b>	FI-193742
<b>Recovery</b>	Not applicable. No Recovery Needed. There will not be any change in the device state.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.90
<b>Technology / Technology Group</b>	Management - SSH2 and SCP - Secure Shell and Copy

<b>Issue</b>	FI-193047
<b>Symptom</b>	The session timeout received in access challenge packet is retained even after successful MAC-authentication/802.1x-authentication.
<b>Condition</b>	MAC/802.1x authentication is enabled on the interface.RADIUS server sends session timeout in access-challenge packet.
<b>Workaround</b>	No
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Security - 802.1x Port-based Authentication

<b>Issue</b>	FI-189679
<b>Symptom</b>	"show chassis" CLI command output displays incorrect fan speed for standby and member units having single fan in their chassis.
<b>Condition</b>	verify "show chassis" output of a stack unit with non-active units having single fan in their chassis.
<b>Workaround</b>	NA
<b>Recovery</b>	NA
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	System - System

<b>Issue</b>	FI-195163
<b>Symptom</b>	Stack system's Active Unit might reload while establishing SSH Inbound session.
<b>Condition</b>	unexpected reload will be observed during SSH login to ICX box when the ICX box connecting and disconnecting to SZ (SmartZone) IP Addresss continuously.
<b>Workaround</b>	Device can be access via Telnet sessions
<b>Recovery</b>	Device will reboot
<b>Probability</b>	
<b>Found In</b>	FI 08.0.90
<b>Technology / Technology Group</b>	Management - SSH2 and SCP - Secure Shell and Copy

<b>Issue</b>	FI-196466
<b>Symptom</b>	Private vlan port is allowed to configure in regular vlan and viceversa.
<b>Condition</b>	Customer should have pvlan and regular vlans configured.
<b>Workaround</b>	N/A
<b>Recovery</b>	N/A

## Issues

Closed with Code Change in Release 08.0.80d

<b>Issue</b>	FI-196466
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	Security

<b>Issue</b>	FI-188469
<b>Symptom</b>	CVE-2018-5390 - Linux kernel versions 4.9+ can be forced to make very expensive calls to tcp_collapse_ofo_queue() and tcp_prune_ofo_queue() for every incoming packet which can lead to a denial of service. CVE-2018-5391 - The Linux kernel, versions 3.9+, is vulnerable to a denial of service attack with low rates of specially modified packets targeting IP fragment re-assembly. An attacker may cause a denial of service condition by sending specially crafted IP fragments. Various vulnerabilities in IP fragmentation have been discovered and fixed over the years. The current vulnerability (CVE-2018-5391) became exploitable in the Linux kernel with the increase of the IP fragment reassembly queue size.
<b>Condition</b>	By sending specially crafted TCP packets within existing two-way TCP sessions.
<b>Workaround</b>	NA
<b>Recovery</b>	NA
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.70 FI 08.0.61 FI 08.0.40 FI 08.0.30 FI 08.0.80 FI 08.0.90
<b>Technology / Technology Group</b>	Security - Security Vulnerability

## Closed with Code Change in Release 08.0.80d

This section lists software issues that were closed with code changes with Critical, High, and Medium Technical Severity in FastIron release 08.0.80d.

<b>Issue</b>	FI-181579
<b>Symptom</b>	RADIUS Accounting request for user login does not have user-name attribute.
<b>Condition</b>	Accounting feature with RADIUS method is enabled for user login.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Security - RADIUS

<b>Issue</b>	FI-186762
<b>Symptom</b>	On snmp walk , ifNumber object would display wrong value
<b>Condition</b>	1. Configure snmp server 2. Do snmp walk for the object IF-MIB::ifNumber.0 3. On snmp walk , ifNumber object would display wrong value
<b>Workaround</b>	NA
<b>Recovery</b>	NA
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.70 FI 08.0.61
<b>Technology / Technology Group</b>	Management - SNMP - Simple Network Management Protocol

<b>Issue</b>	FI-192117
<b>Symptom</b>	Code upgrade from SZ fails when 'enable telnet authentication' and TACACS+ are used together.
<b>Condition</b>	The issue is seen only when 'enable telnet authentication' and TACACS+ are used together.
<b>Workaround</b>	None
<b>Recovery</b>	Disable telnet authentication as a workaround
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	Cloud Management - Switch Registrar/Tunnel Aggregator

<b>Issue</b>	FI-190300
<b>Symptom</b>	BGP neighbor up-time is quicker than system uptime .
<b>Condition</b>	When BGP is enabled BGP neighbor time is quicker than system time .
<b>Workaround</b>	N/A
<b>Recovery</b>	N/A
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Layer 3 Routing/Network Layer - BGP4 - IPv4 Border Gateway Protocol

<b>Issue</b>	FI-190019
<b>Symptom</b>	Panasonic KX-NT560 model of phone is not getting IP address.
<b>Condition</b>	When Panasonic KX-NT560 model of ip phone is connected to the ICX DHCP Server, the phone will not get the IP address assigned.
<b>Workaround</b>	N/A
<b>Recovery</b>	
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	Management - DHCP (IPv4)

## Issues

### Known Issues in Release 08.0.80ca

<b>Issue</b>	FI-190835
<b>Symptom</b>	Spurious syslog messages similar to the ones below are seen Oct 8 17:22:53:!:System: SSL server 192.168.11.1:443 is disconnected Oct 8 17:22:53:!:System: SSL server 192.168.11.1:443 is now connected
<b>Condition</b>	Only seen in FI 08.0.80c
<b>Workaround</b>	The command "no sz registrar" when applied as below will stop the messages Router#conf t Router(config)#no sz registrar
<b>Recovery</b>	None
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	Cloud Management - Switch Registrar/Tunnel Aggregator

## Known Issues in Release 08.0.80ca

This section lists known software issues with Critical, High, and Medium Technical Severity in FastIron release 08.0.80ca.

<b>Issue</b>	
<b>Symptom</b>	Spurious syslog messages similar to the ones below are seen Oct 8 17:22:53:!:System: SSL server 192.168.11.1:443 is disconnected Oct 8 17:22:53:!:System: SSL server 192.168.11.1:443 is now connected
<b>Condition</b>	Only seen in FI 08.0.80c
<b>Workaround</b>	The command "no sz registrar" when applied as below will stop the messages Router#conf t Router(config)#no sz registrar
<b>Recovery</b>	None
<b>Probability</b>	High
<b>Found In</b>	
<b>Technology / Technology Group</b>	Cloud Management - Switch Registrar/Tunnel Aggregator

## Closed with Code Changes in Release 08.0.80b

This section lists software issues with Critical, High, and Medium Technical Severity closed with a code change in FastIron release 08.0.80b.

<b>Issue</b>	FI-188985
<b>Symptom</b>	On a reload, the ICX device loses configuration for some applications. So, the configuration will not take effect in those applications.
<b>Condition</b>	This happens when the ICX device reloads when its configuration has Management VLAN along with other applications' configuration.
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	08.0.80
<b>Technology / Technology Group</b>	

## Known Issues in Release 08.0.80b

This section lists known software issues with Critical, High, and Medium Technical Severity in FastIron release 08.0.80ab.

<b>Issue</b>	FI-188546
<b>Symptom</b>	On an ICX stack or ICX SPX stack having more than one named ACLs configured or a security feature (e.g. DHCP Snooping, IP Source Guard, RA Guard etc) configured, performing a software upgrade using ISSU feature may result in either a crash during ISSU or unpredictable behavior after the ISSU is complete.
<b>Condition</b>	More than one named ACLs configured or a security feature (e.g. DHCP Snooping, IP Source Guard, RA Guard etc) configured
<b>Workaround</b>	A non-ISSU based upgrade can be used to perform software upgrade.
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	08.0.80
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-188203
<b>Symptom</b>	When either of Dynamic ARP Inspection, IPv6 Neighbor Discover Inspection and Router Advertisement Guard features are enabled on VLAN and the VLAN has ports of PE which is connected to standby unit, Upon reload of the standby unit the respective security features will not work over these ports.
<b>Condition</b>	Configure either of Dynamic ARP Inspection, IPv6 Neighbor Discover Inspection and Router Advertisement Guard features on a VLAN and the VLAN has ports of PE which is connected to standby unit and either the SPX reload or the standby reload or stack failover happens.
<b>Workaround</b>	None.
<b>Recovery</b>	Unconfiguring followed by re-configuring of the respective feature from the VLAN will allow the feature to work. Alternate recovery mechanism is to remove and re-add the respective PE's ports from the vlans on which the respective feature is enabled.
<b>Probability</b>	
<b>Found In</b>	08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-188172
<b>Symptom</b>	In SPX ring topology when either of DHCP v4/v6 snooping, Dynamic ARP Inspection, IPv6 Neighbor Discover Inspection and Router Advertisement Guard features are enabled on VLAN and path of the PE unit to CB unit changes because of logical block movement, these features may not work for this particular PE unit. Similarly after the logical block movement, when these features are disabled on a VLAN they may continue to work.
<b>Condition</b>	In SPX ring topology when there is a logical block movement.
<b>Workaround</b>	None.
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	08.0.70
<b>Technology / Technology Group</b>	

## Issues

Closed with Code Changes in Release 08.0.80

<b>Issue</b>	FI-187872
<b>Symptom</b>	When the DHCP Clients are connected via PE which is connected to Standby Unit and when the standby unit goes for reload, the dhcp snooping will fail and the snooping database will not be populated for all those clients which are connected to this PE which is connected to standby unit.
<b>Condition</b>	Configure the DHCP snooping on a VLAN and the VLAN has ports of PE which is connected to standby unit and either the SPX reload or the standby reload or stack failover happens.
<b>Workaround</b>	None.
<b>Recovery</b>	Unconfiguring followed by re-configuring of DHCP snooping from the VLAN will allow the DHCP snooping entries to be populated in the snooping database for all those clients which are connected to standby unit via PE. Alternate recovery mechanism is to remove and re-add the respective PE's ports from the vlans on which DHCP snooping is enabled.
<b>Probability</b>	
<b>Found In</b>	08.0.70
<b>Technology / Technology Group</b>	

## Closed with Code Changes in Release 08.0.80

This section lists software issues with Critical, High, and Medium Technical Severity closed with a code change in release 08.0.80.

<b>Issue</b>	FI-185991
<b>Symptom</b>	'Broadcast limit', 'multicast limit' and 'unknown-unicast limit' configurations are accepted on PE ports but they do not work.
<b>Condition</b>	'Broadcast limit', 'multicast limit' or 'unknown-unicast limit' are configured on PE port.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-185997
<b>Symptom</b>	Command link-error-disable doesn't work on lag ports
<b>Condition</b>	"link-error-disable " doesn't work on a lag port .
<b>Workaround</b>	N/A
<b>Recovery</b>	N/A
<b>Probability</b>	High
<b>Found In</b>	
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-186388
<b>Symptom</b>	After active unit resets and it comes back up and becomes active again, IPv4 routed traffic ingress on standby unit's ports are trapped to active CPU instead of hardware forwarding causing high CPU on active.
<b>Condition</b>	During Active/Standby synchronization of ARP/IP Cache table if switchover happens during that time the problem could be seen, thus it a corner case timing problem. It could happens with the following conditions: 1: the setup is scaled SPX or Stacking setup, (seen on SPX with 29 PE) 2: Active unit has higher priority than standby unit 3: arp table and ip cache table size is more than 1000, 4: Active unit Resets and comes back up and it automatically switch-over to active.
<b>Workaround</b>	Reduce the Priority of Active to be same as Standby, and if required after active resets and comes back up as Standby. Wait till on new Active message "[L3 UCAST HITLESS FAILOVER]: IPv4 Unicast hitless failover completed" is printed, then do switch over manually to make Standby becomes Active again.
<b>Recovery</b>	In the problem state "clear arp" on active unit can solve the issue and traffic will do hardware forwarding after re-learning of ARP.
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	Layer 3 Routing/Network Layer - ARP - Address Resolution Protocol

<b>Issue</b>	FI-181850
<b>Symptom</b>	When there are multiple ip subnets configured on the interface, the DHCP Server might not offer the IP address from the subnet of the secondary ip addresses.
<b>Condition</b>	Configure a DHCP server with multi-subnet VE
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-182608
<b>Symptom</b>	ICX device might unexpectedly reload when the last port is removed from a LAG
<b>Condition</b>	Remove the last port from the LAG
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	

## Issues

Closed with Code Changes in Release 08.0.80

<b>Issue</b>	FI-183943
<b>Symptom</b>	Authentication, Authorization and Accounting of login feature like telnet, SSH, EXEC stops working after few login and logouts.
<b>Condition</b>	AAA is enabled for login features like telnet, SSH and EXEC.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.30
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-184063
<b>Symptom</b>	A traceroute command to a destination succeeds but does not return the prompt (except ctrl-c ) after completion.
<b>Condition</b>	After execution of traceroute command, it has to send ITC response notification to SSH module to release the prompt, but it sent to SNMS module. So, user needs to hit Ctrl+C to come out of the prompt.
<b>Workaround</b>	User can hit Ctrl+C to come out of the prompt.
<b>Recovery</b>	
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-184066
<b>Symptom</b>	When IP ACL and DSCP remark commands are configured on an interface, after reload, traffic is blocked by the interface.
<b>Condition</b>	IP-ACL and DSCP remark commands are configured on an ve interface then traffic is blocked after reload due to wrong programming.
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-185032
<b>Symptom</b>	While processing HTTPS, SSH, requests, occasionally system reloads due to memory leak.
<b>Condition</b>	Memory leak issue is observed while handling HTTPS, SSH requests.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.30
<b>Technology / Technology Group</b>	



<b>Issue</b>	FI-179167
<b>Symptom</b>	Sometime the Bosch camera which is a POE PD devcie does not get powered up after connecting it to ICX7150 stacking standby unit and reloading the stack. This issue happens very rarely and it is a corner case. In this case the port state mismatch is observed between stacking Active and the Standby where the Active shows port status as Down and Standby port status is shown as Up
<b>Condition</b>	This issue happens in a very rare case when Bosch camera PD device is connected to the ICX7150 POE port on the stacking standby unit afer the stack reload is performed
<b>Workaround</b>	None
<b>Recovery</b>	Recovery procedure is to reload the particular stacking unit or the entire stack
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-186125
<b>Symptom</b>	PC/Webauth Client does not get the DHCP IP address
<b>Condition</b>	When the uplink port is in standby/member unit of an ICX stack and it is member of a Vlan. And Admin has configured Webauth on the same vlan but has not enabled Webauth
<b>Workaround</b>	Enable Webauth and configure the uplink port as trust port
<b>Recovery</b>	Enable Webauth and configure the uplink port as trust port
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-185930
<b>Symptom</b>	IP Multicast packets with TTL=1 will hit CPU when IGMP Snooping or IPv4 PIM routing or IPv6 PIM routing is enabled.
<b>Condition</b>	IP Multicast packets with TTL=1 will hit CPU in following conditions 1. When IGMP snooping is enabled on those VLANs 2. When PIM routing is enabled on those network interfaces.
<b>Workaround</b>	If possible, increase the TTL value of the multicast stream at the source
<b>Recovery</b>	If possible, increase the TTL value of the multicast stream at the source
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	

## Issues

Closed with Code Changes in Release 08.0.80

<b>Issue</b>	FI-185913
<b>Symptom</b>	Under rare circumstances, when a stack switch-over is performed, the unit transitioning from active role to standby role crashes and boots back up.
<b>Condition</b>	FlexAuth is enabled and active on the system, and FlexAuth sessions are learned on ports across many Stacking and SPX units.
<b>Workaround</b>	None
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-185058
<b>Symptom</b>	CISCO catalyst device unable to discover ICX device in show lldp neighbor output when port-id-subtype 5 (ifName) configured on ICX.
<b>Condition</b>	1. lldp run on both CISCO and ICX 2. configure lldp advertise port-id-subtype 5 ports eth all on ICX side 3. show lldp neighbor on CISCO catalyst will not show ICX , neighbor discovery does not happen
<b>Workaround</b>	NA
<b>Recovery</b>	NA
<b>Probability</b>	
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Management - SNMP - Simple Network Management Protocol

<b>Issue</b>	FI-184089
<b>Symptom</b>	Switch reloads on executing a batch buffer script on a stack setup.
<b>Condition</b>	A reload is triggered by executing a batch buffer script on a stack setup when the script execution leaves the CLI prompt in any mode other than PRIVILEGED EXEC mode
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	Management - CLI - Command Line Interface

<b>Issue</b>	FI-183580
<b>Symptom</b>	1G link is marked down when connected to a fiber port on 4x10G module of ICX7150-24P, with speed-duplex 1000-full configured on ICX7150-48ZP
<b>Condition</b>	1. ICX7150-48ZP connected to ICX7150-24P with speed configured to 1G. 2. Removal and insertion of 1G SFP on ICX7150-24P side makes the port down on ICX7150-24P side
<b>Workaround</b>	enable and disable of ICX7150-24P port brings the link up
<b>Recovery</b>	NA
<b>Probability</b>	
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Other - Other

<b>Issue</b>	FI-183100
<b>Symptom</b>	System resets rarely while connecting third party network monitoring tool with ICX device.
<b>Condition</b>	More number of HTTP, HTTPS, SSL requests polling the web management module, leads to system reset.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-109837
<b>Symptom</b>	SSH configuration with ACLs on the SSH access group is not working.
<b>Condition</b>	1. Change ssh port number: ip ssh port <xxx> 2. Configure access list: access-list <y> permit any 3. Configure access list on ssh: ssh access-group <y> 4. wr mem and reload
<b>Workaround</b>	
<b>Recovery</b>	None
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.30
<b>Technology / Technology Group</b>	Management - Configuration Fundamentals

<b>Issue</b>	FI-181239
<b>Symptom</b>	DHCP clients such as SONOS speakers, Ring cameras, EcoBee3 devices are not getting IP address from ICX.
<b>Condition</b>	When ICX device is used as DHCP server, the DHCP clients such as SONOS speakers, Ring cameras, EcoBee3 are not able to get IP address.
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Management - DHCP (IPv4)

<b>Issue</b>	FI-184735
<b>Symptom</b>	A software reset occurs on the mentioned condition
<b>Condition</b>	An SPX solution with DHCP snooping configured on ports of PE which is connected to standby and has a high scale of DHCP clients being updated simultaneously results in this software defect. This defect is intermittent and could happen in 1 out of 5 times when such a condition exists.
<b>Workaround</b>	
<b>Recovery</b>	Reload the Ruckus ICX Switch/Router and remove the DHCP configuration from the device.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	

## Issues

Closed with Code Changes in Release 08.0.80

<b>Issue</b>	FI-182302
<b>Symptom</b>	Although destination MAC address is correctly learned, traffic is getting flooded out on multiple ports.
<b>Condition</b>	When the stacking port goes down, ACL unbind is called where the port bit mask is updated for all the rules on that port.
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-180143
<b>Symptom</b>	Unexpected reload seen in ICX stack of 1 unit
<b>Condition</b>	On ICX devices while trying to print buffer in console, reload occurs due to negative length value.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.30
<b>Technology / Technology Group</b>	Management

<b>Issue</b>	FI-181683
<b>Symptom</b>	When support save all (display or tftp) command is executed, CPU spikes to 99% and data traffic is dropped
<b>Condition</b>	On ICX7XXX devices, supportsave all display command is triggered when flexauth dot1x is enabled.
<b>Workaround</b>	removing flexauth config will not create any issue in supportsave display. But this is not possible workaround for all customers.
<b>Recovery</b>	
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Management - Configuration Fundamentals

<b>Issue</b>	FI-182196
<b>Symptom</b>	When MAC-Auth succeeds and returns U:x, T:y, 2 sessions are opened with one each for Untagged and tagged VLANs (the trigger is sending tagged packets from client). Later when VLAN movement happens for updating the untagged session, the tagged VLAN session also gets updated with untagged VLAN. On subsequent receipt of tagged packets from same client, another tagged session gets created (duplicate).
<b>Condition</b>	Any MAC Authentication time
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	Security - MAC Port-based Authentication

<b>Issue</b>	FI-182899
<b>Symptom</b>	Security vulnerability in web server due to a script.
<b>Condition</b>	Security vulnerability in web server due to a script.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.30
<b>Technology / Technology Group</b>	Security - Security Vulnerability

<b>Issue</b>	FI-183753
<b>Symptom</b>	When reauth period and session timeout sent from RADIUS server are same values (which is generally not same, as reauth-period tend to be high and session-timeout small), 2 reauth attempts are made for the session which triggers the reauth failure from RADIUS client on the switch.
<b>Condition</b>	Reauth time
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	Security - MAC Port-based Authentication

<b>Issue</b>	FI-184384
<b>Symptom</b>	In FIPS-CC mode, Secure logging / Secure radius server connection establishment would fail
<b>Condition</b>	When device uses chain of certificates for OSCP validation to establish secure logging/secure radius server connection in FIPS-CC mode.
<b>Workaround</b>	Use single certificate for OSCP validation instead of chain of certificates or Remove OSCP validation For example, Below configuration has to be removed ocspp http post revocation-check ocspp ocspp-url http://10.176.166.18:2556
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	Management - AAA

## Issues

Closed with Code Changes in Release 08.0.80

<b>Issue</b>	FI-183964
<b>Symptom</b>	When 802.1X enable flag is changed from 0 to 1 during reauthentication, the session gets cleared on the local units where the session are originated from. As the control is changed from MAC-Auth to 802.1X, the session removal on the ACTIVE unit doesn't happen, which leaves the session entry. When subsequent packets hit the ACTIVE unit for MAC-Auth, as the session exists, authentication is not performed and MAC is learnt in the FDB tables.
<b>Condition</b>	Reauth time
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	Security - 802.1x Port-based Authentication

<b>Issue</b>	FI-184269
<b>Symptom</b>	Traffic drop due to CCEP gets blocked
<b>Condition</b>	Traffic drop for CCEP ingress traffic that belongs to a VLAN not running any L2 control protocols in a MCT switch.
<b>Workaround</b>	Reload the MCT switch
<b>Recovery</b>	Reload the MCT switch.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-181825
<b>Symptom</b>	Continuous reload seen when adding a new unit to the stack.
<b>Condition</b>	1."urpf" configured on the stack with "system-max ip-route/system-max ip6-route" set to a non-default value on the stack. 2.New unit with no running config is added to the stack. 3.New unit gets into continuous reload.
<b>Workaround</b>	NA
<b>Recovery</b>	
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Stacking - Secure Setup, Autoconfig, Manifest files, Autocopy

<b>Issue</b>	FI-184093
<b>Symptom</b>	when user remove the vxlan overlay gateway configuration with "no overlay gateway" command, "mem L2X field VFI value does not fit" could be seen on any of active/standby/member units.
<b>Condition</b>	Vxlan configuration is scaled configuration with 256 vlan-vni mapping and 32 remote sites configured. And all 256 vlan are extended in every remote site. With this scale configuration when we execute "no overlay gateway" command the error/warning message could be seen.
<b>Workaround</b>	Workaround is to delete vxlan configuration by deleting remote sites and vlan-vni mapping separately, instead of deleting all configuration with single command "no overlay gateway".
<b>Recovery</b>	N/A
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-184047
<b>Symptom</b>	System crash while freeing the mac entry.
<b>Condition</b>	System configured with overlay-gateway configuration. And LAG is part of VNI mapped VLAN & some MACs are on that LAG interface. And then while deleting the LAG interface, user may see the crash.
<b>Workaround</b>	Before deleting the LAG interface, perform "clear mac" on LAG interface and then delete LAG interface.
<b>Recovery</b>	Reload the system.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-181508
<b>Symptom</b>	When multiple telnet sessions are opened and multiple configuration download operations are done, system can go into a state where it continuously prints "Failed to open gpio value for reading".
<b>Condition</b>	When multiple telnet sessions are opened and multiple configuration download operations are done, system can continuously print "Failed to open gpio value for reading".
<b>Workaround</b>	Do not run multiple configuration downloads from multiple telnet sessions simultaneously .
<b>Recovery</b>	Reload the system to recover from this state.
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	Management - IPv4/IPv6 Host Management

## Issues

Closed with Code Changes in Release 08.0.80

<b>Issue</b>	FI-182229
<b>Symptom</b>	snmp bulkwalk gives incorrect value for bgp4V2PeerDescription.
<b>Condition</b>	1.configure snmp-server. 2.Establish BGP connection with 4-5peers. 3.Try snmpwalk and snmpbulkwalk of bgp4V2PeerDescription. snmpbulkwalk values will be incorrect.
<b>Workaround</b>	NA
<b>Recovery</b>	
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.30
<b>Technology / Technology Group</b>	Management - SNMP - Simple Network Management Protocol

<b>Issue</b>	FI-182031
<b>Symptom</b>	Scheduled reset from secondary in a stack boots from primary.
<b>Condition</b>	reload at <time> from <secondary> cli command boots from primary in a stack.
<b>Workaround</b>	NA
<b>Recovery</b>	
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Stacking - Traditional Stacking

<b>Issue</b>	FI-182122
<b>Symptom</b>	During Dhcp Atuo Provisioning While applying the configuration downloaded from TFTP server the remark configuration done for ACL's will be overwritten .
<b>Condition</b>	DHCP auto provisioning should be used to load the running configuration with multiple ACL's having remarks .
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-183203
<b>Symptom</b>	The RX_Power value obtained from mib browser and by running show optic command is different
<b>Condition</b>	Verify the show optic for that particular interface from cli and from mib browser.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	



<b>Issue</b>	FI-183002
<b>Symptom</b>	Mac from KG350s Encryptor's might not be learnt on the 7150 switches.
<b>Condition</b>	Send EAPOL Packet with Ethertype as 0x888e and destination mac address as 01:aa:bb:cc:00:01 from Encryptor to ICX7150.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.60
<b>Technology / Technology Group</b>	Security - 802.1x Port-based Authentication

<b>Issue</b>	FI-181681
<b>Symptom</b>	User was not able do mac-authentication
<b>Condition</b>	When Flexauth port is disabled and then enabled again
<b>Workaround</b>	
<b>Recovery</b>	Reload the Stack
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Security - MAC Port-based Authentication

<b>Issue</b>	FI-181812
<b>Symptom</b>	dot1x capable PC stays in "CONNECTING" state after coming out of sleep
<b>Condition</b>	When PC goes to sleep and comes back, it is unable to do dot1x authentication
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	Security - 802.1x Port-based Authentication

<b>Issue</b>	FI-182214
<b>Symptom</b>	In Telnet/SSH the "show ip bgp route" command output not paged
<b>Condition</b>	In Telnet/SSH the "show ip bgp route" command page more is not working
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	

## Issues

Closed with Code Changes in Release 08.0.80

<b>Issue</b>	FI-181537
<b>Symptom</b>	show clock detail shows summer time start and end date incorrectly.
<b>Condition</b>	configure "clock summer-time" and "clock timezone us Eastern". show clock details displays incorrect start and end date for summer time
<b>Workaround</b>	NA
<b>Recovery</b>	NA
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Management - CLI - Command Line Interface

<b>Issue</b>	FI-181728
<b>Symptom</b>	When stp-bpdu's are received, the interface will move to Up and Disabled state.
<b>Condition</b>	In ICX7250 enable stp-bpdu-guard in the interface level and when stp-bpdu's are received.
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Layer 2 Switching - BPDU Guard - Bridge Protocol Data Unit

<b>Issue</b>	FI-181448
<b>Symptom</b>	linkDown snmp trap contains unexpected value
<b>Condition</b>	On ICX devices, when operationally enabled port is disabled then operational status will be shown in snmp TRAP on mib browser as "Up" always. Issue seen only with snmp trap.
<b>Workaround</b>	No functional impact.
<b>Recovery</b>	
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.30
<b>Technology / Technology Group</b>	Management - SNMP - Simple Network Management Protocol

<b>Issue</b>	FI-181529
<b>Symptom</b>	Sflow collector reports XDR error.
<b>Condition</b>	802.1x authentication and sflow are enabled on the same interface. Sflow sends user-name attribute in the sample packet.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.30
<b>Technology / Technology Group</b>	Security

<b>Issue</b>	FI-182212
<b>Symptom</b>	On ICX7750 stack when polled for temperature values for all the units remote units temperature will be shown as 0.
<b>Condition</b>	Issue is seen with ICX7750 stack when polled for temperature of remote units .
<b>Workaround</b>	None
<b>Recovery</b>	
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Management - SNMP - Simple Network Management Protocol

<b>Issue</b>	FI-181963
<b>Symptom</b>	Configured max-reauth request value is not updated in show dot1x configuration
<b>Condition</b>	On ICX devices, it always shows default value for max-reauth request in show dot1x configuration even though user change it to a different value.
<b>Workaround</b>	No functional impact
<b>Recovery</b>	
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.30
<b>Technology / Technology Group</b>	Management - CLI - Command Line Interface

<b>Issue</b>	FI-182216
<b>Symptom</b>	A software reset of the device occurs on the mentioned condition
<b>Condition</b>	A device with user vlan having a lag interface as a member and when webauth configuration is removed or the vlan itself is removed results in a software reset.
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-182136
<b>Symptom</b>	show ip address output is not distinguishing between a tunnel, ve or loopback interface
<b>Condition</b>	Configuring ip address on a tunnel or ve or loopback interface and executing show ip address. The Interface column in the output will have no distinction between tunnel or ve or loopback, their respective IDs are displayed.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Management - CLI - Command Line Interface

Issues

Closed with Code Changes in Release 08.0.80

<b>Issue</b>	FI-179449
<b>Symptom</b>	On ICX7450 switch stack when the stack failover is done then in some rare cases the port state becomes inconsistent in the output of switch CLI. For example the port could be physically up but it shows up as Down in the switch CLI output like "show interface" when this command is issued from Active or Standby unit
<b>Condition</b>	This issue happens rarely on ICX7450 stack when the stack failover followed by a switch over . This issue happens rarely when port is changed from untagged to tagged configuration.
<b>Workaround</b>	None
<b>Recovery</b>	Recovery procedure is to disable and enable the port, the issue does not have any functional impact.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.60
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-178663
<b>Symptom</b>	GRE Tunnel (and potentially IP Unicast) Traffic forwarding via PE port is not getting redirected to new port even if alternative port available when PE goes down, traffic recovers when PE joins back, resulting is traffic loss even if there is alternative path.
<b>Condition</b>	GRE Tunnel (and potentially IP Unicast) Traffic egressing on a SPX PE Port and doing ISSU/HA operation resulting in temporary PE detach during that operation.
<b>Workaround</b>	Customer are advised to have PE connected to multiple CB via CB uplink spx-lag before performing switchover or failover to avoid PE Detach. For ISSU or any PE detach condition there is no workaround.
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-181603
<b>Symptom</b>	On ICX7650 1G copper port. When the port is configured at 100 Mbps full duplex mode and connected to link partner which is also configured at 100 Mbps full duplex mode with auto negotiation disabled. Then if the EEE (energy efficient ethernet) is enabled globally, the port goes to 100 Mbps half duplex mode.
<b>Condition</b>	The problem happens only when auto negotiation is disabled on the link partner and EEE configuration is enabled globally on the ICX 7650 1G port along with fixed 100 Mbps full duplex mode configuration.
<b>Workaround</b>	
<b>Recovery</b>	If a port gets into the mentioned symptom, follow the below steps for recovery. 1) "disable" the port. 2) Run the command "no eee" on the port. 3) "enable" the port.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-180921
<b>Symptom</b>	An error is displayed when applying an IPv6 ACL on the VE interface when there is already an existing IPv6 ACL on same interface. The error message is similar to the following message: ICX7450-24 Router(config-vif-499)#ipv6 traffic-filter scale1 in Insufficient hardware resources to apply the V6 ACL. Please remove already applied ACL(s) and/or Security features and try again. ERROR: Insufficient hardware (TCAM) resource on unit 60028 for binding the IPv6 ACL scale1 to interface 499. SYSLOG: <10> Nov 11 04:59:23 ERROR: Insufficient hardware (TCAM) resource on unit 60028 for binding the IPv6 ACL scale1 to interface 499. On the data path, the new ACL will not be programmed into TCAM and the old ACL rules still persist.
<b>Condition</b>	1. Configure and apply an IPv6 ACL on a VE interface 2. Now apply another IPv6 ACL on the VE interface which has logging enabled and the sizes of these two IPv6 ACLs together will exhaust the TCAM resource
<b>Workaround</b>	Do not enable logging on the new IPv6 ACL
<b>Recovery</b>	1. Remove the existing IPv6 ACL applied on the VE interface. 2. And then, apply the new IPv6 ACL on the VE interface.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-180553
<b>Symptom</b>	PoE powersupply is shown as regular powersupply during bootup in active unit.
<b>Condition</b>	Issue can be seen while executing the below set of commands. 1.clear syslog 2. reload the device 3. show log
<b>Workaround</b>	No Workaround
<b>Recovery</b>	None.
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.30
<b>Technology / Technology Group</b>	Monitoring - Syslog

<b>Issue</b>	FI-181466
<b>Symptom</b>	Following error messages displayed on Console/telnet/ssh: 0:_soc_mem_write_sanity_check: soc_mem_write: invalid index 87617 for memory L2_ENTRY_ONLY_ECC 0:_soc_ser_sram_correction: SER SRAM correction encountered error(-4) in mem write
<b>Condition</b>	There are no specific user triggers as this is a hardware single bit error and can happen due to changes in atmosphere.
<b>Workaround</b>	
<b>Recovery</b>	Single Bit Error recovery in software automatically recovers the single bit error and error message stop after some time.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	Monitoring - OAM - Operations, Admin & Maintenance

## Issues

Closed with Code Changes in Release 08.0.80

<b>Issue</b>	FI-177848
<b>Symptom</b>	This problem happens in a scaled scenario where we have either exhausted the TCAM or adding a new filter to an ACL used for a PBR route-map will result in exhausting the TCAM resource. In this scenario, user does not get an error when adding a filter to the ACL which is used in PBR route-map. But the new filter does not get reflected in the TCAM as TCAM resource is exhausted. This applies to ACLs that are used in PBRv4 as well as PBRv6 route-maps.
<b>Condition</b>	Adding a filter in ACL which is used by PBR/PBRv6, when TCAM resource are exhausted or in the verge of getting exhausted.
<b>Workaround</b>	No workaround.
<b>Recovery</b>	User can add new filter after freeing up some TCAM space by deleting some existing ACL rules. The ACL rules that need to be freed up can be across any ACLs in the system and not just the ones used for PBR route-maps.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-181332
<b>Symptom</b>	On ICX7450 platform when the external USB is plugged in and the FIPS mode is enabled then some time the message is seen on console indicating the external USB has been plugged out "External USB-Mass-Storage Plugged-out"
<b>Condition</b>	
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-180871
<b>Symptom</b>	Duplicate packets will be received for a short window of 7 milliseconds at the device connected to this switch. Applications using Ping or any UDP based applications will report error on duplicate packet reception.
<b>Condition</b>	
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-181567
<b>Symptom</b>	On very rare occasions, during ICX7650 reload, system can encounter an unexpected kernel exception error with following message in console and not able to proceed further in the boot sequence. Sample error message: [ 51.081969] iproc-idm idm: idm_aci_pcie_s1 ( 1 21005900 358) fault
<b>Condition</b>	This condition was observed only when ICX7650 was reloaded back to back in a tight loop for several hours. Not seen with the normal scenarios when system is in steady state.
<b>Workaround</b>	None
<b>Recovery</b>	Reset the power for the failed unit if it is stuck in the same state.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	Other - Other

<b>Issue</b>	FI-180631
<b>Symptom</b>	When scaled VXLAN overlay gateway configuration is deleted, it MAY not get deleted completely.
<b>Condition</b>	This issue MAY be seen when VXLAN overlay gateway (having below scaled configuration) is deleted 1. Many VLANs are mapped to VNIs i.e. more than 64 Vlan mapped to VNI 2. Multiple sites are configured i.e. more than 8 Tunnels/Sites. 3. Mapped VLANs are extended to multiple sites.
<b>Workaround</b>	Delete all the sites (one at a time) from the VXLAN overlay gateway, before deleting the VXLAN overlay gateway. 1). Remove site configuration one at a time. 2). This burdens CPU, so the system needs time for the CPU to come back to low, so wait for 30-60 sec for the system to settle down. Before removing next site. 3). Remove overlay-gateway in the end.
<b>Recovery</b>	Save the configuration and reload the switch. Once the switch boots up with partial VXLAN overlay gateway configuration, delete the VXLAN overlay gateway.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-181137
<b>Symptom</b>	Key used by OSPF and provisioned in key chain will be different.after Switcher/Fail over/ISSU as applications like OSPFv2/OSPFv3 that uses key-chain does not find a valid key to use for packet authentication, this may also result in adjacency flap.
<b>Condition</b>	When key-ids inside the key-chain are configured with expire time less than 10 seconds for all the keys and performing switch over or Fail over or ISSU.
<b>Workaround</b>	Key-ids inside a key-chain needs to be configured with expire time greater than 10 sec.
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

## Issues

Closed with Code Changes in Release 08.0.80

<b>Issue</b>	FI-180510
<b>Symptom</b>	Power is not released from certain ports during back to back disconnect and connect of PDs
<b>Condition</b>	Power might not get released on some ports when several PDs are disconnected and reconnected in one go several times.
<b>Workaround</b>	Avoid disconnecting several PDs in one go. Disconnect one by one with time lag of few seconds (5 secs).
<b>Recovery</b>	configure "no inline power" and then "inline power" on the ports where the issue is seen.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-179153
<b>Symptom</b>	After the switchover, traffic policy counters on new active may not have correct values (w.r.t old active) for it's own ports.
<b>Condition</b>	1. There should be some traffic hitting the traffic policy before unit becomes active from standby 2. Switchover should happen at stats collection timer expiry.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-181565
<b>Symptom</b>	On ICX7650, if the stacking trunk is configured, and trying to do unit replacement on standby unit, could causes the protocols packet not reaching the standby unit.
<b>Condition</b>	This issue is observed only when stacking trunk is configured and unit replacement is done for the standby unit.
<b>Workaround</b>	None
<b>Recovery</b>	Reload the standby unit will recover from this condition
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	IP Multicast - IGMP - Internet Group Management Protocol

<b>Issue</b>	FI-108037
<b>Symptom</b>	The link does not come up between ICX7450-32ZP 2.5G port and ICX7750-48C 10G copper port connected using Crossover Ethernet cable with ports configured in 1G speed using "speed-duplex 1000-full-master" command
<b>Condition</b>	This issue happen in a connection between ICX7450-32ZP and ICX7750-48C using Crossover Ethernet cable and ports configured in 1G mode
<b>Workaround</b>	
<b>Recovery</b>	None
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.40
<b>Technology / Technology Group</b>	



<b>Issue</b>	FI-121244
<b>Symptom</b>	When UDLD is enabled, LACP enabled LAG interface can flap if large ACL is applied/ deleted on it.
<b>Condition</b>	1) UDLD must be enabled. 2) LAG should contain ports from stack member units. 3) ACL should contain more than 1000 filters.
<b>Workaround</b>	
<b>Recovery</b>	LAG interface will come back UP after the ACL programming is completed.
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Security - ACLs - Access Control Lists

<b>Issue</b>	FI-116561
<b>Symptom</b>	The CPU usage remains 90% for longer time when openflow controller is configured to auto download the flows and 12K flows are configured. It may cause other L2 and L3 protocol flaps.
<b>Condition</b>	This issue is applicable only for manual switchover cases with the highly scaled configuration and flows.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.40
<b>Technology / Technology Group</b>	SDN - OpenFlow

<b>Issue</b>	FI-179025
<b>Symptom</b>	On ICX7750 when the cable is connected on the ports which are pre-configure to auto-lacp then the newly connected port comes up, goes down and then comes up again quickly. This port flap is observed only once during cable plug-in and after that the port works fine. This issue is observed only with auto-lacp and not with dynamic or static LAG
<b>Condition</b>	This issue is observed on ICX7750 ports when the port is configured for auto-lacp and then the cable is connected into the port to bring the link up
<b>Workaround</b>	There is no workaround as the port comes up after one flap and then works properly
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	

## Known Issues in Release 08.0.80

This section lists open software issues with Critical, High, and Medium Technical Severity in FastIron release 08.0.80.

<b>Issue</b>	FI-187838
<b>Symptom</b>	show version CLI doesn't work. Displays an information message and returns to the prompt.
<b>Condition</b>	Doesn't happen easily. Happened just once in a stacking setup after 3 days of longevity, which is basically just traffic forwarding w/o any triggers or configuration changes.
<b>Workaround</b>	None
<b>Recovery</b>	None identified so far.
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	Management - CLI - Command Line Interface

<b>Issue</b>	FI-187670
<b>Symptom</b>	In multiple-untagged mode and with multiple Mac-Auth/802.1X sessions having dynamic ACLs and using the same User ACL for all sessions, any change of User ACL definitions (addition/deletion of filters in ACL) may cause high CPU usage.
<b>Condition</b>	With multiple sessions using the same User ACL, any filter change triggers unbinding of old filters and binding of new filters for all the sessions on that port. Depending on the number of sessions and number of filters in the User ACL, the time consumed to program ACL filters in TCAM may take significant time causing the console/telnet/ssh access to hang until the operation is complete.
<b>Workaround</b>	There is no workaround and the only way to prevent is not changing the User ACLs or having less number of MAC-Auth/802.1X sessions on a port and/or less number of filters in the User ACL
<b>Recovery</b>	There is no recovery for this symptom
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-187631
<b>Symptom</b>	The ACL show commands (e.g. show ip access-lists) display duplicate entries or missing entries when the show commands are issued from multiple sessions simultaneously.
<b>Condition</b>	The show commands are issued from multiple sessions simultaneously.
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-186770
<b>Symptom</b>	1. When ICX is configured with a flow that should send PacketIn messages to the controller only when "no flow entries are matched", the ICX is instead sending PacketIn messages with the "reason" field set to "0" (NO_MATCH) when there is actually match with the flow entries 2. When ICX is configured with a flow that should send PacketIn messages to the controller only for packets that have matched flow entries, the ICX is sending PacketIn messages as expected but the reason code is set to "0" (NO_MATCH)
<b>Condition</b>	ICX is configured with a flow that should send PacketIn messages to the controller only when "no flow entries are matched" OR ICX is configured with a flow that should send PacketIn messages to the controller only for packets that have matched flow entries
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-186891
<b>Symptom</b>	Telnet from ICX7150 to Cisco ASA devices fail.
<b>Condition</b>	Cisco ASA negotiates to use terminal type for telnet access. Terminal-type command is not supported by ICX.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	Other - Other

<b>Issue</b>	FI-187175
<b>Symptom</b>	TFTP access will not be allowed in the active
<b>Condition</b>	Issue will be simulated with the below steps. 1. Perform stack switch over when a TFTP running configuration download is in progress (via DHCP auto provision or CLI TFTP operations). 2. Perform second stack switch over which will not allow subsequent TFTP operations on the active device
<b>Workaround</b>	1. Other download mechanism like SCP, HTTPS can be used. 2. The switch over can be performed when TFTP operations have completed or DHCP auto provision is complete for running configuration download.
<b>Recovery</b>	Reload the device or perform the third switch over operation.
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	Other - Other

## Issues

Known Issues in Release 08.0.80

<b>Issue</b>	FI-184093
<b>Symptom</b>	when user remove the vxlan overlay gateway configuration with "no overlay gateway" command, "mem L2X field VFI value does not fit" could be seen on any of active/standby/member units.
<b>Condition</b>	Vxlan configuration is scaled configuration with 256 vlan-vni mapping and 32 remote sites configured. And all 256 vlan are extended in every remote site. With this scale configuration when we execute "no overlay gateway" command the error/warning message could be seen.
<b>Workaround</b>	Workaround is to delete vxlan configuration by deleting remote sites and vlan-vni mapping separately, instead of deleting all configuration with single command "no overlay gateway".
<b>Recovery</b>	N/A
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-187052
<b>Symptom</b>	An ACL is getting incorrectly configured on ports of standby unit, when user tries to remove/unbind an ACL that is not bound to those standby ports.
<b>Condition</b>	The issue happens on stacking setup only when 1. User tries to un-configure an ACL when there is no ACL bound to that port 2. If an ACL 'X' is configured on ports of standby unit and user incorrectly tries to remove ACL 'Y' on these ports then ACL 'Y' will replace ACL 'X' on these ports.
<b>Workaround</b>	None
<b>Recovery</b>	Apply some ACL on the impacted standby ports and then remove/unbind the ACL.
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-186983
<b>Symptom</b>	show interface brief " displays "state" as BLOCKING for linked-up interfaces on which spanning-tree is disabled and the interface's untagged VLAN is participating in xSTP.
<b>Condition</b>	Happens when spanning-tree is disabled on an interface first and then the interface's untagged VLAN starts participating in xSTP
<b>Workaround</b>	Disable spanning-tree on the interface only after enabling spanning-tree in the interface's untagged VLAN.
<b>Recovery</b>	Enable and disable spanning-tree on the interface after every time spanning tree is enabled on the interface's untagged VLAN.
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-186969
<b>Symptom</b>	ICX goes on reload , When "reload" button is submitted from web GUI while HTTPS download is in progress from CLI.
<b>Condition</b>	This issue occurs only with in below steps 1. Initiate a HTTPS download using the CLI command. For example: "copy https flash 10.10.10.10 icx.bin primary" 2. Open a web GUI interface for the device. 3. When HTTPS download in progress through CLI, clicks the reload button through web GUI interface
<b>Workaround</b>	Perform reload operation from other user interfaces or wait for download operation to complete before triggering the reload.
<b>Recovery</b>	NA
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-186565
<b>Symptom</b>	if an abrupt switch over or failure open, ACL rules might not be complete if hot swap was in progress.
<b>Condition</b>	switch over or fail over while ACL hot swap is in progress.
<b>Workaround</b>	reload the units to make sure hot swap is complete.
<b>Recovery</b>	reload the units to make sure hot swap is complete.
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-186384
<b>Symptom</b>	High CPU utilization or CPU spike.
<b>Condition</b>	CDP enabled on a scaled 802.1BR setup with over 2200 ports.
<b>Workaround</b>	None
<b>Recovery</b>	Disabling CDP will reduce the CPU spike
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-186782
<b>Symptom</b>	it observes a crash in the active unit.
<b>Condition</b>	User enters erase start and reload, it observed a crash.
<b>Workaround</b>	none.
<b>Recovery</b>	after the crash, it may recover.
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	Stacking - Mixed Stacking

## Issues

Known Issues in Release 08.0.80

<b>Issue</b>	FI-186742
<b>Symptom</b>	Egress ACL applied on the Virtual Router Interface (VE), does not filter the traffic as per ACL rules on the PE ports of the vlan.
<b>Condition</b>	1. A PE port is part of more than 1 vlan 2. More than one vlan the PE port belongs have egress ACL applied on the Virtual router interface.
<b>Workaround</b>	If an egress ACL is to be applied on a virtual interface of a vlan with PE ports, then have the PE ports only in that single vlan. OR Apply Egress ACL on only one of the VEs the port is a member of
<b>Recovery</b>	1. Remove the given PE port from all the Vlan's it is part of. 2. Add the PE port back to all the required vlan's 3. Apply egress ACL only on one of the VEs
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-186616
<b>Symptom</b>	Under rare circumstances, non active member of ICX7650 stack can stop showing the increments in port statistics.
<b>Condition</b>	Display of port statistics can stop incrementing in rare circumstances. This does not have any functional impact to the switching/routing capability.
<b>Workaround</b>	No workaround available.
<b>Recovery</b>	When ICX7650 gets into the above mentioned scenario, use "dm restart-bcm-counter" in the corresponding unit to recover from this state.
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-186492
<b>Symptom</b>	Control packet is not forwarded from a 7450-48F (active unit). When the input is received from a member or standby unit and it RCPUs the packet to a 7450-48F active.
<b>Condition</b>	Interpp filter outs the packet. 7450-48F have two packet processor, if the standby and member unit tries to RCPU to the active unit, the control packet comes in one packet processor and tries to forward to another port on the 2nd processor. If the output port matches the interpp filter, it will get filter out.
<b>Workaround</b>	This issue has to match the configuration in the topology, in this case, tries to avoid using */3/4 port because it matches the port ID of the interpp link.
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-186518
<b>Symptom</b>	Console connection to CB unresponsive for 25 seconds.
<b>Condition</b>	End SPX PE units in a ring become unreachable causing intermediate PEs in a ring to become unreachable as well, in a scaled up SPX deployment with large number of VLANs, MACs and STP instances.
<b>Workaround</b>	None.
<b>Recovery</b>	Console becomes responsive after 25 seconds.
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	Layer 2 Switching - xSTP - Spanning Tree Protocols

<b>Issue</b>	FI-185957
<b>Symptom</b>	The message "INFO: all 2 display buffers are busy, please try later." will be displayed in the show command output, instead of expected functionality output. (Example show commands: "show stack", "show version")
<b>Condition</b>	Seen when all below conditions are met 1. The DUT is a scaled setup with huge data to display in show command 2. Two or more telnet/ssh sessions are connected. 3. The show command is performed in two sessions and output is pending for user input in the page mode in both the sessions. 4. The show command performed in the new session will show the error message "INFO: all 2 display buffers are busy, please try later."
<b>Workaround</b>	Abort the pending show command by pressing "Ctrl + c" in one of the two sessions or by completing the output display before performing the show command in new session. If the sessions are abruptly closed without completing the pending output, reload of the device is required
<b>Recovery</b>	NA
<b>Probability</b>	
<b>Found In</b>	
<b>Technology / Technology Group</b>	Cloud Management - Cloud Agent

<b>Issue</b>	FI-185679
<b>Symptom</b>	ACL accounting does not work for MAC filters (L2 ACLs) applied on LAG interfaces. While the statistics get collected at a per port level, the "show access-list accounting" command on lag interface does not display the accumulated statistics.
<b>Condition</b>	Executing a mac filter show command on a lag interface with ACL accounted enabled on MAC filters.
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	Security - ACLs - Access Control Lists

## Issues

### Known Issues in Release 08.0.80

<b>Issue</b>	FI-185437
<b>Symptom</b>	Clients device connected to ICX devices not being assigned an IP address (via DHCP) when the ICX device is the configured DHCP server and is in a different vlan than the client. In this scenario the DHCP server seem to allot an IP Address to the client but the client has not received the allocation.
<b>Condition</b>	A client device requesting an IP address through DHCP fails to receive an IP address. As a fallback mechanism it transmits a DHCP discover packet on all the vlans/ interfaces to obtain an IP address. In this condition the IP address is not allocated to the client.
<b>Workaround</b>	Network administrator can release IP binding for that client through a CLI command on the server. The client side configuration should be in the right vlan as a DHCP server.
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-181567
<b>Symptom</b>	On very rare occasions, during ICX7650 reload, system can encounter an unexpected kernel exception error with following message in console and not able to proceed further in the boot sequence. Sample error message: [ 51.081969] iproc-idm idm: idm_aci_pcie_s1 ( 1 21005900 358) fault
<b>Condition</b>	This condition was observed only when ICX7650 was reloaded back to back in a tight loop for several hours. Not seen with the normal scenarios when system is in steady state.
<b>Workaround</b>	None
<b>Recovery</b>	Reset the power for the failed unit if it is stuck in the same state.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	Other - Other

<b>Issue</b>	FI-185240
<b>Symptom</b>	IPv6 MLD snooping mcache entries are not removed from old default vlan, when the default vlan is changed.
<b>Condition</b>	If default VLAN is changed while Ipv6 Mutlicast traffic is received via default VLAN, IPv6 MLD snooping mcache entries related to old default VLAN is not removed from hardware. Issue seen only on switch where MLD snooping is allowed for default VLAN. This problem is applicable to all ICX products.
<b>Workaround</b>	Disable Multicast under default VLAN before configure/un-configure of default VLAN.
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	



<b>Issue</b>	FI-183000
<b>Symptom</b>	"show cli-command-history" does not display output in page mode.
<b>Condition</b>	"show cli-command-history" output is not displayed in page mode even after executing "page-display" command
<b>Workaround</b>	None
<b>Recovery</b>	None
<b>Probability</b>	
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-184769
<b>Symptom</b>	ICX7450 can have an unexpected reload, when a very huge file (of the order of GBs) is copied from external USB to the unit.
<b>Condition</b>	Copying a very huge file (such as 1GB) from external USB to the unit can make the system busy for a longer duration. System would sense this busy condition with a watchdog timeout and will reboot automatically to recover.
<b>Workaround</b>	Use external USB to copy only firmware image and configuration files. These would not cause the busy condition leading to a watchdog timeout.
<b>Recovery</b>	System reboots and recovers itself after this unexpected
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-184384
<b>Symptom</b>	In FIPS-CC mode, Secure logging / Secure radius server connection establishment would fail
<b>Condition</b>	When device uses chain of certificates for OCSP validation to establish secure logging/secure radius server connection in FIPS-CC mode.
<b>Workaround</b>	Use single certificate for OCSP validation instead of chain of certificates or Remove OCSP validation For example, Below configuration has to be removed ocsppost revocation-check ocsppost ocsppost-url http://10.176.166.18:2556
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	Management - AAA

## Issues

### Known Issues in Release 08.0.80

<b>Issue</b>	FI-184378
<b>Symptom</b>	Ports with same configured speed will not be allowed to form a LAG as one of the below port physical characteristic didn't match, 1. Port link type is different. (Example: 1G and 10G can't form a LAG) 2. Port default speed doesn't match.
<b>Condition</b>	On ICX 7650 ZP and 48F platforms variants, LAG can't be formed between first 24 ports(1/1/1 to 1/1/24) and last 24ports (1/1/25 to 1/1/48) even though the configured speed is same.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-184003
<b>Symptom</b>	The key/certificate generation performed when a previous key/certificate generation command is still in progress, would fail with error message "A key pair generation is already in progress..."
<b>Condition</b>	When ssl certificate/ssh key generation command is performed during the previous ssh key/ssl certificate generation is in progress. Example commands for ssh key and ssl certificate generation: ssl certificate: "crypto-ssl certificate generate" ssh key: crypto key generate rsa modulus 2048 This scenario would be possible during config download if the configuration file has both the key generation commands.
<b>Workaround</b>	Perform the next ssl certificate/ssh key generation command after the previous key/certificate generation command completes.
<b>Recovery</b>	Reexecute the key/certificate generation command.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-183122
<b>Symptom</b>	PIM Mcache (show ip pim mcache) will continue to show the old OIF(Port) that got converted into Lag, with no impact on HW forwarding.
<b>Condition</b>	This is seen when a OIF Port is part of the PIM Mcache is converted into Lag or vice versa by configuration change.
<b>Workaround</b>	
<b>Recovery</b>	Execute the command "Clear ip pim mcache" to clear the mcache. But this will have traffic impact for the existing flow.
<b>Probability</b>	High
<b>Found In</b>	FI 08.0.80
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-177848
<b>Symptom</b>	This problem happens in a scaled scenario where we have either exhausted the TCAM or adding a new filter to an ACL used for a PBR route-map will result in exhausting the TCAM resource. In this scenario, user does not get an error when adding a filter to the ACL which is used in PBR route-map. But the new filter does not get reflected in the TCAM as TCAM resource is exhausted. This applies to ACLs that are used in PBRv4 as well as PBRv6 route-maps.
<b>Condition</b>	Adding a filter in ACL which is used by PBR/PBRv6, when TCAM resource are exhausted or in the verge of getting exhausted.
<b>Workaround</b>	No workaround.
<b>Recovery</b>	User can add new filter after freeing up some TCAM space by deleting some existing ACL rules. The ACL rules that need to be freed up can be across any ACLs in the system and not just the ones used for PBR route-maps.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	

<b>Issue</b>	FI-113814
<b>Symptom</b>	Currently the system is allowing the user to configure PBR on the same interface where FlexAuth is also enabled and the user configured RADIUS to apply ACL on the FlexAuth session. Traffic forwarding is nondeterministic due the order in which the access list rules are configured on member units when PBR and dynamic ACLs are configured on the same interface.
<b>Condition</b>	This happens when user configures PBR on the same interface where FlexAuth is also enabled and the user configured RADIUS to apply ACL on the FlexAuth session. It is not a recommended way to use the system.
<b>Workaround</b>	
<b>Recovery</b>	
<b>Probability</b>	Low
<b>Found In</b>	FI 08.0.61
<b>Technology / Technology Group</b>	Security - PBR - Policy-Based Routing

<b>Issue</b>	FI-181286
<b>Symptom</b>	User might see i2c error messages displayed in console when plugging in or when accessing an unsupported SFPP. Sample error message: I2C_CORE: B80:D51 Read Failed.Bytes read=0 Bytes to read=1.
<b>Condition</b>	User might see i2c related error messages, when plugging in an unsupported SFPP. This was observed on SFPP with part name: AFBR-707ASDZ-BR2
<b>Workaround</b>	Please use only supported SFPP.
<b>Recovery</b>	Replace any unsupported SFPP in the unit with a supported one.
<b>Probability</b>	
<b>Found In</b>	FI 08.0.70
<b>Technology / Technology Group</b>	Other - Other

## Issues

Known Issues in Release 08.0.80

<b>Issue</b>	FI-123259
<b>Symptom</b>	Pre-provisioned ACL configurations that applies to a PE are not properly applied on that PE during hotswap.
<b>Condition</b>	Filters of one or more ACLs that belong to pre-provisioned ACL configurations that apply to the PE being hotswapped, are assigned new sequence numbers through 'resequence' command while the PE hotswap is in progress.
<b>Workaround</b>	Do not attempt to resequence the filters of any ACLs while any PE hotswap is in progress. Check SYSLOG for messages regarding the ongoing and completion related messages for PE hotswaps for making the decision.
<b>Recovery</b>	Reload the affected PE.
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.50
<b>Technology / Technology Group</b>	Security - ACLs - Access Control Lists

<b>Issue</b>	FI-116781
<b>Symptom</b>	A binding of ACL using filters matching one or more ranges of TCP/UDP ports to ports of a member unit fails due to TCAM rules unavailability.
<b>Condition</b>	The ACL (using filters matching one or more ranges of TCP/UDP ports) that is bound to ports of member units is bound "after" several ACLs using filters matching one or more ranges of TCP/UDP ports are already applied to ports of Active unit.
<b>Workaround</b>	Apply the ACL (using filters matching one or more ranges of TCP/UDP ports) to ports of member units "before" applying any ACLs using filters matching one or more ranges of TCP/UDP ports are applied to ports of the Active unit.
<b>Recovery</b>	Unbind all ACLs (using filters matching one or more ranges of TCP/UDP ports) that are bound to the ports of the Active unit, and then attempt to apply the ACL (using filters matching one or more ranges of TCP/UDP ports) to ports of member units.
<b>Probability</b>	Medium
<b>Found In</b>	FI 08.0.60
<b>Technology / Technology Group</b>	Security - ACLs - Access Control Lists



© 2019 ARRIS Enterprises LLC. All rights reserved.  
Ruckus Wireless, Inc., a wholly owned subsidiary of ARRIS International plc.  
350 West Java Dr., Sunnyvale, CA 94089 USA  
[www.ruckuswireless.com](http://www.ruckuswireless.com)