

Ruckus ZoneDirector 10.3.1 Refresh 3 Release Notes

Supporting ZoneDirector 10.3.1 Refresh 3

Copyright, Trademark and Proprietary Rights Information

© 2020 CommScope, Inc. All rights reserved.

No part of this content may be reproduced in any form or by any means or used to make any derivative work (such as translation, transformation, or adaptation) without written permission from CommScope, Inc. and/or its affiliates ("CommScope"). CommScope reserves the right to revise or change this content from time to time without obligation on the part of CommScope to provide notification of such revision or change.

Export Restrictions

These products and associated technical data (in print or electronic form) may be subject to export control laws of the United States of America. It is your responsibility to determine the applicable regulations and to comply with them. The following notice is applicable for all products or technology subject to export control:

These items are controlled by the U.S. Government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations.

Disclaimer

THIS CONTENT AND ASSOCIATED PRODUCTS OR SERVICES ("MATERIALS"), ARE PROVIDED "AS IS" AND WITHOUT WARRANTIES OF ANY KIND, WHETHER EXPRESS OR IMPLIED. TO THE FULLEST EXTENT PERMISSIBLE PURSUANT TO APPLICABLE LAW, COMMSCOPE DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, FREEDOM FROM COMPUTER VIRUS, AND WARRANTIES ARISING FROM COURSE OF DEALING OR COURSE OF PERFORMANCE. CommScope does not represent or warrant that the functions described or contained in the Materials will be uninterrupted or error-free, that defects will be corrected, or are free of viruses or other harmful components. CommScope does not make any warranties or representations regarding the use of the Materials in terms of their completeness, correctness, accuracy, adequacy, usefulness, timeliness, reliability or otherwise. As a condition of your use of the Materials, you warrant to CommScope that you will not make use thereof for any purpose that is unlawful or prohibited by their associated terms of use.

Limitation of Liability

IN NO EVENT SHALL COMMSCOPE, COMMSCOPE AFFILIATES, OR THEIR OFFICERS, DIRECTORS, EMPLOYEES, AGENTS, SUPPLIERS, LICENSORS AND THIRD PARTY PARTNERS, BE LIABLE FOR ANY DIRECT, INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, EXEMPLARY OR CONSEQUENTIAL DAMAGES, OR ANY DAMAGES WHATSOEVER, EVEN IF COMMSCOPE HAS BEEN PREVIOUSLY ADVISED OF THE POSSIBILITY OF SUCH DAMAGES, WHETHER IN AN ACTION UNDER CONTRACT, TORT, OR ANY OTHER THEORY ARISING FROM YOUR ACCESS TO, OR USE OF, THE MATERIALS. Because some jurisdictions do not allow limitations on how long an implied warranty lasts, or the exclusion or limitation of liability for consequential or incidental damages, some of the above limitations may not apply to you.

Trademarks

ARRIS, the ARRIS logo, COMMSCOPE, RUCKUS, RUCKUS WIRELESS, the Ruckus logo, the Big Dog design, BEAMFLEX, CHANNELFLY, FASTIRON, ICX, SMARTCELL and UNLEASHED are trademarks of CommScope, Inc. and/or its affiliates. Wi-Fi Alliance, Wi-Fi, the Wi-Fi logo, Wi-Fi Certified, the Wi-Fi CERTIFIED logo, Wi-Fi Protected Access, the Wi-Fi Protected Setup logo, Wi-Fi Protected Setup, Wi-Fi Multimedia and WPA2 and WMM are trademarks or registered trademarks of Wi-Fi Alliance. All other trademarks are the property of their respective owners.

Contents

Document History	4
Introduction	4
New in This Release	4
New Access Points.....	4
New Features.....	4
Changed Behavior.....	4
Hardware and Software Support	5
Supported Platforms.....	5
Supported Access Points.....	5
Upgrade Information	5
Supported Upgrade Paths.....	5
Known Issues	6
Resolved Issues	6
Resolved Issues in Build 10.3.1.0.45.....	7
Resolved Issues in Build 10.3.1.0.42.....	7
Resolved Issues in Build 10.3.1.0.24.....	7
Resolved Issues in Build 10.3.1.0.21.....	7
Client Interoperability	8
PC OS.....	8
Smartphone/Tablet OS.....	8
Officially Supported Browsers.....	8
Not Officially Supported Browsers	9
Zero-IT Compatibility with Client Devices.....	9
Client Interoperability Known Issues.....	10

Document History

Revision Number	Summary of changes	Publication date
A	Initial release notes	June 2020

Introduction

This document provides release information on ZoneDirector release 10.3.1, including new features, enhancements, known issues, caveats, workarounds, upgrade details and interoperability information for version 10.3.1.

NOTE

By downloading this software and subsequently upgrading the ZoneDirector and/or the AP to version 10.3.1, please be advised that:

- The ZoneDirector will periodically connect to Ruckus and Ruckus will collect the ZoneDirector serial number, software version and build number. Ruckus will transmit a file back to the ZoneDirector and this will be used to display the current status of the ZoneDirector Support Contract.
- The AP may send a query to Ruckus containing the AP's serial number. The purpose is to enable your AP to autonomously connect with a wireless LAN controller operated by your choice of cloud service provider. Ruckus may transmit back to the AP, the Fully Qualified Domain Name (FQDN) or IP address of the controller that the AP will subsequently attempt to join.

Please be advised that this information may be transferred and stored outside of your country of residence where data protection standards may be different.

New in This Release

This section lists the new features and changed behavior in this release.

New Access Points

- R750

This release adds native support for the R750 802.11ax access point, previously only supported via new AP model patch in the 10.3 GA release.

The Ruckus R750 is a dual-band 4x4:4 indoor Wi-Fi 6 (802.11ax) Access Point featuring one 2.5 Gbps Ethernet port that supports 802.3af/at Power Over Ethernet, one 1 Gbps (non-PoE) Ethernet port, onboard BLE/ZigBee, and a USB port for IoT applications.

New Features

- None

Changed Behavior

- None

Hardware and Software Support

Supported Platforms

ZoneDirector firmware version **10.3.1.0.45** supports the following ZoneDirector models:

- ZoneDirector 1200

Supported Access Points

ZoneDirector version **10.3.1.0.45** supports the following Ruckus Access Point models:

Indoor AP	Outdoor AP
C110	T300
E510	T300e
H320	T301n
H510	T301s
R310	T310c
R320	T310d
R500	T310n
R510	T310s
R600	T610
R610	T610s
R700	T710
R710	T710s
R720	
R730	
R750*	

NOTE

R750 is new in this release.

Upgrade Information

Supported Upgrade Paths

The following ZoneDirector release builds can be directly upgraded to this release:

- 10.1.0.0.1515 (10.1 GA)
- 10.1.1.0.26 (10.1 MR1)
- 10.1.1.0.35 (10.1 MR1 Refresh 1)
- 10.1.1.0.42 (10.1 MR1 Refresh 2)
- 10.1.1.0.55 (10.1 MR1 Refresh 3)
- 10.1.1.0.79 (10.1 MR1 Refresh 4)

Known Issues

- 10.1.2.0.120 (10.1 MR2)
- 10.1.2.0.210 (10.1 MR2 Refresh 1)
- 10.1.2.0.251 (10.1 MR2 Refresh 2)
- 10.1.2.0.270 (10.1 MR2 Refresh 3)
- 10.1.2.0.275 (10.1 MR2 Refresh 4)
- 10.1.2.0.277 (10.1 MR2 Refresh 5)
- 10.1.2.0.306 (10.1 MR2 Refresh 6)
- 10.2.0.0.189 (10.2 GA)
- 10.2.1.0.75 (10.2 MR1)
- 10.2.1.0.79 (10.2 MR1 Patch1)
- 10.2.1.0.129 (10.2 MR1 Refresh 1)
- 10.2.1.0.135 (10.2 MR1 Refresh 2)
- 10.2.1.0.147 (10.2 MR1 Refresh 3)
- 10.2.1.0.159 (10.2 MR1 Refresh 4)
- 10.2.1.0.183 (10.2 MR1 Refresh 5)
- 10.3.0.0.362 (10.3 GA)
- 10.3.0.0.398 (10.3 GA Refresh 1)
- 10.3.1.0.21 (10.3 MR1)
- 10.3.1.0.24 (10.3 MR1 Refresh1)
- 10.3.1.0.42 (10.3 MR1 Refresh 2)

If you are running an earlier version, you must upgrade ZoneDirector to one of the above builds before upgrading to this release.

If you do not have a valid Support Entitlement contract, you will be unable to upgrade ZoneDirector to this release. See the *Administer > Support* page for information on Support Entitlement activation.

NOTE

For information and detailed instructions (including video tutorials) on upgrading ZoneDirector, visit the Ruckus Support How-To Hub at <https://support.ruckuswireless.com/how-to-hub>.

Known Issues

This sections lists the caveats, limitations and known issues in this release.

Issue	None
Description	None

Resolved Issues

This section lists the issues that have been resolved in this release.

Resolved Issues in Build 10.3.1.0.45

- Resolved several security issues related to CLI vulnerabilities on AP. For security incidents and responses, see www.ruckuswireless.com/security.

Resolved Issues in Build 10.3.1.0.42

- Resolved several security issues related to UI vulnerabilities. For security incidents and responses, see www.ruckuswireless.com/security.
- Resolved an issue where "Join another Controller" would not work properly for migrating a ZoneDirector AP to SmartZone/Cloud AP. [ER-7730]
- Resolved an issue where the "Directed-Multicast" setting would not persist on the WLAN and Ethernet interfaces on APs. [ER-7600]
- Resolved an issue where the reported MAC address and other content was inaccurate in packets sent from the AP to the Aeroscout server. [ER-7937/ER-8161]
- Resolved a Kernel Panic issue on R730 APs. [ER-7896]
- Resolved an issue that could cause R730 APs to unexpectedly reboot due to watchdog timeout. [ER-7870]
- Resolved a soft lockup issue on R730 AP. [ER-7736]
- Resolved an issue where connection failure events would increase drastically in fast roaming cases. [ER-7920]
- Resolved an issue where AP will not return to static channel setting after DFS detection expire. [ER-7745]
- Resolved an issue where clients in sleep mode could not receive multicast/broadcast packets. [ER-8085]
- Resolved an issue that could cause APs to unexpectedly reboot due to target fail detected. [ER-7874]
- Resolved an issue where the temporary license for AP management was not deleted properly after a ZoneDirector factory reset. [ER-8046]
- Resolved an issue where the configured gateway for the management interface would not work properly on ZoneDirector. [ER-8053]
- Resolved an issue where accessing the "Access Point" page in the ZoneDirector web interface would fail due to special characters in rogue AP event messages. [ER-8082]
- Resolved an issue with false alarms reported for "URL filtering License file download fail". [ER-8192]
- Resolved an issue where accessing the ZoneDirector GUI would intermittently fail. [ER-8267/ER-8217/ER-8056]
- Resolved an issue with throughput performance in WPA/WAP2 WLANs. [ER-7956]

Resolved Issues in Build 10.3.1.0.24

- The SmartCell Insight management password is no longer visible on the ZoneDirector web interface. [ZF-21179]
- Resolved two security issues related to UI vulnerabilities. For security incidents and responses, see www.ruckuswireless.com/security.

Resolved Issues in Build 10.3.1.0.21

- Resolved an issue where clients might intermittently fail to obtain a DHCP IP address. [ER-7665]
- Resolved an issue that could cause failure to configure an NTP server when the server name contains dashes. [ER-7843]
- Resolved an issue where CLI commands would not work properly for configuring auto channel selection algorithms. [ER-7846]
- Resolved an issue that could cause failure to configure an AP via the web interface. [ER-7834]
- Resolved an issue that could cause R730 Access Points to randomly reboot. [ER-7736]
- Resolved a ZoneDirector memory leak issue. [ER-7475]
- Resolved an issue where clients would fail to authenticate when tunnel MTU was configured to a value smaller than 1200. [ER-7568]

Client Interoperability

- Resolved an issue that could cause wireless clients fail to associate with R730 Access Points. [ER-7686]
- Resolved a Kernel panic issue on R730 Access Points. [ER-7702/ER-7674]
- Resolved an issue where the AP CLI command "get scanresults" did not work properly. [ER-7630]
- Resolved an issue where client isolation did not work properly. [ER-7355]
- Resolved an issue where saved Access Point configurations could randomly become corrupted. [ER-7225]
- Resolved an issue where the Force DHCP feature did not work properly after client roaming or reconnect. [ER-7579]
- Resolved an issue where multicast traffic unexpectedly dropped for wireless clients associated with Open/None WLANs with tunnel mode enabled. [ER-7291]
- Resolved an issue that could cause APs to unexpectedly reboot with reason "reset button". [ER-7419]
- Resolved an issue where mesh APs would intermittently disconnect from root APs. [ER-7260]

Client Interoperability

ZoneDirector and Ruckus APs use standard protocols to interoperate with third-party Wi-Fi devices. Ruckus qualifies its functionality on the most common clients.

The following client operating systems and browsers have been tested for compatibility with this release (for specific OS and browser limitations, including compatibility with Zero-IT, see subsequent sections below).

PC OS

- Windows 7
- Windows 8
- Windows 8.1
- Windows 10
- Mac OS 10.9.5
- Mac OS 10.10
- Mac OS 10.11
- Mac OS 10.12
- Mac OS 10.13

Smartphone/Tablet OS

- iOS (6.1, 7.0, 7.1, 8.1, 8.4, 9.2, 9.3,10.0,10.2,10.3,11.1/2/3/4,12.0)
- Android (4.1.2, 4.2.2, 4.3, 4.4.2, 4.4.4, 5.0.1, 5.0.2, 5.1, 6.0, 7.0, 7.1.1, 8.0)
- Windows Phone (7, 8, 8.1, 10)
- BlackBerry OS (10, 10.3.2) not supported with Zero-IT
- Chrome OS (47.0, 49.0) not Supported with Zero-IT

Officially Supported Browsers

- Internet Explorer 10, 11
- Firefox 34 and later

- Chrome 39 and later

Not Officially Supported Browsers

Safari, Dolphin, Opera Mini, Android Default, BlackBerry Default, etc.

Zero-IT Compatibility with Client Devices

TABLE 1 Zero-IT Compatibility

OS	WPA2 WLAN			802.1x EAP (external Radius Server)		
	Step 1	Step 2	Step 3	Step 1	Step 2	Step 3
iOS 6.x	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 7.x	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 8.0	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 8.0.2	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 8.1	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 9.0	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 10 .0	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 10 .2	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 10 .3	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 11.x	Y (ZF-19663)	Y (ZF-19663)	N (ZF-2888)	Y (ZF-19663)	Y (ZF-19663)	N (ZF-2888)
iOS 12.0	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
MAC OS 10.8.5	Y	Y	Y	Y	Y	N (ZF-4699)
Mac OS 10.9.3	Y	Y	Y	Y	Y	N (ZF-4699)
MAC OS 10.9.4	Y	Y	Y	Y	Y	N (ZF-4699)
Mac OS 10.9.5	Y	Y	Y	Y	Y	N (ZF-4699)
Mac OS 10.10	Y	Y	Y	Y	Y	N (ZF-4699)
Mac OS 10.11	Y	Y	Y	Y	Y	N (ZF-4699)
Mac OS 10.12	Y	Y	Y	Y	Y	N (ZF-4699)
Mac OS 10.13	Y	Y	Y	Y	Y	N (ZF-4699)
Windows 7	Y	Y	Y	Y	Y	Y
Windows 8	Y	Y	Y	Y	Y	Y
Windows 8.1	Y	Y	Y	Y	Y	Y
Windows 10	Y	Y	Y	Y	Y	Y
Windows Phone 8	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)
Windows Phone 8.1	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)
BlackBerry OS 10.1	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)
BlackBerry OS 10.3	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)
Kindle 7.4.9	Y	Y	Y	Y	Y	Y
Android 4.0.4	Y	Y	Y	Y	Y	Y
Android 4.1.2	Y	Y	Y	Y	Y	Y
Android 4.4.4	Y	Y	Y	Y	Y	Y

Client Interoperability

Client Interoperability Known Issues

TABLE 1 Zero-IT Compatibility (continued)

Android 5.0	Y	Y	Y	Y	Y	Y
Android 6.0	Y (ZF-19664)	Y	Y	Y (ZF-19664)	Y	Y
Android 7.0	Y (ZF-19664)	Y	Y	Y (ZF-19664)	Y	Y
Android 7.1.1	Y (ZF-19664)	Y	Y	Y (ZF-19664)	Y	Y
Android 8.0	Y (ZF-19664)	Y	Y	Y (ZF-19664)	Y	Y
Chrome OS	N (ZF-8076)	N (ZF-8076)	N (ZF-8076)	N (ZF-8076)	N (ZF-8076)	N (ZF-8076)

- Step 1: Download Zero-IT file
- Step 2: Install Zero-IT script
- Step 3: Automatically connect to the appropriate SSID

Client Interoperability Known Issues

- Zero-IT is not supported on Windows Phone 7/8/8.1 devices. [ZF-3478]
- Zero-IT is not supported on Blackberry OS devices. [ZF-6402]
- Zero-IT is not supported on Chrome OS devices. [ZF-8076]
- iOS clients cannot connect to the Zero-IT WLAN automatically. Users must reconnect to the target WLAN after installing the Zero-IT configuration file. [ZF-2888]
- Mac OS 10.7 and 10.8 cannot automatically connect to an 802.1x EAP WLAN after installing Zero-IT script. [ZF-4699]
- In some situations, Chromebook clients can take up to 10-50 seconds to resume sending traffic after a channel change. [ZF-14883]

COMMScope®
RUCKUS®

© 2020 CommScope, Inc. All rights reserved.
350 West Java Dr., Sunnyvale, CA 94089 USA
<https://www.commscope.com>