

Ruckus ZoneDirector 10.0.1 Refresh 7 Release Notes

Supporting ZoneDirector 10.0.1 Refresh 7

Copyright, Trademark and Proprietary Rights Information

© 2020 CommScope, Inc. All rights reserved.

No part of this content may be reproduced in any form or by any means or used to make any derivative work (such as translation, transformation, or adaptation) without written permission from CommScope, Inc. and/or its affiliates ("CommScope"). CommScope reserves the right to revise or change this content from time to time without obligation on the part of CommScope to provide notification of such revision or change.

Export Restrictions

These products and associated technical data (in print or electronic form) may be subject to export control laws of the United States of America. It is your responsibility to determine the applicable regulations and to comply with them. The following notice is applicable for all products or technology subject to export control:

These items are controlled by the U.S. Government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations.

Disclaimer

THIS CONTENT AND ASSOCIATED PRODUCTS OR SERVICES ("MATERIALS"), ARE PROVIDED "AS IS" AND WITHOUT WARRANTIES OF ANY KIND, WHETHER EXPRESS OR IMPLIED. TO THE FULLEST EXTENT PERMISSIBLE PURSUANT TO APPLICABLE LAW, COMMSCOPE DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, FREEDOM FROM COMPUTER VIRUS, AND WARRANTIES ARISING FROM COURSE OF DEALING OR COURSE OF PERFORMANCE. CommScope does not represent or warrant that the functions described or contained in the Materials will be uninterrupted or error-free, that defects will be corrected, or are free of viruses or other harmful components. CommScope does not make any warranties or representations regarding the use of the Materials in terms of their completeness, correctness, accuracy, adequacy, usefulness, timeliness, reliability or otherwise. As a condition of your use of the Materials, you warrant to CommScope that you will not make use thereof for any purpose that is unlawful or prohibited by their associated terms of use.

Limitation of Liability

IN NO EVENT SHALL COMMSCOPE, COMMSCOPE AFFILIATES, OR THEIR OFFICERS, DIRECTORS, EMPLOYEES, AGENTS, SUPPLIERS, LICENSORS AND THIRD PARTY PARTNERS, BE LIABLE FOR ANY DIRECT, INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, EXEMPLARY OR CONSEQUENTIAL DAMAGES, OR ANY DAMAGES WHATSOEVER, EVEN IF COMMSCOPE HAS BEEN PREVIOUSLY ADVISED OF THE POSSIBILITY OF SUCH DAMAGES, WHETHER IN AN ACTION UNDER CONTRACT, TORT, OR ANY OTHER THEORY ARISING FROM YOUR ACCESS TO, OR USE OF, THE MATERIALS. Because some jurisdictions do not allow limitations on how long an implied warranty lasts, or the exclusion or limitation of liability for consequential or incidental damages, some of the above limitations may not apply to you.

Trademarks

ARRIS, the ARRIS logo, CommScope, Ruckus, Ruckus Wireless, Ruckus Networks, Ruckus logo, the Big Dog design, BeamFlex, ChannelFly, Edgelron, FastIron, HyperEdge, ICX, IronPoint, OPENG, SmartCell, Unleashed, Xclaim, and ZoneFlex are trademarks of CommScope, Inc. and/or its affiliates. Wi-Fi Alliance, Wi-Fi, the Wi-Fi logo, Wi-Fi Certified, the Wi-Fi CERTIFIED logo, Wi-Fi Protected Access, the Wi-Fi Protected Setup logo, Wi-Fi Protected Setup, Wi-Fi Multimedia and WPA2 and WMM are trademarks or registered trademarks of Wi-Fi Alliance. All other trademarks are the property of their respective owners.

Contents

About This Release.....	4
Supported Platforms and Upgrade Information.....	4
Supported Platforms.....	4
Access Points.....	4
Upgrading to This Version.....	5
Enhancements and Resolved Issues.....	6
New Access Points.....	6
Enhancements.....	7
Resolved Issues in Build 10.0.1.0.93.....	8
Resolved Issues in Build 10.0.1.0.90.....	8
Resolved Issues in Build 10.0.1.0.88.....	9
Resolved Issues in Build 10.0.1.0.83.....	9
Resolved Issues in Build 10.0.1.0.61.....	10
Resolved Issues in Build 10.0.1.0.44.....	10
Resolved Issues in Build 10.0.1.0.35.....	11
Resolved Issues in Build 10.0.1.0.17.....	11
Resolved Issues in Build 10.0.0.0.1449.....	12
Resolved Issues in Build 10.0.0.0.1424.....	12
Caveats, Limitations, and Known Issues.....	12
Known Issues.....	13
General.....	13
R720.....	13
Bonjour Fencing.....	14

About This Release

This document provides release information on ZoneDirector release 10.0.1, including new features, enhancements, known issues, caveats, workarounds, upgrade details and interoperability information for version 10.0.1.

NOTE

By downloading this software and subsequently upgrading the ZoneDirector and/or the AP to version 10.0.1, please be advised that:

- The ZoneDirector will periodically connect to Ruckus and Ruckus will collect the ZoneDirector serial number, software version and build number. Ruckus will transmit a file back to the ZoneDirector and this will be used to display the current status of the ZoneDirector Support Contract.
- The AP may send a query to Ruckus containing the AP's serial number. The purpose is to enable your AP to autonomously connect with a wireless LAN controller operated by your choice of cloud service provider. Ruckus may transmit back to the AP, the Fully Qualified Domain Name (FQDN) or IP address of the controller that the AP will subsequently attempt to join.

Please be advised that this information may be transferred and stored outside of your country of residence where data protection standards may be different.

Supported Platforms and Upgrade Information

Supported Platforms

ZoneDirector version **10.0.1.0.93** supports the following ZoneDirector models:

- ZoneDirector 1200
- ZoneDirector 3000
- ZoneDirector 5000

Access Points

ZoneDirector version **10.0.1.0.93** supports the following Access Point models:

- C110
- H320
- H500
- H510
- R300
- R310
- R500
- R510
- R600
- R610
- R700
- R710
- R720
- T300

- T300e
- T301n
- T301s
- T610
- T610s
- T710
- T710s
- ZF7055
- ZF7352
- ZF7372
- ZF7372-E
- ZF7781CM
- ZF7782
- ZF7782-E
- ZF7782-N
- ZF7782-S
- ZF7982

Upgrading to This Version

This section lists important notes on upgrading ZoneDirector to this version.

Officially Supported Upgrade Paths

The following ZoneDirector builds can be directly upgraded to this ZoneDirector this 10.0.1 MR1 Refresh release:

- 9.12.0.0.336 (9.12 GA)
- 9.12.1.0.140 (9.12 MR1)
- 9.12.1.0.148 (9.12 MR1 refresh)
- 9.12.2.0.101 (9.12 MR2)
- 9.12.2.0.204 (9.12 MR2 Patch)
- 9.12.2.0.219 (9.12 MR2 Refresh)
- 9.12.3.0.28 (9.12 MR3)
- 9.12.3.0.34 (9.12 MR3 Refresh)
- 9.12.3.0.49 (9.12 MR3 Refresh 2)
- 9.12.3.0.61 (9.12 MR3 Refresh 3)
- 9.12.3.0.75 (9.12 MR3 Refresh 4)
- 9.12.3.0.83 (9.12 MR3 Refresh 5)
- 9.12.3.0.105 (9.12 MR3 Refresh 6)
- 9.12.3.0.134 (9.12 MR3 Refresh 7)
- 9.12.3.0.136 (9.12 MR3 Refresh 8)
- 9.13.0.0.232 (9.13 GA)

Enhancements and Resolved Issues

- 9.13.1.0.11 (9.13 MR1)
- 9.13.1.0.26 (9.13 MR1 Refresh)
- 9.13.2.0.33 (9.13 MR2)
- 9.13.3.0.22 (9.13 MR3)
- 9.13.3.0.41 (9.13 MR3 Refresh)
- 9.13.3.0.106 (9.13 MR3 Refresh 2)
- 9.13.3.0.121 (9.13 MR3 Refresh 3)
- 9.13.3.0.133 (9.13 MR3 Refresh 4)
- 9.13.3.0.145 (9.13 MR3 Refresh 5)
- 9.13.3.0.157 (9.13 MR3 Refresh 6)
- 9.13.3.0.164 (9.13 MR3 Refresh 7)
- 10.0.0.0.1424 (10.0 GA)
- 10.0.0.0.1449 (10.0 Patch 1)
- 10.0.1.0.17 (10.0 MR1)
- 10.0.1.0.35 (10.0 MR1 Refresh)
- 10.0.1.0.44 (10.0 MR1 Refresh 2)
- 10.0.1.0.61 (10.0 MR1 Refresh 3)
- 10.0.1.0.83 (10.0 MR1 Refresh 4)
- 10.0.1.0.88 (10.0 MR1 Refresh 5)
- 10.0.1.0.90 (10.0 MR1 Refresh 6)

NOTE

If you do not have a valid Support Entitlement contract at this time, then typically you would not be able to upgrade ZoneDirector to this release. But, due to Security Bulletin 20191224 the entitlement check will be suspended temporarily to allow the upgrade of your ZoneDirector. Please upgrade your controllers as soon as possible, so that you do not miss out on this critical upgrade.

If you are running an earlier version, you must first upgrade to one of the above builds before upgrading to this release.

Enhancements and Resolved Issues

This section lists new features and enhancements that have been added in this release, and any customer-reported issues from previous releases that have been resolved in this release.

New Access Points

- New Access Point: H320

The H320 is an 802.11a/b/g/n/ac Wave 2 dual band access point with integrated 3-port Ethernet, in a form factor designed for mounting to electrical outlet boxes. The H320 is targeted for hospitality and MDU applications where it will be installed one per room for a typical hotel room. The switch ports can be used for in-room wired applications like IPTV and/or to provide a wired alternative for guest internet access.

The H320 has one 10/100/1000 Mbps Ethernet port and two 10/100 Mbps Ethernet ports. The Gigabit port on the rear of the unit supports 802.3af PoE input. The PD will identify as a Class 3 device with a max draw of 12.95W.

NOTE

The H320 does not support mesh.

- New Access Point: R720

The R720 is a new dual-band concurrent 4x4:4 802.11ac Wave 2 access point capable of 160 MHz and 80+80 MHz channelization, designed for high density indoor applications. The R720 features one 10/100/1000 Ethernet port, and one 100/1000/2500 Ethernet port that supports 802.3af and 802.3at Power Over Ethernet (PoE), and a USB port for IoT applications.

See the *Known Issues* section for more information on R720 limitations/power supply considerations.

Enhancements

- Increased ZoneDirector 1200 Capacity Limits

The maximum AP and client limits that ZoneDirector 1200 supports have been increased. The max number of APs has been increased from 75 to 150, and the max clients/DPSKs/guest passes has been increased from 2,000 to 4,000. The max number of temporary licenses remains 75.

- New User Interface

This release includes an updated and redesigned web user interface. The new UI provides an updated layout, updated network health dashboard overview, reorganized menu structure, and a new map view interface based on Google Maps.

- New AP Model Support

This feature allows administrators to import a new AP model patch file to ZoneDirector to add new AP models without requiring a full upgrade of the ZoneDirector firmware. In this way, new APs can be introduced without the need to wait for the next ZD firmware release.

- Bonjour Fencing

Bonjour Fencing provides a mechanism to limit the scope of Bonjour (mDNS) service discovery in the physical/spatial domain. While Bonjour Fencing is related to Bonjour Gateway, they are two separate features designed for different purposes. Bonjour Gateway bridges mDNS services across VLANs, and is useful because Bonjour is designed as a same-VLAN protocol.

Bonjour Fencing limits the range of Bonjour service discovery within physical space, which is useful because logical network boundaries (VLANs) do not always correlate well to physical boundaries within a building/floor.

- RADIUS CoA Message Support

Added support for RADIUS Change of Authorization (CoA) messages. CoA enables the dynamic reconfiguration of sessions from external authentication, authorization, and accounting (AAA) servers. The following CoA attributes are supported in this release:

- Idle timeout
- Session Timeout
- Accounting interval
- Uplink rate limit
- Downlink rate limit
- Filter ID (ACL ID)

- Role Based and Named ACL

The Role Based ACL feature allows administrators to apply different access controls to different groups of users based on role. This enhancement complements the existing per-WLAN ACL functionality by providing another way to enforce access control rules without the need to create separate WLANs for different user groups.

- 160 MHz and 80+80 MHz Channelization for R720 and T610
- BSS Min Rate, OFDM Only and Mgmt Tx Rate

Enhancements and Resolved Issues

Resolved Issues in Build 10.0.1.0.93

Added the ability to set BSS Min Rate, OFDM Only and Mgmt Tx Rate in WLAN configuration forms. These options can be configured to improve overall throughput capacity and prevent older 802.11b clients from joining in high density environments.

- Per-SSID Rate Limiting

Added the option to configure rate limiting on a per-WLAN basis (in addition to the existing per-user rate limiting). If per-SSID rate limiting is enabled, per-user rate limiting is disabled.

- Application Recognition and Control Enhancements

This release adds the ability to import new application signature packages to ZoneDirector to update the list of system-defined applications and the ability to define QoS traffic shaping and rate limiting on a per-application basis.

- 802.11w Protected Management Frames

Added the ability to enable management frame protection for any WPA2-AES (either 802.1X or PSK) encrypted WLANs. The Protected Management Frame (PMF), also known as Management Frame Protection (MFP), is defined in 802.11w to protect 802.11 Robust Management frames, including Disassociation, Deauthentication, and Robust Action frames.

- Spectrum Analysis

Spectrum Analysis is now supported on all 802.11ac Wave 1 and Wave 2 APs.

- 802.1X WLAN Performance Enhancement

Improved 802.1X handling procedures to prevent overloading in high density 802.1X environments.

- Captive Portal WLAN Performance Enhancement

This enhancement improves handling of captive portal service by offloading the process to the AP, reducing the impact on ZoneDirector's resources. Additionally, several enhancements have been made to ZoneDirector to improve handling of HTTP/HTTPS requests and authentication rate.

- Guest Access Enhancements

Guest access options have been redesigned to allow greater flexibility and convenience for both admin-generated guest passes and self-service guest passes. The guest pass generation workflow has been updated, and guest passes can now be generated and managed from the Monitor page as well as the configuration page.

- The Self-Service Guest Pass sponsor email now contains ZoneDirector's IP address.

- Added the ability to manually approve AP join requests via CLI command.

Resolved Issues in Build 10.0.1.0.93

- Resolved two security issues related to UI vulnerabilities. For security incidents and responses, see www.ruckuswireless.com/security.

Resolved Issues in Build 10.0.1.0.90

- Resolved an issue that could cause failure to configure an AP via the web interface. [ER-7834]
- Resolved an issue that could cause failure to configure an NTP server when the server name contains dashes. [ER-7843]
- Resolved an issue where ZoneDirector would not report session data by default when management by SmartCell Insight was enabled. [ER-7762]
- Resolved an issue where multicast traffic unexpectedly dropped for wireless clients associated with Open/None WLANs with tunnel enabled. [ER-7291]
- Resolved an issue related to TCP SACK Panic - Kernel Vulnerability CVE-2019-11477, CVE-2019-11478 and CVE-2019-11479. [AP-11589]
- Resolved an issue where configuration saved in Access Point might corrupted randomly.[ER-7225]

Resolved Issues in Build 10.0.1.0.88

- Resolved an issue where the LDAP authentication would fail if extended ASCII characters were used in user name accounts. [ER-6372]
- Resolved an issue where the "Remarks" column did not display correctly in the "Generated Guest Pass" web page. [ER-7257]
- Resolved an issue where Access Points might fail to receive WLAN setting from ZoneDirector after failover in high density environments. [ER-7307]
- Resolved a kernel panic issue on APs located in high density environments when associated wireless clients were frequently roaming in and out of range. [ER-6689]
- Resolved an issue on R310 APs where the 5G radio would not function properly in 20 MHz channelization mode. [ER-6969]
- Resolved an issue on 11ac Wave 1 APs where unsupported data rates were used to send the first data packet to a wireless client over the 5 GHz radio. [ER-7018]
- Resolved an issue where the incorrect redirection URL was sent for guest authentication by ZoneDirector if the "domain" field was not set in the uploaded certificate. [ER-7156]
- Removed unnecessary space character in the wireless client roam out event messages. [ER-7332]

Resolved Issues in Build 10.0.1.0.83

- Resolved an issue where ZF7782-E AP would fail to join ZoneDirector. [ER-6690]
- Resolved a performance issue on 11ac Wave 2 APs caused by beacon drifting. [ER-6425/ER-4988]
- Resolved a target fail detected issue on APs. [ER-6665]
- Resolved an issue where sqllited daemon on ZoneDirector would not function properly under certain conditions. [ER-6706]
- Enhanced the AP group configuration flow in the ZoneDirector GUI with additional warning messages. [ER-6715]
- Enhanced GUI performance when accessing Access Point list and Dashboard web pages. [ER-6858]
- Resolved an issue where the following special characters would be disallowed when used in WPA2-PSK passphrases: "", ";", "%", "\$", "&", "| |". [ER-6875]
- Resolved an issue where ZoneDirector would fail to display updated GPS data received from outdoor APs. [ER-6439]
- Resolved an issue where client fingerprinting would fail to properly identify clients running Windows 10 version 1803. [ER-6414]
- Resolved an issue where client fingerprinting would fail to properly identify clients running Ubuntu version 17. [ER-6325]
- Resolved an issue where dips would happen intermittently on Client Trend and Application Traffic graphs. [ER-6420]
- Resolved an issue where the description field setting for Role Policy would be lost after upgrading to 10.0.1. [ER-6418]
- Resolved an issue where SCI would intermittently fail to receive statistics data from the active ZoneDirector with Smart Redundancy enabled. [ER-6476]
- Resolved an issue where RADIUS Authentication with TLS encryption enabled would fail due to ZoneDirector using the default certificate instead of the newly imported certificate. [ER-6316]
- Resolved a target fail detected issue on 11ac Wave 2 APs when MU-MIMO was enabled. [ER-6233, ER-6214]
- Resolved an issue where ARP packets for internal communications between the AP and cable modem modules could leak out to the cable network. [ER-5985]
- Resolved an issue with incorrect protocol and device types in Ekahau tag frames. [ER-6139]
- Resolved an issue with the general health status filter on the ZoneDirector Dashboard. [ER-6149]
- Resolved an issue where Rogue Device reporting didn't work properly when the SSID name was configured as a non-English name. [ER-6248]
- Resolved an issue where AeroScout RFID tag detection did not function properly on 11ac Wave 2 APs. [ER-5935]

Enhancements and Resolved Issues

Resolved Issues in Build 10.0.1.0.61

- Resolved an issue where SNMP walk results on node "ruckusZDWLANStaSignalStrength" were inaccurate and renamed the node name from the previous name "ruckusZDWLANStaAvgRSSI" to "ruckusZDWLANStaAvgSNR". [ER-6943]
- Resolved an issue where users attempting to authenticate to a Hotspot WLAN 10 times within 5 minutes would be unexpectedly blocked by ZoneDirector. [ER-6978]
- Updated Ruckus logo in guest service and setup wizard with new ARRIS logo. [ZF-18682]

Resolved Issues in Build 10.0.1.0.61

- Resolved an AP target failure reboot issue when no valid rates for transmission were found. [ER-6021]
- Resolved an issue where ZoneDirector would fail to apply WLAN configuration settings to an AP when packet loss occurred as the AP was joining. [ER-6022]
- Resolved an issue where traffic counters would receive incorrect accumulation data in accounting packets. [ER-6042]
- Resolved an issue where ZoneDirector would fail to forward tunneled packets if the 802.1p value was set as a non-zero value. [ER-6150]
- Resolved an issue where the Apple auto pop-up browser might not show up after association to a Social Media WLAN. [ER-6086]
- Resolved an issue where ZoneDirector would not send a new syslog message when a station rejoins with the same IP address. [ER-6049]
- Resolved an issue where the Zero-IT file could not be downloaded from ZoneDirector via URL [https://ZD IP\(domain\)/user/user_extern_prov.jsp](https://ZD IP(domain)/user/user_extern_prov.jsp) [ER-6063]
- Resolved an issue where clicking one of the health status filters on the Dashboard would not properly redirect to the filtered list of clients/APs according to the health status level. [ER-6149]
- Removed the extraneous line "signal" from the wireless client detail page. [ER-6151]
- Resolved an issue where a false alarm 'failure' message would be displayed when the SMS message was actually sent successfully. [ER-6044]

Resolved Issues in Build 10.0.1.0.44

- Resolved an issue where the SNMP ID of the WLAN interface would change after an AP reboot or failover. [ER-5718]
- Resolved a security issue related to DNSMASQ (CVE-2017-14491, CVE-2015-3294). For information on security incidents and responses, see <https://www.ruckuswireless.com/security>. [AP-6652]
- Resolved an issue where an AP couldn't forward wireless client multicast packets to the network. [ER-5100]
- Resolved an issue where the station MAC address is wrongly carried as the user name in the radius accounting messages. [ER-5623]
- Resolved multiple unexpected reboot issues on C110 AP. [ER-5851]
- Resolved an issue where ZoneDirector would incorrectly approve unsupported AP join requests when the AP model value carried in the join request packet was empty. [ER-5763]
- Resolved an issue where per-station rate limit settings could not be configured via web UI when the interface language selected was a European language other than English. [ER-5744]
- Added "Ruckus-Location" attribute in RADIUS request packets for 802.1x WLAN authentication. [ER-5880]
- Resolved an issue where multicast and broadcast IPs could not be configured as destination in L3 ACL rules via ZD CLI. [ER-5894]
- Resolved an issue where LLDP settings would be overwritten after upgrading. With this fix, ZoneDirector will now by default configure APs' LLDP settings as "Keep AP setting" to prevent overwriting the existing settings. [ER-5106]
- Resolved several display issues on Guest Pass printout pages. [ER-5901/ER-5975]
- Resolved an issue where an additional blank page would appear in the Guest Pass printout page. [ER-5966]

Resolved Issues in Build 10.0.1.0.35

- Resolved an issue related to the WPA KRACK vulnerability. For information on security incidents and responses, see <https://www.ruckuswireless.com/security>. [AP-6463]

This release fixes multiple vulnerabilities (also known as KRACK vulnerabilities) discovered in the four-way handshake stage of the WPA protocol. The Common Vulnerabilities and Exposures (CVE) IDs that this release addresses include:

- CVE-2017-13077
- CVE-2017-13078
- CVE-2017-13079
- CVE-2017-13080
- CVE-2017-13081
- CVE-2017-13082

Client devices that have not yet been patched are vulnerable to KRACK attacks. To help protect unpatched client devices from KRACK attacks, Ruckus strongly recommends running the CLI commands below:

```
ruckus# config
ruckus(config)# system
ruckus(config-sys)# eapol-no-retry
```

Use the following command to disable:

```
ruckus(config-sys)# no eapol-no-retry
```

Enabling the eapol-no-retry feature (disabled by default) prevents the AP from retrying packets in the key exchange process that have been found to be vulnerable to KRACK attacks. Note that enabling this feature may introduce client connectivity delay in high client density environments.

For more information about KRACK vulnerabilities, visit the Ruckus Support Resource Center at <https://support.ruckuswireless.com/krack-ruckus-wireless-support-resource-center>.

- Resolved an issue with guest pass email and SMS messages where the validity period would be displayed incorrectly, including the following typo: "MOE_ days." [ER-5716]

Resolved Issues in Build 10.0.1.0.17

- Resolved an issue that R710/R610/T710/T610 APs' Ethernet link could not come up with certain multipleG supported switches. [ER-5466]
- Resolved an issue where rate limiting did not work properly for WLANs with the "drop multicast packets from associated clients" option enabled. [ER-5319]
- Resolved an issue where Domain Name System (DNS) in the AP crashed randomly when it attempts to resolve a Domain Name [ER-5398]
- Updated the "Generating and Delivering a Single Guest Pass" chapter in the online help to remove a few unnecessary steps. [ER-5597]
- Resolved several guest pass issues: [ER-5612]
 - The validation date of an existing guest pass did not show correctly in the printed instructions, if the user logged off and then logged back on.
 - The "Guest Pass Generated" page displayed duplicated guest passes.
 - 'Generated PSK/certificate' under Monitor tab was shown as 'Generierte' instead of 'Generierte PSK/Zertifikate'
 - "Day" in Guest Pass printout was shown as "Tage" when German was selected as the system language.
- Resolved an issue where a newly created AP group failed to inherit Tx power setting from the default AP group as "Full." [ER-5586]
- Resolved an issue where DVLAN for 802.1x EAP+MAC authentication could not be enabled using the ZoneDirector CLI. [ER-5584]
- Resolved an issue where the Microsoft VSA value for the RADIUS server was incorrectly applied as the station's rate limit. [ER-5461]

Caveats, Limitations, and Known Issues

Resolved Issues in Build 10.0.0.0.1449

- Resolved an issue where the LLDP settings were overwritten after ZoneDirector was upgraded. With the fix, ZoneDirector now retains the AP's LLDP settings ("Keep AP setting"). [ER-5106]
- Resolved an issue where SNMP OIDs related to APLAN statistics showed incorrect values. [ER-5560]
- Guest pass printout instructions should no longer display incorrect values for guest pass validity. [ER-5499]

Resolved Issues in Build 10.0.0.0.1449

- Resolved an issue with Facebook WiFi WLANs where mobile device redirection stopped working after upgrading to 10.0. [ER-5481]
- The C110 Cable Modem APs can now be configured with both Ethernet ports as Access Ports. [ER-5244]
- Optimized the severity levels of several syslog messages to prevent flooding syslog servers with excessive log messages. [ER-5400, ER-5410]
- Resolved a "Terms of Use" display issue on Android devices using the default browser. [ER-5422]
- Resolved an issue where Guest Passes generated via the admin console would display as "Invalid Guest Pass" when the WLAN name contained special characters. [ER-5439, ZF-17090]
- Resolved an issue where clients could be assigned incorrect VLAN IDs if the client switches between 802.1x and portal based WLANs with different VLAN settings. [ER-5362]
- Resolved an AP kernel panic reboot issue caused by receiving malformed BTM response frames from some types of clients. [ER-5386]

Resolved Issues in Build 10.0.0.0.1424

- Upgraded Dropbear version to 2016.74 to address security vulnerabilities. [ER- 5033]
- Resolved an issue that could cause AP heartbeats to be lost and APs to move from one controller to another, and added syslog messages to indicate when ARP usage and UIF queue thresholds are exceeded. [ER-5117]
- Lowered the severity level of an incorrectly categorized error message that could cause customer syslogs to fill up with "ieee80211_vlan_clr_filter" errors. [ER- 5065]
- Resolved an issue that could prevent Ubuntu clients from being properly identified as Linux OS. [ER-5121]
- Resolved a false radar detection issue for 7982 and R500 APs. [ER-4632]
- Resolved a security issue related to the x-frame options. See <https://www.ruckuswireless.com/security> for security incidents and responses. [ER-4966]
- Double colons "::" can now be used in IPv6 addresses when creating IPv6 ACLs from the web interface. [ER-5182]
- Upgraded OpenSSL version from 1.0.1q (1.0.1m) to 1.0.2i to address security vulnerabilities. [ZF-15764]
- 802.11r Fast BSS Transition can no longer be enabled when WLAN type is Autonomous. [ER-5135]

Caveats, Limitations, and Known Issues

This section lists the caveats, limitations and known issues in this release.

Known Issues

General

- When Ekahau tag detection is enabled, the AP encapsulates tag frames in TZSP and UDP, but the TZSP header is incorrectly encapsulated with the protocol byte set to the wrong value and device type bytes missing in the 802.11 data field. [ZF-15992]
- MAC Authentication Bypass on ZF 7055 wired ports does not work when a Management IP address is enabled. [ZF-15335, ER-3789]
Workaround: Disable the “Default gateway is connected with this interface” option.
- Some web pages are not completely translated into all languages supported by the new web user interface. [ZF-17158]
- QoS Null Data frames cannot be captured by Ruckus AP’s packet capture using Wireshark with its default settings. [ZF-16840]
- With Ruckus AP R720 when in sniffer mode, the Phy type, bandwidth and data rate elements are decoded incorrectly. [ZF-16839]
- Zero-IT provisioning file is not properly downloading for some Android clients running older versions of Chrome browser. [ZF-16771]
- 160 MHz and 80+80 MHz channelization options are not available in AP group settings. [ZF-16584]

Workaround: Configure 160 / 80+80 MHz channelization for specific APs from the AP settings.

R720

- 160 MHz channelization is only available in 2x2:2 mode.
- On APs that support 160/80+80 MHz channelization (R610 and R720), Smart Mesh is currently unsupported if the AP is configured with either 160 or 80+80 MHz channelization. Mesh is supported for all other channelization modes. [AP- 4425]
- LACP bonding of Eth1 and Eth0 is not supported in the initial R720 GA release. [SCG-64854]
- Configuring static link speed on the R720’s 2.5G Ethernet port using Ruckus AP CLI command is not supported. The port will auto-negotiate to 2.5Gbps/1000Mbps/100Mbps rates. [SCG-63519]
- When an AP running the solo image configured to use 80+80 MHz channelization attempts to join a ZoneDirector, it will reboot repeatedly. [ZF-17061]
Workaround: Set channelization to 80 MHz, or factory reset the AP before migrating it to ZoneDirector.
- 160/80+80 MHz requires two chains for Tx and Rx. In 802.3af mode, there is only sufficient power to enable one Tx chain on 2.4 GHz and 5 GHz on R720. Due to this constraint, the AP will effectively operate in 80 MHz channelization mode even if it is configured to operate in 160/80+80 MHz mode. [ZF-16890]
- 802.1x operation of the Eth1 (PoE) interface may not operate in supplicant or authenticator mode. [SCG-67078, SCG-67079]
- In 80+80 channelization mode, Channel 138 is unable to detect radar so this channel has been removed from the supported AP channels. However, channels 132-144 might still be visible on the SmartZone web interface. [SCG-66704]
- Sensitive 2.4GHz clients might get disconnected from the AP. This issue occurs because of baseband timeouts, which cause clients to reconnect or roam. Enabling the OFDM-only option reduces these client reconnects or roams. [SCG- 66325]
- SpeedFlex uplink test results are lower than actual. The performance deviation can be as high as 30%. [SCG-64611]
- TCPDUMP via AP Shell on Eth1 fails to capture LLDP packets. To capture LLDP frames, Ruckus Wireless recommends performing port mirroring on the AP interconnect switch port. [SCG-64323]
- The PoE switch port must run link layer discovery protocol (LLDP) power over Ethernet/MDI (PoE+) in order for the R720 to operate in AT-power mode (802.3at). This may require enabling both LLDP and Power via MDI (dot3) on the switch, if available. When operating with an 802.3af-only capable switch, the AP radios will operate in suboptimal (1x4) mode.

The following table lists the R720’s power modes and the corresponding feature set under the different power modes.

Caveats, Limitations, and Known Issues

Bonjour Fencing

PoE Mode	Power Level	5GHz Radio	2.4GHz Radio	2.5G Eth Port	1G Eth Port	USB	160/ 80+80
DC	Full Power	4 x 4	4 x 4	2500M/ 1000M/ 100M	10M/100M/ 1000M	0.5 W	Yes 2 x 2
802.3af	15.4 W	1 x 4	1 x 4	2500M/ 1000M/ 100M	X	X	No
802.3at	25.54 W	4 x 4	4 x 4	2500M/ 1000M/ 100M	X	X	Yes 2 x 2

Bonjour Fencing

- Background scanning and rogue AP detection take some time when performing neighbor AP updates. The amount time varies depending on the scanning frequency, the physical environment and other factors. As a result, Bonjour services provided by a neighbor AP may not be discoverable by wireless users immediately.
- For wired fencing, only one wired rule can be configured per Bonjour service in each Bonjour fencing policy. [ZF-16911]
- Services coming from Bonjour fencing-disabled APs cannot be fenced.
- Bonjour fencing of Chromecast services is not supported in this release.
- Bonjour fencing is not supported on Mesh APs in this release.
- Bonjour fencing is not supported for tunneled WLANs in this release.



© 2020 CommScope, Inc. All rights reserved.
Ruckus Wireless, Inc., a wholly owned subsidiary of CommScope, Inc.
350 West Java Dr., Sunnyvale, CA 94089 USA
www.ruckuswireless.com