

RUCKUS ZoneDirector 10.5.1 GA Refresh 4 Release Notes

Supporting ZoneDirector 10.5.1

Copyright, Trademark and Proprietary Rights Information

© 2023 CommScope, Inc. All rights reserved.

No part of this content may be reproduced in any form or by any means or used to make any derivative work (such as translation, transformation, or adaptation) without written permission from CommScope, Inc. and/or its affiliates ("CommScope"). CommScope reserves the right to revise or change this content from time to time without obligation on the part of CommScope to provide notification of such revision or change.

Export Restrictions

These products and associated technical data (in print or electronic form) may be subject to export control laws of the United States of America. It is your responsibility to determine the applicable regulations and to comply with them. The following notice is applicable for all products or technology subject to export control:

These items are controlled by the U.S. Government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations.

Disclaimer

THIS CONTENT AND ASSOCIATED PRODUCTS OR SERVICES ("MATERIALS"), ARE PROVIDED "AS IS" AND WITHOUT WARRANTIES OF ANY KIND, WHETHER EXPRESS OR IMPLIED. TO THE FULLEST EXTENT PERMISSIBLE PURSUANT TO APPLICABLE LAW, COMMSCOPE DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, FREEDOM FROM COMPUTER VIRUS, AND WARRANTIES ARISING FROM COURSE OF DEALING OR COURSE OF PERFORMANCE. CommScope does not represent or warrant that the functions described or contained in the Materials will be uninterrupted or error-free, that defects will be corrected, or are free of viruses or other harmful components. CommScope does not make any warranties or representations regarding the use of the Materials in terms of their completeness, correctness, accuracy, adequacy, usefulness, timeliness, reliability or otherwise. As a condition of your use of the Materials, you warrant to CommScope that you will not make use thereof for any purpose that is unlawful or prohibited by their associated terms of use.

Limitation of Liability

IN NO EVENT SHALL COMMSCOPE, COMMSCOPE AFFILIATES, OR THEIR OFFICERS, DIRECTORS, EMPLOYEES, AGENTS, SUPPLIERS, LICENSORS AND THIRD PARTY PARTNERS, BE LIABLE FOR ANY DIRECT, INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, EXEMPLARY OR CONSEQUENTIAL DAMAGES, OR ANY DAMAGES WHATSOEVER, EVEN IF COMMSCOPE HAS BEEN PREVIOUSLY ADVISED OF THE POSSIBILITY OF SUCH DAMAGES, WHETHER IN AN ACTION UNDER CONTRACT, TORT, OR ANY OTHER THEORY ARISING FROM YOUR ACCESS TO, OR USE OF, THE MATERIALS. Because some jurisdictions do not allow limitations on how long an implied warranty lasts, or the exclusion or limitation of liability for consequential or incidental damages, some of the above limitations may not apply to you.

Trademarks

ARRIS, the ARRIS logo, COMMSCOPE, RUCKUS, RUCKUS WIRELESS, the Ruckus logo, the Big Dog design, BEAMFLEX, CHANNELFLY, FASTIRON, ICX, SMARTCELL and UNLEASHED are trademarks of CommScope, Inc. and/or its affiliates. Wi-Fi Alliance, Wi-Fi, the Wi-Fi logo, Wi-Fi Certified, the Wi-Fi CERTIFIED logo, Wi-Fi Protected Access, the Wi-Fi Protected Setup logo, Wi-Fi Protected Setup, Wi-Fi Multimedia and WPA2 and WMM are trademarks or registered trademarks of Wi-Fi Alliance. All other trademarks are the property of their respective owners.

Contents

Document History	4
Introduction	4
New in This Release	4
New Access Point in 10.5.1.0.124.....	4
New Features.....	4
Changed Behavior.....	5
Hardware and Software Support	5
Supported Platforms.....	5
Supported Access Points.....	5
Upgrade Information	6
Supported Upgrade Paths.....	6
Known Issues	8
Resolved Issues	8
Resolved Issues in Build 10.5.1.0.240.....	8
Resolved Issues in Build 10.5.1.0.199.....	8
Resolved Issues in Build 10.5.1.0.193.....	9
Resolved Issues in Build 10.5.1.0.176.....	9
Resolved Issues in Build 10.5.1.0.124.....	9
Client Interoperability	10
PC OS.....	10
Smartphone/Tablet OS.....	10
Officially Supported Browsers.....	10
Not Officially Supported Browsers	10
Zero-IT Compatibility with Client Devices.....	11
Client Interoperability Known Issues.....	12

Document History

Revision Number	Summary of Changes	Publication Date
A	Initial release notes	March 2023

Introduction

This document provides release information on ZoneDirector release 10.5.1, including new features, enhancements, known issues, caveats, workarounds, upgrade details, and interoperability information for version 10.5.1.

NOTE

By downloading this software and subsequently upgrading the ZoneDirector and/or the AP to version 10.5.1, please be advised that:

- The ZoneDirector will periodically connect to RUCKUS and RUCKUS will collect the ZoneDirector serial number, software version, and build number. RUCKUS will transmit a file back to the ZoneDirector and this will be used to display the current status of the ZoneDirector Support Contract.
- The AP may send a query to RUCKUS containing the AP's serial number. The purpose is to enable your AP to autonomously connect with a wireless LAN controller operated by your choice of cloud service provider. RUCKUS may transmit back to the AP, the Fully Qualified Domain Name (FQDN) or IP address of the controller that the AP will subsequently attempt to join.

Please be advised that this information may be transferred and stored outside of your country of residence where data protection standards may be different.

New in This Release

This section lists the new features and changed behavior in this release.

New Access Point in 10.5.1.0.124

- H350

This release adds ZoneDirector support for the new H350 indoor 802.11ax AP.

H350 is an 802.11ax Dual-Band Concurrent 2x2:2 .11ax (5GHz) and 2x2:2 .11ax (2.4GHz) for indoor applications that comes with a three port Ethernet (10/100/1000) with PoE input. It doesn't have USB port.

- T350se

T350se is an 802.11ax Dual-Band Concurrent 2x2:2 .11ax (5GHz) and 2x2:2 .11ax (2.4GHz) for outdoor applications that comes with a single port Ethernet (1000/100/10M). It also has an integrated USB port.

New Features

- ZD upgrade support multiple version migration

Beginning from ZoneDirector 10.5.1, the upgrade limitation of N-2 version is removed. Following versions can be directly upgraded to 10.5.1 with configuration migration.

- 10.1.0.0, 10.1.1.0, 10.1.2.0, 10.2.0.0, 10.2.1.0, 10.3.0.0, 10.3.1.0, 10.4.0.0, 10.4.1.0, 10.5.0

- Wi-Fi 6 disable

From the UI, the user can enable or disable Wi-Fi 6 in WLAN for 11ax APs.

- Replace FTP with HTTPS

As a security enhancement, File Transfer Protocol (FTP) is replaced with Hypertext Transfer Protocol Secure (HTTPS).

- Channel 144 support

Channel 144 is supported for country codes "US" and "JP" when DFS is enabled.

- Configuration change recoding

Records all the configuration change commands from the web UI, CLI, mobile app, and UMM to track the configuration changes.

- DNSmasq upgrade for security issue

DNSmasq is upgraded to address a security issue.

Changed Behavior

- Remove AP USB page from ZD web UI because uploading AP USB command has not been supported on the platform. [ZF-21993]
- Beginning with Zone Director 10.5.1, the AP image upgrade uses HTTPS. If there is an upgrade failure using HTTPS, you can enable the legacy AP image upgrade option to FTP under **Administrator > Upgrade** tab. Zone Director supports either HTTPS or FTP as the AP image upgrade option.

Hardware and Software Support

Supported Platforms

ZoneDirector firmware version **10.5.1.0.240** supports the following ZoneDirector models:

- ZoneDirector 1200

Supported Access Points

ZoneDirector version **10.5.1.0.240** supports the following RUCKUS Access Point models:

Indoor AP	Outdoor AP
C110	E510
H320	T300
H510	T300e
R310	T301n
R320	T301s
R500	T310c
R510	T310d
R550	T310n
R600	T310s
R610	T610
R650	T610s
R710	T710

Upgrade Information

Indoor AP	Outdoor AP
R720	T710s
R730	T750
R750	T750se
R850	T350c
R350	T350d
H550	T350se*
H350*	

NOTE

H350 and T350se were introduced in the GA release.

Upgrade Information

Supported Upgrade Paths

The following ZoneDirector release builds can be directly upgraded to this release:

- 10.1.0.0.1515 (10.1 GA)
- 10.1.1.0.26 (10.1 MR1)
- 10.1.1.0.35 (10.1 MR1 Refresh 1)
- 10.1.1.0.42 (10.1 MR1 Refresh 2)
- 10.1.1.0.55 (10.1 MR1 Refresh 3)
- 10.1.1.0.62 (10.1 MR1 Refresh 4)
- 10.1.1.0.79 (10.1 MR1 Refresh 5)
- 10.1.2.0.120 (10.1 MR2)
- 10.1.2.0.210 (10.1 MR2 Refresh 1)
- 10.1.2.0.251 (10.1 MR2 Refresh 2)
- 10.1.2.0.270 (10.1 MR2 Refresh 3)
- 10.1.2.0.275 (10.1 MR2 Refresh 4)
- 10.1.2.0.277 (10.1 MR2 Refresh 5)
- 10.1.2.0.306 (10.1 MR2 Refresh 6)
- 10.1.2.0.318 (10.1 MR2 Refresh 7)
- 10.2.0.0.189 (10.2 GA)
- 10.2.1.0.58 (10.2 Patch Release - R720 LACP)
- 10.2.1.0.75 (10.2 MR1)
- 10.2.1.0.129 (10.2 MR1 Refresh 1)
- 10.2.1.0.135 (10.2 MR1 Refresh 2)
- 10.2.1.0.147 (10.2 MR1 Refresh 3)
- 10.2.1.0.159 (10.2 MR1 Refresh 4)
- 10.2.1.0.183 (10.2 MR1 Refresh 5)

- 10.2.1.0.192 (10.2 MR1 Refresh 6)
- 10.2.1.0.200 (10.2 MR1 Refresh 7)
- 10.2.1.0.212 (10.2 MR1 Refresh 8)
- 10.2.1.0.218 (10.2 MR1 Refresh 9)
- 10.3.0.0.362 (10.3 GA)
- 10.3.0.0.389 (10.3 GA for R750)
- 10.3.0.0.398 (10.3 GA Refresh 1)
- 10.3.1.0.21 (10.3 MR1)
- 10.3.1.0.24 (10.3 MR1 Refresh 1)
- 10.3.1.0.30 (10.3 Patch for ER-7600)
- 10.3.1.0.42 (10.3 MR Refresh 2)
- 10.3.1.0.45 (10.3 MR1 Refresh 3)
- 10.3.1.0.46 (10.3 MR Patch for ER-8328)
- 10.3.1.0.52 (10.3 MR Patch for AP-13802)
- 10.4.0.0.69 (10.4 GA)
- 10.4.0.0.70 (10.4 GA Refresh 1)
- 10.4.0.0.98 (10.4 GA Refresh 2)
- 10.4.0.0.109 (10.4 Patch for ER-8683)
- 10.4.1.0.214 (10.4.1 GA)
- 10.4.1.0.226 (10.4.1 GA Refresh 1 for T750se)
- 10.4.1.0.236 (10.4.1 Patch for ER-9106)
- 10.4.1.0.238 (10.4.1 GA Refresh 2)
- 10.4.1.0.248 (10.4.1 Patch for ER-9807)
- 10.4.1.0.254 (10.4.1 GA Refresh 3)
- 10.4.1.0.257 (10.4.1 GA Refresh 4)
- 10.4.1.0.272 (10.4.1 GA Refresh 5)
- 10.5.0.0.150 (10.5 GA Release)
- 10.5.0.0.190 (10.5 GA Refresh 1)
- 10.5.0.0.212 (10.5 GA Refresh 2)
- 10.5.1.0.124 (10.5.1 GA)
- 10.5.1.0.167 (10.5.1 Patch 1)
- 10.5.1.0.176 (10.5.1 GA Refresh 1)
- 10.5.1.0.193 (10.5.1 GA Refresh 2)
- 10.5.1.0.199 (10.5.1 GA Refresh 3)

If you are running an earlier version, you must upgrade ZoneDirector to one of the above builds before upgrading to this release.

If you do not have a valid Support Entitlement contract, you will be unable to upgrade ZoneDirector to this release. See the *Administer > Support* page for information on Support Entitlement activation.

Known Issues

NOTE

For information and detailed instructions (including video tutorials) on upgrading ZoneDirector, visit the RUCKUS Support How-To Hub at <https://support.ruckuswireless.com/how-to-hub>.

Known Issues

This sections lists the caveats, limitations, and known issues in this release.

Issue	ZF-22071
Description	In ZoneDirector GUI, device model MAC OS 12.0.1 is shown as MAC OS X 10.15.7.

TABLE 1 Channel 144 Support

Issue	ZF-22013
Description	Channel 144 is not available on 11ac APs in Japan.

Resolved Issues

This section lists the customer-reported issues that have been resolved in this release.

Resolved Issues in Build 10.5.1.0.240

- Resolved an issue where AP T310D failed to go beyond the provisioning stage after upgrading to 10.5.1.0.199. [ER-12227]
- Resolved a kernel panic issue caused by some specific DNS packets. [ER-12012]
- Resolved an issue that 11ac w1 AP failed to forward PN-DCP packets. [ER-12089]
- Resolved a target assert issue caused by cyclecnt wraparound or HW register reading error. [ER-11947]
- Resolved an issue where APs T710/T710s showed incorrect link speed on 1G-SFP port in the 'SNMP GET' results. [ER-11605]
- Resolved an 11ax target assert issue when AP was doing Radio calibration. [ER-11740]
- Resolved a client's IP/Hostname display issue in ZD GUI. [ER-12046]

Resolved Issues in Build 10.5.1.0.199

- Resolved a target assert issue during some kinds of pdev reset. [ER-11551]
- Resolved an Air Time Fairness-related issue for 2*2 11ac wave2 APs. [ER-11374]
- Resolved an issue that caused AP kernel panic in case of PPDU status is OK, but DONE bit not set. [ER-11361]
- Resolved a kernel panic issue caused by insufficient headroom. [ER-11327]
- Resolved a kernel panic issue happened during AP scanning under certain conditions. [ER-11164]
- Resolved an issue that a large number of visitors shown on vSpot server. [ER-11208]
- Resolved an issue AP may reboot due to watchdog timeout. [ER-11113]
- Resolved a kernel panic issue caused by SKB corruption. [ER-10725]
- Resolved a fingerprints related issue. [ER-10981]
- Added support for Twilio's new API. [UN-6659]

- Resolved a WPA2 decryption issue on 2.4G radio of 11ac Wave 1 APs. [ER-11449]
- Resolved an issue where bound DPSK key is not updated in standby ZD under certain condition. [ER-11661]
- Resolved a Bonjour profile name character limit issue. [ER-11542]

Resolved Issues in Build 10.5.1.0.193

- Resolved an issue where packet loss issue during background scanning on some particular APs. [ER-10181]
- Resolved an Air Time Fairness (ATF) issue on T350/H550 and R550 APs. [ER-11360]
- Resolved an issue where certain clients could not be authenticated with 8021.X for AD. [ER-11482]
- Resolved an issue where an AP rpm key "wlan-band-bal-enable" had an invalid value. [ER-10115]
- Enhanced DNS spoofing on Access Point to resolve the domain name of ZoneDirector for clients associated with WISPr and web authentication WLANs. [ER-11376]
- Resolved an issue where ZD failed to get certain data from AP when there was a special symbol '\$' in the password. [ER-11615]

Resolved Issues in Build 10.5.1.0.176

- Resolved an issue where the STAMGR daemon on ZoneDirector crashed due to corrupted data received. [ER-10850]
- Resolved an issue where the STAMGR daemon on ZoneDirector crashed due to unexpected overwrite in memory data. [ER-10906]
- Resolved an issue where duplicate MAC entries in different letter cases were allowed in the L2 ACL list. [ER-11056]
- Resolved an issue where the FTP setting changed to disable after upgrading to 10.5.1. [ER-10990]
- Resolved an issue where the DPSK client was no longer able to authenticate successfully after ZoneDirector failover. [ER-10967]
- Resolved an issue where certain allowed service was unexpectedly blocked when the application policy denial rule was configured as block all tunneling. [ER-11140]
- Resolved an intermittent client disconnect issue. [ER-10674/ER-10760]
- Enhanced the SMS notification feature to support JSON format in POST data. [ER-11148]
- Resolved an issue where the redirector time is longer than expected for Facebook WLAN authentication. [ER-10917]
- Resolved an issue that caused AP with clients roaming reboot frequently due to kernel panic. [ER-11242]
- Resolved an issue that caused R750 AP to reboot due to kernel panic. [ER-10795]
- Resolved an issue where connected clients lost network connection randomly. [ER-10797]
- Resolved an issue where client entries did not clear properly after inactivity timeout. [ER-10844]
- Resolved an issue that caused AP kernel panic due to buffer overflow. [ER-10918]
- Resolved an issue that caused R850 AP to reboot due to kernel panic under certain conditions. [ER-10944]
- Resolved an issue that caused R710 AP and R610 AP to reboot due to kernel panic under certain conditions. [ER-10607]
- Resolved an airtime fairness-related issue for 11ac APs. [ER-10530]
- Resolved an issue where certain kind of clients were unable to obtain IP addresses when proxy ARP is enabled on the WLAN. [ER-10593]
- Resolved a performance issue on AP with 3X3 MIMO devices. [ER-10474]

Resolved Issues in Build 10.5.1.0.124

- Resolved an issue where "Block client" option in Wireless LANs was not working. [ER-10820]
- Resolved an issue where Channel 144 is supported in Wi-Fi 6 AP with "Japan" country code. [ER-10189]
- Resolved an issue where Zero-IT prov.apk file failed to download using Chrome Browser. [ZF-22091]

Client Interoperability

ZoneDirector and RUCKUS APs use standard protocols to interoperate with third-party Wi-Fi devices. RUCKUS qualifies its functionality on the most common clients.

The following client operating systems and browsers have been tested for compatibility with this release (for specific OS and browser limitations, including compatibility with Zero-IT, see subsequent sections below).

PC OS

- Windows 7
- Windows 8
- Windows 8.1
- Windows 10
- Windows 11
- Windows 12
- Mac OS 10.9.5
- Mac OS 10.10
- Mac OS 10.11
- Mac OS 10.12
- Mac OS 10.13
- Mac OS 10.14
- Mac OS 10.15
- Mac OS 11

Smartphone/Tablet OS

- iOS (6.1, 7.0, 7.1, 8.1, 8.4, 9.2, 9.3, 10.0, 10.2, 10.3, 11.1/2/3/4, 12.0, 12.1, 12.2, 12.4, 13.0, 13.1, 13.2, 13.4, 13.5, 13.6, 13.7, 14.0, 14.1, 14.5, 14.6, 14.7)
- Android (4.1.2, 4.2.2, 4.3, 4.4.2, 4.4.4, 5.0.1, 5.0.2, 5.1, 6.0, 7.0, 7.1.1, 8, 9, 10, 11)
- Windows Phone (7, 8, 8.1, 10)
- BlackBerry OS (10, 10.3.2) not supported with Zero-IT
- Chrome OS (47.0, 49.0) not Supported with Zero-IT

Officially Supported Browsers

- Internet Explorer 10, 11
- Firefox 34 and later
- Chrome 39 and later

Not Officially Supported Browsers

Safari, Dolphin, Opera Mini, Android Default, BlackBerry Default, etc.

Zero-IT Compatibility with Client Devices

TABLE 2 Zero-IT Compatibility

OS	WPA2 WLAN			802.1x EAP (external Radius Server)		
	Step 1	Step 2	Step 3	Step 1	Step 2	Step 3
iOS 6.x	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 7.x	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 8.0	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 8.0.2	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 8.1	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 9.0	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 10 .0	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 10 .2	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 10 .3	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
iOS 11.x	Y (ZF-19663)	Y (ZF-19663)	N (ZF-2888)	Y (ZF-19663)	Y (ZF-19663)	N (ZF-2888)
iOS 12.0	Y	Y	N (ZF-2888)	Y	Y	N (ZF-2888)
MAC OS 10.8.5	Y	Y	Y	Y	Y	N (ZF-4699)
Mac OS 10.9.3	Y	Y	Y	Y	Y	N (ZF-4699)
MAC OS 10.9.4	Y	Y	Y	Y	Y	N (ZF-4699)
Mac OS 10.9.5	Y	Y	Y	Y	Y	N (ZF-4699)
Mac OS 10.10	Y	Y	Y	Y	Y	N (ZF-4699)
Mac OS 10.11	Y	Y	Y	Y	Y	N (ZF-4699)
Mac OS 10.12	Y	Y	Y	Y	Y	N (ZF-4699)
Mac OS 10.13	Y	Y	Y	Y	Y	N (ZF-4699)
Windows 7	Y	Y	Y	Y	Y	Y
Windows 8	Y	Y	Y	Y	Y	Y
Windows 8.1	Y	Y	Y	Y	Y	Y
Windows 10	Y	Y	Y	Y	Y	Y
Windows Phone 8	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)
Windows Phone 8.1	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)	N (ZF-3478)
BlackBerry OS 10.1	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)
BlackBerry OS 10.3	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)	N (ZF-6402)
Kindle 7.4.9	Y	Y	Y	Y	Y	Y
Android 4.0.4	Y	Y	Y	Y	Y	Y
Android 4.1.2	Y	Y	Y	Y	Y	Y
Android 4.4.4	Y	Y	Y	Y	Y	Y
Android 5.0	Y	Y	Y	Y	Y	Y
Android 6.0	Y (ZF-19664)	Y	Y	Y (ZF-19664)	Y	Y
Android 7.0	Y (ZF-19664)	Y	Y	Y (ZF-19664)	Y	Y
Android 7.1.1	Y (ZF-19664)	Y	Y	Y (ZF-19664)	Y	Y
Android 8.0	Y (ZF-19664)	Y	Y	Y (ZF-19664)	Y	Y
Chrome OS	N (ZF-8076)	N (ZF-8076)	N (ZF-8076)	N (ZF-8076)	N (ZF-8076)	N (ZF-8076)

Client Interoperability

Client Interoperability Known Issues

- Step 1: Download Zero-IT file
- Step 2: Install Zero-IT script
- Step 3: Automatically connect to the appropriate SSID

Client Interoperability Known Issues

- Zero-IT is not supported on Windows Phone 7/8/8.1 devices. [ZF-3478]
- Zero-IT is not supported on Blackberry OS devices. [ZF-6402]
- Zero-IT is not supported on Chrome OS devices. [ZF-8076]
- iOS clients cannot connect to the Zero-IT WLAN automatically. Users must reconnect to the target WLAN after installing the Zero-IT configuration file. [ZF-2888]
- Mac OS 10.7 and 10.8 cannot automatically connect to an 802.1x EAP WLAN after installing Zero-IT script. [ZF-4699]
- In some situations, Chromebook clients can take up to 10-50 seconds to resume sending traffic after a channel change. [ZF-14883]
- iOS 11.x cannot download successfully Zero-IT profile by way of a mini browser. [ZF-19049]
- With OS version 10.0.19043, Microsoft Surface Pro 3 fails to connect when both 11r and 11w options are enabled in Open Auth WLAN. (Also failing with WPA2/WPA3-Mixed encryption). [ZF-22081]



© 2023 CommScope, Inc. All rights reserved.
350 West Java Dr., Sunnyvale, CA 94089 USA
<https://www.commscope.com>