

# Ruckus ZoneDirector Release Notes 9.13.3

Supporting ZoneDirector 9.13.3 Refresh 7

Part Number: 800-71912-001 Rev A

Publication Date: May 2018

## **Copyright, Trademark and Proprietary Rights Information**

© 2018 ARRIS Enterprises LLC. All rights reserved.

No part of this content may be reproduced in any form or by any means or used to make any derivative work (such as translation, transformation, or adaptation) without written permission from ARRIS International plc and/or its affiliates ("ARRIS"). ARRIS reserves the right to revise or change this content from time to time without obligation on the part of ARRIS to provide notification of such revision or change.

## **Export Restrictions**

These products and associated technical data (in print or electronic form) may be subject to export control laws of the United States of America. It is your responsibility to determine the applicable regulations and to comply with them. The following notice is applicable for all products or technology subject to export control:

These items are controlled by the U.S. Government and authorized for export only to the country of ultimate destination for use by the ultimate consignee or end-user(s) herein identified. They may not be resold, transferred, or otherwise disposed of, to any other country or to any person other than the authorized ultimate consignee or end-user(s), either in their original form or after being incorporated into other items, without first obtaining approval from the U.S. government or as otherwise authorized by U.S. law and regulations.

### Disclaimer

THIS CONTENT AND ASSOCIATED PRODUCTS OR SERVICES ("MATERIALS"), ARE PROVIDED "AS IS" AND WITHOUT WARRANTIES OF ANY KIND, WHETHER EXPRESS OR IMPLIED. TO THE FULLEST EXTENT PERMISSIBLE PURSUANT TO APPLICABLE LAW, ARRIS DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, FREEDOM FROM COMPUTER VIRUS, AND WARRANTIES ARISING FROM COURSE OF DEALING OR COURSE OF PERFORMANCE. ARRIS does not represent or warrant that the functions described or contained in the Materials will be uninterrupted or error-free, that defects will be corrected, or are free of viruses or other harmful components. ARRIS does not make any warranties or representations regarding the use of the Materials in terms of their completeness, correctness, accuracy, adequacy, usefulness, timeliness, reliability or otherwise. As a condition of your use of the Materials, you warrant to ARRIS that you will not make use thereof for any purpose that is unlawful or prohibited by their associated terms of use.

## Limitation of Liability

IN NO EVENT SHALL ARRIS, ARRIS AFFILIATES, OR THEIR OFFICERS, DIRECTORS, EMPLOYEES, AGENTS, SUPPLIERS, LICENSORS AND THIRD PARTY PARTNERS, BE LIABLE FOR ANY DIRECT, INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, EXEMPLARY OR CONSEQUENTIAL DAMAGES, OR ANY DAMAGES WHATSOEVER, EVEN IF ARRIS HAS BEEN PREVIOUSLY ADVISED OF THE POSSIBILITY OF SUCH DAMAGES, WHETHER IN AN ACTION UNDER CONTRACT, TORT, OR ANY OTHER THEORY ARISING FROM YOUR ACCESS TO, OR USE OF, THE MATERIALS. Because some jurisdictions do not allow limitations on how long an implied warranty lasts, or the exclusion or limitation of liability for consequential or incidental damages, some of the above limitations may not apply to you.

### **Trademarks**

ARRIS, the ARRIS logo, Ruckus, Ruckus Wireless, Ruckus Networks, Ruckus logo, the Big Dog design, BeamFlex, ChannelFly, EdgeIron, FastIron, HyperEdge, ICX, IronPoint, OPENG, SmartCell, Unleashed, Xclaim, ZoneFlex are trademarks of ARRIS International plc and/or its affiliates. Wi-Fi Alliance, Wi-Fi, the Wi-Fi logo, the Wi-Fi CERTIFIED logo, Wi-Fi Protected Access (WPA), the Wi-Fi Protected Setup logo, and WMM are registered trademarks of Wi-Fi Alliance. Wi-Fi Protected Setup<sup>™</sup>, Wi-Fi Multimedia<sup>™</sup>, and WPA2<sup>™</sup> are trademarks of Wi-Fi Alliance. All other trademarks are the property of their respective owners.

# **Contents**

About This Release	4
Introduction	4
Supported Platforms and Upgrade Information	
Supported Platforms	
Upgrading to This Version	5
Enhancements and Resolved Issues	6
New Access Points	
Resolved Issues	7
Caveats, Limitations, and Known Issues	11
Known Issues	11

## **About This Release**

## Introduction

This document provides release information on ZoneDirector release 9.13.3, including new features, enhancements, known issues, caveats, workarounds, upgrade details and interoperability information for version 9.13.3.

#### NOTE

By downloading this software and subsequently upgrading the ZoneDirector and/or the AP to version 9.13.3, please be advised that:

- The ZoneDirector will periodically connect to Ruckus and Ruckus will collect the ZoneDirector serial number, software version and build number. Ruckus will transmit a file back to the ZoneDirector and this will be used to display the current status of the ZoneDirector Support Contract.
- The AP may send a query to Ruckus containing the AP's serial number. The purpose is to enable your AP to autonomously connect with a wireless LAN controller operated by your choice of cloud service provider. Ruckus may transmit back to the AP, the Fully Qualified Domain Name (FQDN) or IP address of the controller that the AP will subsequently attempt to join.

Please be advised that this information may be transferred and stored outside of your country of residence where data protection standards may be different.

# **Supported Platforms and Upgrade Information**

## **Supported Platforms**

ZoneDirector version **9.13.3.0.164** supports the following ZoneDirector models:

- ZoneDirector 1200
- ZoneDirector 3000
- ZoneDirector 5000

### **Access Points**

ZoneDirector version **9.13.3.0.164** supports the following Access Point models:

- C110
- H500
- H510
- R300
- R310
- R500
- R510
- R600
- R610
- R700

- R710
- T300
- T300e
- T301n
- T301s
- T610
- T610s
- T710
- T710s
- ZF7055
- ZF7352
- ZF7372
- ZF7372-E
- ZF7781CM
- ZF7782
- ZF7782-E
- ZF7782-N
- ZF7782-S
- ZF7982

### EoS (End of Sale) APs

The following AP models have reached end-of-sale (EoS) status and, therefore, are no longer supported in this release. If your ZoneDirector is currently managing any of these models, a warning will appear when you attempt to upgrade.

If your ZoneDirector is currently managing any of these models, do NOT upgrade to this release. ZoneDirector will be unable to manage them.

- 7321
- 7321-U
- 7441
- 7761-CM
- 7762 series
- 7363
- 7343
- 7341
- sc8800-s
- sc8800-s-ac

## **Upgrading to This Version**

This section lists important notes on upgrading ZoneDirector to this version.

### Officially Supported 9.13.3 Upgrade Paths

The following ZoneDirector builds can be directly upgraded to ZoneDirector build 9.13.3.0.164:

- 9.10.0.0.218 (9.10 GA)
- 9.10.1.0.59 (9.10 MR1)
- 9.10.2.0.11 (9.10 MR2)
- 9.10.2.0.29 (9.10 MR2 Refresh)
- 9.10.2.0.41 (9.10 MR2 Refresh 2)
- 9.10.2.0.52 (9.10 MR2 Refresh 3)
- 9.12.0.0.336 (9.12 GA)
- 9.12.1.0.140 (9.12 MR1)
- 9.12.1.0.148 (9.12 MR1-Refresh)
- 9.12.2.0.101 (9.12.2 MR2)
- 9.12.2.0.204 (9.12.2 MR2 Patch)
- 9.12.2.0.219 (9.12 MR2 Refresh)
- 9.12.3.0.28 (9.12 MR3)
- 9.12.3.0.34 (9.12 MR3 Refresh)
- 9.12.3.0.49 (9.12 MR3 Refresh 2)
- 9.12.3.0.61 (9.12 MR3 Refresh 3)
- 9.12.3.0.75 (9.12 MR3 Refresh 4)
- 9.13.0.0.232 (9.13 GA)
- 9.13.1.0.11 (9.13.1 MR1)
- 9.13.1.0.26 (9.13.1 MR1 Refresh)
- 9.13.2.0.33 (9.13 MR2)
- 9.13.3.0.22 (9.13 MR3)
- 9.13.3.0.41 (9.13 MR3 Refresh 1)
- 9.13.3.0.106 (9.13 MR3 Refresh 2)
- 9.13.3.0.121 (9.13 MR3 Refresh 3)
- 9.13.3.0.133 (9.13 MR3 Refresh 4)
- 9.13.3.0.145 (9.13 MR3 Refresh 5)
- 9.13.3.0.157 (9.13 MR3 Refresh 6)

#### **NOTE**

If you do not have a valid Support Entitlement contract, you will be unable to upgrade ZoneDirector to this release. See **Administer** > **Support** page for information on Support Entitlement activation.

If you are running an earlier version, you must first upgrade to one of the above builds before upgrading to this release.

# **Enhancements and Resolved Issues**

This section lists new features and enhancements that have been added in this release and resolved issues from previous releases.

### **New Access Points**

New Access Point: C110

The C110 is a new 802.11ac dual-band concurrent wall plate cable modem AP. Designed to be installed in an outlet box with a coaxial cable termination, the C110 features a DOCSIS/EuroDOCSIS 3.0 cable modem for backhaul, a USB port for uses such as a BLE dongle or other IoT applications, and two RJ-45 LAN ports for in-room wired Ethernet access.

New Access Point: T610 and T610s

The T610 is a carrier-grade 802.11ac Wave 2 outdoor AP designed for enterprise and service provider outdoor WLAN applications. The T610 includes dual radios with 4x4:4 spatial streams, two 10/100/1000 Ethernet ports (one port supports PoE input), and 802.1ax Ethernet port aggregation. The T610 also includes a USB port for BLE Smart Beacon, Zigbee or other IoT devices.

The T610s is the sector antenna version of the T610. It includes all of the same features as the T610.

## **Resolved Issues**

### Resolved Issues in Build 164

- Resolved an issue where client fingerprinting would fail to properly identify clients running Windows 10 version 1803. [ER-6414]
- Resolved an issue where LDAP authentication would fail if the user name included extended ASCII characters. [ER-6372]
- Resolved an issue where Radius authentication with TLS encryption would fail due to ZoneDirector's use of the default certificate instead of the newly imported certificate. [ER-6316]
- Resolved an issue where ARP packets for internal communication between C110 AP and CM modules could leak out to the cable network. [ER-5985]
- Resolved a target fail detected issue on 11ac wave2 APs. [ER-5977]
- Resolved an issue where the AeroScout RFID tag detection would not function properly on 11ac Wave2 APs. [ER-5935]

### Resolved Issues in Build 157

- Resolved an issue where ZoneDirector would not send a new syslog message when a station rejoins with the same IP address. [ER-6049]
- Resolved an issue where a false alarm 'failure' message would appear on the web interface when the SMS message was actually sent successfully. [ER-6044]
- Resolved an issue where the Zero-IT file could not be downloaded from ZoneDirector via URL https://ZD IP(domain)/ user/user\_extern\_prov.jsp [ER-6063]
- Revolved an issue where R710/T710/R610/T610/R720 Ethernet port links might not come up when connected to some switches. [ER-5466]
- Resolved an issue with incorrect protocol and device types in Ekahau tag frames. [ER-6139]
- Resolved an issue on 11ac wave 2 APs where application data would not appear on the wireless client page. [ER-6034]
- Resolved an issue with traffic counters receiving incorrect accumulated usage data in RADIUS accounting packets. [ER-6042]

#### Resolved Issues in Build 145

- Resolved an issue that could cause ZoneDirector to be unable to properly update client's IP address assigned by DHCP.
   [ER-5634]
- Resolved an issue that could cause sqlited process failure and the resulting false alarm "system recovered from failure" to be triggered. [ER-5741]
- Optimized the severity levels of several syslog messages to prevent flooding syslog servers with excessive log messages. [ER-5400]
- Resolved an issue where ZoneDirector would incorrectly approve unsupported AP join requests when the AP model value carried in the join request packet was empty. [ER-5763]
- Resolved an issue where per-station rate limit settings could not be configured via web UI when the interface language selected was a European language other than English. [ER-5744]
- Resolved an issue that could cause AP heartbeats lost and APs to move from one controller to another, and added syslog messages to indicate when ARP usage and UIF queue thresholds have been exceeded. [ER-5117]
- Add "Ruckus-Location" attribute in radius request packets for 802.1x WLAN authentication. [ER-5880]
- Resolved an issue where multicast and broadcast IPs could not be configured as destination in L3 ACL rules. [ER-5894]
- Resolved a memory leak issue related to the mesh network process that could cause the APs to disconnect and be unable to reconnect. [ER-4265]
- Resolved an issue where an AP couldn't forward wireless client multicast packets to the network. [ER-5100]
- Resolved a security issue related to DNSMASQ (CVE-2017-14491, CVE-2015-3294). For information on security incidents and responses, see <a href="https://www.ruckuswireless.com/security">https://www.ruckuswireless.com/security</a>. [AP-6652]
- Resolved a Target Assert issue on wave-2 APs that occurred when APs received ADDBA frames that contain the win\_credit parameter with a value of zero (invalid). [ER-4982, SCG-64151]

#### Resolved Issues in Build 133

 Resolved an issue related to the WPA KRACK vulnerability. For information on security incidents and responses, see https://www.ruckuswireless.com/security. [AP-6463]

This release fixes multiple vulnerabilities (also known as KRACK vulnerabilities) discovered in the four-way handshake stage of the WPA protocol. The Common Vulnerabilities and Exposures (CVE) IDs that this release addresses include:

- CVE-2017-13077
- CVE-2017-13078
- CVE-2017-13079
- CVE-2017-13080
- CVE-2017-13081
- CVE-2017-13082

Client devices that have not yet been patched are vulnerable to KRACK attacks. To help protect unpatched client devices from KRACK attacks, Ruckus strongly recommends running the CLI commands below:

```
ruckus# config
ruckus(config)# system
ruckus(config-sys)# eapol-no-retry
```

Use the following command to disable:

```
ruckus(config-sys)# no eapol-no-retry
```

Enabling the eapol-no-retry feature (disabled by default) prevents the AP from retrying packets in the key exchange process that have been found to be vulnerable to KRACK attacks. Note that enabling this feature may introduce client connectivity delay in high client density environments.

For more information about KRACK vulnerabilities, visit the Ruckus Support Resource Center at https://support.ruckuswireless.com/krack-ruckus-wireless-support-resource-center.

- Resolved an issue with Aeroscout tags not functioning properly on R510 APs. [ER-5191]
- Resolved an issue where Dynamic VLAN could not be enabled via CLI for 802.1x EAP+MAC authentication. [ER-5584]
- Resolved an issue where a newly created AP group would fail to inherit Tx power settings from the system default AP group as "Full". [ER-5586]
- Resolved an issue with online help "Generating and Delivering a Single Guest Pass" chapter where unnecessary steps were removed. [ER-5597]

### Resolved Issues in Build 121

- Resolved an issue with R510 APs that could cause the AP to reboot due to an incorrect sleep function call being invoked in an interrupt context, causing unexpected behavior. **[ER-5213]**
- Resolved an AP kernel panic reboot issue caused by receiving malformed BTM response frames from certain clients. **[ER-5386]**
- Resolved an issue where rate limiting would not work properly for WLANs with the "drop multicast packets from associated clients" option enabled. **[ER-5319]**
- Guest pass printout instructions should no longer display incorrect values for guest pass validity. [ER-499]
- Resolved a memory leak issue which was causing R510 APs to target assert. [ER-5383]
- Resolved an issue that potentially blocked users from configuring the AP port setting through ZD CLI. [ER-5587]

### Resolved Issues in Build 106

- Fixed an AP reboot issue caused by corruption of beacon buffer. [ER-4212]
- Resolved an issue where new APs locked to country code Z2 would fail to join a ZoneDirector configured with country code Egypt. **[ER-5308]**
- Resolved an issue where LLDP settings would be overwritten after upgrading from 9.8.1. With this fix, ZoneDirector will now by default configure APs' LLDP settings as "Keep AP setting" to prevent overwriting the existing settings. **[ER-5106]**
- Resolved an issue where the following erroneous error message would recur every hour: "Radius server [] has not responded to multiple requests. [This server may be down or unreachable.]." [ER-5122]
- Resolved an issue with an 'X-Frame Options Header Not Set' configuration error reported by Nessus. [ER-4966]
- Resolved an issue that could cause incorrect user name data to be sent in RADIUS accounting packets under specific circumstances. [ER-5315]
- Resolved an issue where both Ethernet ports on the C110 Cable Modem AP could not be configured as Access Ports with wired 802.1x authentication enabled. [ER-5244]
- Double colons "::" can now properly be used in IPv6 addresses when creating IPv6 ACLs from the web interface. **[ER-5182]**
- Resolved an LLDP MAC address issue. [ER-5228]
- Resolved a device fingerprinting issue where Ubuntu clients would fail to be categorized as Linux OS clients. [ER-5121]
- Resolved an issue where, if Force DHCP was enabled, clients would be deauthenticated after roaming to another AP if the VLAN after roaming was the same as the previous VLAN. [ER-4992]

#### Enhancements and Resolved Issues

Resolved Issues

- Resolved an issue with excessive "ieee80211 vlan clr filter" error messages sent to syslog. [ER-5065]
- Resolved an issue where an AP could fail to stay on a statically configured channel. [ER-5074]
- Resolved an R700 Target Assert failure issue occurring on multiple APs. [ER-4971]
- Resolved an issue with excessive AP-to-AP ARP traffic causing network congestion in high-density settings where port isolation rather than fast roaming is used. **[ER-5138]**

### Resolved Issues in Build 41

- Resolved an issue that could cause the ZoneDirector web interface to become unresponsive and new clients unable to connect when very large numbers of 802.1X clients attempted to authenticate at the same time. [ZF-16335, ER-4712]
- Resolved an issue that could cause ZoneDirector 5000 web process failure, resulting in failover to the standby ZoneDirector. [ER-4123, ER-5003]
- Resolved an issue where R710 Root APs would be incorrectly categorized as Mesh APs when Link Aggregation was enabled and in Auto mode. [ER-4616]
- Improved handling of LWAPP packets to reduce errors due to ZoneDirector unexpectedly receiving certain kinds of LWAPP packets. [ER-4793]
- Added language translations for Self-Service Guest Pass UI pages. New languages include Dutch, German, Japanese, Swedish, Arabic, Czech, Turkish, and Brazilian Portuguese. [ER-4956]
- Resolved a "Terms of Use" display issue. [ER-4975]
- Resolved an issue where, in dense environments, sometimes the AP sent an incorrect number of associated client events to the controller. **[ER-4844]**
- Resolved an issue that could cause clients configured with static IP addresses to be incorrectly displayed as automatically assigned DHCP addresses. [ER-5027]
- Resolved an ARP table leak issue that could prevent clients from completing hotspot authentication after ZoneDirector had been running for a long time. **[ER-5041]**
- Resolved an R710 "target fail detected" issue. [ER-4982]
- Upgraded Dropbear version to 2016.74 to address security vulnerabilities.[ER-5033]]

#### Resolved Issues in Build 22

- Resolved a security issue related to Redhat CVE-2016-5195. For information on security incidents and responses, see https://www.ruckuswireless.com/security. [ER-4687]
- Resolved several Ruckus Cloud security issues. For information on security incidents and responses, see <a href="https://www.ruckuswireless.com/security">https://www.ruckuswireless.com/security</a>. [ER-4697], [ER-4555], [ER-4560]
- Resolved a kernel memory leak issue on APs, which eventually caused watchdog timeout reboots. [ER-3544]
- Guest Pass keys are no longer incorrectly displayed on the screen when the Notification Method is set to "Mobile" and not "Show on Screen." [ER-3188]
- Resolved an issue that could cause ZD-controlled ZF 7372 APs to reboot due to watchdog timeout. [ER-1922]
- Resolved an issue where IPTV connected to AP may experience pixelation due to packet loss on eth0 interface. [ER-4038]
- Resolved an issue with printing multiple Guest Passes at once, where the printout would incorrectly show "invalid date" for the expiration date. [ER-4724]
- Resolved an issue with cloning L3/L4/IP address ACLs that would prevent the user from replicating an existing ACL successfully. [ER-4792]

- Resolved an Ethernet port stuck issue on R510 APs that could cause the APs to reboot and disconnect from the controller. [ER-4685]
- Resolved an issue that could cause ZF7781-CM APs to reboot continuously with the message "reset to factory defaults." This fix enables the AP to detect the condition and reboot to recover when this condition occurs. [ER-4689]

## Caveats, Limitations, and Known Issues

This section lists the caveats, limitations and known issues in this release.

### **Known Issues**

- C110 stops sending packets in testing when using an Ethernet port as the uplink and pushing 60-80Mbps tunneled traffic to ZoneDirector. This issue should have no customer impact since the C110 typically uses its coaxial cable port as its uplink. [ZF-16212]
- C110 Cable Modem IP address is displayed incorrectly on ZoneDirector monitoring pages when the CM is assigned an IPv6 address. [ZF-16183]
- T610 USB Port status is displayed incorrectly on ZoneDirector monitoring pages when the AP is in 802.3af PoE mode. [**ZF-16278**]
- The Zero-IT prov file might fail to download/install via the auto pop-up mini browser on Macbook/Android devices. **[ZF-16510]**

**Workaround**: Manually open any of the normal web browsers (Safari, Chrome, IE or Firefox) to re-download and install the zero-IT prov file.