

Omni Switch 6450/ 6350

Release 6.7.2.52.R01

The following is a list of issues that have been identified and corrected in AOS software release. This document is intended to be used as a pre-upgrade guide and does not replace the Release Notes, which are created for every GA release of software.

Important Notice: For a copy of software, release not posted on the Web or if you have any question or concern please contact Alcatel’s Technical Support Department.

Problems Fixed Between Builds 49 and 52 2

Problems Fixed Between Builds 49 and 52

PR **226162** Build: 52
Summary: stack reboot after upgraded to 6.7.2.R01
Explanation: Prevent system hang/reboot when executing CLI command “show ip helper dhcp-snooping binding”
