

Ruckus ZoneDirector 10.1 Release Notes For T310 Series

Supporting ZoneDirector 10.1

Part Number: 800-71828-001 Rev A Publication Date: January 2018

Copyright Notice and Proprietary Information

© 2018 ARRIS Enterprises, LLC. All rights reserved.

No part of this documentation may be used, reproduced, transmitted, or translated, in any form or by any means, electronic, mechanical, manual, optical, or otherwise, without prior written permission of or as expressly provided by under license from ARRIS.

Destination Control Statement

Technical data contained in this publication may be subject to the export control laws of the United States of America. Disclosure to nationals of other countries contrary to United States law is prohibited. It is the reader's responsibility to determine the applicable regulations and to comply with them.

Disclaimer

THIS DOCUMENTATION AND ALL INFORMATION CONTAINED HEREIN ("MATERIAL") IS PROVIDED FOR GENERAL INFORMATION PURPOSES ONLY. ARRIS and RUCKUS WIRELESS, INC. AND THEIR LICENSORS MAKE NO WARRANTY OF ANY KIND, EXPRESS OR IMPLIED, WITH REGARD TO THE MATERIAL, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY, NON-INFRINGEMENT AND FITNESS FOR A PARTICULAR PURPOSE, OR THAT THE MATERIAL IS ERROR-FREE, ACCURATE OR RELIABLE. ARRIS and RUCKUS RESERVE THE RIGHT TO MAKE CHANGES OR UPDATES TO THE MATERIAL AT ANY TIME.

Limitation of Liability

IN NO EVENT SHALL ARRIS OF RUCKUS BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, SPECIAL OR CONSEQUENTIAL DAMAGES, OR DAMAGES FOR LOSS OF PROFITS, REVENUE, DATA OR USE, INCURRED BY YOU OR ANY THIRD PARTY, WHETHER IN AN ACTION IN CONTRACT OR TORT, ARISING FROM YOUR ACCESS TO, OR USE OF, THE MATERIAL.

Trademarks

Ruckus Wireless, Ruckus, the bark logo, BeamFlex, ChannelFly, Dynamic PSK, FlexMaster, ICX, Simply Better Wireless, SmartCell, SmartMesh, SmartZone, Unleashed, ZoneDirector and ZoneFlex are trademarks of Ruckus Wireless, Inc. in the United States and in other countries. Other trademarks may belong to third parties.

Contents

About This Release	4
Supported Platforms and Upgrade Information	4
Supported Platforms	
Access Points	4
Upgrading to This Version	
Enhancements and Resolved Issues	6
New Access Points	6
Enhancements and New Features	7
Resolved Issues	8
Caveats, Limitations and Known Issues.	ç

About This Release

This document provides release information on ZoneDirector release 10.1, including new features, enhancements, known issues, caveats, workarounds, upgrade details and interoperability information for version 10.1.

NOTE

By downloading this software and subsequently upgrading the ZoneDirector and/or the AP to version 10.1, please be advised that:

- The ZoneDirector will periodically connect to Ruckus and Ruckus will collect the ZoneDirector serial number, software
 version and build number. Ruckus will transmit a file back to the ZoneDirector and this will be used to display the current
 status of the ZoneDirector Support Contract.
- The AP may send a query to Ruckus containing the AP's serial number. The purpose is to enable your AP to
 autonomously connect with a wireless LAN controller operated by your choice of cloud service provider. Ruckus may
 transmit back to the AP, the Fully Qualified Domain Name (FQDN) or IP address of the controller that the AP will
 subsequently attempt to join.

Please be advised that this information may be transferred and stored outside of your country of residence where data protection standards may be different.

Supported Platforms and Upgrade Information

Supported Platforms

ZoneDirector version 10.1.0.0.1525 supports the following ZoneDirector models:

- ZoneDirector 1200
- ZoneDirector 3000

NOTE

ZoneDirector 5000 is discontinued as of this release, and cannot be upgraded to version 10.1 or later.

Access Points

ZoneDirector version 10.1.0.0.1525 supports the following Access Point models:

- C110
- H320
- H500
- H510
- R300
- R310
- R500
- R510
- B600
- R610
- R700

- R710
- R720
- T300
- T300e
- T301n
- T301s
- T310c*
- T310d*
- T310n*
- T310s*
- T610
- T610s
- T710
- T710s
- ZF7055
- ZF7352
- ZF7372
- ZF7372-E
- ZF7781CM
- ZF7782
- ZF7782-E
- ZF7782-N
- ZF7782-S
- ZF7982

NOTE

*This patch release adds support for new APs: T310c, T310d, T310n, T310s.

Upgrading to This Version

This section lists important notes on upgrading ZoneDirector to this version.

Officially Supported 10.1 Upgrade Paths

The following release builds can be directly upgraded to this release:

• 10.1.0.0.1515 (10.1 GA)

If you are running an earlier version, you must upgrade to one of the above builds before upgrading to this release.

If you do not have a valid Support Entitlement contract, you will be unable to upgrade ZoneDirector to this release. See the *Administer > Support* page for information on Support Entitlement activation.

Adding a New AP Model

ZoneDirector 10.1 release supports the registration of new AP models that were not yet available when this ZoneDirector version was released.

Before starting this procedure, verify that the controller is running release 10.1 (GA) or later.

NOTE

This procedure will restart ZoneDirector services. During the upgrade process, service outage will occur as the ZoneDirector will restart automatically to complete the upgrade.

Follow these steps to register a new AP model with the controller:

- 1. Contact Ruckus for the AP patch file that will enable the controller to support the new AP model (for example, T310-10.1.0.0.1525.encrypted.patch).
- 2. Get the AP patch file, and then save or move the patch file to a location that you can access from the computer that you are using to access the controller's web interface.
- 3. Log on to the controller's web interface as Super Admin.
- 4. Go to the Administer > Upgrade page, and then click Choose File under AP Patch Firmware. Select the AP Patch file to upload.
- 5. Click Upgrade.
- 6. The controller adds the T310 series (T310c, T310d, T310n, T310s) to AP release 10.1.0.0.1525. (New AP models are added into *Administer > Upgrade* page under *Current Software*.)
- 7. After the controller completes upgrading, connect the new AP model to the network. The new AP model registers with the controller, and then the controller upgrades the AP firmware to release 10.1.0.0.1525.
- 8. Go to the *Access Points* page, and then verify that the new AP model you added to the controller is listed under *Currently Managed APs*.
- 9. Under the **Status** column, verify that new AP model isn't Approval Pending. **Allow** it from the **Action** column if it is Approval Pending.

You have completed adding a new AP model to the controller.

Enhancements and Resolved Issues

This section lists new features and enhancements that have been added in this release, and any customer-reported issues from previous releases that have been resolved in this release.

New Access Points

New Access Point: T310 Series

The T310 series (T310c, T310d, T310n, T310s) is a new outdoor dual-band 802.11ac Wave 2 AP designed for flexible installation in a wide variety of outdoor environments.

The T310d has an omni antenna, an extended temperature range (-40C to 65C), one 10/100/1000 Ethernet port that supports 802.3af PoE in, optional DC power input, and a USB port for IoT devices, such as a BLE or Zigbee dongle, Z-Wave, etc.

The T310c has an omni antenna, with narrower operating temperature range, and no USB port or DC power supply.

The T310s is the sector antenna variant of the T310 series, and the T310n is the narrow sector antenna variant.

Enhancements and New Features

This section lists the new features and enhancements in this release.

• New UI - Phase 2

This release introduces the second stage of the new redesigned web interface, which highlights network health and traffic statistics visibility, and includes several enhancements to the overall UI organization and user-friendliness.

Adaptive Band Balancing

This feature enhances the existing Band Balancing feature by allowing client redistribution dynamically after association, rather than only once during the initial association.

Additional SMS Service Provider Support

Customers can now configure a custom SMS service provider for delivering alarms and guest passes, in addition to the existing Twilio and Clickatell SMS provider options.

Client Connection Troubleshooting

This feature is designed to help customers diagnose wireless client connection issues to determine why a client fails to connect to the wireless network.

Multiple Social Media Logins on the Same WLAN

Existing Social Media login methods (Facebook, Google, LinkedIn and Microsoft) can now be used simultaneously on the same WLAN.

WeChat Support

A new social media WLAN type – WeChat – is now available.

Social Media Login Scale Enhancement

Enhanced the scaling capabilities of Social Media WLANs.

Role-Based Application Recognition and Control

Application Recognition and Control (ARC) features can now be applied to users based on user role, in addition to the existing per-WLAN configuration. Role-based application policies take precedence when both role-based and WLAN-based policies exist.

• Source IP/Port-Based Access Control Lists

Customers can now configure ACLs to allow or deny access to wireless clients from an external source IP address or port.

LWAPP Tunnel Performance Enhancement

This enhancement improves the performance of tunneled WLAN traffic by reducing some time-consuming operations in the Ruckus GRE tunnel module.

Ability to Export DPSK Records

The Dynamic PSK Batch Generation page now provides an additional option to download generated DPSK records.

• Recovery SSID Enhancement

Enhanced the AP configure and recovery SSIDs to allow remote wireless configuration of newly installed APs and recovery of isolated mesh APs.

Client Flow Data Logging

This feature allows ZoneDirector to transmit client session data to a syslog server for use in legal obligation compliance for Hotspot service providers in certain countries, or for emerging Wi-Fi monetization projects, where the ability to export session data could be useful for marketing or for use by a third-party platform.

DTIM, Directed Multicast, and RTS-CTS Configuration Options

Enhancements and Resolved Issues

Resolved Issues

The following new configuration options are available for configuring advanced wireless settings: DTIM, Directed Multicast/Broadcast Threshold, and Protection Mode.

New SNMP OID Support

Several new SNMP OIDs have been introduced for configuring 802.11d and BSS Minrate settings.

Bonjour Fencing Enhancement

This release enhances the functionality of the Bonjour Fencing feature by allowing fencing policies to be deployed on multiple wired devices.

End of Support for ZoneDirector 5000

ZoneDirector 5000 is discontinued as of this release, and cannot be upgraded to version 10.1 or later.

Disabled TLSv1.0

TLSv1.0 has been disabled in this release due to security concerns, and ZoneDirector now supports only TLSv1.1 and v1.2. For information on security incidents and responses, see https://www.ruckuswireless.com/security.

Resolved Issues

Resolved an issue related to the WPA KRACK vulnerability. For information on security incidents and responses, see https://www.ruckuswireless.com/security. [AP-6463]

This release fixes multiple vulnerabilities (also known as KRACK vulnerabilities) discovered in the four-way handshake stage of the WPA protocol. The Common Vulnerabilities and Exposures (CVE) IDs that this release addresses include:

- CVE-2017-13077
- CVE-2017-13078
- CVE-2017-13079
- CVE-2017-13080
- CVE-2017-13081
- CVE-2017-13082

Client devices that have not yet been patched are vulnerable to KRACK attacks. To help protect unpatched client devices from KRACK attacks, Ruckus strongly recommends running the CLI commands below:

```
ruckus# config
ruckus(config)# system
ruckus(config-sys)# eapol-no-retry
```

Use the following command to disable:

```
ruckus(config-sys)# no eapol-no-retry
```

Enabling the eapol-no-retry feature (disabled by default) prevents the AP from retrying packets in the key exchange process that have been found to be vulnerable to KRACK attacks. Note that enabling this feature may introduce client connectivity delay in high client density environments.

For more information about KRACK vulnerabilities, visit the Ruckus Support Resource Center at https://support.ruckuswireless.com/krack-ruckus-wireless-support-resource-center.

 Resolved an issue where the max clients limit was not enforced on Autonomous WLANs when an AP was disconnected from ZoneDirector. [ER-3887]

Caveats, Limitations and Known Issues

This section lists the caveats, limitations and known issues in this release.

- Some new or modified UI pages have not been fully translated into all available UI languages. [ZF-17158, ZF-18280, ZF-18230]
- Apple iOS 11.x clients are unable to connect to an 802.1x WLAN using Zero-IT in some situations due to changes in the way iOS 11 handles TLS connections. [ZF-18254]
- When running the R720 AP in sniffer mode, the Phy type, bandwidth and data rate elements are decoded incorrectly. [ZF-16839]
- R720 APs are unable to properly fence Bonjour services when Bonjour Fencing is enabled on the AP. [ZF-18314]
- BSS Fast Transition roaming is not working properly for Google Pixel and Sony Z5 clients. [ZF-18319]
- Client Fingerprinting does not properly display the Host Name for some clients, including some Android 8.0 and Chrome OS clients. [ZF-18143]
- For APs that were upgraded to 10.1 from a previous release, the uniform recovery SSID passphrase will continue to use the
 previous format until after a factory reset (e.g., "ruckus-<admin password>"), instead of the new passphrase format ("<adminpassword>"). [ZF-18625]
- Northbound Portal interface may be incompatible with some versions of curl or python. [ZF-18649]
- Mac OS clients may fail to be redirected to the intended URL after authentication to a Facebook WLAN. [ZF-18607]
- Spectrum Analysis on the 5 GHz radio may fail to run on some outdoor APs in certain situations due to an error that prevents the AP from changing to certain channels correctly. [ZF-18573]
- Nexus 5X clients will not connect to dot1x Zero-IT profiles using the Zero-IT Android APP. [ZF-18252]