



ZoneDirector 9.12.2.0.204 Patch Notes

ZoneDirector Release 9.12.2.0.204 (9.12.2 Patch 1) addresses the following known issues found in release 9.12.2.0.101. If the devices on your network are experiencing these issues, Ruckus Wireless recommends upgrading to this patch release.

Upgrade Paths Supported

- 9.9.0.0.205 (9.9 GA release)
- 9.9.0.0.216 (9.9 GA refresh)
- 9.9.1.0.31 (9.9 MR 1 release)
- 9.10.0.0.214 (9.10 GA release)
- 9.10.0.0.218 (9.10 GA refresh)
- 9.10.0.1.59 (9.10 MR 1 release)
- 9.12.0.0.336 (9.12 GA release)
- 9.12.1.0.140 (9.12 MR 1 release)
- 9.12.1.0.148 (9.12 MR 1 refresh release)
- 9.12.2.0.101 (9.12 MR 2 release)

Resolved Issues

1. Resolved an R710 PoE issue that occurred when the AP was connected to a switch that only supported 802.3af PoE mode. [ER-3225, SCG-47346]
2. Resolved an issue that could result in incorrect channel utilization when sending traffic on the 2.4 GHz radio. [ZF-15156]
3. Resolved an issue where clients connected to an 802.11ac AP would be able to get an IP address, but unable to pass traffic. [ER-3659]