

Release Notes

EWS377AP

Ver. v3.6.5_c1.9.30

Revision History

Revision	Date	Reason of Changes
v3.6.5_c1.9.30	Sep 27, 2019	Change and fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.6.5_c1.9.30
Type	Description
New Feature	N/A
Change	<ol style="list-style-type: none">1. Standalone mode supports Mesh.2. Manage SSID is disabled at controller mode.3. GUI pop-up window to change account/password after first login4. Modify traffic log 100/s -> 10/s to avoid kernel panic issue.
Fix	<ol style="list-style-type: none">1. Fix LLDP that caused high latency issue.2. Fix fingerprint issue for missing client information.3. Chrome IOT issue.