

M36 Change Log

Release Date June 2, 2010

Firmware: 2.1.2	HW Version:
-----------------	-------------

Features Enhanced

- Keep DHCP Broadcast Flag Setting
- Fix ntpc connect once fail
- Snmp trap (linkup/linkdown/coldstart/warmstart)
- Associate packet OUT 00-02-6f
- Fix enable all ssid except SSID1 cause ap scan shown unknown message
- Fix username not allow null character
- Fix crond not work issue
- Fix announce device name length error

Release Date Mar 15, 2010

Firmware: 2.1.0	HW Version:
-----------------	-------------

Features Enhanced

- Increase F/W revision to from 2.0.14 to 2.1.0
-

Release Date Mar 04, 2010

Firmware: 2.0.14	HW Version:
------------------	-------------

Features Enhanced

- Fix issue that br0 doesn't up when enable DHCP Client after setting LAN IP to some range(ex: 192.168."10".1,192.168."99".1)
- Change DHCP option 60 from "udhcp 0.9.9-pre" to "EnGenius"
- Enhance mesh module

Release Date Feb 09, 2010

Firmware: 2.0.13	HW Version:
------------------	-------------

New Features

- Bring device name into Assoc Req/Rsp frame

Features Enhanced

- Fix issue that AP crash when enable isolation, auto channel and multiple ssid function at the same time

Release Date Feb 01, 2010

Firmware: 2.0.12	HW Version:
------------------	-------------

New Features

- Add WPA enterprise Group key & Pairwise key Update timeout setting
- Add WPA enterprise accounting

Features Enhanced

- Correct country name (Bosnia and Herzegovina, Trinidad and Tobago, Vietnam)
- Change the description of field from "Channel/Frequency" to "Frequency/Channel", and change the string from "channel" to "Channel"(GUI)
- Establish a successful connection with AP in b/g mixed mode, the connection status will show "IEEE 802.11b/g Mixed" in repeater mode(GUI)
- Realign Backup/Restore Settings web page(GUI)

Release Date Dec 07, 2009

Firmware: 2.0.9	HW Version:
-----------------	-------------

Features Enhanced

- Remove 802.11b mode in Repeater mode
- Bring security type into site survey function when select hyperlink of Hidden SSID's MAC
- Add description "Super G" to Wireless Mode field of Main webpage

Release Date Nov 26, 2009

Firmware: 2.0.8	HW Version:
-----------------	-------------

Features Enhanced

- Support 802.11b mode in Repeater mode
- Allow user to select Hidden SSID's MAC in Site Survey function
- Fix issue that Change "Data Rate" to any selection except "Auto", it will turn Repeater's MAC to "00:00:00:00:00:00"
- Change connection status webpage refresh interval from 10sec to 30sec
- Change Factory Default & Reboot warning message
 - Factory Default warning message: This will reset all settings back to factory defaults. All of your settings will be erased.
 - Reboot warning message: This will reboot the device and may take few seconds.
- Add Factory Default warning message in Backup/Restore webpage
- Change Device Name from "Access Point" to "M36"
- Change country name "the Former Yugoslav Republic of Macedonia" to "The Former Yugoslav Republic of Macedonia"
- Align id number of multiple ssid to center in Main webpage

Release Date Nov 18, 2009

Firmware: 2.0.7	HW Version:
-----------------	-------------

Features Enhanced

- Fix issue that client site survey display incorrectly when ap enable suppress ssid function
- Fix issue that endpoint can ping DUT after endpoint set DUT IP to gateway and change DUT IP to different subnet

Release Date Oct 30, 2009

Firmware: 2.0.6	HW Version:
-----------------	-------------

Features Enhanced

- Disable reset back door feature
- Fix WPA RADIUS enterprise auth fail issue

Release Date Oct 27, 2009

Firmware: 2.0.5	HW Version:
-----------------	-------------

New Features

- LED on/off