Release notes for 6.3.7:

OV3600:

-       OV3600's backend processes better handle clients that report
        bandwidth spikes (DE2797)

-       For Alcatel-Lucent internal DB and guest users, OV3600 better
        handles cases where user names look like MAC addresses (DE2775)

-       Airespace thin APs are not rebooted by AMP unless WLAN override
        is also set (DE2644)

-       Fix for minor memory leaks