Release Notes

EWS7928P

Ver. v1.05.13-c1.3.11

Revision History

Revision	Date	Reason of Changes
v1.05.13-c1.3.11	May 25, 2015	Change and fix update

Change Log

F/W Version	v1.05.13-c1.3.11
Type	Description
New Feature	N/A
Change	1. [Log Change] Add (continuously retransmission error) to upgrade failure log for the failure of transmitting firmware.
Fix	1. [Bulk Upgrade Fix] Upgrading AP in the environment with high packet loss rate would fail or take very long time. 2. [FW Upgrade Fix] Controller functions will be abnormal, when DUT upgrade FW from c1.0.2 to c1.3.10 then used One-click Upgrade AP FW