

OV3600 Firmware Matrix - part number 0510590-01

OV3600	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version	
3Com							
WX Series and APs	6.0.3.2	--	--	--	--	5.1.0	
	6.0.3.2	●	●	●	Telnet/TFTP/FTP	5.3.0	
	7.0.5.6	●	●	●	Telnet/TFTP/FTP	6.4.0	
Aruba							
200, 800, 6xx, 2400, 3x00, 5000, 6000 & APs	2.5.1.5	--	--	--	--	4.3.0	
	2.5.1.5	--	--	●	Telnet/TFTP	4.4.0	
	2.5.4.26	●	--	●	Telnet/TFTP	4.4.0	
	3.1.0	--	--	●	Telnet/TFTP	5.1.0	
	3.1.1	--	--	●	Telnet/TFTP	5.2.4	
	3.3.0	--	--	●	Telnet/TFTP	5.3.0	
	3.3.0	●	●	●	Telnet/TFTP	6.0.0	
	3.3.1.11	●	●	●	Telnet/TFTP	6.1.0	
	3.3.1.28	●	●	●	Telnet/TFTP	6.3.0	
	3.3.1.31	●	●	●	Telnet/TFTP	6.4.0	
	3.3.2.5	●	●	●	Telnet/TFTP	6.1.0	
	3.3.2.10	●	●	●	Telnet/TFTP	6.2.0	
	3.3.2.16	●	●	●	Telnet/TFTP	6.3.0	
	3.3.2.21	●	●	●	Telnet/TFTP	6.4.0	
	3.3.2.24	●	●	●	Telnet/TFTP	7.0.0	
	3.3.3.0	●	●	●	Telnet/TFTP	6.4.0	
	3.4.0.0	●	●	●	Telnet/TFTP	6.3.0	
	3.4.0.6	●	●	●	Telnet/TFTP	6.4.0	
	3.4.1.0	●	●	●	Telnet/TFTP	6.4.0	
	3.4.2.1	●	●	●	Telnet/TFTP	7.0.0	
	3.4.3.0	●	●	●	Telnet/TFTP	7.1.0	
	3.4.3.2	●	●	●	Telnet/TFTP	7.2.0	
	3.4.4.3	●	●	●	Telnet/TFTP	7.3.0	
	5.0.0.0	●	●	●	Telnet/TFTP	7.0.0	
	5.0.1.0	●	●	●	Telnet/TFTP	7.1.0	
	5.0.2.0	●	●	●	Telnet/TFTP	7.1.0	
	5.0.3.0	●	●	●	Telnet/TFTP	7.2.0	
	5.0.3.3	●	●	●	Telnet/TFTP	7.3.0	
	3x00, RAP-5WN,RAP-2WG	3.3.2.10-rn-3.0.0	●	●	●	Telnet/TFTP	6.2.0
		3.3.2.14-rn-3.1.0	●	●	●	Telnet/TFTP	6.3.0
		3.3.2.18-rn-3.1.3	●	●	●	Telnet/TFTP	6.4.0
		3.3.2.24-rn-3.1.7	●	●	●	Telnet/TFTP	7.0.0
		3.3.2.24-rn-3.1.12	●	●	●	Telnet/TFTP	7.1.0
6xx, 3x00 & APs	6.0.0.0	●	●	●	Telnet/TFTP	7.1.0	
	6.0.0.1	●	●	●	Telnet/TFTP	7.2.0	
	6.0.1.2	●	●	●	Telnet/TFTP	7.3.0	
	6.1.1.0	●	●	●	Telnet/TFTP	7.3.0	
MSR2/4000 MST200 MSR1200	4.2	●	--	--	FTP/TFTP	7.3.0	
Instant	5.0.3.0-1.1.0.0	●	●	●	HTTPS	7.3.0	
Alcatel-Lucent							
OAW-43xx OAW-4x04 OAW-6000 & APs	2.5.1.5	--	--	●	Telnet/TFTP	6.1.0	
	2.5.4.26	●	--	●	Telnet/TFTP	6.1.0	
	3.1.0	--	--	●	Telnet/TFTP	6.1.0	
	3.1.1	--	--	●	Telnet/TFTP	6.1.0	
	3.3.0	●	●	●	Telnet/TFTP	6.1.0	
	3.3.1.11	●	●	●	Telnet/TFTP	6.1.0	
	3.3.1.28	●	●	●	Telnet/TFTP	6.3.0	
	3.3.1.31	●	●	●	Telnet/TFTP	6.4.0	
	3.3.2.5	●	●	●	Telnet/TFTP	6.1.0	
	3.3.2.10	●	●	●	Telnet/TFTP	6.2.0	
	3.3.2.16	●	●	●	Telnet/TFTP	6.3.0	
	3.3.2.21	●	●	●	Telnet/TFTP	6.4.0	
	3.3.2.24	●	●	●	Telnet/TFTP	7.0.0	
	3.3.3.0	●	●	●	Telnet/TFTP	6.4.0	
	3.4.0.6	●	●	●	Telnet/TFTP	6.4.0	
	3.4.1.0	●	●	●	Telnet/TFTP	6.4.0	
	3.4.2.1	●	●	●	Telnet/TFTP	7.0.0	
	3.4.3.2	●	●	●	Telnet/TFTP	7.2.0	
	3.4.4.3	●	●	●	Telnet/TFTP	7.3.0	
	5.0.0.0	●	●	●	Telnet/TFTP	7.0.0	
	5.0.1.0	●	●	●	Telnet/TFTP	7.1.0	
	5.0.2.0	●	●	●	Telnet/TFTP	7.1.0	
	5.0.3.0	●	●	●	Telnet/TFTP	7.2.0	
5.0.3.3	●	●	●	Telnet/TFTP	7.3.0		
OAW-43xx, OAW-6xx & APs	6.0.0.0	●	●	●	Telnet/TFTP	7.2.0	
	6.0.1.2	●	●	●	Telnet/TFTP	7.3.0	
	6.1.1.0	●	●	●	Telnet/TFTP	7.3.0	

OV3600 Firmware Matrix - part number 0510590-01

OV3600	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version	
Dell PowerConnect							
W-6xx, W-3x00 & APs	5.0.1.0	●	--	●	Telnet/TFTP	7.1.0	
	5.0.3.0	●	●	●	Telnet/TFTP	7.1.0	
	6.0.0.0	●	●	●	Telnet/TFTP	7.2.0	
	6.0.1.2	●	●	●	Telnet/TFTP	7.3.0	
Avaya							
AP-1/AP-2	3.95	●	●	●	SNMP/TFTP	2.2.0	
AP-3	2.0	●	--	●	SNMP/TFTP	2.2.0	
	2.3.3	●	--	●	SNMP/TFTP	2.3.0	
	2.4.0	●	●	●	SNMP/TFTP	2.5.0	
	2.4.3	●	●	●	SNMP/TFTP	2.5.0	
	2.4.5	●	●	●	SNMP/TFTP	2.6.0	
	2.4.11	●	●	●	SNMP/TFTP	2.8.0	
	2.5.2	●	●	●	SNMP/TFTP	3.1.2	
	2.5.3	●	●	●	SNMP/TFTP	3.1.3	
AP-4 AP-5 AP-6	2.5.5	●	●	●	SNMP/TFTP	4.1.0	
	2.3.1	●	--	●	SNMP/TFTP	2.11.0	
	2.3.3	●	--	●	SNMP/TFTP	2.11.0	
	2.4.3	●	●	●	SNMP/TFTP	2.11.0	
	2.4.5	●	●	●	SNMP/TFTP	2.11.0	
	2.4.11	●	●	●	SNMP/TFTP	2.11.0	
	2.5.2	●	●	●	SNMP/TFTP	3.1.2	
	2.5.3	●	●	●	SNMP/TFTP	3.1.3	
AP-7	2.5.5	●	●	●	SNMP/TFTP	4.1.0	
	2.5.2	●	●	●	SNMP/TFTP	3.2.1	
	2.6.0	●	●	●	SNMP/TFTP	3.2.1	
	3.1.0	●	●	●	SNMP/TFTP	3.3.3	
	3.2.0	●	●	●	SNMP/TFTP	4.2.0	
	3.2.1	●	●	●	SNMP/TFTP	4.3.0	
AP-8	3.4.0	●	●	●	SNMP/TFTP	4.4.1	
	2.4.5	●	●	●	SNMP/TFTP	2.11.0	
	2.4.11	●	●	●	SNMP/TFTP	2.11.0	
	2.4.12	●	●	●	SNMP/TFTP	3.0.2	
	2.5.2	●	●	●	SNMP/TFTP	3.1.2	
	2.6.0	●	●	●	SNMP/TFTP	3.1.2	
	3.1.0	●	●	●	SNMP/TFTP	3.3.4	
	3.2.0	●	●	●	SNMP/TFTP	4.2.0	
	3.2.1	●	●	●	SNMP/TFTP	4.3.0	
	3.4.0	●	●	●	SNMP/TFTP	4.4.1	
Bel Air							
200	main.2005.03.29	--	--	--	--	4.0.2	
Cisco Pre-VxWorks							
4800	8.65.2	--	--	--	--	3.2.2	
Cisco VxWorks							
340 350	11.01	--	--	--	--	2.2.0	
	11.03	--	--	--	--	2.2.0	
	11.06A	--	--	--	--	2.2.0	
	11.07A	--	--	--	--	2.2.0	
	11.08T1	--	--	--	--	2.2.0	
	11.10T	--	--	--	--	2.2.0	
	11.21	--	--	--	--	2.2.0	
	11.23T	--	--	--	--	2.2.0	
	12.01T1	--	--	--	--	2.5.0	
	12.02T1	--	--	--	--	2.7.0	
	12.03T	--	--	--	--	2.8.0	
	12.04	--	--	--	--	2.9.0	
	12.05	--	--	--	--	3.0.4	
	1200	11.40T	--	--	--	--	2.2.0
		11.42T	--	--	--	--	2.2.0
11.54T		--	--	--	--	2.2.0	
11.56		--	--	--	--	2.2.0	
12.01T1		--	--	--	--	2.5.0	
12.02T1		--	--	--	--	2.7.0	
12.03T		--	--	--	--	2.8.0	
12.04		--	--	--	--	2.9.0	
12.05		--	--	--	--	3.0.4	

OV3600 Firmware Matrix - part number 0510590-01

OV3600	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Cisco IOS						
350 1100 1200	12.2(4)JA	●	●	●	Telnet/TFTP	2.4.0
	12.2(8)JA	●	●	●	Telnet/TFTP	2.4.0
	12.2(11)JA1	●	●	●	Telnet/TFTP	2.4.0
	12.2(13)JA	●	●	●	Telnet/TFTP	2.6.0
	12.2(13)JA1	●	●	●	Telnet/TFTP	2.8.0
	12.2(13)JA3	●	●	●	Telnet/TFTP	2.11.0
	12.2(13)JA4	●	●	●	Telnet/TFTP	2.11.0
	12.2(15)JA	●	●	●	Telnet/TFTP	2.11.0
	12.2(15)XR	●	●	●	Telnet/TFTP	3.0.2
	12.2(15)XR2	●	●	●	Telnet/TFTP	3.0.2
	12.3(2)JA	●	●	●	Telnet/TFTP	3.1.3
	12.3(2)JA2	●	●	●	Telnet/TFTP	3.2.0
	12.3(4)JA	●	●	●	Telnet/TFTP	3.3.0
	12.3(7)JA	●	●	●	Telnet/TFTP	3.4.2
	12.3(7)JA1	●	●	●	Telnet/TFTP	4.0.2
	12.3(7)JA2	●	●	●	Telnet/TFTP	4.0.2
	12.3(8)JA	●	●	●	Telnet/TFTP	4.2.0
12.3(8)JA2	●	●	●	Telnet/TFTP	4.3.0	
12.3(8)JEA	●	●	●	Telnet/TFTP	4.4.0	
12.3(11)JA	●	●	●	Telnet/TFTP	4.4.3	
1130 1240	12.2(13)JA	●	●	●	Telnet/TFTP	3.2.1
	12.3(2)JA	●	●	●	Telnet/TFTP	3.2.1
	12.3(4)JA	●	●	●	Telnet/TFTP	3.3.0
	12.3(7)JA	●	●	●	Telnet/TFTP	3.4.2
	12.3(7)JA1	●	●	●	Telnet/TFTP	4.0.2
	12.3(7)JA2	●	●	●	Telnet/TFTP	4.0.2
	12.3(8)JA	●	●	●	Telnet/TFTP	4.2.0
	12.3(8)JA2	●	●	●	Telnet/TFTP	4.3.0
	12.3(8)JEA	●	●	●	Telnet/TFTP	4.4.0
	12.3(11)JEA	●	●	●	Telnet/TFTP	4.4.1
	12.4(3g)JA	●	●	●	Telnet/TFTP	5.2.5
	12.4(10b)JA	●	●	●	Telnet/TFTP	5.3.0
	12.4(10b)JDA	●	●	●	Telnet/SSH/TFTP/SCP	6.2.0
	12.4(10b)JDA3	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0
12.4(21a)JA1	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0	
1300	12.3(2)JA2	●	●	●	Telnet/TFTP	3.4.0
	12.3(4)JA	●	●	●	Telnet/TFTP	3.4.0
	12.3(7)JA	●	●	●	Telnet/TFTP	3.4.2
	12.3(7)JA1	●	●	●	Telnet/TFTP	4.0.2
	12.3(7)JA2	●	●	●	Telnet/TFTP	4.0.2
	12.3(8)JA	●	●	●	Telnet/TFTP	4.2.0
	12.3(8)JA2	●	●	●	Telnet/TFTP	4.3.0
	12.3(8)JEA	●	●	●	Telnet/TFTP	4.4.0
	12.4(3g)JA	●	●	●	Telnet/TFTP	5.2.5
	12.4(10b)JA	●	●	●	Telnet/TFTP	5.3.0
	12.4(10b)JDA	●	●	●	Telnet/SSH/TFTP/SCP	6.2.0
	12.4(10b)JDA3	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0
12.4(21a)JA1	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0	
1250	12.4(10b)JA	●	●	●	Telnet/TFTP	5.3.0
	12.4(10b)JDA	●	●	●	Telnet/SSH/TFTP/SCP	6.2.0
	12.4(10b)JDA3	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0
	12.4(21a)JA1	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0
1400	12.4(10b)JA3	●	●	●	Telnet/SSH/TFTP/SCP	6.0.0
	12.4(10b)JDA	●	●	●	Telnet/SSH/TFTP/SCP	6.2.0
	12.4(10b)JDA3	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0
	12.4(21a)JA1	●	●	●	Telnet/SSH/TFTP/SCP	6.4.0
1140	12.4(21a)JA1	●	●	●	Telnet/SSH/TFTP/SCP	7.0.0
871w	12.4(4)T7	--	--	●	Telnet/SSH/TFTP/SCP	6.2.0

OV3600 Firmware Matrix - part number 0510590-01

OV3600	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Cisco WLC						
WLC 4012, 4100, 4400 LWAPP 10x0, 1130, 1200	2.2.127.4	●	--	●	--	3.2.4
	3.1.111.0	●	--	●	--	4.0.2
	3.2.78.0	●	--	●	--	4.2.3
	3.2.116.21	●	--	●	--	4.2.3
	3.2.195.10	●	--	●	--	5.1.0
WLC/IWLC 4400, 2x00, 5500 LWAPP 1130, 1140, 1240 1250, 1300, 1500	2.2.127.4	●	--	●	--	4.0.1
	3.1.111.0	●	--	●	--	4.0.2
	3.2.116.21	●	--	●	--	4.2.3
	4.0.155.0	●	--	●	--	4.4.0
	4.0.179.x	●	--	●	--	4.4.0
	4.0.206.0	●	--	●	--	5.1.0
	4.0.217.0	●	--	●	--	5.1.0
	4.1.171.0	●	--	●	--	5.1.0
	4.1.181.0	●	--	●	--	5.2.4
	4.1.185.0	●	--	●	--	5.3.0
	4.2.61.0	●	--	●	--	5.3.0
	4.2.99.0	●	--	●	--	6.0.0
	4.2.130.0	●	--	●	--	6.1.0
	4.2.207.0	●	--	●	--	7.0.0
	5.0.148.0	●	--	●	--	6.0.0
	5.1.151.0	●	--	●	--	6.2.0
	5.2.157.0	●	--	●	--	6.2.0
	5.2.178.0	●	--	●	--	6.3.0
	5.2.193.0	●	--	●	--	6.4.0
	6.0.182.0	●	--	●	--	6.4.0
6.0.196.0	●	--	●	--	7.0.0	
7.0.98.0	●	--	●	--	7.1.0	
7.0.116.0	●	--	●	--	7.3.0	
Enterasys						
Roamabout 3000	1.3.1	--	--	--	--	3.0.4
	2.1.0	--	--	--	--	3.0.4
	2.1.1	--	--	--	--	3.0.4
	2.1.2	--	--	--	--	3.0.4
	2.6.6	--	--	--	--	3.0.5
	3.1.0	--	--	--	--	3.3.1
	3.1.20	--	--	--	--	4.3.0
	3.1.24	--	--	--	--	4.4.0
Roamabout 4102	1.3.1	--	--	--	--	3.0.4
	1.01.25	--	--	--	--	4.3.0
	1.01.32	--	--	--	--	4.4.0
RBT-8XX0 and APs	5.0.12.5	--	--	--	--	5.1.0
	5.0.12.5	●	●	●	Telnet/TFTP/FTP	5.3.0
Foundry						
IronPoint 200	2.01	--	--	--	SNMP	6.1.0
	2.02	--	--	--	SNMP	6.1.0
IronPoint 250	3.0	--	--	--	SNMP	6.2.0
	3.1	--	--	--	SNMP	6.2.0
	3.2	--	--	--	SNMP	6.2.0
Hirschmann						
BAT-54	7.00.0070	--	--	--	--	5.0.0
	7.10.0022	--	--	--	--	5.3.0
	7.60.0165	--	--	--	--	7.0.0
Intermec						
2100 / 2101 / 2102	1.94	--	--	●	SNMP/TFTP	4.0.2
2106	1.90	--	--	●	SNMP/TFTP	4.0.2
WA 21 / WA 22	2.30	--	--	●	SNMP/TFTP	4.0.2
Juniper Netscreen						
Netscreen 5GT	5.0.0	--	--	●	SNMP/TFTP	3.4.2
LANCOM						
L-54g L-54ag OAP-54 Lancom 3550	4.02.0003	--	--	--	--	3.2.4
	5.02.0012	--	--	--	--	3.2.4
	5.02.0018	--	--	--	--	3.2.4
	5.02.0020	--	--	--	--	3.4.0
	6.02.0008	--	--	--	--	4.2.0
	6.10.0038	--	--	--	--	4.3.0
	7.00.0070	--	--	--	--	5.0.0
	7.22.0016	--	--	--	--	5.3.0
	7.26.0049	--	--	--	--	5.3.0

OV3600 Firmware Matrix - part number 0510590-01

OV3600	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Meru						
MC1000 & APs	3.3-118	--	--	--	--	5.1.0
	3.4.SR5-21	--	--	--	--	5.3.0
	3.5.Beta-29	--	--	--	--	6.0.0
	3.6	--	--	--	--	6.1.0
	3.6-124	--	--	--	--	6.3.0
	3.6-127	--	--	--	--	6.3.0
	3.6-270	--	--	--	--	6.4.0
	3.6.1-49	--	--	--	--	7.0.0
Nomadix						
HSG	2.3.234	--	--	--	--	3.1.1
	2.4.31	--	--	--	--	3.1.2
AG 2000	1.3.211	--	--	--	--	3.3.1
	1.4.129	--	--	--	--	4.0.2
AG 2100	11.4.138	--	--	--	--	4.0.2
AG 3000	21.4.139	--	--	--	--	4.0.2
AG 5000	5.4.113	--	--	--	--	4.0.2
Nortel						
WSS23x0 & APs	5.0.11.4	--	--	--	--	5.1.0
	5.0.11.4	●	●	●	Telnet/TFTP/FTP	5.3.0
	6.0.3.2	--	--	--	--	5.3.0
	6.0.3.2	●	●	●	Telnet/TFTP/FTP	5.3.0
	7.0.5.6	●	●	●	Telnet/TFTP/FTP	6.4.0
ProCurve Networking by HP						
420	2.0.38	--	--	--	--	3.0.5
	2.0.39	--	--	--	--	3.0.6
	2.1.0	--	--	--	--	3.3.2
	2.1.3	--	--	--	--	3.3.2
	2.1.5	--	--	--	--	4.3.0
	2.1.7	--	--	--	--	4.5.0
	2.2.0	--	--	--	--	5.1.6
	2.2.5	--	--	--	--	6.3.0
DWL-520	2.0	●	--	●	SNMP/TFTP	2.2.0
	2.3.3	●	--	●	SNMP/TFTP	2.3.0
	2.4.0	●	●	●	SNMP/TFTP	2.5.0
	2.4.3	●	●	●	SNMP/TFTP	2.5.0
	2.4.5	●	●	●	SNMP/TFTP	2.6.0
	2.5.2	●	●	●	SNMP/TFTP	3.1.2
530	WA.01.16	--	--	--	--	4.3.0
	WA.01.16	--	--	--	--	5.0.0
	WA.01.19	--	--	--	--	5.0.0
	WA.02.10	--	--	--	--	6.0.0
	WA.02.19	--	--	--	--	6.1.0
xl WESM & APs	WS.01.05	--	--	●	Telnet/TFTP	4.4.0
	WS.02.01	--	--	●	Telnet/TFTP	5.2.5
	WS.02.07	●	●	●	Telnet/SSH/TFTP	5.3.0
zl WESM & APs	WT.01.03	--	--	●	Telnet/SSH/TFTP	5.3.0
	WT.01.15	●	●	●	Telnet/SSH/TFTP	7.0.0
	WT.01.28	●	●	●	Telnet/SSH/TFTP	7.0.0
MSM7xx & APs	5.3.1.8-01-7189	--	--	--	--	6.4.0

OV3600 Firmware Matrix - part number 0510590-01

OV3600	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Proxim						
AP 600	2.3.1	●	--	●	SNMP/TFTP	2.2.0
	2.3.3	●	--	●	SNMP/TFTP	2.3.0
	2.4.3	●	●	●	SNMP/TFTP	2.5.0
	2.4.5	●	●	●	SNMP/TFTP	2.6.0
	2.4.11	●	●	●	SNMP/TFTP	2.8.0
	2.5.2	●	●	●	SNMP/TFTP	3.1.2
	2.5.3	●	●	●	SNMP/TFTP	3.1.2
	2.5.4	●	●	●	SNMP/TFTP	4.1.0
AP 700	2.5.5	●	●	●	SNMP/TFTP	3.3.1
	2.5.2	●	●	●	SNMP/TFTP	3.2.1
	2.6.0	●	●	●	SNMP/TFTP	3.2.1
	3.1.0	●	●	●	SNMP/TFTP	3.4.2
	3.2.0	●	●	●	SNMP/TFTP	4.2.0
	3.2.1	●	●	●	SNMP/TFTP	4.3.4
	3.4.0	●	●	●	SNMP/TFTP	4.4.1
	3.6.2	●	●	●	SNMP/TFTP	5.3.0
AP 2000	3.7.0	●	●	●	SNMP/TFTP	6.1.0
	4.0.1	●	●	●	SNMP/TFTP	6.2.0
	4.0.2	●	●	●	SNMP/TFTP	6.3.0
	2.0	●	--	●	SNMP/TFTP	2.2.0
	2.3.3	●	--	●	--	2.3.0
	2.4.0	●	●	●	SNMP/TFTP	2.5.0
	2.4.3	●	●	●	SNMP/TFTP	2.5.0
	2.4.5	●	●	●	SNMP/TFTP	2.6.0
AP 4000	2.4.11	●	●	●	SNMP/TFTP	2.8.0
	2.5.2	●	●	●	SNMP/TFTP	3.1.2
	2.5.3	●	●	●	SNMP/TFTP	3.1.3
	2.5.4	●	●	●	SNMP/TFTP	3.3.1
	2.5.5	●	●	●	SNMP/TFTP	4.1.0
	2.4.5	●	●	●	SNMP/TFTP	2.11.0
	2.4.11	●	●	●	SNMP/TFTP	2.11.0
	2.4.12	●	●	●	SNMP/TFTP	3.0.2
AP 4000M AP 4900M	2.5.2	●	●	●	SNMP/TFTP	3.1.2
	2.6.0	●	●	●	SNMP/TFTP	3.1.3
	3.1.0	●	●	●	SNMP/TFTP	3.4.2
	3.2.0	●	●	●	SNMP/TFTP	4.2.0
	3.2.1	●	●	●	SNMP/TFTP	4.3.4
	3.4.0	●	●	●	SNMP/TFTP	4.4.1
	3.6.2	●	●	●	SNMP/TFTP	5.3.0
	3.7.0	●	●	●	SNMP/TFTP	6.1.0
Tsunami MP.11a	4.0.0	●	●	●	SNMP/TFTP	6.2.0
	4.0.2	●	●	●	SNMP/TFTP	6.3.0
	3.2.0	●	●	●	SNMP/TFTP	4.3.4
	3.2.1	●	●	●	SNMP/TFTP	4.3.4
	3.4.0	●	●	●	SNMP/TFTP	4.4.1
	3.6.2	●	●	●	SNMP/TFTP	5.3.0
Tsunami MP.11 5054,4954, 954, 2454, 5012	3.7.0	●	●	●	SNMP/TFTP	6.1.0
	4.0.0	●	●	●	SNMP/TFTP	6.2.0
	4.0.2	●	●	●	SNMP/TFTP	6.3.0
	2.0.1	●	●	●	SNMP/TFTP	3.2.4
Tsunami MP.11a	2.2.0	●	●	●	SNMP/TFTP	3.2.4
	2.2.2	●	●	●	SNMP/TFTP	3.2.4
	2.2.6	●	●	●	SNMP/TFTP	3.4.2
	2.3.0	●	●	●	SNMP/TFTP	5.2.0
Tsunami MP.11 5054,4954, 954, 2454, 5012	4.0.0	●	●	●	SNMP/TFTP	5.2.0

OV3600 Firmware Matrix - part number 0510590-01

OV3600	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Symbol						
3021	04.01-23	●	●	●	SNMP/TFTP	4.0.1
	04.02-19	●	●	●	SNMP/TFTP	4.0.1
4121	3.52.13	●	--	●	SNMP/TFTP	2.2.0
	2.70.06	●	●	●	SNMP/TFTP	2.2.0
4131	3.51-20	●	--	●	SNMP/TFTP	2.2.0
	3.70-72	●	●	●	SNMP/TFTP	3.0.4
	3.92-29	●	●	●	SNMP/TFTP	3.0.7
	3.93-00	●	●	●	SNMP/TFTP	3.4.2
	3.94-15	●	●	●	SNMP/TFTP	4.3.0
5131	3.95-04	●	●	●	SNMP/TFTP	7.3.0
	1.1.0.0.045R	--	--	--	--	5.2.1
	1.1.0.0.045R	--	--	●	Telnet/TFTP	5.2.4
	2.0.0	●	●	●	Telnet/TFTP	6.1.0
	2.1.0	●	●	●	Telnet/TFTP	6.2.0
	2.2.0	●	●	●	Telnet/TFTP	6.3.0
	2.3.1.0	●	●	●	Telnet/TFTP	7.0.0
7131	2.4.1.0	●	●	●	Telnet/TFTP/FTP	7.1.0
	2.5.0.0	●	●	●	Telnet/TFTP/FTP	7.1.0
	3.2.2	●	●	●	Telnet/TFTP/FTP	7.1.0
	4.0.3	●	●	●	Telnet/TFTP/FTP	7.1.0
	4.1.0	●	●	●	Telnet/TFTP/FTP	7.1.0
5181	4.1.2	●	●	●	Telnet/TFTP/FTP	7.1.0
	1.1.2	●	●	●	Telnet/TFTP	6.2.0
WS5000 & APs	0.0-35R	--	--	--	--	4.3.0
	2.0.0	--	--	--	--	4.4.0
WS2000 & APs	0.0-35R	--	--	●	Telnet/TFTP	5.0.0
	2.2.3.0-020R	--	--	●	Telnet/TFTP	6.0.0
	2.2.3.0-020R	●	--	●	Telnet/TFTP	6.1.0
	2.3.2.0-003R	●	--	●	Telnet/TFTP	6.3.0
	2.4.0.0-023R	●	--	●	Telnet/TFTP	6.3.0
	2.4.1.0-005R	●	--	●	Telnet/TFTP	6.4.0
WS5100 & APs	2.4.4.0-001R	●	--	●	Telnet/TFTP	7.1.0
	2.4.5	●	--	●	Telnet/TFTP	7.3.0
	2.0.0	--	--	--	--	4.4.0
	3.0.0	--	--	●	Telnet/TFTP	5.0.0
	3.0.2	●	●	●	Telnet/TFTP	5.3.0
	3.0.3	●	●	●	Telnet/TFTP	5.3.0
	3.0.3	●	●	●	Telnet/SSH/TFTP	6.0.0
	3.1.0	●	●	●	Telnet/SSH/TFTP	6.1.0
	3.2.0	●	●	●	Telnet/SSH/TFTP	6.1.0
	3.3.1	●	●	●	Telnet/SSH/TFTP/FTP	6.3.0
RFSx000 & APs	3.3.3	●	●	●	Telnet/SSH/TFTP/FTP	7.1.0
	3.3.4	●	●	●	Telnet/SSH/TFTP/FTP	7.3.0
	1.0.0.0	●	--	●	Telnet/SSH/TFTP	6.0.0
	1.2.0.0	●	●	●	Telnet/SSH/TFTP/FTP	6.3.0
	3.2.0	●	●	●	Telnet/SSH/TFTP	6.2.0
	4.0.0.0	●	●	●	Telnet/SSH/TFTP/FTP	6.3.0
	4.1.0.0	●	●	●	Telnet/SSH/TFTP/FTP	7.1.0
	4.1.0.1	●	●	●	Telnet/SSH/TFTP/FTP	7.3.0
Systemax	4.2.1.0	●	●	●	Telnet/SSH/TFTP/FTP	7.1.0
	4.3.0.0	●	●	●	Telnet/SSH/TFTP/FTP	7.1.0
	4.3.3	●	●	●	Telnet/SSH/TFTP/FTP	7.3.0
	2.4.5	●	●	●	SNMP/TFTP	3.2.0
Airspeed 542	2.4.11	●	●	●	SNMP/TFTP	3.2.0
	2.4.12	●	●	●	SNMP/TFTP	3.2.0
	2.5.2	●	●	●	SNMP/TFTP	3.2.0
	2.6.0	●	●	●	SNMP/TFTP	3.2.0
Teklogix						
9150/9160	C234p	--	--	●	--	4.4.0

OV3600 Firmware Matrix - part number 0510590-01

OV3600	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
Trapeze						
MX Series & MPs	5.0.12.2	--	--	--	--	5.1.0
	5.0.12.2	●	●	●	Telnet/TFTP/FTP	5.3.0
	6.0.2.2	--	--	--	--	5.1.0
	6.0.2.2	●	●	●	Telnet/TFTP/FTP	5.3.0
	6.0.4.2	●	●	●	Telnet/TFTP/FTP	5.3.0
	7.0.5.6	●	●	●	Telnet/TFTP/FTP	6.4.0
Tropos						
4/5210, 5320, 9422, 9532	5.1.4.7	--	--	--	--	5.0.0
3/4/5210, 5320, 9422, 9532	5.1.4.7	--	--	--	--	5.3.0
	6.5.1.3	--	--	--	--	5.3.0
	6.6.0.0	--	--	--	--	5.3.0
	6.6.1.3	--	--	--	--	6.2.0
Vivato						
VP1200	1.3.1.r4	--	--	--	--	3.3.2
VA2200	1.1.r2	--	--	--	--	3.3.1
	2.2	--	--	--	--	3.4.2
VP2200	3.0.r9	--	--	--	--	5.2.4

© 2011 Alcatel-Lucent. Alcatel, Lucent, Alcatel-Lucent, and the Alcatel-Lucent logo are trademarks of Alcatel-Lucent. All rights reserved. All other trademarks are the property of their respective owners.