

# **Release Notes**

**EAP300**

**Ver. 1.6.8**

## Revision History

Revision	Date	Reason of Changes
V1.6.8	August 22, 2014	Enhancement and bug fix update

## Change Log

F/W Version	V1.6.8
Type	Description
New Feature	N/A
Change	<ol style="list-style-type: none"><li>1. [Traffic Shaping] UI update to change "Outgoing" to "Download" and "Incoming" to "Upload" in traffic shaping.</li><li>2. Update wifi driver from 9.2.0.10 to 10.1.478.</li></ol>
Fix	<ol style="list-style-type: none"><li>1. Fixed the bug that users cannot use VLAN PC to login DUT webpage.</li><li>2. [LED] LED cannot be turned off in RP mode when LED control set off.</li></ol>