

# **Release Notes**

**EWS357AP**

**Ver. v3.5.10\_c1.9.20**

## Revision History

Revision	Date	Reason of Changes
v3.5.10_c1.9.20	Jun 6, 2019	Fix update

## Change Log

**Notice:** APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.5.10_c1.9.20
Type	Description
New Feature	N/A
Change	N/A
Fix	1. Fix Wi-Fi client not able to connect in long distance apart when Band Steering enabled with Force 5GHz.