

# **Release Notes**

**EAP1750H**

**Ver. 2.0.112**

## Revision History

Revision	Date	Reason of Changes
V2.0.112	Feb 13, 2015	New feature, enhancement, and bug fix update

## Change Log

F/W Version	V2.0.112
Type	Description
New Feature	<ol style="list-style-type: none"><li>1. Add the support of IEEE 802.11k and 802.11r by enabling “Fast Roaming” under SSID1 profile settings in 2.4GHz and 5GHz wireless settings respectively.</li><li>2. Add the management web GUI support for multiple languages with English, Portuguese, German, French, Spanish, Russian, and Simplified Chinese.</li><li>3. Add the support of Information Link on management web GUI</li></ol>
Change	<ol style="list-style-type: none"><li>1. Update default RSSI value of Fast Handover from -70 to -85dBm</li><li>2. Update the RSSI range of Fast Handover from (-60 ~ -90dBm) to (-60 ~ -100dBm)</li></ol>
Fix	<ol style="list-style-type: none"><li>1. Fix the bug that VLAN pass-through fails in 5GHz WDS mode.</li></ol>