

Release Notes

EAP300

Ver. 1.7.20

Revision History

Revision	Date	Reason of Changes
V1.7.20	Oct 21, 2015	Fix update

Change Log

F/W Version	V1.7.20
Type	Description
New Feature	N/A
Change	N/A
Fix	<ol style="list-style-type: none">1. Fixed memory leak from SNMP access.2. Fixed the issue that DHCP server will be enabled upon firmware upgrade or operation mode being changed.