

EVR100_Changelog

Release Date Feb. 17, 2011

WEB version: 1.0.11

Firmware upgrade:

- **EVR100-V1-0-11-162 .dlf**

MD5 Checksum:

- **APPS : d78e5611b777429f15dde113f9ec24b6**

New Features:

- **N/A**

Problems Resolved:

- **N/A**

Change:

- **Disable Network Turbine by default.**

Request from customer:

- **N/A**

Release Date Jan. 21, 2011

WEB version: 1.0.10

Firmware upgrade:

- **EVR100-V1-0-10-159 .dlf**

MD5 Checksum:

- **APPS : 261fd78f1434a117c0654edb7b418c61**

New Features:

- N/A

Problems Resolved:

- Fixed security gateway display error information when user enters over 20 characters in IPSec site to site through VPN wizard.

Change:

- N/A

Request from customer:

- N/A