

Release Notes

EWS370AP

Ver. v3.5.0_c1.9.04

Revision History

Revision	Date	Reason of Changes
v3.5.0_c1.9.04	Sep 3, 2018	Change and fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.9 software.

F/W Version	v3.5.0_c1.9.04
Type	Description
New Feature	N/A
Change	Update CAPWAP to c1.9.04
Fix	Enclose fix for L2-isolation that doesn't work properly when VLAN enabled