

Release Notes

EWS330AP

Ver. v3.0.1_c1.8.59

Revision History

Revision	Date	Reason of Changes
v3.0.1_c1.8.59	Mar 5, 2018	Fix update

Change Log

Notice: APs upgraded to this version can only be managed by ezMaster/EWS Switch running c1.8 software.

F/W Version	v3.0.1_c1.8.59
Type	Description
New Feature	N/A
Change	N/A
Fix	1. Enclose fix for GUI Portuguese translation.