

OV3600 Firmware Matrix - part number 0510591

OV3600	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version	
<b>3Com</b>							
8750	2.03.13	--	--	●	Telnet/TFTP	3.4	
WX Series and APs	6.0.3.2	--	--	--	--	5.1.0	
	6.0.3.2	●	●	--	Telnet/TFTP/FTP	5.3	
<b>Apple</b>							
(Graphite) Airport	3.84	--	--	●	--	3.2.2	
<b>Aruba</b>							
200, 800, 2400, 3x00, 5000, 6000 & APs	2.5.1.5	--	--	--	--	4.3.0	
	2.5.1.5	--	--	●	Telnet/TFTP	4.4.0	
	2.5.4.26	●	--	●	Telnet/TFTP	4.4.0	
	3.1.0	--	--	●	Telnet/TFTP	5.1.0	
	3.1.1	--	--	●	Telnet/TFTP	5.2.4	
	3.3.0	--	--	●	Telnet/TFTP	5.3	
	3.3.0	●	●	●	Telnet/TFTP	6.0.0	
	3.3.1.11	●	●	●	Telnet/TFTP	6.1.0	
	3.3.1.28	●	●	●	Telnet/TFTP	6.3.0	
	3.3.2.5	●	●	●	Telnet/TFTP	6.1.0	
	3.3.2.10	●	●	●	Telnet/TFTP	6.2.0	
	3.3.2.16	●	●	●	Telnet/TFTP	6.3.0	
	3.4.0.0	●	●	●	Telnet/TFTP	6.3.0	
	3x00, RAP-5WN,RAP-2WG	3.3.2.10-rn-3.0.0	●	●	●	Telnet/TFTP	6.2.0
	3.3.2.14-rn-3.1.0	●	●	●	Telnet/TFTP	6.3.0	
<b>Alcatel-Lucent</b>							
OAW-43xx OAW-4x04 OAW-6000 & APs	2.5.1.5	--	--	●	Telnet/TFTP	6.1.0	
	2.5.4.26	●	--	●	Telnet/TFTP	6.1.0	
	3.1.0	--	--	●	Telnet/TFTP	6.1.0	
	3.1.1	--	--	●	Telnet/TFTP	6.1.0	
	3.3.0	●	●	●	Telnet/TFTP	6.1.0	
	3.3.1.11	●	●	●	Telnet/TFTP	6.1.0	
	3.3.1.28	●	●	●	Telnet/TFTP	6.3.0	
	3.3.2.5	●	●	●	Telnet/TFTP	6.1.0	
	3.3.2.10	●	●	●	Telnet/TFTP	6.2.0	
	3.3.2.16	●	●	●	Telnet/TFTP	6.3.0	
<b>Avaya</b>							
AP-1/AP-2	3.95	●	●	●	SNMP/TFTP	2.2.0	
AP-3	2.0	●	--	--	SNMP/TFTP	2.2.0	
	2.3.3	●	--	●	SNMP/TFTP	2.3.0	
	2.4.0	●	●	●	SNMP/TFTP	2.5.0	
	2.4.3	●	●	●	SNMP/TFTP	2.5.0	
	2.4.5	●	●	●	SNMP/TFTP	2.6.0	
	2.4.11	●	●	●	SNMP/TFTP	2.8.0	
	2.5.2	●	●	●	SNMP/TFTP	3.1.2	
	2.5.3	●	●	●	SNMP/TFTP	3.1.3	
	2.5.5	●	●	●	SNMP/TFTP	4.1.0	
AP-4 AP-5 AP-6	2.3.1	●	--	●	SNMP/TFTP	2.11.0	
	2.3.3	●	--	●	SNMP/TFTP	2.11.0	
	2.4.3	●	●	●	SNMP/TFTP	2.11.0	
	2.4.5	●	●	●	SNMP/TFTP	2.11.0	
	2.4.11	●	●	●	SNMP/TFTP	2.11.0	
	2.5.2	●	●	●	SNMP/TFTP	3.1.2	
AP-7	2.5.3	●	●	●	SNMP/TFTP	3.1.3	
	2.5.5	●	●	●	SNMP/TFTP	4.1.0	
	2.5.2	●	●	●	SNMP/TFTP	3.2.1	
	2.6.0	●	●	●	SNMP/TFTP	3.2.1	
	3.1.0	●	●	●	SNMP/TFTP	3.3.3	
	3.2.0	●	●	●	SNMP/TFTP	4.2.0	
AP-8	3.2.1	●	●	●	SNMP/TFTP	4.3.0	
	3.4.0	●	●	●	SNMP/TFTP	4.4.1	
	2.4.5	●	●	●	SNMP/TFTP	2.11.0	
	2.4.11	●	●	●	SNMP/TFTP	2.11.0	
	2.4.12	●	●	●	SNMP/TFTP	3.0.2	
	2.5.2	●	●	●	SNMP/TFTP	3.1.2	
	2.6.0	●	●	●	SNMP/TFTP	3.1.2	
	3.1.0	●	●	●	SNMP/TFTP	3.3.4	
Bel Air	200	main.2005.03.29	--	--	--	4.0.2	
	<b>Cisco Pre-VxWorks</b>						
	4800	8.65.2	●	●	●	Telnet/TFTP	3.2.2
	<b>Cisco VxWorks</b>						
340 350	11.01	●	--	●	SNMP/TFTP	2.2.0	
	11.03	●	--	●	SNMP/TFTP	2.2.0	
	11.06A	●	--	●	SNMP/TFTP	2.2.0	
	11.07A	●	--	●	SNMP/TFTP	2.2.0	
	11.08T1	●	--	●	SNMP/TFTP	2.2.0	
	11.10T	●	--	●	SNMP/TFTP	2.2.0	
	11.21	●	●	●	SNMP/TFTP	2.2.0	
	11.23T	●	●	●	SNMP/TFTP	2.2.0	
	12.01T1	●	●	●	SNMP/TFTP	2.5.0	
	12.02T1	●	●	●	SNMP/TFTP	2.7.0	
	12.03T	●	●	●	SNMP/TFTP	2.8.0	
	12.04	●	●	●	SNMP/TFTP	2.9.0	
	12.05	●	●	●	SNMP/TFTP	3.0.4	
	1200	11.40T	●	--	●	SNMP/TFTP	2.2.0
		11.42T	●	--	●	SNMP/TFTP	2.2.0
		11.54T	●	--	●	SNMP/TFTP	2.2.0
11.56		●	●	●	SNMP/TFTP	2.2.0	
12.01T1		●	●	●	SNMP/TFTP	2.5.0	
12.02T1		●	●	●	SNMP/TFTP	2.7.0	
12.03T		●	●	●	SNMP/TFTP	2.8.0	
12.04		●	●	●	SNMP/TFTP	2.9.0	
12.05	●	●	●	SNMP/TFTP	3.0.4		

OV3600 Firmware Matrix - part number 0510591

OV3600	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
<b>Cisco IOS</b>						
350 1100 1200	12.2(4)JA	●	●	●	Telnet/TFTP	2.4.0
	12.2(8)JA	●	●	●	Telnet/TFTP	2.4.0
	12.2(11)JA1	●	●	●	Telnet/TFTP	2.4.0
	12.2(13)JA	●	●	●	Telnet/TFTP	2.6.0
	12.2(13)JA1	●	●	●	Telnet/TFTP	2.8.0
	12.2(13)JA3	●	●	●	Telnet/TFTP	2.11.0
	12.2(13)JA4	●	●	●	Telnet/TFTP	2.11.0
	12.2(15)JA	●	●	●	Telnet/TFTP	3.0.2
	12.2(15)XR	●	●	●	Telnet/TFTP	3.0.2
	12.2(15)XR2	●	●	●	Telnet/TFTP	3.1.3
	12.3(2)JA	●	●	●	Telnet/TFTP	3.2
	12.3(2)JA2	●	●	●	Telnet/TFTP	3.2
	12.3(4)JA	●	●	●	Telnet/TFTP	3.3
	12.3(7)JA	●	●	●	Telnet/TFTP	3.4.2
	12.3(7)JA1	●	●	●	Telnet/TFTP	4.0.2
	12.3(7)JA2	●	●	●	Telnet/TFTP	4.0.2
	12.3(8)JA	●	●	●	Telnet/TFTP	4.2.0
	12.3(8)JA2	●	●	●	Telnet/TFTP	4.3.0
	12.3(8)JEA	●	●	●	Telnet/TFTP	4.4.0
	12.3(11)JA	●	●	●	Telnet/TFTP	4.4.3
1130 1240	12.2(13)JA	●	●	●	Telnet/TFTP	3.2.1
	12.3(2)JA	●	●	●	Telnet/TFTP	3.2.1
	12.3(4)JA	●	●	●	Telnet/TFTP	3.3
	12.3(7)JA	●	●	●	Telnet/TFTP	3.4.2
	12.3(7)JA1	●	●	●	Telnet/TFTP	4.0.2
	12.3(7)JA2	●	●	●	Telnet/TFTP	4.0.2
	12.3(8)JA	●	●	●	Telnet/TFTP	4.2.0
	12.3(8)JA2	●	●	●	Telnet/TFTP	4.3.0
	12.3(8)JEA	●	●	●	Telnet/TFTP	4.4.0
	12.3(11)JEA	●	●	●	Telnet/TFTP	4.4.1
	12.4(3g)JA	●	●	●	Telnet/TFTP	5.2.5
	12.4(10b)JA	●	●	●	Telnet/TFTP	5.3
12.4(10b)JDA	●	●	●	Telnet/SSH/TFTP/SCP	6.2.0	
1300	12.3(2)JA2	●	●	●	Telnet/TFTP	3.4
	12.3(4)JA	●	●	●	Telnet/TFTP	3.4
	12.3(7)JA	●	●	●	Telnet/TFTP	3.4.2
	12.3(7)JA1	●	●	●	Telnet/TFTP	4.0.2
	12.3(7)JA2	●	●	●	Telnet/TFTP	4.0.2
	12.3(8)JA	●	●	●	Telnet/TFTP	4.2.0
	12.3(8)JA2	●	●	●	Telnet/TFTP	4.3.0
	12.3(8)JEA	●	●	●	Telnet/TFTP	4.4.0
	12.4(3g)JA	●	●	●	Telnet/TFTP	5.2.5
	12.4(10b)JA	●	●	●	Telnet/TFTP	5.3
	12.4(10b)JDA	●	●	●	Telnet/SSH/TFTP/SCP	6.2.0
	12.4(10b)JA	●	●	●	Telnet/TFTP	5.3
1250	12.4(10b)JA	●	●	●	Telnet/TFTP	5.3
	12.4(10b)JDA	●	●	●	Telnet/TFTP	6.2.0
1400	12.4(10b)JA3	●	●	●	Telnet/SSH/TFTP/SCP	6.0.0
	12.4(10b)JDA	●	●	●	Telnet/SSH/TFTP/SCP	6.2.0
871w	12.4(4)T7	--	--	●	Telnet/SSH/TFTP/SCP	6.2.0
<b>Cisco WLC</b>						
WLC 4012, 4100, 4400 LWAPP 10x0, 1130, 1200	2.2.127.4	●	--	●	--	3.2.4
	3.1.111.0	●	--	●	--	4.0.2
	3.2.78.0	●	--	●	--	4.2.3
	3.2.116.21	●	--	●	--	4.2.3
	3.2.195.10	●	--	●	--	5.1.0
	2.2.127.4	●	--	●	--	4.0.1
WLC/iWLC 4400, 2x00  LWAPP 1130, 1140, 1240 1250, 1300, 1500	3.1.111.0	●	--	●	--	4.0.2
	3.2.116.21	●	--	●	--	4.2.3
	4.0.155.0	●	--	●	--	4.4.0
	4.0.179.x	●	--	●	--	4.4.0
	4.0.206.0	●	--	●	--	5.1.0
	4.0.217.0	●	--	●	--	5.1.0
	4.1.171.0	●	--	●	--	5.1.0
	4.1.181.0	●	--	●	--	5.2.4
	4.1.185.0	●	--	●	--	5.3
	4.2.61.0	●	--	●	--	5.3
	4.2.99.0	●	--	●	--	6.0
	4.2.130.0	●	--	●	--	6.1.0
	5.0.148.0	●	--	●	--	6.0.0
	5.1.151.0	●	--	●	--	6.2.0
5.2.157.0	●	--	●	--	6.2.0	
5.2.178.0	●	--	●	--	6.3.0	
<b>Colubris</b>						
200	2.2.0	●	●	●	SNMP/HTTP	3.0.7
	2.2.0	●	●	●	SNMP/HTTP	3.1.0
	3.1.0	●	●	●	SNMP/HTTP	4.2.3
	4.1.1	●	●	●	SNMP/HTTP	4.3.0
	4.1.2	●	●	●	SNMP/HTTP	3.0.2
320 330	2.2.0	●	●	●	SNMP/HTTP	3.0.7
	2.3.0	●	●	●	SNMP/HTTP	3.1.1
	2.4.0	●	●	●	SNMP/HTTP	3.1.1
	3.1.0	●	●	●	SNMP/HTTP	4.2.3
	4.1.1	●	●	●	SNMP/HTTP	4.3.0
1250	1.3.1	●	●	●	SNMP/HTTP	2.10.0
	1.3.2	●	●	●	SNMP/HTTP	2.11.0
	2.1.2	●	●	●	SNMP/HTTP	3.0.5
	2.2.0	●	●	●	SNMP/HTTP	3.0.5
	2.2.0	●	●	●	SNMP/HTTP	3.0.5
3200 3300	1.3.1	●	●	●	SNMP/HTTP	2.10.0
	1.3.2	●	●	●	SNMP/HTTP	2.11.0
	2.1.2 CN	●	●	●	SNMP/HTTP	3.0.5
	2.1.3	●	●	●	SNMP/HTTP	3.0.5
	2.3.0	●	●	●	SNMP/HTTP	3.0.7
	2.4.0	●	●	●	SNMP/HTTP	3.1.0
	2.4.1	●	●	●	SNMP/HTTP	3.3.1
	3.1.0	●	●	●	SNMP/HTTP	4.2.3
4.1.1	●	●	●	SNMP/HTTP	4.3.0	
3400/3500	dev-03-3399	--	--	●	--	3.1.1

OV3600 Firmware Matrix - part number 0510591

OV3600	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
<b>Compaq</b>						
WL-400	2.5.3	●	●	●	SNMP/TFTP	2.3.0
<b>Dell</b>						
1170	2.3.3 615	●	●	●	SNMP/TFTP	2.2.0
<b>Enterasys</b>						
Roamabout 2000	6.04.13	●	●	●	SNMP/TFTP	2.2.0
	3.00.12	●	●	●	SNMP/HTTP	2.6.0
	4.00.12	●	●	●	SNMP/HTTP	2.6.0
Roamabout R2	5.01.03	●	●	●	SNMP/HTTP	2.6.0
	5.03.01	●	●	●	SNMP/HTTP	2.8.0
	5.04.08	●	●	●	SNMP/HTTP	3.0.2
	6.01.05	●	●	●	SNMP/HTTP	3.2.5
	6.08.03	●	●	●	SNMP/HTTP	4.4.0
Roamabout 3000	1.3.1	●	●	●	SNMP/TFTP	3.0.4
	2.1.0	●	●	●	SNMP/TFTP	3.0.4
	2.1.1	●	●	●	SNMP/TFTP	3.0.4
	2.1.2	●	●	●	SNMP/TFTP	3.0.4
	2.6.6	●	●	●	SNMP/TFTP	3.0.5
	3.1.0	●	●	●	SNMP/TFTP	3.3.1
	3.1.20	●	●	●	SNMP/TFTP	4.3.0
	3.1.24	●	●	●	SNMP/TFTP	4.4.0
	1.3.1	●	●	●	SNMP/TFTP	3.0.4
Roamabout 4102	1.01.25	●	●	●	SNMP/TFTP	4.3.0
	1.01.32	●	●	●	SNMP/TFTP	4.4.0
RBT-8XX0 and APs	5.0.12.5	--	--	--	--	5.1.0
	5.0.12.5	●	●	●	Telnet/TFTP/FTP	5.3
<b>Ericsson</b>						
DSSS A11	3.00.19	●	●	●	SNMP/TFTP	2.2.0
<b>Foundry</b>						
IronPoint 200	2.01	--	--	--	SNMP	6.1.0
	2.02	--	--	--	SNMP	6.1.0
IronPoint 250	3.0	--	--	--	SNMP	6.2.0
	3.1	--	--	--	SNMP	6.2.0
	3.2	--	--	--	SNMP	6.2.0
<b>Funkwerk</b>						
Artem ComPoint	4.49	●	--	●	NDC API	3.0.3
	4.78	●	--	●	NDC API	3.0.3
	4.81	●	--	●	NDC API	3.2.1
<b>Hirschmann</b>						
BAT-54	7.00.0070	●	●	●	SNMP/TFTP	5.0
	7.10.0022	●	●	●	SNMP/TFTP	5.3.0
<b>IBM</b>						
AP-500	3.95	●	●	●	SNMP/TFTP	2.2.0
<b>Intel</b>						
2011B	3.00-19	●	--	●	SNMP/TFTP	2.2.0
	3.51-20	●	--	●	SNMP/TFTP	2.2.0
2011	2.21-01	●	●	●	SNMP/TFTP	2.2.0
	2.51-16	●	●	●	SNMP/TFTP	2.2.0
<b>Intermec</b>						
2100 / 2101 / 2102	1.94	--	--	●	SNMP/TFTP	4.0.2
2106	1.90	--	--	●	SNMP/TFTP	4.0.2
WA 21 / WA 22	2.30	--	--	●	SNMP/TFTP	4.0.2
<b>Juniper Netscreen</b>						
Netscreen 5GT	5.0.0	--	--	●	SNMP/TFTP	3.4.2
<b>LANCOM</b>						
L-54g L-54ag OAP-54 Lancom 3550	4.02.0003	--	--	●	--	3.2.4
	5.02.0012	●	●	●	--	3.2.4
	5.02.0018	●	●	●	--	3.2.4
	5.02.0020	●	●	●	SNMP/TFTP	3.4.0
	6.02.0008	●	●	●	SNMP/TFTP	4.2.0
	6.10.0038	●	●	●	SNMP/TFTP	4.3.0
	7.00.0070	●	●	●	SNMP/TFTP	5.0
	7.22.0016	●	●	●	SNMP/TFTP	5.3
	7.26.0049	●	●	●	SNMP/TFTP	5.3
<b>Meru</b>						
MC1000 & APs	3.3-118	--	--	--	--	5.1.0
	3.4.SR5-21	--	--	--	--	5.3.0
	3.5.Beta-29	--	--	--	--	6.0.0
	3.6	--	--	--	--	6.1.0
	3.6-124	--	--	--	--	6.3.0
	3.6-127	--	--	--	--	6.3.0
<b>NEC</b>						
Pasolink	4.20	--	--	--	--	6.0
<b>Nomadix</b>						
HSG	2.3.234	--	--	●	SNMP/TFTP	3.1.1
	2.4.31	--	--	●	SNMP/TFTP	3.1.2
AG 2000	1.3.211	--	--	●	SNMP/TFTP	3.3.1
	1.4.129	--	--	●	SNMP/TFTP	4.0.2
AG 2100	11.4.138	--	--	●	--	4.0.2
AG 3000	21.4.139	--	--	●	--	4.0.2
AG 5000	5.4.113	--	--	●	--	4.0.2
<b>Nortel</b>						
WSS23x0 & APs	5.0.11.4	--	--	--	--	5.1.0
	5.0.11.4	●	●	●	Telnet/TFTP/FTP	5.3
	6.0.3.2	--	--	--	--	5.3
	6.0.3.2	●	●	●	Telnet/TFTP/FTP	5.3
<b>Proxim/ORINOCO</b>						
AP 500/1000	3.95	●	●	●	SNMP/TFTP	2.2.0
Wavepoint II	3.95	●	●	●	SNMP/TFTP	2.2.0

OV3600 Firmware Matrix - part number 0510591

OV3600	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
<b>ProCurve Networking by HP</b>						
420	2.0.38	●	●	●	Telnet/TFTP	3.0.5
	2.0.39	●	●	●	Telnet/TFTP	3.0.6
	2.1.0	●	●	●	Telnet/TFTP	3.3.2
	2.1.3	●	●	●	Telnet/TFTP	3.3.2
	2.1.5	●	●	●	Telnet/TFTP	4.3.0
	2.1.7	●	●	●	Telnet/TFTP	4.5.0
	2.2.0	●	●	●	Telnet/TFTP	5.1.6
DWL-520	2.2.5	●	●	●	Telnet/TFTP	6.3.0
	2.0	●	--	●	SNMP/TFTP	2.2.0
	2.3.3	●	--	●	SNMP/TFTP	2.3.0
	2.4.0	●	●	●	SNMP/TFTP	2.5.0
	2.4.3	●	●	●	SNMP/TFTP	2.5.0
	2.4.5	●	●	●	SNMP/TFTP	2.6.0
530	2.5.2	●	●	●	SNMP/TFTP	3.1.2
	WA.01.16	--	--	--	--	4.3.0
	WA.01.16	●	●	●	Telnet/TFTP	5.0
	WA.01.19	●	●	●	Telnet/TFTP	5.0
	WA.02.10	●	●	●	Telnet/TFTP	6.0
xl WESM & APs	WA.02.19	●	●	●	Telnet/TFTP	6.1
	WS.01.05	--	--	●	Telnet/TFTP	4.4
	WS.02.01	--	--	●	Telnet/TFTP	5.2.5
zl WESM & APs	WS.02.07	●	●	●	Telnet/SSH/TFTP	5.3
	WT.01.03	--	--	●	Telnet/SSH/TFTP	5.3
<b>Proxim</b>						
AP 600	2.3.1	●	--	●	SNMP/TFTP	2.2.0
	2.3.3	●	--	●	SNMP/TFTP	2.3.0
	2.4.3	●	●	●	SNMP/TFTP	2.5.0
	2.4.5	●	●	●	SNMP/TFTP	2.6.0
	2.4.11	●	●	●	SNMP/TFTP	2.8.0
	2.5.2	●	●	●	SNMP/TFTP	3.1.2
	2.5.3	●	●	●	SNMP/TFTP	3.1.2
	2.5.4	●	●	●	SNMP/TFTP	4.1.0
AP 700	2.5.5	●	●	●	SNMP/TFTP	3.3.1
	2.5.2	●	●	●	SNMP/TFTP	3.2.1
	2.6.0	●	●	●	SNMP/TFTP	3.2.1
	3.1.0	●	●	●	SNMP/TFTP	3.4.2
	3.2.0	●	●	●	SNMP/TFTP	4.2.0
	3.2.1	●	●	●	SNMP/TFTP	4.3.4
	3.4.0	●	●	●	SNMP/TFTP	4.4.1
	3.6.2	●	●	●	SNMP/TFTP	5.3
	3.7.0	●	●	●	SNMP/TFTP	6.1.0
	4.0.1	●	●	●	SNMP/TFTP	6.2.0
AP 2000	4.0.2	●	●	●	SNMP/TFTP	6.3.0
	2.0	●	--	●	SNMP/TFTP	2.2.0
	2.3.3	●	--	●	SNMP/TFTP	2.3.0
	2.4.0	●	●	●	SNMP/TFTP	2.5.0
	2.4.3	●	●	●	SNMP/TFTP	2.5.0
	2.4.5	●	●	●	SNMP/TFTP	2.6.0
	2.4.11	●	●	●	SNMP/TFTP	2.8.0
	2.5.2	●	●	●	SNMP/TFTP	3.1.2
	2.5.3	●	●	●	SNMP/TFTP	3.1.3
	2.5.4	●	●	●	SNMP/TFTP	3.3.1
AP 4000	2.5.5	●	●	●	SNMP/TFTP	4.1.0
	2.4.5	●	●	●	SNMP/TFTP	2.11.0
	2.4.11	●	●	●	SNMP/TFTP	2.11.0
	2.4.12	●	●	●	SNMP/TFTP	3.0.2
	2.5.2	●	●	●	SNMP/TFTP	3.1.2
	2.6.0	●	●	●	SNMP/TFTP	3.1.3
	3.1.0	●	●	●	SNMP/TFTP	3.4.2
	3.2.0	●	●	●	SNMP/TFTP	4.2.0
	3.2.1	●	●	●	SNMP/TFTP	4.3.4
	3.4.0	●	●	●	SNMP/TFTP	4.4.1
AP 4000M AP 4900M	3.6.2	●	●	●	SNMP/TFTP	5.3
	3.7.0	●	●	●	SNMP/TFTP	6.1.0
	4.0.0	●	●	●	SNMP/TFTP	6.2.0
	4.0.2	●	●	●	SNMP/TFTP	6.3.0
	3.2.0	●	●	●	SNMP/TFTP	4.3.4
	3.2.1	●	●	●	SNMP/TFTP	4.3.4
	3.4.0	●	●	●	SNMP/TFTP	4.4.1
	3.6.2	●	●	●	SNMP/TFTP	5.3
Tsunami MP.16 3500(i) SS, 3500 BS	3.7.0	●	●	●	SNMP/TFTP	6.1.0
	4.0.0	●	●	●	SNMP/TFTP	6.2.0
	4.0.2	●	●	●	SNMP/TFTP	6.3.0
Tsunami MP.11a	1.2.0(115)	●	●	●	SNMP/TFTP	5.0
	1.2.0(124)	●	●	●	SNMP/TFTP	5.1
	2.0.1	●	●	●	SNMP/TFTP	3.2.4
	2.2.0	●	●	●	SNMP/TFTP	3.2.4
Tsunami MP.11	2.2.2	●	●	●	SNMP/TFTP	3.2.4
	2.2.6	●	●	●	SNMP/TFTP	3.4.2
	2.3.0	●	●	●	SNMP/TFTP	5.2.0
5054,4954, 954, 2454, 5012	4.0.0	●	●	●	SNMP/TFTP	5.2.0

OV3600 Firmware Matrix - part number 0510591

OV3600	Firmware	Upgrade	Downgrade	Configuration	Protocol	Supported since Version
<b>Siemens</b>						
W788-2 PRO	1.2.4	--	--	--	--	3.2.2
<b>Symbol</b>						
3021	04.01-23	●	●	●	SNMP/TFTP	4.0.1
	04.02-19	●	●	●	SNMP/TFTP	4.0.1
4121	3.52.13	●	--	●	SNMP/TFTP	2.2.0
	2.70.06	●	●	●	SNMP/TFTP	2.2.0
4131	3.51-20	●	--	●	SNMP/TFTP	2.2.0
	3.70-72	●	●	●	SNMP/TFTP	3.0.4
	3.92-29	●	●	●	SNMP/TFTP	3.0.7
	3.93-00	●	●	●	SNMP/TFTP	3.4.2
	3.94-15	●	●	●	SNMP/TFTP	4.3.0
5131	1.1.0.0.045R	--	--	--	--	5.2.1
	1.1.0.0.045R	--	--	●	Telnet/TFTP	5.2.4
	2.0	●	●	●	Telnet/TFTP	6.1.0
	2.1.0	●	●	●	Telnet/TFTP	6.2.0
5181	2.2.0	●	●	●	Telnet/TFTP	6.3.0
	1.1.2	●	●	●	Telnet/TFTP	6.2.0
WS5000 & APs	0.0-35R	--	--	--	--	4.3.0
	2.0.0	--	--	--	--	4.4.0
WS2000 & APs	0.0-35R	--	--	●	Telnet/TFTP	5.0
	2.2.3.0-020R	--	--	●	Telnet/TFTP	6.0
	2.2.3.0-020R	●	--	●	Telnet/TFTP	6.1
	2.3.2.0-003R	●	--	●	Telnet/TFTP	6.3
WS5100 & APs	2.4.0.0-023R	●	--	●	Telnet/TFTP	6.3
	2.0.0	--	--	--	--	4.4.0
	3.0.0	--	--	●	Telnet/TFTP	5.0
	3.0.2	●	●	●	Telnet/TFTP	5.3
	3.0.3	●	●	●	Telnet/TFTP	5.3
	3.0.3	●	●	●	Telnet/SSH/TFTP	6.0.0
	3.1.0	●	●	●	Telnet/SSH/TFTP	6.1.0
	3.2.0	●	●	●	Telnet/SSH/TFTP	6.1.0
3.3.1	●	●	●	Telnet/SSH/TFTP/FTP	6.3.0	
RFS6000	3.2.0	--	--	●	Telnet/SSH/TFTP	6.2.0
RFS7000	1.0.0.0-357R	●	--	●	Telnet/SSH/TFTP	6.0
	1.2.0.0-040R	●	●	●	Telnet/SSH/TFTP/FTP	6.3
	4.0.0.0-067R	●	●	●	Telnet/SSH/TFTP/FTP	6.3
<b>Systimax</b>						
Airspeed 542	2.4.5	●	●	●	SNMP/TFTP	3.2
	2.4.11	●	●	●	SNMP/TFTP	3.2
	2.4.12	●	●	●	SNMP/TFTP	3.2
	2.5.2	●	●	●	SNMP/TFTP	3.2
	2.6.0	●	●	●	SNMP/TFTP	3.2
<b>Toshiba</b>						
AP 500	3.95	●	●	●	--	2.2.0
<b>Teklogix</b>						
9150/9160	C234p	--	--	●	--	4.4.0
<b>Trapeze</b>						
MX Series & MPs	5.0.12.2	--	--	--	--	5.1.0
	5.0.12.2	●	●	●	Telnet/TFTP/FTP	5.3
	6.0.2.2	--	--	--	--	5.1.0
	6.0.2.2	●	●	●	Telnet/TFTP/FTP	5.3
	6.0.4.2	●	●	●	Telnet/TFTP/FTP	5.3
<b>Tropos</b>						
4/5210, 5320, 9422, 9532	5.1.4.7	--	--	--	--	5.0
3/4/5210, 5320, 9422, 9532	5.1.4.7	--	--	--	--	5.3
	6.5.1.3	--	--	--	--	5.3
	6.6.0.0	--	--	--	--	5.3
	6.6.1.3	--	--	--	--	6.2.0
<b>Vivato</b>						
VP1200	1.3.1.r4	--	--	--	--	3.3.2
VA2200	1.1.r2	--	--	--	--	3.3.1
	2.2	--	--	--	--	3.4.2
VP2200	3.0.r9	--	--	--	--	5.2.4

© 2009 Alcatel-Lucent. Alcatel, Lucent, Alcatel-Lucent, and the Alcatel-Lucent logo are trademarks of Alcatel-Lucent. All rights reserved. All other trademarks are the property of their respective owners.