

Release Notes

EAP300

Ver. 1.7.2

Revision History

Revision	Date	Reason of Changes
V1.7.2	Jan 29, 2015	Enhancement and bug fix update

Change Log

F/W Version	V1.7.2
Type	Description
New Feature	N/A
Change	1. Add patch for stuck beacon
Fix	1. Fixed reboot schedule