

Release Notes

EAP350

Ver. 1.5.16

Revision History

Revision	Date	Reason of Changes
V1.5.16	Feb 26, 2015	New Feature and Fix Update

Change Log

F/W Version	V1.5.16
Type	Description
New Feature	<ol style="list-style-type: none">1. Add L2 isolation support in management GUI.2. Add multicast to unicast support in management GUI, CLI, and SNMP.
Change	N/A
Fix	<ol style="list-style-type: none">1. Fix the issue that two MAC addresses shown in switch arp table when enabling management VLAN.