

<![endif]-->

ESR7750 Changelog

Release Date May 12, 2010

WEB version: 1.1.3

Firmware upgrade:

- ESR-7750-KNL-V1-1-3-75.dlf
- ESR-7750-APPS-V1-1-3-50.dlf

MD5 Checksum:

- APPS : 0be5b12f28784f2ae4e48f82b0792fa9
- KNL : 60423b56011365a37328eabf21f118a7

New Features

- N/A

Problems Resolved:

- N/A.

Change:

- NAT session up to 30000

Release Date Jan 12, 2010

WEB version: 1.1.2

Firmware upgrade:

- ESR-7750-KNL-V1-1-2-74.dlf
- ESR-7750-APPS-V1-1-2-48.dlf

MD5 Checksum:

- APPS : 3af29bf5c879390189592140dd13670c
- KNL : 04e87778fefdfa14eef3ed0445a3f07b

New Features

- N/A

Problems Resolved:

- Fixed the internet can't connect when setting and enable Port Forwarding function.

- Fixed the using build-in Windows 7 wireless (2.4G and 5G) to change wireless encryption type.

Change:

- N/A

Release Date Dec 30, 2009**WEB version: 1.1.1****Firmware upgrade:**

- ESR-7750-KNL-V1-1-1-65.dlf
- ESR-7750-APPS-V1-1-1-43.dlf

MD5 Checksum:

- APPS : 17bb349906f4d8946f07a9711bcff340
- KNL : 4b3bfb92147743335a57f5152e6bd008

New Features

- N/A

Problems Resolved:

- Fixed 5G will be enable when enable 5G WDS after disable 5G radio.

Change:

- N/A

Release Date Dec 18, 2009**WEB version: 1.1.1****Firmware upgrade:**

- ESR-7750-KNL-V1-1-1-61.dlf
- ESR-7750-APPS-V1-1-1-41.dlf

MD5 Checksum:

- APPS : 73b05efc2356b5b70fbb1b3d9588f280
- KNL : d1948b04180776ac6f00b77c251ed4f4

New Features

- N/A

Problems Resolved:

- Fixed WDS encryption in 2.4G issue.
- Fixed 5G WDS enable issue.

Change:

- N/A

Release Date Dec 10, 2009**WEB version: 1.1.1****Firmware upgrade:**

- ESR-7750-KNL-V1-1-1-59.dlf
- ESR-7750-APPS-V1-1-1-40.dlf

MD5 Checksum:

- APPS : 6345568895ada8589484ffccfa4f110f
- KNL : 0949629adbadc065bebb535d97ce1bea

New Features

- Support Windows 7.

Problems Resolved:

- Fix Date Code 0943 issue.
- Fixed WDS encryption issue.

Change:

- N/A

Release Date Nov 12, 2009**WEB version: 1.1.0****Firmware upgrade:**

- ESR-7750-APPS-V1-1-0-18.dlf
- ESR-7750-KNL-V1-1-0-26.dlf

MD5 Checksum:

- APPS : 300827fede5edfe640f054ae8ab2e19d
- KNL : 914f6e9cf78ae68fad59d74a80ef9993

New Features

- N/A

Problems Resolved:

- Fixed UPnP issue in Windows 7.

Change:

- N/A

Release Date Nov 3, 2009

WEB version: 1.1.0

Firmware upgrade:

- ESR-7750-APPS-V1-1-0-15.dlf
- ESR-7750-KNL-V1-1-0-20.dlf

MD5 Checksum:

- APPS : ae2bb00d153d82c89df650eecbc63e5f
- KNL : 4f5b937f5b4bcf8eb4ff8b33b13aebc6

New Features

- Support Windows 7

Problems Resolved:

- Fixed the 5G WPS issue.

Change:

- N/A

Release Date Aug 4, 2009

WEB version: 1.0.1

Firmware upgrade:

- ESR-7750-APPS-V1-0-1-13.dlf
- ESR-7750-KNL-V1-0-1-16.dlf

MD5 Checksum:

- APPS : D108EB4707980F8552797141AF49A236
- KNL : AC7CDA35FBF1AA85B4343AACEF676CF3

New Features

- N/A

Problems Resolved:

- Fixed the PPTP issue.
- Fixed the WLAN client connect issue.
- Fixed the URL filtering issue.

Change:

- N/A

Release Date Jun 18, 2009**WEB version: 1.0.1****Firmware upgrade:**

- ESR-7750-APPS-V1-0-1-3.dlf
- ESR-7750-KNL-V1-0-1-6.dlf

MD5 Checksum:

- APPS : 4C9402BA741131932E2BCD1E5695923C
- KNL : CC3992FAFB2723EA6BFB9D9F9CE706F0

New Features

- No brand

Problems Resolved:

- N/A

Change:

- N/A

Release Date Jun 04, 2009**WEB version: 1.0.0****Firmware upgrade:**

- ESR-7750-APPS-V1-0-0-73.dlf
- ESR-7750-KNL-V1-0-0-103.dlf

MD5 Checksum:

- **APPS : A66C801D07F4570CB64581E1F92F9494**
- **KNL : FB3F4B72184A7B4CB4BA4B9F5790DDF7**

New Features

- N/A

Problems Resolved:

- Fixe reset button don't work issue (2.1.8.1)
- Fixe wireless 5G channel issue (2.6.1.4)
- Fixe PPTP test issue (2.27.4)
- Fixe 5G policy test between wireless client and wired client issue (2.6.1.21)
- Fixe QoS issue (2.33.1.1.2 / 2.33.1.1.3/2.33.1.2.5.1)

Change:

- N/A

Release Date [May 27, 2009](#)

WEB version: 1.0.0

Firmware upgrade:

- **ESR-7750-APPS-V1-0-0-71.dlf**
- **ESR-7750-KNL-V1-0-0-99.dlf**

MD5 Checksum:

| **APPS : 4CAB100081C0F8A60FB76AA430D049D1**

New Features

- N/A

Problems Resolved:

- Fixe disable 5G radio issue (2.6.1)
- Fixe wireless channel test in 2.4G issue (2.6.1.4)
- Fixe enrollee PIN issue (2.6.1.18.1.1 / 2.6.2.18.1.1)
- Fixe policy function in 5G issue (2.6.1.21)
- Fixe country selection in 5G issue (2.6.1.22)
- Fixe WDS in 5G issue (2.6.2)
- Fixe port mapping issue (2.11)
- Fixe port forwarding (Virtual Server) issue (2.12)
- Fixe QoS issue (2.33.1.1.2 / 2.33.1.1.3)

Change:

- Remove country which doesn't support 5G.

<First Release>