

# **Release Notes**

**EWS7926EFP**

**Ver. v1.06.23\_c1.8.77**

## Revision History

Revision	Date	Reason of Changes
v1.06.23_c1.8.77	Nov 5, 2018	Change update

## Change Log

**Notice:** APs upgraded to c1.8.x version can only be managed by ezMaster/EWS Switch running c1.8 software.

F/W Version	v1.06.23_c1.8.77
Type	Description
New Feature	N/A
Change	<ol style="list-style-type: none"><li>1. Update CAPWAP version to c1.8.77</li><li>2. Users should upgrade switch firmware to this version if they like to upgrade the switch to the next generation of EWS switches with controller version c1.9.</li><li>3. This version has supported the checking mechanism on EWS300AP for upgrade to EWS switches with controller version c1.9.</li><li>4. This version has supported the checking mechanism on EAP1300 and ENS620EXT. Users should upgrade both AP firmware to the middle version and then go to the final version.</li></ol>
Fix	N/A