

RUCKUS LTE AP Release Notes SC 04.05.00

© 2022 CommScope, Inc. All rights reserved.

ARRIS, the ARRIS logo, COMMSCOPE, RUCKUS, RUCKUS WIRELESS, the Ruckus logo, and the Big Dog design are trademarks of CommScope, Inc. and/or its affiliates. Wi-Fi Alliance, Wi-Fi, the Wi-Fi logo, Wi-Fi Certified, the Wi-Fi CERTIFIED logo, Wi-Fi Protected Access, the Wi-Fi Protected Setup logo, Wi-Fi Protected Setup, Wi-Fi Multimedia and WPA2 and WMM are trademarks or registered trademarks of Wi-Fi Alliance. All other trademarks are the property of their respective owners.

No part of this content may be reproduced in any form or by any means or used to make any derivative work (such as translation, transformation, or adaptation) without written permission from CommScope, Inc. and/or its affiliates ("CommScope"). CommScope reserves the right to revise or change this content from time to time without obligation on the part of CommScope to provide notification of such revision or change.

CommScope provides this content without warranty of any kind, implied or expressed, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. CommScope may make improvements or changes in the products or services described in this content at any time. The capabilities, system requirements and/or compatibility with third-party products described herein are subject to change without notice.

Contents

- About this Release..... 4
 - Supported Hardware..... 4
- New in this Release..... 4
- Resolved Issues..... 4
- Known Issues..... 4

About this Release

This document provides release information for Ruckus LTE AP Release SC 04.05.0000 including information on new features, resolved issues, and unresolved issues.

Supported Hardware

Ruckus LTE AP Release SC 04.05.0000 supports the following Access Point models:

P01-Q910-US02
P01-Q710-US02
P01-Q410-US01

NOTE

Legacy Access Points P01-Q910-US00 and P01-Q710-US00 are also supported, but without Carrier Aggregation (CA) capabilities.

New in this Release

There are no new features in Ruckus LTE AP Release SC 04.05.00.

Resolved Issues

The following are resolved issues for release 04.05.00.

Resolved Issues	Description
CBRSE-447	Amazon: System Crash(252025000163).
CBRSE-448	Comcast Xfinity Trial: "E_SYSTEM_CRASH" in version 04.04.00.0013.
CBRSE-464	Howard University-11 AP's show disconnected in CHN-CBRS-1 Venue.
CBRSE-481	Amdocs-Howard University-Multiple APs seeing E_SYSTEM_CRASH with SOMC APP.

Known Issues

There are no known issues for release 04.05.00.

COMMScope®
RUCKUS®

© 2022 CommScope, Inc. All rights reserved.
350 West Java Dr., Sunnyvale, CA 94089 USA
<https://www.commscope.com>